Drake Street

1002 & 1030 Drake Street

Columbia, Richland County, SC

August 19, 2022

Terracon Project No. 73227142



Prepared for: Terra Alta Ventures LLC Salt Lake City, Utah

Prepared by:

Terracon Consultants, Inc. Columbia, South Carolina

terracon.com



Environmental Facilities Geotechnical Materials

August 19, 2022



Terra Alta Ventures LLC 1775 E 4500th S Salt Lake City, UT 84117

Attn: Mr. David Madsen

P: (801) 916-6366

E: david@thorntonwalker.com

Re: Phase I Environmental Site Assessment

Drake Street

1002 Drake Street

Columbia, Richland County, South Carolina 29209

Terracon Project No. 73227142

Dear Mr. Madsen:

Terracon Consultants, Inc. (Terracon) is pleased to submit the enclosed Phase I Environmental Site Assessment (ESA) report for the above-referenced site. This assessment was performed in accordance with Terracon Proposal No. P73227142 authorized July 5, 2022.

We appreciate the opportunity to be of service to you on this project. In addition to Phase I services, our professionals provide geotechnical, environmental, construction materials, and facilities services on a wide variety of projects locally, regionally and nationally. For more detailed information on all of Terracon's services please visit our website at www.terracon.com. If there are any questions regarding this report or if we may be of further assistance, please do not hesitate to contact us.

Sincerely,

Terracon Consultants, Inc.

William W. Hinson

Staff Scientist

Norman E. Partin Jr., CHMM

Department Manager

Attachments



Terracon Consultants Inc. 521 Clemson Rd Columbia, SC 29229-4307

P 803-741-9000 F 803-741-9900 terracon.com

TABLE OF CONTENTS

| | | A | Page No. |
|------|-----|---|----------|
| EXEC | _ | SUMMARY | |
| | | ngs and Opinions lusions | |
| | | | |
| 4.0 | | mmendations | |
| 1.0 | | ODUCTION | |
| | 1.1 | Site Description | |
| | 1.2 | Scope of Services | |
| | 1.3 | Standard of Care | |
| | 1.4 | Additional Scope Limitations, ASTM Deviations and Data Gaps | |
| | 1.5 | Reliance | |
| | 1.6 | Client Provided Information | |
| 2.0 | | SICAL SETTING | |
| 3.0 | | ORICAL USE INFORMATION | |
| | 3.1 | Historical Topographic Maps, Aerial Photographs, Sanborn Maps | |
| | 3.2 | Historical City Directories | |
| | 3.3 | Site Ownership | |
| | 3.4 | Title Search | |
| | 3.5 | Environmental Liens and Activity and Use Limitations | |
| | 3.6 | Interviews Regarding Current and Historical Site Uses | |
| | 3.7 | Prior Report Review | |
| 4.0 | | ORDS REVIEW | |
| | 4.1 | Federal and State/Tribal Databases | _ |
| | 4.2 | Local Agency Inquiries | |
| 5.0 | | RECONNAISSANCE | |
| | 5.1 | General Site Information | |
| | 5.2 | Overview of Current Site Occupants | 13 |
| | 5.3 | Overview of Current Site Operations | 13 |
| | 5.4 | Site Observations | |
| 6.0 | ADJ | DINING PROPERTY RECONNAISSANCE | 17 |
| 7.0 | ADD | ITIONAL SERVICES | 17 |
| QΛ | DEC | LARATION | 10 |

TABLE OF CONTENTS (continued)

APPENDICES

APPENDIX A Exhibit 1 - Topographic Map

Exhibit 2 - Site Diagram

APPENDIX B Site Photographs

APPENDIX C Historical Documentation and User Questionnaire

APPENDIX D Environmental Database Information

APPENDIX E Credentials

APPENDIX F Description of Terms and Acronyms

Drake Street ■ Columbia, SC

August 19, 2022 Terracon Project No. 73227142



i

EXECUTIVE SUMMARY

This Phase I Environmental Site Assessment (ESA) was performed in accordance with Terracon Proposal No. P73227142 authorized July 5, 2022, and was conducted consistent with the procedures included in ASTM E1527-13, *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process.* The ESA was conducted under the supervision or responsible charge of Norman E. Partin Jr., CHMM, Environmental Professional. William W. Hinson performed the site reconnaissance on July 20, 2022.

Findings and Opinions

A summary of findings is provided below. It should be recognized that details were not included or fully developed in this section, and the report must be read in its entirety for a comprehensive understanding of the items contained herein.

Site Description and Use

The approximately 6.8-acre tract of land (Richland County Parcel R16408-01-01) is improved with four, one story structures. The northernmost structure (1030 Drake) is a hanger-style building currently occupied by two tenants and utilized for construction materials storage and workspace. The three structures located in the central portion of the site (1002 Drake) consist of a former office building, a former hanger style maintenance building (collapsed), and an open sided shed (collapsed). The three centrally located structures are vacant with no current operations. Site topography is slightly sloping to the south-southeast.

Historical Information

Based on a review of the historical information, the site was primarily agricultural land until the central portion of the site was developed with the large warehouse building, small office building, and the open-sided shed in the early 1940s. The site was improved with the large warehouse building on the northern site boundary by 1951. The site remains developed with the four structures today; however, the centrally located warehouse building and open-sided shed have collapsed. Commercial development began on the south adjoining property (Columbia Organic Chemical Company) in the 1940s. Commercial development began on the eastern adjoining properties in the early 1950s. The northern adjoining property was improved with a large apparent commercial warehouse from the late 1950s to the late 1990s. The western adjacent properties were improved with single-family residential dwellings starting in 2013.

Records Review

Revise according to section 4.1.

Site Reconnaissance

During the site reconnaissance, Terracon observed the interior of the hanger-style warehouse on the northern portion of the property and the former office building located on the central

Drake Street Columbia, SC

August 19, 2022 Terracon Project No. 73227142



portion of the site. The remaining two structures (former hanger-style maintenance building and former open sided shed) were observed to be very dilapidated and collapsed. Site features of note include five pole-mounted transformers, two portable air compressors, multiple 55-gallon metal and plastic drums, one heating oil UST, large amounts of dumped construction debris and trash associated with apparent homeless camps, and several groundwater monitoring wells from previous assessments.

Adjoining Properties

The site is bound to the north by undeveloped wooded land; to the east by abandoned railroad lines, William Construction, Multi-unit commercial retail space, and apartments; to the south by wooded land (the former Cardinal Organic Chemical Property); and to the west by Drake Street with multi-tenant residential apartments and single-family residential dwellings.

Conclusions

We have performed a Phase I ESA consistent with the procedures included in ASTM Practice E 1527-13 at 1002 Drake Street, Columbia, Richland County, South Carolina, the site. The following Recognized Environmental Conditions (RECs) or Controlled RECs (CRECs) were identified in connection with the site:

- Documented contamination on the subject site sourced from past on-site and off-site activities.
- The on-site heating oil UST

Recommendations

Based on the scope of services, limitations, and conclusions of this assessment, Terracon recommends the following additional actions.

- Further soils characterization is necessary to fully define the horizontal and vertical extent of site soil impacts and to determine appropriate remedial action prior to site redevelopment.
- Prior to closing on the property, Terracon recommends that the client prepare a Non-Responsible Party application to the SCDHEC Voluntary Cleanup Program.

Drake Street • 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 • Terracon Project No. 73227142



1.0 INTRODUCTION

1.1 Site Description

| Site Name | Drake Street |
|-----------------------------|---|
| Site Location/Address | 1002 & 1030 Drake Street, Columbia, Richland County, SC |
| Land Area | Approximately 6.86-acres |
| | Approximately 15,000-sf hanger-style warehouse |
| Site Improvements | Approximately 2,500-sf vacant former office building |
| Site Improvements | Approximately 10,000-sf former maintenance building (collapsed) |
| | Approximately 3,900-sf former open-sided shed (collapsed) |
| Anticipated Future Site Use | Redevelopment |
| Reason for the ESA | Acquiring the site |
| | I . |

The location of the site is depicted on Exhibit 1 of Appendix A, which was reproduced from a portion of the USGS 7.5-minute series topographic map. The site and adjoining properties are depicted on the Site Diagram, which is included as Exhibit 2 of Appendix A. Acronyms and terms used in this report are described in Appendix F.

1.2 Scope of Services

This Phase I ESA was performed in accordance with Terracon Proposal No. P73227142 authorized July 5, 2022, and was conducted consistent with the procedures included in ASTM E1527-13, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process. The purpose of this ESA was to assist the client in developing information to identify RECs in connection with the site as reflected by the scope of this report. This purpose was undertaken through user-provided information, a regulatory database review, historical and physical records review, interviews, including local government inquiries, as applicable, and a visual noninvasive reconnaissance of the site and adjoining properties. Limitations, ASTM deviations, and significant data gaps (if identified) are noted in the applicable sections of the report.

ASTM E1527-13 contains a new definition of "migrate/migration," which refers to "the movement of hazardous substances or petroleum products in any form, including, for example, solid and liquid at the surface or subsurface, and vapor in the subsurface." By including this explicit reference to migration in ASTM E1527-13, the Standard clarifies that the potential for vapor migration should be addressed as part of a Phase I ESA. This Phase I ESA has considered vapor migration in evaluation of RECs associated with the site.

Drake Street ■ 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 ■ Terracon Project No. 73227142



1.3 Standard of Care

This ESA was performed in accordance with generally accepted practices of this profession, undertaken in similar studies at the same time and in the same geographical area. We have endeavored to meet this standard of care, but may be limited by conditions encountered during performance, a client-driven scope of work, or inability to review information not received by the report date. Where appropriate, these limitations are discussed in the text of the report, and an evaluation of their significance with respect to our findings has been conducted.

Phase I ESAs, such as the one performed at this site, are of limited scope, are noninvasive, and cannot eliminate the potential that hazardous, toxic, or petroleum substances are present or have been released at the site beyond what is identified by the limited scope of this ESA. In conducting the limited scope of services described herein, certain sources of information and public records were not reviewed. It should be recognized that environmental concerns may be documented in public records that were not reviewed. No ESA can wholly eliminate uncertainty regarding the potential for RECs in connection with a property. Performance of this practice is intended to reduce, but not eliminate, uncertainty regarding the potential for RECs. No warranties, express or implied, are intended or made. The limitations herein must be considered when the user of this report formulates opinions as to risks associated with the site or otherwise uses the report for any other purpose. These risks may be further evaluated – but not eliminated – through additional research or assessment. We will, upon request, advise you of additional research or assessment options that may be available and associated costs.

1.4 Additional Scope Limitations, ASTM Deviations and Data Gaps

Based upon the agreed-on scope of services, this ESA did not include subsurface or other invasive assessments, vapor intrusion assessments or indoor air quality assessments (i.e. evaluation of the presence of vapors within a building structure), business environmental risk evaluations, or other services not particularly identified and discussed herein. Credentials of the company (Statement of Qualifications) have not been included in this report but are available upon request. Pertinent documents are referred to in the text of this report, and a separate reference section has not been included. Reasonable attempts were made to obtain information within the scope and time constraints set forth by the client; however, in some instances, information requested is not, or was not, received by the issuance date of the report. Information obtained for this ESA was received from several sources that we believe to be reliable; nonetheless, the authenticity or reliability of these sources cannot and is not warranted hereunder.

An evaluation of the significance of limitations and missing information with respect to our findings has been conducted, and where appropriate, significant data gaps are identified and discussed in the text of the report. However, it should be recognized that an evaluation of significant data gaps is based on the information available at the time of report issuance, and an evaluation of information received after the report issuance date may result in an alteration of our conclusions, recommendations, or opinions. We have no obligation to provide information

Drake Street ■ 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 ■ Terracon Project No. 73227142



obtained or discovered by us after the issuance date of the report, or to perform any additional services, regardless of whether the information would affect any conclusions, recommendations, or opinions in the report. This disclaimer specifically applies to any information that has not been provided by the client.

This report represents our service to you as of the report date and constitutes our final document; its text may not be altered after final issuance. Findings in this report are based upon the site's current utilization, information derived from the most recent reconnaissance and from other activities described herein; such information is subject to change. Certain indicators of the presence of hazardous substances or petroleum products may have been latent, inaccessible, unobservable, or not present during the most recent reconnaissance and may subsequently become observable (such as after site renovation or development). Further, these services are not to be construed as legal interpretation or advice.

1.5 Reliance

This ESA report is prepared for the exclusive use and reliance of Terra Alta Ventures LLC. Use or reliance by any other party is prohibited without the written authorization of Terra Alta Ventures LLC and Terracon Consultants, Inc. (Terracon).

Reliance on the ESA by the client and all authorized parties will be subject to the terms, conditions and limitations stated in the proposal, ESA report, and Terracon's Agreement for Services. The limitation of liability defined in the Agreement for Services is the aggregate limit of Terracon's liability to the client and all relying parties.

Continued viability of this report is subject to ASTM E1527-13 Sections 4.6 and 4.8. If the ESA will be used by a different user (third party) than the user for whom the ESA was originally prepared, the third party must also satisfy the user's responsibilities in Section 6 of ASTM E1527-13.

1.6 Client Provided Information

Prior to the site visit, David Madsen, client's representative, was asked to provide the following user questionnaire information as described in ASTM E1527-13 Section 6.

Client Questionnaire Responses

| Client Questionnaire Item | Client Did Not | Client's Response | |
|--|----------------|----------------------|----|
| | Respond | Yes | No |
| Specialized Knowledge or Experience that is material to a REC in connection with the site. | | Х | |
| Actual Knowledge of Environmental Liens or Activity Use Limitations (AULs) that may encumber the site. | | | X |

Drake Street • 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 • Terracon Project No. 73227142



| Client Questionnaire Item | Client Did Not | Client's Response | |
|--|----------------|----------------------|----|
| | Respond | Yes | No |
| Actual Knowledge of a Lower Purchase Price because contamination is known or believed to be present at the site. | | Х | |
| Commonly Known or Reasonably Ascertainable Information that is material to a REC in connection with the site. | | Х | |
| Obvious Indicators of Contamination at the site. | | Х | |

The client acknowledged that Terracon performed a Phase II ESA on the property dated July 23, 2008, and to refer to the prior report for all "Yes" answers. A copy of the questionnaire is included in Appendix C.

2.0 PHYSICAL SETTING

| Pi | nysical Setting Information | Source | | | |
|-----------------------|--|--|--|--|--|
| Topography | | | | | |
| Site Elevation | Approximately 245 - 255 feet above sea level | USGS Topographic | | | |
| Topographic Gradient | Gently sloping towards the south-southwest | Map, Fort Jackson | | | |
| Closest Surface Water | Wildcat Creek, approximately 3,750 feet north of the site. | South, SC, 1987 (Appendix A) | | | |
| | Soil Characteristics | | | | |
| Soil Type | Dothan loamy sand Dothan-Urban land Complex Fuquay-Urban Land Complex The Dothan series is characterized as nearly | | | | |
| Description | level, deep, well drained soils that are easily worked. They are moderately permeable and have a medium to high water holding capacity. Deep well drained soils on nearly level to rolling uplands of the coastal plains. Urban land is land mostly covered by streets, parking lots, buildings, and other structures of urban areas. Very deep, well drained, nearly level to sloping soils on uplands in the upper coastal plain. Urban land is mostly covered by streets, parking lots, buildings, and other structures of urban areas. | Richland County, SC Soil Source issued August 11, 2022 | | | |
| Geology/Hydrogeology | | | | | |
| Formation | Recent to Cretaceous-age sediments | Geology of the | | | |

Drake Street • 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 • Terracon Project No. 73227142



| Phys | Source | |
|--|---|---|
| Description | Coastal Plain physiographic province - a seaward thickening wedge of unconsolidated sands, silts, and clays deposited over a rock basement. | Carolinas, Carolina Geological Society, 1991 |
| Estimated Depth to First Occurrence of Groundwater | Approximately 12-25 feet bgs | Terracon's Phase II Site Investigation Report dated July 23, 2008 |
| *Hydrogeologic Gradient | Not known - may be inferred to be parallel to topo to the north). | graphic gradient (primarily |

^{*} The groundwater flow direction and the depth to shallow, unconfined groundwater, if present, would likely vary depending upon seasonal variations in rainfall and other hydrogeological features. Without the benefit of on-site groundwater monitoring wells surveyed to a datum, groundwater depth and flow direction beneath the site cannot be directly ascertained.

3.0 HISTORICAL USE INFORMATION

Terracon reviewed the following historical sources to develop a history of the previous uses of the site and surrounding area, in order to help identify RECs associated with past uses. Copies of selected historical documents are included in Appendix C.

3.1 Historical Topographic Maps, Aerial Photographs, Sanborn Maps

Readily available historical USGS topographic maps and selected historical aerial photographs (at approximately 10-to-15-year intervals) were reviewed to evaluate land development and obtain information concerning the history of development on and near the site. Reviewed historical topographic maps and aerial photographs are summarized below.

Historical fire insurance maps produced by the Sanborn Map Company were requested from ERIS to evaluate past uses and relevant characteristics of the site and surrounding properties. Based upon inquiries to the above-listed Sanborn provider, Sanborn maps were not available for the site.

- Topographic map: Hopkins, SC 1948; Fort Jackson North & Fort Jackson South, SC 1953, 1972, 1982, 1987, 2014, 2017, 2020; (1" = 2000')
- Aerial photograph: ASCS 1938, 1943, 1951, 1959; USN 1961; USAF 1964;
 USGS 1971, 1978, 1983, 1989, 1994; USDA 2005, 2006, 2011, 2013, 2015, 2017, 2019; (1" = 500')

Drake Street • 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 • Terracon Project No. 73227142



Historical Maps and Aerial Photographs

| Direction | Description |
|-----------|--|
| Site | Agricultural land (1938); Central portion of the site developed with apparent large warehouse building, small office building, and open-sided shed (1943); Improved with large warehouse building on the northern site boundary (1951); Site developed with two large warehouses, open-sided shed building, small office, and wooded land (1959-2020); Tractor trailers and machinery observed (1971 & 1983) |
| North | Apparent residential dwelling with wooded land beyond (1938-1951); Commercial structure with wooded land beyond (1959-1961); Commercial property with residential neighborhoods beyond (1964-1994); Adjoining commercial building demolished (2005); Wooded land with residential neighborhoods beyond (2006-2020) |
| East | Railroad with agricultural land beyond (1938-1951); Adjoining commercial properties with railroad and wooded land beyond (1959-1989); Commercial properties with railroad, wooded land and interstate beyond (1994); Commercial properties with railroad, apartments and interstate beyond as depicted today (2005-2020) |
| South | Agricultural land (1938); Agricultural land with apparent shed building (1943-1951); Apparent commercial manufacturing property (1959-1961); Commercial manufacturing property (1964-1994); Wooded land with shopping center beyond (2005-2020) |
| West | Agricultural land and undeveloped roadway (1938-1943); Roadway with grassed and wooded land beyond (1951-1978); Roadway with multi-tenant dwellings and wooded land beyond (1983-2011); Roadway with further residential development (2011-2013); Residential developments along Drake Street as depicted today (2015-2020) |

3.2 Historical City Directories

The Walsh's, Hill's, Polk's, and Digital Business Directory city directories used in this study were made available through ERIS (selected years reviewed: 1925-2020) and were reviewed at approximate five-year intervals, if readily available. Street listings not available prior to 1958. The current street address for the site was identified as 1002 Drake Street.

Historical City Directories

| Direction | Description | | |
|-----------|--|--|--|
| Site | 1002 Drake Street: Bass Bldg Specialties Inc (1958); No Return (1964); Kahn M B Constn Co Shop (1970-1981); Vacant (1986) 1030 Drake Street: Bonitz Insulation Co of SC (1958); Palmetto Metal Products Inc Mfrs (1964); Industrial Electric Co Inc (1970); Vacant (1976); Casselman Sheet Metal SVC (1996-2008); Master-Plaster Finishing (2012-2020) | | |
| | 6430 Norris Street: Capitol Glass Co Inc (1958); Greenwood Geo R (1958-1964) | | |
| North | 6432 Norris Street: Defender Building Maintenance Co (1964); Defender Chemical Co (1964-1970); Carolina Tool & Die Co (1964-1976); Defender Service Co Hotel & Restaurant Sup (1970); Defender Industrial Maintenance Corp (1970-1976); Defender Chemical Co (1976-1981); R & K Industries (1986); R & K Industries Mach Mfrs (1991) | | |

Drake Street • 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 • Terracon Project No. 73227142



| Direction | Description |
|-----------|---|
| | 951 True Street: Air Products & Chemicals Inc (1986); Carolina Compound Inc Jan Sups (1991); Not Verified (1996); California Closet Co (2000-2008) |
| | 921 True Street: Eleazer A Fred (1964-1981) |
| East | 919 True Street: Carr James H & Associate Environmental Testing Lab (1976-1991); Carr James H Assocs (1996); James H Carr Assoc Inc (2000-2012); Medical Reimbursement Svc (2003); Military Ministries Campus (2003) |
| | 1001 True Street: Multi-Tenant Residential (2008) |
| South | 912 Drake Street: Columbia Organic Chemicals Co (Mfrs) (1970); Columbia Organic Chemicals Co (Mfrs) (1976); Cationic's Inc Div Cola Org Chem Co Chem Mfrs (1981); Columbia Organic Chemicals Co Mfrs (1981); Vacant (1986) |
| West | 933 Drake Street: Frierson Richard (1986); Sato Hitoshi (1986); Vacant (1986-1991); - 1002 Vacant (1991); Morris Lavino L (1991); B Not Verified (1996); Tate Theresa (1996); Theresa Tate (2000-2003); Marlene Harris (2008) |
| | 1001 Drake Street: Todd Reese (2016-2020) |
| | 1003 Drake Street: Nicholas Beers (2016) |

3.3 Site Ownership

Based on a review of information obtained from the Richland County assessor's records, the current site owner is Cedar Corp Inc.

3.4 Title Search

At the direction of the client, a title search was not included as part of the scope of services. Unless notified otherwise, we assume that the client is evaluating this information outside the scope of this report.

3.5 Environmental Liens and Activity and Use Limitations

The ERIS regulatory database report included a review of both Federal and State Engineering Control (EC) and Institutional Control (IC) databases. Based on a review of the database report, the site was not listed on the EC or IC databases. Please note that in addition to these federal and state listings, AULs can be recorded at the county and municipal level that may not be listed in the regulatory database report. Environmental lien and activity and use limitation records recorded against the site were not provided by the client. At the direction of the client, performance of a review of these records was not included as part of the scope of services and unless notified otherwise, we assume that the client is evaluating this information outside the scope of this report.

3.6 Interviews Regarding Current and Historical Site Uses

The following individuals were interviewed regarding the current and historical use of the site.

Drake Street • 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 • Terracon Project No. 73227142



Interviews

| Interviewer | Name / Phone # | Title | Date/Time |
|-------------------|----------------------------|----------------------|------------------------|
| William W. Hinson | Alan Khan / (803) 227-1229 | Owner Representative | August 18, 2022 / 1030 |

Terracon interviewed Mr. Alan Khan, Owner Representative, after the site reconnaissance via phone. Mr. Khan indicated that he has been familiar with the site since 1965. Mr. Khan confirmed that M.B. Khan utilized the centrally located hanger style building (now collapsed) as a shop for vehicle and equipment maintenance as well as construction materials storage. Mr. Khan confirmed that to his knowledge, no environmental assessments have occurred on-site since Terracon's Phase II Environmental Site Assessment in July 2008.

3.7 Prior Report Review

Terracon requested the client provide any previous environmental reports they are aware of for the site. Previous reports were not provided by the client to Terracon for review. However, Terracon completed a Phase II Environmental Site Assessment dated July 23, 2008 on-site, which is summarized in section 4.1.

4.0 RECORDS REVIEW

Regulatory database information was provided by ERIS, a contract information services company. The purpose of the records review was to identify RECs in connection with the site. Information in this section is subject to the accuracy of the data provided by the information services company and the date at which the information is updated. The scope herein did not include confirmation of facilities listed as "unmappable" by regulatory databases.

In some of the following subsections, the words up-gradient, cross-gradient and down-gradient refer to the topographic gradient in relation to the site. As stated previously, the groundwater flow direction and the depth to shallow groundwater, if present, would likely vary depending upon seasonal variations in rainfall and the depth to the soil/bedrock interface. Without the benefit of on-site groundwater monitoring wells surveyed to a datum, groundwater depth and flow direction beneath the site cannot be directly ascertained.

4.1 Federal and State/Tribal Databases

Listed below are the facility listings identified on federal and state/tribal databases within the ASTM-required search distances from the approximate site boundaries. Database definition, descriptions, and the database search report are included in Appendix D.

Drake Street • 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 • Terracon Project No. 73227142



Federal Databases

| Database | Description | Distance (miles) | Listings |
|----------|---|---------------------|----------|
| CERC | Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS | 0.5 | 1 |
| CERL | CERCLIS Liens | Site | 1 |
| CNFR | CERCLIS - No Further Remedial Action Planned | 0.5 | 0 |
| EC | Federal Engineering Controls-ECs | 0.5 | 0 |
| ERN1 | Emergency Response Notification System | Site | 0 |
| ERN2 | Emergency Response Notification System | Site | 0 |
| ERNS | Emergency Response Notification System | Site | 0 |
| FBFL | The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database | 0.5 | 1 |
| FRS | Facility Registry Service/Facility Index | Site | 3 |
| HMIR | Hazardous Materials Information Reporting System | 0.10 | 0 |
| HTSC | Hist TSCA | 0.10 | 0 |
| IC | Federal Institutional Controls- ICs | 0.5 | 1 |
| IODI | EPA Report on the Status of Open Dumps on Indian Lands | 0.5 | 0 |
| NCDL | National Clandestine Drug Labs | Site | 0 |
| NPL | National Priority List | 1 | 0 |
| NPLD | Delisted NPL | 0.5 | 0 |
| NPLP | National Priority List - Proposed | 1 | 0 |
| ODI | Inventory of Open Dumps, June 1985 | 0.5 | 0 |
| RCOR | RCRA CORRACTS- Corrective Action | 1 | 0 |
| RGEN | RCRA Generator List | 0.25 | 4 |
| RNGN | RCRA Non-Generators | 0.25 | 1 |
| RTSD | RCRA non-CORRACTS TSD Facilities | 0.5 | 0 |
| TRI | Toxics Release Inventory (TRI) Program | Site | 0 |
| TSCA | Toxic Substances Control Act | 0.10 | 0 |

State/Tribal Databases

| Database | Description | Distance (miles) | Listings |
|----------|---|---------------------|----------|
| ALL | Site Assessment and Remediation Public Record Database | 0.5 | 0 |
| BFLD | Brownfields Sites Listing | 0.5 | 4 |
| ILST | Leaking Underground Storage Tanks (LUSTs) on Indian Lands | 0.5 | 0 |
| IUST | Underground Storage Tanks (USTs) on Indian Lands | 0.25 | 0 |
| LAST | Leaking Aboveground Storage Tank List | 0.5 | 0 |
| LUST | Leaking Underground Storage Tank List | 0.5 | 11 |

Drake Street ■ 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 ■ Terracon Project No. 73227142



| Database | Description | Distance (miles) | Listings |
|----------|--------------------------------------|---------------------|----------|
| RCR | Registry of Conditional Remedies | 0.5 | 4 |
| SHWS | Site Assessment Section Project List | 1 | 4 |
| SPL | Spills List | 0.10 | 0 |
| SWF | Permitted Landfills List | 0.5 | 0 |
| UST | Underground Storage Tank List | 0.25 | 6 |
| VCP | Voluntary Cleanup Sites | 0.5 | 1 |

In addition to the above ASTM-required listings, Terracon reviewed other federal, state, local, and proprietary databases provided by the database firm. A list of the additional reviewed databases is included in the regulatory database report included in Appendix D.

The following table summarizes the site-specific information provided by the database and/or gathered by this office for identified facilities. Facilities are listed in order of proximity to the site. Additional discussion for selected facilities follows the summary table.

Listed Facilities

| Facility Name and Location | Estimated Distance / Direction/Gradient | Database Listings | Is a REC, CREC, or HREC to the Site |
|-------------------------------|---|----------------------|-------------------------------------|
| Drake St. Property | SITE | FINDS/FRS, | REC |
| 1002, 1030 Drake St. | | BROWNFIELDS | |
| | | (3), FED | |
| | | BROWNFIELDS, | |
| | | SASPL | |
| Columbia Organic | Adjoining the site to the south, | FINDS/FRS, ICIS, | REC |
| Chemical-Drake | cross-gradient | RCRA NON-GEN, | |
| (South Carolina Refining | | PRP (2), SEMS, | |
| and Disposal) | | SEMS LIEN, | |
| 912 Drake Ave | | CERCLIS, | |
| | | CERCLIS LIENS | |
| Air Products & Chemical | Adjoining the site to the SE | UST | NO |
| 951 True St | cross-gradient | | |
| James H Carr & Associates | Adjoining the site to the SE | RCRA VSQG | NO |
| 919 True St | cross-gradient | | |
| Cedar Terrace | Approximately 50 feet NW | SASPL, | NO |
| Development | cross-gradient | BROWNFIELDS, | |
| 1015 Drake St | | VCP | |

Drake Street Property

The site was identified on the; Facility Registry Services (FINDS/FRS), Site Assessment Section Project List (SASPL), Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database (FED BROWNFIELDS), and the Brownfields Sites (BROWNFIELDS) databases. The site was reportedly previous utilized by M.B. Kahn Construction Company for

Drake Street ■ 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 ■ Terracon Project No. 73227142



material handling and storage, vehicle and equipment maintenance/fueling, and servicing. Numerous different environmental assessments have taken place at the site throughout the early 2000's. Terracon completed a Phase II Environmental Site Assessment at the site in 2008, to evaluate the potential on-site and off-site impacts. The 2008 assessment included soil and ground water sampling to identify VOCs, SVOCs, Pesticides, PCB's, dioxins/furans and metals in surface soils across the site and in groundwater downgradient of the site's structures. The site was divided into six areas of investigation and a background location. These areas were approximately 1-acre in size are were designated as Grid "A" through "F". A total of 35 soil samples were collected for TAL/TCL analysis and 11 soil samples were collected for dioxin/furan analysis. During the 2008 assessment, pesticides were identified above residential PRGs in soil collected from grid sections A, B, C, and F. Metals such as arsenic, copper, and lead were identified above Residential PRGs in Section A and lead was above residential PRGs in Section B. PCBs were identified in one soil sample section A above residential PRGs. Based on the results of Terracon's Phase II Site Investigation Report dated July 23, 2008, environmental contamination exists on the site. Exhibits and analytical data from Terracon's previous assessment is provided in Appendix G.

Columbia Organic Chemical Company (COCC)

The southern adjoining former COCC facility was identified on the FINDS/FRS, Integrated Compliance Information System (ICIS), Resource Conservation and Recovery Act (RCRA) Non-Generator, Potential Responsible Part (PRP), Superfund Enterprise Management System (SEMS), SEMS Lien, Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS), and the CERCLIS Liens databases.

According to the SCDHEC file information and online pollution reports, the COCC facility operated on the southern adjoining property from 1944 until 1984. The facility manufactured a wide variety of specialty chemicals, insecticides, industrial cleaning products, and small quantity research chemicals. Primary production lines reportedly included bromine, iodine substituted aliphatics, mercaptans, alkyl phosphonates, nitriles, and dimethyl sulfide. Waste production materials were reportedly buried and dumped on the ground surface at the facility. Additionally, a chemical holding tank was installed at the facility in the 1970s to collect waste liquids. Records suggest that the majority of the waste product held in the tank eventually leaked out to the ground surface. Terracon completed a Phase II Environmental Site Assessment at the northadjacent Drake Street Property (Site) in 2008. Soils impacted by dioxin/furans (above the ASTDR action level) were identified near the former Columbia Organic Chemical Company (COCC). Tetrachloroethylene (TCE) was identified in monitoring wells MW-3 and MW-15, located along the property boundary with the former COCC. The Phase II Site Investigation Report concluded that real environmental contamination exists on the site associated with historical recognized environmental conditions (RECs) sourced from the south adjoining former COCC facility. The former COCC property is considered a REC to the site.

Air Products & Chemical

The eastern adjoining former Air Products & Chemical facility was identified on the FINDS/FRS and Underground Storage Tanks (UST) databases. The facility formerly operated a 1,000-gallon

Drake Street ■ 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 ■ Terracon Project No. 73227142



diesel UST. No releases were observed in connection with the UST and it is not considered a REC to the site.

James H Carr & Associates

One RCRA Very Small Quantity Generator (VSQG) listing was observed associated with the eastern adjoining property. As of April 2022, no records of compliance monitoring or enforcement violation records were observed associated with the facility. The James H Carr & Associates facility is not considered a REC to the site.

The remaining facilities listed in the database report do not appear to represent RECs to the site at this time based upon regulatory status, apparent topographic gradient, and/or distance from the site.

Unmapped facilities are those that do not contain sufficient address or location information to evaluate the facility listing locations relative to the site. The report listed five facilities in the unmapped section. Determining the location of unmapped facilities is beyond the scope of this assessment; however, none of these facilities were identified as the site or adjacent properties. These facilities are listed in the database report in Appendix D.

4.2 Local Agency Inquiries

| Agency Contacted / Contact Method | Response |
|--|---|
| Columbia Fire Department – Station 8 / (803) 545-3700 | At the issuance of this report, a response had not been received from the Fire Department |
| Richland County Tax Assessors website | This information is discussed in section 3.3. |
| SCDHEC Underground Storage Tanks Registry | Terracon accessed the SCDHEC online UST Registry to verify the information in the ERIS database report. |
| SCDHEC Freedom of Information Request | A Freedom of Information (FOI) request was submitted for the site and the southern adjoining property. Documents released from the FOI request are summarized in section 4.1 & 5.4. |

5.0 SITE RECONNAISSANCE

5.1 General Site Information

Information contained in this section is based on a visual reconnaissance conducted while walking through the site and the accessible interior areas of structures, if any, located on the site. The site and adjoining properties are depicted on the Site Diagram, which is included in Exhibit 2 of Appendix A. Photo documentation of the site at the time of the visual reconnaissance is provided in Appendix B. Credentials of the individuals planning and conducting the site visit are included in Appendix E.

Drake Street ■ 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 ■ Terracon Project No. 73227142



General Site Information

| Site Reconnaissance | | |
|---------------------|----------------------------------|--|
| Field Personnel | William W. Hinson | |
| Reconnaissance Date | July 20, 2022 | |
| Weather Conditions | Sunny / Clear skies | |
| Site Contact/Title | Alan Khan / Owner Representative | |

| Building Description | | | | |
|----------------------------|--|---------------------------|-------------------------|--------------------|
| Building Identification | Building Use | Approx. Construction Date | Number of Stories | Approx. Size (ft²) |
| 1030 Drake Street | 50% Construction material storage, 50% Woodworking warehouse | 1940s | 1 | 15,000 |
| 1002 Drake Street | Vacant former office building | 1940s | 1 | 2,500 |
| 1002 Drake Street | Collapsed former maintenance building | 1940s | 1 | 10,000 |
| 1002 Drake Street | Collapsed open-sided shed | 1940s | 1 | 3,900 |
| Site Utilities | | | | |
| Drinking Water | City of Columbia | | | |
| Wastewater | Unknown | | | |
| Electric | Dominion Energy | | | |
| Natural Gas | Dominion Energy | | | |

5.2 Overview of Current Site Occupants

The approximately 6.8-acre tract of land (Richland County Parcel R16408-01-01) is improved with four, one story structures. The northernmost structure (1030 Drake) is a hanger-style warehouse building utilized for construction materials storage and workspace. The three structures located in the central portion of the site (1002 Drake) consist of a former office building, a former hanger style maintenance building (collapsed), and an open sided shed (collapsed). Site topography slightly sloping with general gradient to the south-southeast.

5.3 Overview of Current Site Operations

The northernmost structure is currently occupied by two tenants and utilized for construction materials storage and workspace. The remaining three structures are vacant with no current operations.

Drake Street • 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 • Terracon Project No. 73227142



5.4 Site Observations

The following table summarizes site observations and interviews. Affirmative responses (designated by an "X") are discussed in more detail following the table.

Site Characteristics

| Category | Item or Feature | Observed or Identified |
|--------------------------|---|------------------------|
| | Emergency generators | |
| | Elevators | |
| | Air compressors | Χ |
| | Hydraulic lifts | |
| | Dry cleaning | |
| | Photo processing | |
| | Ventilation hoods and/or incinerators | |
| | Waste treatment systems and/or water treatment systems | |
| Site Operations, | Heating and/or cooling systems | |
| Processes, and Equipment | Paint booths | |
| , , | Sub-grade mechanic pits | |
| | Wash-down areas or carwashes | |
| | Pesticide/herbicide production or storage | |
| | Printing operations | |
| | Metal finishing (e.g., electroplating, chrome plating, galvanizing, etc.) | |
| | Salvage operations | |
| | Oil, gas or mineral production | |
| | Other processes or equipment | X |
| Aboveground | Aboveground storage tanks | |
| Chemical or Waste | Drums, barrels and/or containers ≥ 5 gallons | Х |
| Storage | MSDS or SDS | |

Drake Street • 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 • Terracon Project No. 73227142



| Category | Item or Feature | Observed or Identified |
|-------------------------------------|--|---------------------------|
| Underground | Underground storage tanks or ancillary UST equipment | Χ |
| | Sumps, cisterns, French drains, catch basins and/or dry wells | |
| | Grease traps | |
| Chemical or Waste Storage, Drainage | Septic tanks and/or leach fields | Х |
| or Collection Systems | Oil/water separators, clarifiers, sand traps, triple traps, interceptors | |
| | Pipeline markers | |
| | Interior floor drains | |
| Electrical Transformers/ | Transformers and/or capacitors | Χ |
| PCBs | Other equipment | |
| | Stressed vegetation | |
| | Stained soil | |
| | Stained pavement or similar surface | |
| | Leachate and/or waste seeps | |
| Releases or | Trash, debris and/or other waste materials | |
| Potential Releases | Dumping or disposal areas | Χ |
| | Construction/demolition debris and/or dumped fill dirt | |
| | Surface water discoloration, odor, sheen, and/or free-floating product | |
| | Strong, pungent or noxious odors | |
| | Exterior pipe discharges and/or other effluent discharges | |
| | Surface water bodies | |
| Other Notable Site | Quarries or pits | |
| Features | Wastewater lagoons | |
| | Wells | Х |

Site Operations, Processes, and Equipment

Air compressors

Two portable air compressors were observed in the occupied warehouse building located on the northern portion of the site. No indications of staining were visible on or beneath the compressors.

Other processes or equipment

Terracon observed a doorway to an apparent basement under the occupied warehouse building on the northern portion of the property. The doorway was welded shut and Terracon was unable

Drake Street • 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 • Terracon Project No. 73227142



to access the basement area. The ARM Phase I Environmental Site Assessment dated May 2007 (provided by the SCDHEC) stated that a boiler is located in the small basement beneath the warehouse. The boiler system reportedly appeared to be a solid fuel boiler based on the presence of an apparent coal grate. Terracon does not consider the boiler to be a REC to the site.

Aboveground Chemical or Waste Storage

<u>Drums</u>, <u>barrels</u>, <u>and/or containers</u> ≥ 5 <u>gallons</u>

Terracon observed numerous 55-gallon metal and plastic drums discarded throughout the site. Terracon also observed several plastic drums beneath the collapsed open sided shed on the central portion of the site. Terracon was not able to determine the contents of the drums located under the collapsed shed due to safety concerns regarding the structure. However, the remaining drums observed scattered throughout the site were empty and showed no signs of contamination.

Underground Chemical or Waste Storage, Drainage or Collection Systems

Underground storage tanks or ancillary UST equipment

One heating oil UST was observed adjacent to the east of the centrally located former office building. The observed heating oil UST is considered a REC. Given the age of the buildings, it is possible that the remaining structures may have utilized heating oil UST. However, no other indications of underground storage tanks were observed around the remaining structures.

Septic tanks and/or leach fields

The ARM Phase I Environmental Site Assessment dated May 2007 (provided by the SCDHEC) reported one septic tank system located approximately 20 feet west of the occupied warehouse building located on the northern portion of the property. Terracon did not observe any indications of the septic tank system on the ground surface in the reported area. Terracon did not observe any indications of septic tanks surrounding the remaining structures on-site. Septic tank use and locations are unknown.

Electrical Transformers/PCBs

Transformers and/or capacitors

Five pole-mounted transformers serviced by Dominion Energy were noted on-site; however, no information with regard to PCB content of the transformer fluids was observed. Transformers contain mineral oil which may contain minor amounts of PCB and could be considered "PCB contaminated" (PCB content of 50-500 ppm). Dominion Energy maintains responsibility for the transformers, and if the transformers were "PCB contaminated," the utility company is not required to replace the transformer fluids until a release is identified. However, no current or prior releases were observed in the vicinity of the electrical equipment during the site inspection.

Drake Street ■ 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 ■ Terracon Project No. 73227142



Other Notable Site Features

Dumping or disposal areas

Terracon observed large amounts of debris near the collapsed open sided shed on the central portion of the site. The observed debris mainly included construction materials, concrete, and paint canisters. Large amounts of trash were also observed throughout the site likely associated with homeless camps. The observed trash and debris did not appear hazardous in nature and is not considered a REC to the site.

Other Notable Site Features

Wells

Terracon observed several groundwater monitoring wells throughout the site. One of the monitoring wells (MW-3) was damaged and removed from the ground during apparent ground clearing activities. The monitoring wells are further discussed in section 4.1.

One apparent water supply well was observed located on the northwestern side of the collapsed former maintenance building. The well pump and its contents appear to have been removed. The well bore hole did not appear to be abandoned.

6.0 ADJOINING PROPERTY RECONNAISSANCE

Visual observations of adjoining properties (from site boundaries) are summarized below.

Adjoining Properties

| Direction | Description |
|-----------|---|
| North | Wooded land |
| East | Abandoned railroad lines, William Construction, Multi-unit retail and commercial space, and multi-tenant apartments |
| South | Wooded land (the former Cardinal Organic Chemical property) |
| West | Drake Street with multi-tenant residential apartments and single-family residential dwellings |

Indications of RECs were not observed with the current uses of adjoining properties. However, indications of RECs were observed associated with the former facilities on the southern adjoining property and are further discussed in section 4.1.

7.0 ADDITIONAL SERVICES

Per the agreed scope of services specified in the proposal, additional services were not conducted.

Drake Street • 1002 & 1030 Drake Street, Columbia, SC August 19, 2022 • Terracon Project No. 73227142



8.0 DECLARATION


I, Norman E. Partin Jr., CHMM, declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in Section 312.10 of 40 CFR 312; and I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the site. I have developed and performed the All-Appropriate Inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.


Norman E Dantin In CLIMAN

Norman E. Partin Jr., CHMM Department Manager

APPENDIX A

FIGURE 1 – TOPOGRAPHIC MAP FIGURE 2 – SITE DIAGRAM





APPENDIX B SITE PHOTOGRAPHS





Photo #1 View of the commercial warehouse on the northern portion of the site



Photo #2 View of the interior of the warehouse



Photo #3 View of a battery powered forklift



Photo #4 View of a vacant office space



Photo #5 View of stored gas cans for small engine equipment



Photo #6 Alternate view of the warehouse space





Photo #7 View of two portable air compressors



Photo #8 View of stored paint, varnish, and cleaning products



Photo #9 View of the read of the warehouse and the eastern property boundary



Photo #10 View of a monitoring well located near the southwest corner of the warehouse



Photo #11 View of a solid waste dumpster



Photo #12 View of a doorway (welded shut) to an apparent boiler system





Photo #13 View of the southwestern property boundary



Photo #14 View of the cleared overhead powerline easement



Photo #15 View of an apparent former loading platform



Photo #16 View of dumped trash and debris



Photo #17 Typical view of a empty 55-gallon drum



Photo #18 View of the vacant dwelling





Photo #19 View of the fuel oil UST located on the east side of the structure in photo 18



Photo #20 View inside of the structure



Photo #21 View of an apparent abandoned water supply well located west of the collapsed warehouse building



Photo #22 View of the perimeter of the collapsed warehouse building



Photo #23 View of the interior of the collapsed warehouse building



Photo #24 View of the collapsed storage shed located east of the collapsed warehouse building





Photo #25 View of drums located underneath the collapsed shed building



Photo #26 View of the wooded land on the northeast portion of the site



Photo #27 View of the western entrance to the site at the intersection of Drake Street and Clifton Street



Photo #28 View of the intersection of Drake Street and Clifton street with adjacent residential dwellings



Photo #29 View of the southern site boundary and the fence separating the site and the adjoining property



Photo #30 View of an groundwater monitoring well casing damaged by apparent recent clearing activities





Photo #31 View of the cleared land along the southern property boundary



Photo #32 View of the eastern adjoining property



Photo #33 View of the cleared land along the southeastern property boundary



Photo #34 View of discarded trash located in the central portion of the site



Photo #35 View of monitoring well (BF-2)



Photo #36 Typical view of pole mounted transformers

APPENDIX C HISTORICAL DOCUMENTATION

Client/User Required Questionnaire



| Darson Completing Questionneire | Name: David Madsen | Phone: 801-916-6366 | |
|--|---|--|--|
| Person Completing Questionnaire | Company: Terra Alta Ventures, LLC | Email: david@thorntonwalker.com | |
| Site Name | Drake Street | Lindii. david@tilomtonwaiker.com | |
| Site Address | 1002 Drake Street, Columbia, South Carolina 29209 | | |
| Point of Contact for Access | Name: Alan Kahn Company: Owner | Phone: 803-422-8165 Email: alankahn@kahndevelopment.com | |
| Access Restrictions or Special Site | X_NoYes (If yes, please explain) | alatikanin se karingevelopinent.com | |
| Requirements? | | | |
| Confidentiality Requirements? | X_NoYes (If yes, please explain) | | |
| Current Site Owner | Name: Alan Kahn Company: Owner | Phone: 803-422-8165 Email:alankahn@kahndevelopment.com | |
| Current Site Operator | Name: N/A Company: | Phone: Email: | |
| Reasons for ESA | Acquisition | | |
| (e.g., financing, acquisition, lease, etc.) | Acquisition | | |
| Anticipated Future Site Use | Townhome/condo development (owner oc | cupied) | |
| | Discourant de Terresco | Dhara Lan II 50Aa Aabaataa Oomaaa | |
| Relevant Documents? | | Phase I or II ESAs, Asbestos Surveys, | |
| | | ts, Underground Storage Tank documents, | |
| | or documents. | Diagrams or Maps, or other relevant reports | |
| | ASTM User Questionnaire | | |
| In order to qualify for one of the Landowner L | ability Protections (LLPs) offered by the Small Bus | siness Relief and Brownfields Revitalization Act of | |
| | er must respond to the following questions. Failur | | |
| | gaps, which may limit our ability to identify rec | | |
| | not complete. This form represents a type of inte | | |
| answer all questions in good faith, to the exter | | | |
| | ecords (or judicial records where appropria ral, tribal, state, or local law (40 CFR 312.25) | te) identify any environmental liens filed or | |
| | and send Terracon a copy of the title records | | |
| * | | tte) identify any activity and use limitations | |
| I | | hat are in place at the property and/or have | |
| been filed or recorded against the proper | ty under federal, tribal, state, or local law (40 | CFR 312.26)? | |
| X No Yes (If yes, explain below a | and send Terracon a copy of the title records | or judicial records reviewed.) | |
| 3) Do you have any specialized knowled | ge or experience related to the site or nearby | properties? For example, are you involved | |
| | nt or former occupants of the site or an adjoir | | |
| specialized knowledge of the chemicals and processes used by this type of business (40 CFR 312-28)? | | | |
| X_NoYes (If yes, explain below) | | | |
| 4) Do you have actual knowledge of a lower purchase price because contamination is known or believed to be present at the site | | | |
| (40 CFR 312.29)?No _X_YesNot applicable (If yes or Not applicable, explain below) | | | |
| 5) Are you aware of commonly known or reasonably ascertainable information about the site that would help the environmental | | | |
| professional to identify conditions indicative of releases or threatened releases (40 CFR 312.30)? | | | |
| No _X_Yes (If yes, explain below) | | | |
| 6) Based on your knowledge and experience related to the site, are there any obvious indicators that point to the presence or | | | |
| likely presence of contamination at the site (40 CFR 312.31)? | | | |
| No _X_Yes (If yes, explain below) | | | |
| | id a Phase II Environmental Site Assessment | t on this property July, 23, 2008. The Project | |
| | as 73077038. Please refer to that report for al | | |
| | | | |



Project Property: Drake Street

1002 Drake Street

Columbia SC 29209


Project No: 73227142

Requested By: Terracon

Order No: 22071200085

Date Completed: July 12, 2022

Please note that no information was found for your site or adjacent properties.



Project Property: Drake Street

1002 Drake Street

Columbia SC 29209

73227142 **Project No:**

Requested By: Terracon

Order No: 22071200085

Date Completed: July 12, 2022 We have searched USGS collections of current topographic maps and historical topographic maps for the project property. Below is a list of maps found for the project property and adjacent area. Maps are from 7.5 and 15 minute topographic map series, if available.

| Year | Map Series |
|------|------------|
| 1948 | 15 |
| 1953 | 7.5 |
| 1972 | 7.5 |
| 1982 | 7.5 |
| 1987 | 7.5 |
| 2014 | 7.5 |
| 2017 | 7.5 |
| 2020 | 7.5 |
| | |

Topographic Map Symbology for the maps may be available in the following documents:

Pre-1947

Page 223 of 1918 Topographic Instructions Page 130 of 1928 Topographic Instructions 1947-2009

Topographic Map Symbols

2009-present

US Topo Map Symbols


Topographic Maps included in this report are produced by the USGS and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc.(in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS', using Topographic Maps produced by the USGS. This maps contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Environmental Risk Information Services

A division of Glacier Media Inc.

1.866.517.5204 | info@erisinfo.com | erisinfo.com





Checked By:


Approved By:

File Name:

Date:









| Drawn By: | Scale: | |
|--------------|------------|--|
| Checked By: | File Name: | |
| Approved By: | Date: | |




| TOPOGRAPHIC MAP (1982) | |
|------------------------|--|
| | |
| | |
| | |
| | |





| Project Manager: | Project No: | | TOPOGRAPHIC MAP (1987) | |
|------------------|-------------|-----------------|------------------------|--|
| Drawn By: | Scale: | ierracon | | |
| Checked By: | File Name: | | | |
| Approved By: | Date: | | | |



| Project Manager. | Project No. | | TOPOGRAPHIC MAP (2014) | |
|------------------|-------------|-----------------|------------------------|--|
| Drawn By: | Scale: | ierracon | | |
| Checked By: | File Name: | | | |
| Approved By: | Date: | | | |







Project Property:Drake Street

1002 Drake Street

Columbia South Carolina 29209

Project No.: 73227142

Requested By: Terracon

Order No: 22071200085

Date Completed: July 12,2022

Aerial Maps included in this report are produced by the sources listed above and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property. ERIS provides no warranty of accuracy or liability. The information contained in this report has been produced using aerial photos listed in above sources by ERIS Information Inc. (in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS'. The maps contained in this report do not purport to be and do not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Environmental Risk Information Services


| Date | Source | Scale | Comments |
|------|---|-----------|----------|
| 1938 | Agricultural Stabilization & Conserv. Service | 1" = 500' | |
| 1943 | Agricultural Stabilization & Conserv. Service | 1" = 500' | |
| 1951 | Agricultural Stabilization & Conserv. Service | 1" = 500' | |
| 1959 | Agricultural Stabilization & Conserv. Service | 1" = 500' | |
| 1961 | United States Navy | 1" = 500' | |
| 1964 | United States Air Force | 1" = 500' | |
| 1971 | United States Geological Survey | 1" = 500' | |
| 1978 | United States Geological Survey | 1" = 500' | |
| 1983 | United States Geological Survey | 1" = 500' | |
| 1989 | United States Geological Survey | 1" = 500' | |
| 1994 | United States Geological Survey | 1" = 500' | |
| 2005 | United States Department of Agriculture | 1" = 500' | |
| 2006 | United States Department of Agriculture | 1" = 500' | |
| 2011 | United States Department of Agriculture | 1" = 500' | |
| 2013 | United States Department of Agriculture | 1" = 500' | |
| 2015 | United States Department of Agriculture | 1" = 500' | |
| 2017 | United States Department of Agriculture | 1" = 500' | |
| 2019 | United States Department of Agriculture | 1" = 500' | |






Scale: Drawn by: Checked by: File Name: Approved by: Date:





Checked by: File Name: Approved by: Date:






| THE RESERVE THE PARTY OF THE PA | THE APPENDING A COVER |
|--|-----------------------|
| Project Manager: | Project No. |
| Drawn by: | Scale: |
| Checked by: | File Name: |
| Approved by: | Date: |






| Project Manager: | Project No. |
|------------------|-------------|
| Drawn by: | Scale: |
| Checked by: | File Name: |
| Approved by: | Date: |





| | THE RESERVE OF THE PARTY OF THE |
|------------------|--|
| Project Manager: | Project No. |
| Drawn by: | Scale: |
| Checked by: | File Name: |
| Approved by: | Date: |






Scale: Drawn by: Checked by: File Name:

Date:

Approved by:



AERIAL PHOTO (1971 - USGS)



| Project Manager: | Project No. |
|------------------|-------------|
| Drawn by: | Scale: |
| Checked by: | File Name: |
| Approved by: | Date: |





| Project Manager: | Project No. |
|------------------|-------------|
| Drawn by: | Scale: |
| Checked by: | File Name: |
| Approved by: | Date: |







| Project Manager: | Project No. |
|------------------|-------------|
| Drawn by: | Scale: |
| Checked by: | File Name: |

Date:






Scale: Drawn by: Checked by: File Name: Approved by: Date:



AERIAL PHOTO (2005 - USDA)



| AL SHARE STREET | THE RESERVE OF THE PARTY OF THE |
|------------------|--|
| Project Manager: | Project No. |
| Drawn by: | Scale: |
| Checked by: | File Name: |

Approved by:

Date:






Project Manager: Project No.

Drawn by: Scale:

Checked by: File Name:

Approved by: Date:





Drawn by: Scale: Checked by: File Name: Approved by: Date:





| THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW | |
|--|-------------|
| Project Manager: | Project No. |
| Drawn by: | Scale: |
| Checked by: | File Name: |

Date:





| | THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAME |
|------------------|--|
| Project Manager: | Project No. |
| Drawn by: | Scale: |
| Checked by: | File Name: |


Date:





| | A C. C. |
|------------------|-------------|
| Project Manager: | Project No. |
| Drawn by: | Scale: |
| Checked by: | File Name: |
| Approved by: | Date: |





Project Property: Drake Street

1002 Drake Street

Columbia,SC 29209

Project No: 73227142
Requested By: Terracon

Order No: 22071200085 **Date Completed:** July 14, 2022

July 14, 2022 RE: CITY DIRECTORY RESEARCH 1002 Drake Street Columbia,SC 29209

Thank you for contacting ERIS for an City Directory Search for the site described above. Our staff has conducted a reverse listing City Directory search to determine prior occupants of the subject site and adjacent properties. We have provided the nearest addresses(s) when adjacent addresses are not listed. If we have searched a range of addresses, all addresses in that range found in the Directory are included.

Note: Reverse Listing Directories generally are focused on more highly developed areas. Newly developed areas may be covered in the more recent years, but the older directories will tend to cover only the "central" parts of the city. To complete the search, we have either utilized the ACPL, Library of Congress, State Archives, and/or a regional library or history center as well as multiple digitized directories. These do not claim to be a complete collection of all reverse listing city directories produced.

ERIS has made every effort to provide accurate and complete information but shall not be held liable for missing, incomplete or inaccurate information. To complete this search we used the general range(s) below to search for relevant findings. If you believe there are additional addresses or streets that require searching please contact us at 866-517-5204.

Search Criteria: 900-1100 of Drake St ALL of Norris St 900-1100 of True St Search Notes:

Search Results Summary

| Date | Source | Comment |
|------|----------------------------|---------|
| 2020 | DIGITAL BUSINESS DIRECTORY | |
| 2016 | DIGITAL BUSINESS DIRECTORY | |
| 2012 | DIGITAL BUSINESS DIRECTORY | |
| 2008 | DIGITAL BUSINESS DIRECTORY | |
| 2003 | DIGITAL BUSINESS DIRECTORY | |
| 2000 | DIGITAL BUSINESS DIRECTORY | |
| 1996 | POLKS | |
| 1991 | POLKS | |
| 1986 | POLKS | |
| 1981 | HILLS | |
| 1976 | HILLS | |
| 1970 | HILLS | |
| 1964 | HILLS | |
| 1958 | HILLS | |
| 1955 | HILLS | |
| 1950 | HILLS | |
| 1945 | HILLS | |
| 1940 | HILLS | |
| 1935 | HILLS | |
| 1930 | HILLS | |
| 1925 | WALSH | |

DRAKE ST 2020

SOURCE: DIGITAL BUSINESS DIRECTORY

NORRIS ST 2020 SOURCE: DIGITAL BUSINESS DIRECTORY

1001 TODD REESE...RESIDENTIAL 1030

MASTER-PLASTER FINISHING...PLASTERING CONTRACTORS

6439 TERENCE THOMPSON...RESIDENTIAL

| 2020 <i>SOURCE: </i> D | TRUE ST IGITAL BUSINESS DIRECTORY |
|----------------------------------|---------------------------------------|
| 901 | KISHA KNAPPERRESIDENTIAL |
| 901 | SUSAN JOHNSONRESIDENTIAL |
| 906 | ELLIOTT RICHARDSONRESIDENTIAL |
| 906 | LAURA GONSALVESRESIDENTIAL |
| 1001 | ALICE BENTONresidential |
| 1001 | AMELIA GREENERESIDENTIAL |
| 1001 | ANA-LICIA WILLIAMSRESIDENTIAI |
| 1001 | ANTHONY RELLERRESIDENTIAL |
| 1001 | AVIS JOHNSONRESIDENTIAL |
| 1001 | CHARLES RANKINRESIDENTIAL |
| 1001 | CHERELLE HARRISONRESIDENTIAL |
| 1001 | CODY CROSBYRESIDENTIAL |
| 1001 | CRYSTAL JENKINSRESIDENTIAL |
| 1001 | CYNDY MARTINRESIDENTIAL |
| 1001 | DOROTHY SULERESIDENTIAL |
| 1001 | DUSTIE VILLANUEVARESIDENTIAL |
| 1001 | FRAN JAKUBUWSKIRESIDENTIAL |
| 1001 | GALEN BEVERLYRESIDENTIAL |
| 1001 | HITESH PATELRESIDENTIAL |
| 1001 | HUNTINGTON PLACE APARTMENTSAPARTMENTS |
| 1001 | JANICE DAVISRESIDENTIAL |
| 1001 | JERWAYNE ELLISRESIDENTIAL |
| 1001 | JUNE DEMONDRESIDENTIAL |
| 1001 | KACI BARFIELDRESIDENTIAL |
| 1001 | KATHRYN JONESRESIDENTIAL |
| 1001 | LEMS MICHAUDRESIDENTIAL |
| 1001 | LISA BIRDresidential |
| 1001 | MELISSA GILLILANDresidential |
| 1001 | MICHAEL BROWNRESIDENTIAL |

1001 MICHAEL HEDGECOCK...RESIDENTIAL 1001 MICHAEL HILLARD...RESIDENTIAL 1001 NANCY EVERSMANN...RESIDENTIAL 1001 **OLGA FRITTS**...RESIDENTIAL REGINALD MCFADDEN...RESIDENTIAL 1001 1001 RICHARD, CHRISTINE T...REHABILITATION SERVICES 1001 RICHARD, CHRISTINE T...SPEECH PATHOLOGISTS 1001 ROBER GLOTFELTY...RESIDENTIAL 1001 ROBERT CANNON...RESIDENTIAL SHARI STANEK...RESIDENTIAL 1001 1001 SUSAN BARAKAT...RESIDENTIAL

THEODORE HARRISON JR...RESIDENTIAL

2016 DRAKE ST

SOURCE: DIGITAL BUSINESS DIRECTORY

| 925 925 | JEANETTE DEWBERRYRESIDENTIAL |
|------------|---|
| - | SOUTH CAROLINA CONSERVATORYnonclassified establishments |
| 1001 | TODD REESEresidential |
| 1003 | NICHOLAS BEERSresidential |
| 1030 | MASTER-PLASTER FINISHINGplastering contractors |

1001

2016 NORRIS ST

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2016 TRUE ST

SOURCE: DIGITAL BUSINESS DIRECTORY

| 901 | KISHA KNAPPERRESIDENTIAL |
|------|---|
| 901 | SUSAN JOHNSONRESIDENTIAL |
| 906 | ELLIOTT RICHARDSONRESIDENTIAL |
| 906 | LAURA GONSALVESRESIDENTIAL |
| 906 | MARIA YOUNGRESIDENTIAL |
| 1001 | ALICE BENTONRESIDENTIAL |
| 1001 | ANNA RUFFNERRESIDENTIAL |
| 1001 | ANTHONY LAVIGNERESIDENTIAL |
| 1001 | ANTHONY RELLERRESIDENTIAL |
| 1001 | AVIS JOHNSONRESIDENTIAL |
| 1001 | CHERELLE HARRISONRESIDENTIAL |
| 1001 | CODY CROSBYRESIDENTIAL |
| 1001 | CYNDY MARTINresidential |
| 1001 | DAMON DAVISresidential |
| 1001 | DANIEL KUIPERSresidential |
| 1001 | DAVID KEENEresidential |
| 1001 | DICK KAWOOYAresidential |
| 1001 | |
| | DINAHI CASTILLORESIDENTIAL |
| 1001 | DOROTHY SULERESIDENTIAL |
| 1001 | FRAN JAKUBUWSKIRESIDENTIAL |
| 1001 | GALEN BEVERLYresidential |
| 1001 | GLENN AGNGARAYNGAYresidential |
| 1001 | HITESH PATELresidential |
| 1001 | HUNTINGTON PLACE APARTMENTSAPARTMENTS |
| 1001 | JAMES DEAN JRRESIDENTIAL |
| 1001 | JANICE DAVISRESIDENTIAL |
| 1001 | JEAN RELLERRESIDENTIAL |
| 1001 | JENNIFER DAVISRESIDENTIAL |
| 1001 | JERWAYNE ELLISRESIDENTIAL |
| 1001 | JUDY HOUSTON-ELLISONRESIDENTIAL |
| 1001 | KATHERINE CROSBYRESIDENTIAL |
| 1001 | KATHRYN JONESRESIDENTIAL |
| 1001 | LEWIS MICHAUDRESIDENTIAL |
| 1001 | LISA BIRDRESIDENTIAL |
| 1001 | MANHARLAL THAKKERRESIDENTIAL |
| 1001 | MICHAEL BROWNresidential |
| 1001 | MICHAEL HILLARDRESIDENTIAL |
| 1001 | NANCY EVERSMANNRESIDENTIAL |
| 1001 | OLGA FRITTSresidential |
| 1001 | PAMELA MICHAUDRESIDENTIAL |
| 1001 | RAY DEANresidential |
| 1001 | REGINALD MCFADDENRESIDENTIAL |
| 1001 | RICHARD, CHRISTINE TSPEECH PATHOLOGISTS |
| 1001 | ROBER GLOTFELTYRESIDENTIAL |
| 1001 | ROBERT CANNONRESIDENTIAL |
| 1001 | ROBERT EVERSMANNresidential |
| 1001 | ROBERT NINERESIDENTIAL |
| 1001 | SHARI STANEKRESIDENTIAL |
| 1001 | SUSAN BARAKATresidential |
| 1001 | THEODORE HARRISON JRRESIDENTIAL |
| .001 | |

SOURCE: DIGITAL BUSINESS DIRECTORY

2012 NORRIS ST

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

925 LINDA BROWN...residential
929 CHENOA RIVERS...residential

1030 MASTER-PLASTER FINISHING...PLASTERING CONTRACTORS

| | 2012 | TRUE ST |
|--|------|---------|
|--|------|---------|

SOURCE: DIGITAL BUSINESS DIRECTORY

| 901 | JASON SANDIFERRESIDENTIAL |
|------|--|
| 901 | RON MCKNIGHTresidential |
| 901 | SUSAN JOHNSONRESIDENTIAL |
| 902 | IRIS STONERESIDENTIAL |
| 902 | NANCY HOLMESresidential |
| 906 | DAVID RICHARDRESIDENTIAL |
| 919 | JAMES H CARR ASSOC INCLABORATORIES-TESTING |
| 1001 | A SCHMIDTLEINresidential |
| 1001 | AARON MARTERERRESIDENTIAL |
| 1001 | BENJAMIN JONESRESIDENTIAL |
| 1001 | BRANDON DEENresidential |
| 1001 | CHRIS JONESRESIDENTIAL |
| 1001 | CHRIS WARDRESIDENTIAL |
| 1001 | CHRISTINE MURIELRESIDENTIAL |
| 1001 | CRAIG CHILDSresidential |
| 1001 | CYNTHIA MARTINRESIDENTIAL |
| 1001 | DANA NORRISRESIDENTIAL |
| 1001 | DEMETRIA ALSTONRESIDENTIAL |
| 1001 | DOROTHY SULERESIDENTIAL |
| 1001 | GORDAN JAMESRESIDENTIAL |
| 1001 | HUNTINGTON PLACE APARTMENTSAPARTMENTS |
| 1001 | JASON BURDENRESIDENTIAL |
| 1001 | JENNY BURDENRESIDENTIAL |
| 1001 | JOHNNY DAVISresidential |
| 1001 | K FRINKRESIDENTIAL |
| 1001 | KENNETH FRINKRESIDENTIAL |
| 1001 | LENA PINKSTONresidential |
| 1001 | LON MCELRATHRESIDENTIAL |
| 1001 | M SCHMIDTLEINresidential |
| 1001 | MANHARLAL THAKKERRESIDENTIAL |
| 1001 | NASRUDDIN SHAIKSresidential |
| 1001 | NEIL BLUERESIDENTIAL |
| 1001 | PETER BEVERLYRESIDENTIAL |
| 1001 | ROBERT JONES RESIDENTIAL |
| 1001 | ROSA BOOKERRESIDENTIAL |
| 1001 | RUBY DAVISRESIDENTIAL |
| 1001 | STEPHEN VONRESIDENTIAL |
| 1001 | TANISHA CHUNIESINGHRESIDENTIAL |
| 1001 | TENESIA VANNresidential |
| 1001 | THOMAS BUNDRORESIDENTIAL |

TONY HEDRICK...RESIDENTIAL

TONYA SEABROOKS...RESIDENTIAL

VENKATESH HEGDE...RESIDENTIAL WILLIAM BOLIN...RESIDENTIAL

2008 DRAKE ST

SOURCE: DIGITAL BUSINESS DIRECTORY

| 925 | LINDA BROWNRESIDENTIAL | |
|------|-----------------------------|------------------------------|
| 929 | P MCLAUGHLINRESIDENTIAL | |
| 929 | STEPHANIE BAXTERRESIDENTIAL | |
| 929 | V TANDERSONRESIDENTIAL | |
| 933 | MARLENE HARRISRESIDENTIAL | |
| 1030 | CASSELMAN SHEET METAL SVC | SHEET METAL WORK CONTRACTORS |

1001

1001

1001

1001

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2008 TRUE ST

SOURCE: DIGITAL BUSINESS DIRECTORY

| | al records. Part 1 of 3 | | |
|--------------|--|--|--|
| 902 | I S STONERESIDENTIAL | | |
| 906 | A J DIMARIARESIDENTIAL | | |
| 906 | A PALMresidential | | |
| 906 | AMANDA COURT APARTMENTSAPARTMENTS | | |
| 906 906 | ANTHONY & JANNA SEIFERTresidential C G BROWNresidential | | |
| 906 | DENISE MIDDLETONresidential | | |
| 906 | FONTAINE DIMERYresidential | | |
| 906 | FRANK MLCOCHRESIDENTIAL | | |
| 906 | GILBERT GATERESIDENTIAL | | |
| 906 | J A LEWSresidential | | |
| 906 | LAURA T GONSALVESRESIDENTIAL | | |
| 906 | MARIAN NURSERESIDENTIAL | | |
| 906 | P D THOMPSONresidential | | |
| 906 | SARAH YOUNGERRESIDENTIAL | | |
| 906 | TBRASSRESIDENTIAL | | |
| 906 | TODD RICHARDSONRESIDENTIAL | | |
| 906 | TROY HAMMONDresidential | | |
| 906 | WON Y KIMRESIDENTIAL | | |
| 919 951 | JAMES H CARR ASSOC INCLABORATORIES-TESTING | | |
| 1001 | CALIFORNIA CLOSET COCLOSET ORGANIZERS DESIGN AND INSTALLATION A CIDRESIDENTIAL | | |
| 1001 | AARON & ELKE SANDERresidential | | |
| 1001 | AARON WILSONRESIDENTIAL | | |
| 1001 | ADRIAN SHIRAISHIRESIDENTIAL | | |
| 1001 | AJITA S PRABHUresidential | | |
| 1001 | ALAN G JAMESRESIDENTIAL | | |
| 1001 | ALEX & DIANE HILLresidential | | |
| 1001 | ALEX REYESRESIDENTIAL | | |
| 1001 | ALLAN HAYNESresidential | | |
| 1001 | ALLEN JR GLEATONRESIDENTIAL | | |
| 1001 | ALLISON MCINNISRESIDENTIAL | | |
| 1001 | ANDREW J BARBITTARESIDENTIAL | | |
| 1001 | ANTHONY SIMSresidential | | |
| 1001 1001 | APRIL N JONESresidential APRIL PHILLIPSresidential | | |
| 1001 | BARRY S BAILEYresidential | | |
| 1001 | BEN & LAURIE MOORERESIDENTIAL | | |
| 1001 | BENJAMIN M RENFROWRESIDENTIAL | | |
| 1001 | BO BROWNRESIDENTIAL | | |
| 1001 | BRAD PERRYRESIDENTIAL | | |
| 1001 | BRANTLEY MORRISRESIDENTIAL | | |
| 1001 | BREJ GRUSKINRESIDENTIAL | | |
| 1001 | BRIAN A SCHOOLEYRESIDENTIAL | | |
| 1001 | BRIAN SHELLEYRESIDENTIAL | | |
| 1001 | BRUCE CAMPBELLRESIDENTIAL | | |
| 1001 | C R HATTRICHRESIDENTIAL | | |
| 1001 1001 | CALVIN L MCDONALDresidential CATHLEEN GROSS-PAILETresidential | | |
| 1001 | CHAFFEY JOHNSONresidential | | |
| 1001 | CHARLIE GARDINERresidential | | |
| 1001 | CHRISTOPHER J RUEHLMANNRESIDENTIAL | | |
| 1001 | CORY WHITERESIDENTIAL | | |
| 1001 | CUI-FENG ZHANGRESIDENTIAL | | |
| 1001 | D M MORRISONRESIDENTIAL | | |
| 1001 | DANIEL E POOLERESIDENTIAL | | |
| 1001 | DARREN GRAYresidential | | |
| 1001 | DAVID BAGLIETORESIDENTIAL | | |
| 1001 | DEAN BEAUDOINresidential | | |
| 1001 | DEAN W BEAUDOINRESIDENTIAL | | |
| 1001 | DEREK SCOTTRESIDENTIAL | | |
| 1001 1001 | DINO VOLAKAKISresidential E M LEADBITTERresidential | | |
| 1001 | E R GIFFORDresidential | | |
| 1001 | EDWARD & CHRISTINA GRAVELYresidential | | |
| 1001 | ELIZABETH M ALLISONresidential | | |
| 1001 | EMBRAY JACKSONRESIDENTIAL | | |
| | | | |

2008 TRUE ST

SOURCE: DIGITAL BUSINESS DIRECTORY

| SOURCE: L | DIGITAL BUSINESS DIRECTORY |
|--------------|--|
| D-40- | -4.0 |
| Part 2 c | |
| 1001 | ERIN C KEISLERRESIDENTIAL |
| 1001 | ERIN VANDALERESIDENTIAL |
| 1001 | FRANCENE LANERESIDENTIAL |
| 1001 | FRANK CASSESERESIDENTIAL |
| 1001 | GAETAN BOINETRESIDENTIAL |
| 1001 | GARY & CHANTAL ECKLOFRESIDENTIAL |
| 1001 | GERALD & FANNIE GARYRESIDENTIAL |
| 1001 | GLORIA SCOTTresidential |
| 1001 | GOUTHAM MENONRESIDENTIAL |
| 1001 | GREGG MATSUMOTORESIDENTIAL |
| 1001 | HARRY J BAILEYRESIDENTIAL |
| 1001 | HEATHER N GORDENRESIDENTIAL |
| 1001 | HELEN LEEresidential |
| 1001 | HERBIE COOPERRESIDENTIAL |
| 1001 | HUNTINGTON PLACE APARTMENTSAPARTMENTS |
| 1001 | J CABALLERORESIDENTIAL |
| 1001 | J M STUBBSRESIDENTIAL |
| 1001 1001 | J R FOSTERRESIDENTIAL JAMES & TINA FRANKLINRESIDENTIAL |
| 1001 | |
| | JAMES E JOYEresidential JAMIE CARELOCKresidential |
| 1001 1001 | JASON POWERSresidential |
| | JENNIFER GARDNERresidential |
| 1001 1001 | JEREMY YOUNGresidential |
| 1001 | JESSICA NEVINSresidential |
| 1001 | JOE SNEEDresidential |
| 1001 | JOHN STEELEresidential |
| 1001 | JOHN V REEDRESIDENTIAL |
| 1001 | K BUSHresidential |
| 1001 | K ROGERSresidential |
| 1001 | K WERKINGRESIDENTIAL |
| 1001 | K WOJCIKRESIDENTIAL |
| 1001 | KARIN MILLERRESIDENTIAL |
| 1001 | KATHY WALDENRESIDENTIAL |
| 1001 | KELLIEGH LEDBETTERRESIDENTIAL |
| 1001 | KOSTAS VOLAKAKISresidential |
| 1001 | KRISTEN THOMASRESIDENTIAL |
| 1001 | KYLE & KRISTEN MURRAYRESIDENTIAL |
| 1001 | L A ANDERSONresidential |
| 1001 | L ROSENZWEIGRESIDENTIAL |
| 1001 | LARRY LOHKAMPresidential |
| 1001 | LEAH STEELERESIDENTIAL |
| 1001 | LEIGH D EICHELBERGERRESIDENTIAL |
| 1001 | LES & B PERRYRESIDENTIAL |
| 1001 | LOUISE G WHEELERRESIDENTIAL |
| 1001 | MARK & SARA CHAMBERSRESIDENTIAL |
| 1001 | MARK BRANNENRESIDENTIAL |
| 1001 | MARK J JR BLACKMANRESIDENTIAL |
| 1001 | MARK LINENRESIDENTIAL |
| 1001 | MARK RICHARDSONRESIDENTIAL |
| 1001 | MENTOR CLINICAL CARE NONCLASSIFIED ESTABLISHMENTS |
| 1001 | MICHAEL C BLAIRRESIDENTIAL |
| 1001 | MICHELE KERBOWRESIDENTIAL |
| 1001 | MIKEL LATABURURESIDENTIAL |
| 1001 | N DESALresidential |
| 1001 | NOAH DECAMPSresidential |
| 1001 | PATRICK W TOOLERESIDENTIAL |
| 1001 | R A STUESSYRESIDENTIAL |
| 1001 | RACHEL JENKINSRESIDENTIAL |
| 1001 | RAY WILLIAMSONRESIDENTIAL |
| 1001 | REBECCA RILEYRESIDENTIAL |
| 1001 | RICHARD F TIMMONSRESIDENTIAL |
| 1001 | RICHARD M TAYLORRESIDENTIAL |
| 1001 | RICHARD PERRYRESIDENTIAL |

| Part 3 c | of 3 |
|--------------|--|
| 1001 | RUPAL DOSHIRESIDENTIAL |
| 1001 | SARAH CREECHRESIDENTIAL |
| 1001 | SARAH E CAMPBELLRESIDENTIAL |
| 1001 | SARAH PATTERSONRESIDENTIAL |
| 1001 | SCOTT GRAHAM RESIDENTIAL |
| 1001 | SHANDA SPEARSRESIDENTIAL |
| 1001 | SHANNA MARTINRESIDENTIAL |
| 1001 | SHANNON PARKERRESIDENTIAL |
| 1001 | SHAWN STEINERRESIDENTIAL |
| 1001 | SHELLY JONESRESIDENTIAL |
| 1001 | SHIREEN HIGBERESIDENTIAL |
| 1001 | SONJA R SUMMERSRESIDENTIAL |
| 1001 | STACEY E WARRENRESIDENTIAL |
| 1001 | STEPHEN HALEYRESIDENTIAL |
| 1001 | TAE-YOUNG UHMRESIDENTIAL |
| 1001 | TED DURANTRESIDENTIAL |
| 1001 | TERRY COOPERRESIDENTIAL |
| 1001 | TERRY ROBERTSRESIDENTIAL |
| 1001 | THOMAS L FIELDSRESIDENTIAL |
| 1001 | THOMAS M JACOBSRESIDENTIAL |
| 1001 | TIM & LISA HEARNRESIDENTIAL |
| 1001 | TIMOTHY P MCLELLANRESIDENTIAL |
| 1001 | TOMMARA LADSONRESIDENTIAL |
| 1001 | TONY FERNANDESRESIDENTIAL |
| 1001 | V COLEMANRESIDENTIAL |
| 1001 | V P LEWSRESIDENTIAL |
| 1001 1001 | W P CASTRONUOVOresidential WADE COOPERresidential |
| 1001 | |
| 1001 | WILLIAM QUATTLEBAUMresidential WILLIAM T GRAHAMresidential |
| 1001 | YVONNE FREDERICKRESIDENTIAL |
| 1001 | ZINA D MAYOresidential |
| 1001 | MARGARET H JOHNSONRESIDENTIAL |
| 1002 | LAUREN R BROOKSRESIDENTIAL |
| 1003 | SARAH B JACKSONRESIDENTIAL |
| 1003 | THEODORE HARRISONRESIDENTIAL |
| . 555 | |

1001

1001

1001

1001 1001 RICHARD PERRY...RESIDENTIAL

ROBERT BEATTY...RESIDENTIAL

ROBERT C JONES...RESIDENTIAL

ROBERT DEFLORIO...RESIDENTIAL

ROBERT & SADIE SIMMONS...RESIDENTIAL

SOURCE: DIGITAL BUSINESS DIRECTORY

2003

NORRIS ST

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

929 K R ALEXANDER...RESIDENTIAL
929 SHANA JOHNSON...RESIDENTIAL

929 SHANA JOHNSON...RESIDENTI 933 THERESA TATE...RESIDENTIAL

1030 CASSELMAN SHEET METAL SVC...sprinkler contractors

2003 SOURCE: DIGITAL BUSINESS DIRECTORY 902 IRIS S STONE...RESIDENTIAL 906 **AMANDA COURT APARTMENTS** 906 C MCWHITE...RESIDENTIAL 906 CARL W WARD...RESIDENTIAL 906 LAURA T GONSALVES...RESIDENTIAL 906 OTIS L MINTZ...RESIDENTIAL PHILIP GRADY...RESIDENTIAL 906 906 S WADDELL...RESIDENTIAL VERNA STUKES...RESIDENTIAL 906 919 JAMES H CARR ASSOC INC...PRODUCT TESTING LABORATORIES 919 MEDICAL REIMBURSEMENT SVC...BUSINESS MANAGEMENT

MILITARY MINISTRIES CAMPUS

HUNTINGTON PLACE APARTMENTS

CALIFORNIA CLOSET CO

TRUE ST

919

951

1003

DRAKE ST 2000 SOURCE: DIGITAL BUSINESS DIRECTORY

929 K R ALEXANDER...RESIDENTIAL 929 SHANA JOHNSON...RESIDENTIAL 933 THERESA TATE...RESIDENTIAL

1030 CASSELMAN SHEET METAL SVC...SPRINKLER CONTRACTORS

NORRIS ST 2000 SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

TRUE ST 2000

SOURCE: DIGITAL BUSINESS DIRECTORY

902 IRIS S STONE...RESIDENTIAL 906 **AMANDA COURT APARTMENTS** 906 C MCWHITE...RESIDENTIAL 906 CARL W WARD...RESIDENTIAL 906 LAURA T GONSALVES...RESIDENTIAL 906 OTIS L MINTZ...RESIDENTIAL 906 PHILIP GRADY...RESIDENTIAL 906 S WADDELL...RESIDENTIAL VERNA STUKES...RESIDENTIAL JAMES H CARR ASSOC INC...PRODUCT TESTING LABORATORIES 951 **CALIFORNIA CLOSET CO**

HUNTINGTON PLACE APARTMENTS 1001

SOURCE: POLKS

1996

NORRIS ST

SOURCE: POLKS

NO LISTINGS IN RANGE

925 **UNIFIED FOOD SERV**

929 - 929 NOT VERIFIED 933 **B NOT VERIFIED** 933 TATE THERESA

CASSELMAN SHEET METAL SERVICE BLDG - CONSTN COM ? & 1030

INDUS

| 1996 | TRUE ST |
|-----------|------------------------------|
| SOURCE: P | OLKS |
| 833 | -835 NOT VERIFIED |
| 836 | WHITTLE MERTICE |
| 840 | SPEAR LINDA |
| 843 | HAMPTON ROBERT & DALE |
| 844 | BRANDON CLARA C |
| 849 | EDWARD REGINA |
| 853 | RYAN PENNY E |
| 902 | COOK GUNTHER |
| 902 | STONE IRIS |
| 906 | AMANDA COURT APARTMENTS APTS |
| 906 | C2QWADDELL SANDRA (C2) |
| 906 | D6 BRAGDON LISA (D6) |
| 906 | D6BRAGDON STEVE (D6) |
| 906 | GONSALVES LAURA T (B4) |
| 906 | NASHLEY VIVIAN (D2) |
| 906 | NOT VERIFIED (C1 - D1) |
| 906 | NOT VERIFIED (A1) |
| 906 | NOT VERIFIED (D3 - E2) |
| 919 | CARR JAMES H ASSOCS |
| | |

1991 DRAKE ST SOURCE: POLKS

| 925 | BROWN LR FOOD BROKERAGE |
|-----|-------------------------|
| 929 | ANDERSON RICHARD |
| 929 | RAMOS EUGENIO |
| 929 | RICHARD SANDRA |
| 933 | - 1002 VACANT |
| 933 | MORRIS LAVINO L |
| 933 | VACANT |
| | |

951

NOTVERIFIED

1991 NORRIS ST

SOURCE: POLKS

6432

R & K INDUSTRIES MACH MFRS

1991 TRUE ST SOURCE: POLKS

836 WHITTLE MERTICE

840 VACANT

843 HAMPTON ROBERT

844 BRANDON CLARA C MRS

849 ELLIOTT NORA A 853 RYAN ANNA E

902 STONE IRIS MRS

906 MULTI TENANT RESIDENTIAL

906 WILLIAMS ANGELO

908 BRITTON MIKE

919 CARR JAMES H ASSOCS EVNMTL TESTING LABY

951 CAROLINA COMPOUND INC JAN SUPS

SOURCE: POLKS

VACANT

912 925 **BROWN L R FOOD BROKERAGE**

929 ANDERSON RICHARD 929 **FARLEY GEROGIANNA S**

LIVINGSTON JOHN 929

929 **VACANT**

933 FRIERSON RICHARD

933 SATO HITOSHI 933 VACANT 1002 **VACANT**

NORRIS ST 1986 SOURCE: POLKS

6432 R & K INDUSTRIES

| 1986 SOURCE: F | TRUE ST POLKS |
|-------------------|--|
| 823 | TIM TAM YAU |
| 832 | BRAZELL PAUL G |
| 835 | VACANT |
| 836 | WHITTLE MERTICE |
| 840 | DUKE MATTIE M |
| 843 | HAMPTON ROBERT |
| 844 | BRANDON CLARA C MRS |
| 849 | DOVER VICKIE |
| 853 | RYAN ANDREW H JR |
| 902 | STONE WM |
| 919 | CARR JAMES H ASSOCS ENVIRONMENTAL TESTING LABY |
| 951 | AIR PRODUCTS & CHEMICALS INC |

DRAKE ST 1981 SOURCE: HILLS

| 912 | CATIONICS INC DIV COLA ORG CHEM CO CHEM MFRS |
|------|--|
| 912 | COLUMBIA ORGANIC CHEMICALS CO MFRS |
| 925 | VACANT |
| 1002 | KAHN M B CONSTN CO SHOP |

NORRIS ST 1981

SOURCE: HILLS

6432

6434

DEFENDER CHEMICAL CO

VACANT

TRUE ST 1981

SOURCE: HILLS

801 **BRANTLEY JOSEPH E DENTIST** 801 SOX JOHN T JR DENTIST

804 VACANT

821 **GLENN LILLIAN D MRS**

SOWELL MARY C 822

823 **MIXON MILLIE S**

832 **BRAZELL PAUL G** 835 **CULLEY ELLIE C JR** 836 WHITTLE MERTICE

840 **DUKE THOS** 843 **FAULLING**

844 **BRANDON CLARA C MRS**

849 **LEWIS MELISSA** 853 RYAN ANDREW H JR 902 WRIGHT HUBERT C

919 CARR JAMES H ASSOCS WATER TESTING LABY

921 **ELEAZER A FRED** 1976 DRAKE ST
SOURCE: HILLS

1976 NORRIS ST
SOURCE: HILLS

912 COLUMBIA ORGANIC CHEMICALS CO (MFRS) 1002 KAHN M B CONSTN CO SHOP

1030 VACANT

6432 CAROLINA TOOL & DIE CO
 6432 DEFENDER CHEMICAL CO
 6432 DEFENDER INDUSTRIAL MAINTENANCE CORP
 6434 SQUARE D WHSE

Report ID: 22071200085 - 07/14/2022 www.erisinfo.com

1976 TRUE ST
SOURCE: HILLS

835 CULLEY ELLIE C
836 WHITTLE MERTICE
840 DUKE THOS M
843 STEDMAN PAT'
844 BRANDON CLARA C MRS

WRIGHT HUBERT C

ELEAZER A FRED

CARR JAMES H & ASSOCIATE LABY

849

853

902

919 921 CULLEY ELLIE C
WHITTLE MERTICE
DUKE THOS M
STEDMAN PAT'
BRANDON CLARA C MRS
BENNETT JAMES
RYAN A H JR

1970

912 COLUMBIA ORGANIC CHEMICALS CO (MFRS)

SHIRAH MONROE
TYSON LUCILLE S MRS
KAHN M B CONSTN CO SHOP
INDUSTRIAL ELECTRIC CO INC CONTRS

DRAKE ST

1970 NORRIS ST
SOURCE: HILLS

1970 TRUE ST
SOURCE: HILLS

| 6432 | CAROLINA TOOL & DIE CO | 843 | PRICE DAVID C |
|------|---------------------------------------|-----|----------------------------|
| 6432 | DEFENDER CHEMICAL CO WHOL | 844 | BRANDON CLARA C MRS |
| 6432 | DEFENDER INDUSTRIAL MAINTENANCE CORP | 902 | WRIGHT HUBERT C |
| 6432 | DEFENDER SERVICE CO HOTEL & RESTR SUP | 921 | ELEAZER A FRED |
| | | 926 | VACANT |
| | | | |

1964 DRAKE ST
SOURCE: HILLS

PALMETTO METAL PRODUCTS INC MFRS

SHIRAH MONROE

NO RETURN

925

1002

1030

1964 NORRIS ST

SOURCE: HILLS

6430 GREENWOOD GEO R 6432 CAROLINA TOOL & DIE CO

6432 DEFENDER BUILDING MAINTENANCE CO

6432 **DEFENDER CHEMICAL CO WHOL**

Page: **22**

1964 TRUE ST

833 MAHAFFEY W C 835 **CULLEY ELLIE C** 836 **CUNNINGHAM BROOKS L** 840 **DUKE THOS** 843 STEGALL JOHN S 844 **BRANDON CLARA MRS** 902 LINTCF **ELEAZER A FRED** 921 926 VACANT

1958 DRAKE ST

1002 BASS BLDG SPECIALTIES INC BLDG SUPS 1030 BONITZ INSULATION CO OF SC 1958 NORRIS ST

SOURCE: HILLS

6430 CAPITOL GLASS CO INC

833 YOUNG DAVID G

GREENWOOD GEO R 835 CULLEY ELLIE C
836 BOWEN DWIGHT N
840 FURR WM W
843 BREWER LUTHER G
844 FUE ROSS W
902 BELL HARVEY J

6430

SOURCE: HILLS

1955 NORRIS ST

STREET NOT LISTED

TRUE ST 1955

SOURCE: HILLS

DRAKE ST 1950

STREET NOT LISTED

SOURCE: HILLS

STREET NOT LISTED

Report ID: 22071200085 - 07/14/2022 www.erisin fo.com

1950 NORRIS ST

IORRIS ST

1950 TRUE ST SOURCE: HILLS

STREET NOT LISTED STREET NOT LISTED

SOURCE: HILLS

1945 NORRIS ST

STREET NOT LISTED STREET NOT LISTED

1945 TRUE ST

STREET NOT LISTED

SOURCE: HILLS

1940 DRAKE ST SOURCE: HILLS

STREET NOT LISTED

SOURC

NORRIS ST 1940 SOURCE: HILLS

TRUE ST 1940 SOURCE: HILLS

STREET NOT LISTED STREET NOT LISTED

STREET NOT LISTED

SOURCE: HILLS

1935 NORRIS ST

STREET NOT LISTED

300/10

Page: **31**

1935 TRUE ST

STREET NOT LISTED

SOURCE: HILLS

1930 DRAKE ST SOURCE: HILLS

STREET NOT LISTED

SOURC

1930 NORRIS ST

SOURCE: HILLS

1930 TRUE ST SOURCE: HILLS

STREET NOT LISTED

SOURCE: WALSH

1925 NORRIS ST

SOURCE: WALSH

STREET NOT LISTED

1925 TRUE ST SOURCE: WALSH

APPENDIX D ENVIRONMENTAL DATABASE INFORMATION



Project Property: Drake Street

1002 Drake Street

Columbia SC 29209

Project No: 73227142

Report Type: Database Report

Order No: 22071200085

Requested by: Terracon Consultants, Inc.

Date Completed: July 13, 2022

Table of Contents

| Table of Contents | 2 |
|---|-----|
| Executive Summary | |
| Executive Summary: Report Summary | |
| Executive Summary: Site Report Summary - Project Property | |
| Executive Summary: Site Report Summary - Surrounding Properties | 9 |
| Executive Summary: Summary by Data Source | 13 |
| Map | 21 |
| Aerial | 24 |
| Topographic Map | 25 |
| Detail Report | 26 |
| Unplottable Summary | 96 |
| Unplottable Report | 97 |
| Appendix: Database Descriptions | |
| Definitions | 113 |

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Order No: 22071200085

Executive Summary

| Pro | pertv | Inform | ation: |
|-----|-------|--------|--------|
| | | | |

Project Property: Drake Street

1002 Drake Street Columbia SC 29209

Project No: 73227142

Coordinates:

 Latitude:
 33.98301969

 Longitude:
 -80.95721158

 UTM Northing:
 3,760,274.06

 UTM Easting:
 503,952.20

 UTM Zone:
 UTM Zone 17S

Elevation: 247 FT

Order Information:

 Order No:
 22071200085

 Date Requested:
 July 12, 2022

Requested by: Terracon Consultants, Inc.

Report Type: Database Report

Historicals/Products:

Aerial Photographs Historical Aerials (with Project Boundaries)

City Directory Search CD - 2 Street Search

ERIS Xplorer
Excel Add-On

Excel Add-On

Fire Insurance Maps

US Fire Insurance Maps

Plantial Setting Page (1998)

Physical Setting Report (PSR) Physical Setting Report (PSR)

Topographic MapTopographic MapsterraDOCS ReportterraDOCS (Terracon)

Order No: 22071200085

Executive Summary: Report Summary

| Database | Searched | Search Radius | Project Property | Within 0.12mi | 0.125mi to 0.25mi | 0.25mi to 0.50mi | 0.50mi to 1.00mi | Total |
|--------------------------------|----------|------------------|---------------------|------------------|----------------------|---------------------|---------------------|-------|
| Standard Environmental Records | | | | | | | | |
| Federal | | | | | | | | |
| DOE FUSRAP | Υ | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| NPL | Y | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| PROPOSED NPL | Υ | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| DELETED NPL | Υ | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| SEMS | Υ | 0.5 | 0 | 1 | 0 | 0 | - | 1 |
| SEMS ARCHIVE | Υ | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| ODI | Υ | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| IODI | Υ | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| CERCLIS | Y | 0.5 | 0 | 1 | 0 | 0 | - | 1 |
| CERCLIS NFRAP | Υ | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| CERCLIS LIENS | Υ | PO | 0 | 1 | - | - | - | 1 |
| RCRA CORRACTS | Υ | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| RCRA TSD | Y | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| RCRA LQG | Υ | 0.25 | 0 | 0 | 0 | - | - | 0 |
| RCRA SQG | Υ | 0.25 | 0 | 0 | 1 | - | - | 1 |
| RCRA VSQG | Υ | 0.25 | 0 | 1 | 2 | - | - | 3 |
| RCRA NON GEN | Y | 0.25 | 0 | 1 | 0 | - | - | 1 |
| RCRA CONTROLS | Y | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| FED ENG | Υ | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| FED INST | Υ | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| LUCIS | Υ | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| NPL IC | Υ | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| ERNS 1982 TO 1986 | Υ | PO | 0 | - | - | - | - | 0 |
| ERNS 1987 TO 1989 | Υ | PO | 0 | - | - | - | - | 0 |
| ERNS | Υ | PO | 0 | - | - | - | - | 0 |
| FED BROWNFIELDS | Υ | 0.5 | 1 | 0 | 0 | 0 | - | 1 |
| FEMA UST | Y | 0.25 | 0 | 0 | 0 | - | - | 0 |

Order No: 22071200085

| Dat | abase | Searched | Search Radius | Project Property | Within 0.12mi | 0.125mi to 0.25mi | 0.25mi to 0.50mi | 0.50mi to 1.00mi | Total |
|--|--------------------------------|----------|------------------|---------------------|------------------|----------------------|---------------------|---------------------|-------|
| | FRP | Y | 0.25 | 0 | 0 | 0 | - | - | 0 |
| | DELISTED FRP | Y | 0.25 | 0 | 0 | 0 | - | - | 0 |
| | HIST GAS STATIONS | Υ | 0.25 | 0 | 0 | 0 | - | - | 0 |
| | REFN | Y | 0.25 | 0 | 0 | 0 | - | - | 0 |
| | BULK TERMINAL | Υ | 0.25 | 0 | 0 | 0 | - | - | 0 |
| | SEMS LIEN | Y | PO | 0 | 1 | - | - | - | 1 |
| | SUPERFUND ROD | Υ | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| Sta | ıte | | | | | | | | |
| Oll | | Y | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| | REMEDIATION | Y | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| | SWF/LF | Y | 0.5 | 1 | 1 | 1 | 1 | - | 4 |
| | SASPL | Y | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| | DELISTED SHWS | Y | 0.5 | 0 | 0 | 4 | 7 | | |
| | LUST | | | | | | | - | 11 |
| | LAST | Y | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| | DELISTED LST | Y | 0.5 | 0 | 0 | 1 | 3 | - | 4 |
| | UST | Υ | 0.25 | 0 | 1 | 5 | - | - | 6 |
| | AST | Υ | 0.25 | 0 | 0 | 0 | - | - | 0 |
| | AST SFM | Υ | 0.25 | 0 | 0 | 0 | - | - | 0 |
| | DELISTED TANKS | Y | 0.25 | 0 | 0 | 0 | - | - | 0 |
| | RCR | Y | 0.5 | 0 | 0 | 2 | 2 | - | 4 |
| | VCP | Υ | 0.5 | 0 | 1 | 0 | 0 | - | 1 |
| | BROWNFIELDS | Υ | 0.5 | 3 | 1 | 0 | 0 | - | 4 |
| Tri | bal | | | | | | | | |
| | INDIAN LUST | Y | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| | INDIAN UST | Υ | 0.25 | 0 | 0 | 0 | - | - | 0 |
| | DELISTED ILST | Υ | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| | DELISTED IUST | Y | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Co | | No Co | untv stand | lard enviror | nmental re | cord source | s availahle | for this Sta | te |
| County Standard environmental record sources available for this State. | | | | | | | ic. | | |
| <u>Ad</u> | ditional Environmental Records | | | | | | | | |
| Fee | deral | | | | | | | | |
| | FINDS/FRS | Y | PO | 1 | 2 | - | - | - | 3 |
| | TRIS | Y | PO | 0 | - | - | - | - | 0 |
| | PFAS TRI | Υ | 0.5 | 0 | 0 | 0 | 0 | - | 0 |

| Database | Searched | Search Radius | Project Property | Within 0.12mi | 0.125mi to 0.25mi | 0.25mi to 0.50mi | 0.50mi to 1.00mi | Total |
|----------------------|----------|------------------|---------------------|------------------|----------------------|---------------------|---------------------|-------|
| PFAS NPL | Y | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| PFAS WATER | Υ | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| PFAS SSEHRI | Υ | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| ERNS PFAS | Y | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| HMIRS | Y | 0.125 | 0 | 0 | - | - | - | 0 |
| NCDL | Y | 0.125 | 0 | 0 | - | - | - | 0 |
| TSCA | Y | 0.125 | 0 | 0 | - | - | - | 0 |
| HIST TSCA | Y | 0.125 | 0 | 0 | - | - | - | 0 |
| FTTS ADMIN | Υ | PO | 0 | - | - | - | - | 0 |
| FTTS INSP | Y | PO | 0 | - | - | - | - | 0 |
| PRP | Y | PO | 0 | 3 | - | - | - | 3 |
| SCRD DRYCLEANER | Y | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| ICIS | Y | PO | 0 | 1 | - | - | - | 1 |
| FED DRYCLEANERS | Υ | 0.25 | 0 | 0 | 1 | - | - | 1 |
| DELISTED FED DRY | Υ | 0.25 | 0 | 0 | 0 | - | - | 0 |
| FUDS | Y | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| FORMER NIKE | Y | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| PIPELINE INCIDENT | Y | PO | 0 | - | - | - | - | 0 |
| MLTS | Y | PO | 0 | - | - | - | - | 0 |
| HIST MLTS | Y | PO | 0 | - | - | - | - | 0 |
| MINES | Y | 0.25 | 0 | 0 | 0 | - | - | 0 |
| SMCRA | Y | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| MRDS | Y | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| URANIUM | Y | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| ALT FUELS | Y | 0.25 | 0 | 0 | 0 | - | - | 0 |
| CONSENT DECREES | Y | 0.25 | 0 | 0 | 0 | - | - | 0 |
| AFS | Y | PO | 0 | - | - | - | - | 0 |
| SSTS | Y | 0.25 | 0 | 0 | 0 | - | - | 0 |
| PCBT | Y | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| PCB | Y | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| State | | | | | | | | |
| SPILLS | Y | 0.125 | 0 | 0 | - | - | - | 0 |
| DRYCLEANERS | Y | 0.25 | 0 | 0 | 1 | - | - | 1 |
| DRY CLEANERS | Y | 0.25 | 0 | 0 | 1 | - | - | 1 |
| DELISTED DRYCLEANERS | Y | 0.25 | 0 | 0 | 0 | - | - | 0 |

| Database | Searched | Search Radius | Project Property | Within 0.12mi | 0.125mi to 0.25mi | 0.25mi to 0.50mi | 0.50mi to 1.00mi | Total |
|------------|----------|------------------|---------------------|------------------|----------------------|---------------------|---------------------|-------|
| AIR PERMIT | Y | 0.25 | 0 | 0 | 0 | - | - | 0 |
| UIC | Υ | PO | 0 | - | - | - | - | 0 |
| AGRI FAC | Υ | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Tribal | No Tri | bal additio | onal environ | mental red | cord source | s available | for this Stat | te. |
| County | No Co | unty addit | ional enviro | nmental r | ecord sourc | es available | e for this St | ate. |
| | | | | | | | | |
| - | Total: | | 6 | 16 | 19 | 13 | 0 | 54 |

^{*} PO – Property Only
* 'Property and adjoining properties' database search radii are set at 0.25 miles.

Executive Summary: Site Report Summary - Project Property

| Map Key | DB | Company/Site Name | Address | Direction | Distance (mi/ft) | Elev Diff (ft) | Page Number |
|------------|--------------------|--------------------------|--|-----------|---------------------|-------------------|----------------|
| 1 | FINDS/FRS | DRAKE ST. PROPERTY | 1002, 1030 DRAKE ST. COLUMBIA SC 29209 | S | 0.00 / 0.00 | 2 | <u>26</u> |
| | | | Registry ID: 110038718000 | | | | |
| 1 | SASPL | DRAKE STREET PROPERTY | 1002 DRAKE ST, COLUMBIA SC 29209-1624 SC | S | 0.00 / 0.00 | 2 | <u>26</u> |
| 1 | FED BROWNFIELDS | Drake St. Property | 1002, 1030 Drake St. Columbia SC 29209 | S | 0.00 / 0.00 | 2 | <u>26</u> |
| | | | Acres Property ID: 67361 | | | | |
| 1 | BROWNFIELDS | DRAKE STREET PROPERTY | 1002 DRAKE ST COLUMBIA SC 29209-1624 | S | 0.00 / 0.00 | 2 | <u>28</u> |
| <u>1</u> | BROWNFIELDS | DRAKE STREET PROPERTY | 1002 DRAKE ST COLUMBIA SC 29209-1624 | S | 0.00 / 0.00 | 2 | <u>29</u> |
| 1 | BROWNFIELDS | DRAKE STREET PROPERTY | 1002 DRAKE ST COLUMBIA SC 29209-1624 | S | 0.00 / 0.00 | 2 | <u>29</u> |

Executive Summary: Site Report Summary - Surrounding Properties

| Map Key | DB | Company/Site Name | Address | Direction | Distance (mi/ft) | Elev Diff (ft) | Page Number |
|------------|------------------|--|--|-----------|---------------------|-------------------|----------------|
| 2 | BROWNFIELDS | CEDAR TERRACE DEVELOPMENT | 1015 DRAKE ST COLUMBIA SC 29209-1623 | NW | 0.01 / 28.33 | -2 | <u>29</u> |
| <u>2</u> | VCP | CEDAR TERRACE DEVELOPMENT | 1015 DRAKE ST COLUMBIA SC 29209-1623 | NW | 0.01 / 28.33 | -2 | <u>30</u> |
| 2 | SASPL | CEDAR TERRACE DEVELOPMENT | 1015 DRAKE ST, COLUMBIA SC 29209-1623 SC | NW | 0.01 / 28.33 | -2 | <u>30</u> |
| <u>3</u> | FINDS/FRS | AIR PRODUCTS & CHEMICAL | 951 TRUE ST COLUMBIA SC 29209-1633 Registry ID: 110017146587 | SE | 0.01 / 47.45 | 3 | 3 <u>0</u> |
| <u>3</u> | UST | AIR PRODUCTS & CHEMICAL | 951 TRUE ST COLUMBIA SC 29209-1633 Site No: 07899 | SE | 0.01 / 47.45 | 3 | <u>31</u> |
| <u>4</u> | CERCLIS LIENS | COLUMBIA ORGANIC CHEMICAL-DRAKE | Tank No Status: 1 Abandoned DRAKE AVE COLUMBIA SC 29209 EPA ID: SCD003343571 | SW | 0.01 / 51.84 | 7 | <u>32</u> |
| <u>4</u> | CERCLIS | COLUMBIA ORGANIC CHEMICAL-DRAKE | DRAKE AVE COLUMBIA SC 29209 Site EPA ID: SCD003343571 | SW | 0.01 / 51.84 | 7 | <u>32</u> |
| <u>4</u> | RCRA NON GEN | COLUMBIA ORGANIC CHEMICAL CO | 912 DRAKE ST COLUMBIA SC 29209 EPA Handler ID: SCD003343571 | SW | 0.01 / 51.84 | 7 | <u>37</u> |
| <u>4</u> | FINDS/FRS | COLUMBIA ORGANIC CHEMICAL-DRAKE | DRAKE AVE COLUMBIA SC 29209 Registry ID: 110031457670 | SW | 0.01 / 51.84 | 7 | 38 |
| <u>4</u> | ICIS | COLUMBIA ORGANIC CHEMICAL-DRAKE | DRAKE AVE COLUMBIA SC 29209 Registry ID: 110031457670 | SW | 0.01 / 51.84 | 7 | <u>39</u> |
| <u>4</u> | SEMS | COLUMBIA ORGANIC CHEMICAL-DRAKE | DRAKE AVE COLUMBIA SC 29209 EPA ID: SCD003343571 | SW | 0.01 / 51.84 | 7 | <u>39</u> |
| <u>4</u> | PRP | SOUTH CAROLINA REFINING AND DISPOSAL | 912 DRAKE STREET P.O. BOX 9621 COLUMBIA SC 29290 | SW | 0.01 / 51.84 | 7 | 40 |

| Map Key | DB | Company/Site Name | Address | Direction | Distance (mi/ft) | Elev Diff (ft) | Page Number |
|------------|-----------------|--|---|-------------------|---------------------|--------------------|-----------------|
| | | | Site EPA ID: WVD047989207 | | | | |
| <u>4</u> | PRP | COLUMBIA ORGANIC CHEMICAL CO., INC. | 912 DRAKE STREET COLUMBIA SC 29209 | SW | 0.01 / 51.84 | 7 | <u>41</u> |
| | | | Site EPA ID: SCD981757149 | | | | |
| <u>4</u> | PRP | COLUMBIA ORGANIC CHEMICAL CO., INC. | 912 DRAKE STREET COLUMBIA SC 29209 | SW | 0.01 / 51.84 | 7 | 41 |
| | | | Site EPA ID: SCD980558316 | | | | |
| 4 | SEMS LIEN | COLUMBIA ORGANIC CHEMICAL-DRAKE | 912 DRAKE STREET COLUMBIA, SC SC | SW | 0.01 / 51.84 | 7 | <u>41</u> |
| | | | EPA ID: SCD003343571 | | | | |
| <u>5</u> | RCRA VSQG | JAMES H CARR & ASSOCIATES | 919 TRUE ST COLUMBIA SC 29290 | S | 0.05 / 289.61 | 7 | <u>42</u> |
| | | | EPA Handler ID: SCD987597176 | | | | |
| <u>6</u> | RCRA VSQG | WALGREENS 17066 | 6500 GARNERS FERRY RD COLUMBIA SC 29209 | SW | 0.22 / 1,182.71 | 13 | <u>44</u> |
| | | | EPA Handler ID: SCR000776377 | | | | |
| <u>7</u> | UST | CORNER PANTRY 126 | 6524 GARNERS FERRY RD COLUMBIA SC 29209 | SW | 0.24 / 1,268.59 | 12 | <u>50</u> |
| | | | Site No: 07791 Tank No Status: 2 Currently in Us 5 Extended Out-of-Use | se, 3 Currently | in Use, 4 Curren | tly in Use, 1 Cu | rrently in Use, |
| <u>7</u> | LUST | CORNER PANTRY 126 | 6524 GARNERS FERRY RD COLUMBIA SC 29209 | SW | 0.24 / 1,268.59 | 12 | <u>55</u> |
| | | | Site ID Permit: 07791 R 07791 NFA: 7/9/2007, 10/1/2008 | | | | |
| 7 | RCR | CORNER PANTRY 126 | 6524 GARNERS FERRY RD COLUMBIA SC 29209 | SW | 0.24 / 1,268.59 | 12 | <u>57</u> |
| <u>8</u> . | RCRA VSQG | EXPRESS OIL CANGE AND SERVICE CTR | 6306 GARNERS FERRY RD COLUMBIA SC 29209 | wsw | 0.24 / 1,269.84 | 18 | <u>57</u> |
| | | | EPA Handler ID: SCR000775411 | | | | |
| <u>8</u> | DELISTED LST | KEL TAY EXPRESS | 6306 GARNERS FERRY RD COLUMBIA SC | WSW | 0.24 / 1,269.84 | 18 | <u>58</u> |
| 9 | RCRA | COLUMBIAS CLEANERS | 6320 GARNERS FERRY RD | WSW | 0.24 / | 15 | <u>59</u> |
| | SQG | INC | COLUMBIA SC 29209 EPA Handler ID: SCD981756190 | | 1,274.74 | | |
| | IIIeT | DUDNETTEC CLEANEDC | | 14/614/ | 0.04 / | 45 | |
| 9 | LUST | BURNETTES CLEANERS | 6320 GARNERS FERRY RD COLUMBIA SC 29209 | WSW | 0.24 / 1,274.74 | 15 | <u>68</u> |
| | | | Site ID Permit: 15724 N 15724 | | | | |
| <u>9</u> | SASPL | COLUMBIA'S CLEANERS/FMR BURNETTE'S CLNRS | 6320 GARNERS FERRY RD, COLUMBIA SC 29209 SC | WSW | 0.24 / 1,274.74 | 15 | <u>70</u> |

| Map Key | DB | Company/Site Name | Address | Direction | Distance (mi/ft) | Elev Diff (ft) | Page Number |
|------------|--------------------|--|--|-----------------|---------------------|-------------------|----------------|
| | | | | | | | |
| <u>9</u> | UST | BURNETTES CLEANERS | 6320 GARNERS FERRY RD COLUMBIA SC 29209 | WSW | 0.24 / 1,274.74 | 15 | <u>70</u> |
| | | | Site No: 15724 Tank No Status: 3 Abandoned, 1 | Abandoned, 2 | Abandoned | | |
| <u>9</u> | DRY CLEANERS | COLUMBIA'S CLEANERS/FMR BURNETTE'S CLNRS | 6320 GARNERS FERRY RD COLUMBIA SC | WSW | 0.24 / 1,274.74 | 15 | 7 <u>2</u> |
| 9 | DRYCLEANERS | COLUMBIA'S CLEANERS/FMR BURNETTE'S CLNRS | 6320 GARNERS FERRY RD; COLUMBIA SC | WSW | 0.24 / 1,274.74 | 15 | <u>73</u> |
| 9 | FED DRYCLEANERS | COLUMBAS CLEANERS INCORPORATED | 6320 GARNERS FERRY RD COLUMBIA SC 29209 | WSW | 0.24 / 1,274.74 | 15 | <u>73</u> |
| | | | FRS Facility ID: 110002245204 | | | | |
| <u>10</u> | UST | MEADOW FIELD CHEVRON | 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603 | SW | 0.24 / 1,280.22 | 11 | <u>73</u> |
| | | | Site No: 07807 Tank No Status: 1 Abandoned, 4 | Abandoned, 2 | Abandoned, 3 | Abandoned | |
| <u>10</u> | UST | HENRY CHEVRON | 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603 | SW | 0.24 / 1,280.22 | 11 | <u>76</u> |
| | | | Site No: 10688 Tank No Status: 2 Abandoned, 3 | Abandoned, 1 | Abandoned | | |
| <u>10</u> | LUST | MEADOW FIELD CHEVRON | 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603 | SW | 0.24 / 1,280.22 | 11 | <u>79</u> |
| | | | Site ID Permit: 07807 N 07807 NFA: 12/19/2008 | | | | |
| <u>10</u> | LUST | HENRY CHEVRON | 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603 | SW | 0.24 / 1,280.22 | 11 | <u>81</u> |
| | | | Site ID Permit: 10688 P 10688 NFA: 6/1/2001 | | | | |
| <u>10</u> | UST | RIDGEWAYS AUTO SERVICE | 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603 | SW | 0.24 / 1,280.22 | 11 | <u>82</u> |
| <u>10</u> | RCR | MEADOW FIELD CHEVRON | 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603 | SW | 0.24 / 1,280.22 | 11 | <u>82</u> |
| <u>11</u> | LUST | WJBD VETERANS HOSPITAL | 6439 GARNERS FERRY RD COLUMBIA SC 29209-1638 | WSW | 0.26 / 1,348.54 | 14 | <u>82</u> |
| | | | Site ID Permit: 07394 N 07394 NFA: 7/23/1999, 12/29/1998, 7/23/19 | 999, 11/21/1994 | | | |
| <u>12</u> | DELISTED LST | 6200 BLOCK GARNERS FERRY ROAD | 6200 BLOCK GARNERS FERRY RD COLUMBIA SC | wsw | 0.29 / 1,505.90 | 4 | <u>85</u> |

| Map Key | DB | Company/Site Name | Address | Direction | Distance (mi/ft) | Elev Diff (ft) | Page Number |
|------------|-----------------|-------------------------------|--|-----------|---------------------|-------------------|----------------|
| <u>13</u> | LUST | CIRCLE K 2705134 | 6122 GARNERS FERRY RD COLUMBIA SC 29209-1353 Site ID Permit: 10048 P 10048 NFA: 8/23/2007 | wsw | 0.36 / 1,884.74 | -4 | <u>86</u> |
| <u>13</u> | RCR | CIRCLE K 2705134 | 6122 GARNERS FERRY RD COLUMBIA SC 29209-1353 | WSW | 0.36 / 1,884.74 | -4 | <u>87</u> |
| <u>14</u> | SASPL | FMR LEXINGTON DRY CLEANING | 6041 GARNERS FERRY RD, COLUMBIA SC 29209 SC | W | 0.37 / 1,935.44 | -10 | <u>87</u> |
| <u>14</u> | LUST | LANIER BUILDING | 6041 GARNERS FERRY RD COLUMBIA SC 29202-1304 Site ID Permit: N 14085 | W | 0.37 / 1,935.44 | -10 | <u>88</u> |
| <u>14</u> | DELISTED LST | 6041 GARNERS FERRY RD | NFA: 10/20/1992 6041 GARNERS FERRY RD COLUMBIA SC | W | 0.37 / 1,935.44 | -10 | <u>88</u> |
| <u>15</u> | LUST | WLTX | 6027 GARNERS FERRY RD COLUMBIA SC 29209 Site ID Permit: 11518 N 11518 | W | 0.42 / 2,208.28 | -10 | <u>89</u> |
| <u>16</u> | LUST | GEORGE A CREED & SON INC | NFA: 4/20/1992 813 LEESBURG RD COLUMBIA SC 29209-0000 Site ID Permit: 14568 N 14568 | SE | 0.46 / 2,410.50 | 5 | <u>90</u> |
| <u>17</u> | LUST | FOOD SERVICE SUPPLIES INC | NFA: 12/17/1993, 7/6/2001, 7/6/2001 844 PEPPER ST COLUMBIA SC 29209 | SE | 0.49 / 2,608.85 | 11 | 92 |
| <u>17</u> | DELISTED LST | PEPPER STREET TRACT | Site ID Permit: 14122 N 14122 NFA: 10/9/1992 844 PEPPER ST COLUMBIA SC | SE | 0.49 / 2,608.85 | 11 | <u>93</u> |
| <u>18</u> | LUST | GOLD CIRCLE STORE | 6000 GARNERS FERRY RD COLUMBIA SC 29209 | W | 0.50 / 2,631.48 | 5 | <u>93</u> |
| <u>18</u> | RCR | GOLD CIRCLE STORE | Site ID Permit: 11486 N 11486 NFA: 10/24/2003 6000 GARNERS FERRY RD COLUMBIA SC 29209 | W | 0.50 / 2,631.48 | 5 | <u>95</u> |

Executive Summary: Summary by Data Source

Standard

Federal

SEMS - SEMS List 8R Active Site Inventory

A search of the SEMS database, dated Apr 27, 2022 has found that there are 1 SEMS site(s) within approximately 0.50 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | Map Key |
|------------------------------------|--------------------------------|------------------|------------------|----------|
| COLUMBIA ORGANIC CHEMICAL-DRAKE | DRAKE AVE COLUMBIA SC 29209 | SW | 0.01 / 51.84 | <u>4</u> |
| | EPA ID : SCD003343571 | | | |

CERCLIS - Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS

A search of the CERCLIS database, dated Oct 25, 2013 has found that there are 1 CERCLIS site(s) within approximately 0.50 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | Direction | Distance (mi/ft) | Map Key |
|------------------------------------|--------------------------------|------------------|------------------|----------|
| COLUMBIA ORGANIC CHEMICAL-DRAKE | DRAKE AVE COLUMBIA SC 29209 | SW | 0.01 / 51.84 | <u>4</u> |
| | Site EPA ID: SCD003343571 | | | |

CERCLIS LIENS - CERCLIS Liens

A search of the CERCLIS LIENS database, dated Jan 30, 2014 has found that there are 1 CERCLIS LIENS site(s) within approximately 0.02 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | Direction | Distance (mi/ft) | <u>Map Key</u> |
|------------------------------------|--------------------------------|------------------|------------------|----------------|
| COLUMBIA ORGANIC CHEMICAL-DRAKE | DRAKE AVE COLUMBIA SC 29209 | SW | 0.01 / 51.84 | <u>4</u> |
| | EPA ID : SCD003343571 | | | |

RCRA SQG - RCRA Small Quantity Generators List

A search of the RCRA SQG database, dated Apr 11, 2022 has found that there are 1 RCRA SQG site(s) within approximately 0.25 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | Map Key |
|-------------------------------|--|------------------|------------------|---------|
| COLUMBIAS CLEANERS INC | 6320 GARNERS FERRY RD COLUMBIA SC 29209 | WSW | 0.24 / 1,274.74 | 9 |
| | EPA Handler ID: SCD981756190 | | | |

RCRA VSQG - RCRA Very Small Quantity Generators List

A search of the RCRA VSQG database, dated Apr 11, 2022 has found that there are 3 RCRA VSQG site(s) within approximately 0.25 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | <u>Map Key</u> |
|--------------------------------------|--|------------------|------------------|----------------|
| JAMES H CARR & ASSOCIATES | 919 TRUE ST COLUMBIA SC 29290 | S | 0.05 / 289.61 | <u>5</u> |
| | EPA Handler ID: SCD987597176 | | | |
| WALGREENS 17066 | 6500 GARNERS FERRY RD COLUMBIA SC 29209 | SW | 0.22 / 1,182.71 | <u>6</u> |
| | EPA Handler ID: SCR000776377 | | | |
| EXPRESS OIL CANGE AND SERVICE CTR | 6306 GARNERS FERRY RD COLUMBIA SC 29209 | WSW | 0.24 / 1,269.84 | <u>8</u> |
| | EPA Handler ID: SCR000775411 | | | |

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Apr 11, 2022 has found that there are 1 RCRA NON GEN site(s) within approximately 0.25 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | <u>Map Key</u> |
|---------------------------------|-----------------------------------|------------------|------------------|----------------|
| COLUMBIA ORGANIC CHEMICAL CO | 912 DRAKE ST COLUMBIA SC 29209 | SW | 0.01 / 51.84 | <u>4</u> |
| | EPA Handler ID: SCD003343571 | | | |

<u>FED BROWNFIELDS</u> - The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database

A search of the FED BROWNFIELDS database, dated Aug 20, 2021 has found that there are 1 FED BROWNFIELDS site(s) within approximately 0.50 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | Direction | Distance (mi/ft) | <u>Map Key</u> |
|------------------------|---|------------------|------------------|----------------|
| Drake St. Property | 1002, 1030 Drake St. Columbia SC 29209 | S | 0.00 / 0.00 | 1 |
| | Acres Property ID: 67361 | | | |

SEMS LIEN - LIEN on Property

A search of the SEMS LIEN database, dated Apr 27, 2022 has found that there are 1 SEMS LIEN site(s) within approximately 0.02 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | Map Key |
|------------------------------------|-------------------------------------|------------------|------------------|----------|
| COLUMBIA ORGANIC CHEMICAL-DRAKE | 912 DRAKE STREET COLUMBIA, SC SC | SW | 0.01 / 51.84 | <u>4</u> |
| | EPA ID : SCD003343571 | | | |

State

SASPL - Site Assessment Section Project List

A search of the SASPL database, dated Jun 2, 2022 has found that there are 4 SASPL site(s) within approximately 0.50 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | Map Key |
|---|---|------------------|------------------|-----------|
| DRAKE STREET PROPERTY | 1002 DRAKE ST, COLUMBIA SC 29209-1624 SC | S | 0.00 / 0.00 | 1 |
| COLUMBIA'S CLEANERS/FMR BURNETTE'S CLNRS | 6320 GARNERS FERRY RD, COLUMBIA SC 29209 SC | wsw | 0.24 / 1,274.74 | <u>9</u> |
| Lower Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | Map Key |
| CEDAR TERRACE DEVELOPMENT | 1015 DRAKE ST, COLUMBIA SC 29209-1623 SC | NW | 0.01 / 28.33 | 2 |
| FMR LEXINGTON DRY CLEANING | 6041 GARNERS FERRY RD, COLUMBIA SC 29209 SC | W | 0.37 / 1,935.44 | <u>14</u> |

<u>LUST</u> - Leaking Underground Storage Tank List

A search of the LUST database, dated Apr 27, 2022 has found that there are 11 LUST site(s) within approximately 0.50 miles of the project property.

| Equal/Higher Elevation | Address | <u>Direction</u> | Distance (mi/ft) | Map Key |
|---------------------------|---|------------------|------------------|-----------|
| CORNER PANTRY 126 | 6524 GARNERS FERRY RD COLUMBIA SC 29209 | SW | 0.24 / 1,268.59 | <u>7</u> |
| | Site ID Permit: 07791 R 07791 NFA: 7/9/2007, 10/1/2008 | | | |
| BURNETTES CLEANERS | 6320 GARNERS FERRY RD COLUMBIA SC 29209 | WSW | 0.24 / 1,274.74 | 9 |
| | Site ID Permit: 15724 N 15724 | | | |
| HENRY CHEVRON | 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603 | SW | 0.24 / 1,280.22 | <u>10</u> |
| | Site ID Permit: 10688 P 10688 NFA: 6/1/2001 | | | |
| MEADOW FIELD CHEVRON | 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603 | SW | 0.24 / 1,280.22 | <u>10</u> |
| | Site ID Permit : 07807 N 07807 NFA : 12/19/2008 | | | |
| WJBD VETERANS HOSPITAL | 6439 GARNERS FERRY RD COLUMBIA SC 29209-1638 | WSW | 0.26 / 1,348.54 | <u>11</u> |
| | Site ID Permit : 07394 N 07394 NFA : 7/23/1999, 12/29/1998, 7/23/1999, | 11/21/1994 | | |
| GEORGE A CREED & SON INC | 813 LEESBURG RD COLUMBIA SC 29209-0000 | SE | 0.46 / 2,410.50 | <u>16</u> |
| | Site ID Permit: 14568 N 14568 NFA: 12/17/1993, 7/6/2001, 7/6/2001 | | | |
| FOOD SERVICE SUPPLIES INC | 844 PEPPER ST COLUMBIA SC 29209 | SE | 0.49 / 2,608.85 | <u>17</u> |

| Equal/Higher Elevation | Address | <u>Direction</u> | Distance (mi/ft) | Map Key |
|------------------------|--|------------------|------------------|-----------|
| | Site ID Permit : 14122 N 14122 NFA : 10/9/1992 | | | |
| GOLD CIRCLE STORE | 6000 GARNERS FERRY RD COLUMBIA SC 29209 | W | 0.50 / 2,631.48 | <u>18</u> |
| | Site ID Permit : 11486 N 11486 NFA : 10/24/2003 | | | |
| Lower Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | Map Key |
| CIRCLE K 2705134 | 6122 GARNERS FERRY RD COLUMBIA SC 29209-1353 | WSW | 0.36 / 1,884.74 | <u>13</u> |
| | Site ID Permit: 10048 P 10048 NFA: 8/23/2007 | | | |
| LANIER BUILDING | 6041 GARNERS FERRY RD COLUMBIA SC 29202-1304 | W | 0.37 / 1,935.44 | <u>14</u> |
| | Site ID Permit: N 14085 NFA: 10/20/1992 | | | |
| WLTX | 6027 GARNERS FERRY RD COLUMBIA SC 29209 | W | 0.42 / 2,208.28 | <u>15</u> |
| | Site ID Permit: 11518 N 11518 NFA: 4/20/1992 | | | |

DELISTED LST - Delisted Leaking Storage Tanks

A search of the DELISTED LST database, dated Apr 27, 2022 has found that there are 4 DELISTED LST site(s) within approximately 0.50 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | Map Key |
|----------------------------------|--|------------------|------------------|----------------|
| KEL TAY EXPRESS | 6306 GARNERS FERRY RD COLUMBIA SC | WSW | 0.24 / 1,269.84 | <u>8</u> |
| 6200 BLOCK GARNERS FERRY ROAD | 6200 BLOCK GARNERS FERRY RD COLUMBIA SC | wsw | 0.29 / 1,505.90 | <u>12</u> |
| PEPPER STREET TRACT | 844 PEPPER ST COLUMBIA SC | SE | 0.49 / 2,608.85 | <u>17</u> |
| Lower Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | <u>Map Key</u> |
| 6041 GARNERS FERRY RD | 6041 GARNERS FERRY RD COLUMBIA SC | W | 0.37 / 1,935.44 | <u>14</u> |

<u>UST</u> - Underground Storage Tank List

A search of the UST database, dated Apr 27, 2022 has found that there are 6 UST site(s) within approximately 0.25 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | Map Key | |
|-------------------------------|--|--------------------------|-----------------------------|--------------------------|--|
| AIR PRODUCTS & CHEMICAL | 951 TRUE ST COLUMBIA SC 29209-1633 | SE | 0.01 / 47.45 | <u>3</u> | |
| | Site No: 07899 Tank No Status: 1 Abandoned | | | | |
| CORNER PANTRY 126 | 6524 GARNERS FERRY RD COLUMBIA SC 29209 | SW | 0.24 / 1,268.59 | <u>7</u> | |
| | Site No: 07791 Tank No Status: 2 Currently in Use, 3 Out-of-Use | Currently in Use, 4 Cu | ırrently in Use, 1 Curren | tly in Use, 5 Extended | |
| BURNETTES CLEANERS | 6320 GARNERS FERRY RD COLUMBIA SC 29209 | WSW | 0.24 / 1,274.74 | 9 | |
| | Site No: 15724 Tank No Status: 3 Abandoned, 1 Aba | andoned, 2 Abandoned | | | |
| MEADOW FIELD CHEVRON | 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603 | SW | 0.24 / 1,280.22 | <u>10</u> | |
| | Site No: 07807 Tank No Status: 1 Abandoned, 4 Aba | andoned, 2 Abandoned | , 3 Abandoned | | |
| HENRY CHEVRON | 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603 | SW | 0.24 / 1,280.22 | <u>10</u> | |
| | Site No: 10688 Tank No Status: 2 Abandoned, 3 Abandoned, 1 Abandoned | | | | |
| RIDGEWAYS AUTO SERVICE | 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603 | SW | 0.24 / 1,280.22 | <u>10</u> | |

RCR - Registry of Conditional Remedies

A search of the RCR database, dated Jun 9, 2022 has found that there are 4 RCR site(s) within approximately 0.50 miles of the project property.

| Equal/Higher Elevation CORNER PANTRY 126 | Address 6524 GARNERS FERRY RD COLUMBIA SC 29209 | <u>Direction</u> SW | Distance (mi/ft) 0.24 / 1,268.59 | <u>Map Key</u> |
|--|---|-------------------------|-------------------------------------|----------------|
| MEADOW FIELD CHEVRON | 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603 | SW | 0.24 / 1,280.22 | <u>10</u> |
| GOLD CIRCLE STORE | 6000 GARNERS FERRY RD COLUMBIA SC 29209 | W | 0.50 / 2,631.48 | <u>18</u> |
| Lower Elevation CIRCLE K 2705134 | Address 6122 GARNERS FERRY RD COLUMBIA SC 29209-1353 | <u>Direction</u> WSW | Distance (mi/ft) 0.36 / 1,884.74 | <u>Map Key</u> |

Order No: 22071200085

VCP - Site Assessment and Remediation Public Record Database

A search of the VCP database, dated May 19, 2022 has found that there are 1 VCP site(s) within approximately 0.50 miles of the project property.

| Lower Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | <u>Map Key</u> |
|---------------------------|---|------------------|------------------|----------------|
| CEDAR TERRACE DEVELOPMENT | 1015 DRAKE ST COLUMBIA SC 29209-1623 | NW | 0.01 / 28.33 | <u>2</u> |

BROWNFIELDS - Brownfields Sites Listing

A search of the BROWNFIELDS database, dated May 23, 2022 has found that there are 4 BROWNFIELDS site(s) within approximately 0.50 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | Map Key |
|------------------------------|---|------------------|------------------|----------------|
| DRAKE STREET PROPERTY | 1002 DRAKE ST COLUMBIA SC 29209-1624 | S | 0.00 / 0.00 | 1 |
| DRAKE STREET PROPERTY | 1002 DRAKE ST COLUMBIA SC 29209-1624 | S | 0.00 / 0.00 | 1 |
| DRAKE STREET PROPERTY | 1002 DRAKE ST COLUMBIA SC 29209-1624 | S | 0.00 / 0.00 | 1 |
| Lower Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | <u>Map Key</u> |
| CEDAR TERRACE DEVELOPMENT | 1015 DRAKE ST COLUMBIA SC 29209-1623 | NW | 0.01 / 28.33 | <u>2</u> |

Non Standard

Federal

FINDS/FRS - Facility Registry Service/Facility Index

A search of the FINDS/FRS database, dated Nov 2, 2020 has found that there are 3 FINDS/FRS site(s) within approximately 0.02 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | Map Key |
|------------------------------------|---|------------------|------------------|----------|
| DRAKE ST. PROPERTY | 1002, 1030 DRAKE ST. COLUMBIA SC 29209 | S | 0.00 / 0.00 | 1 |
| | Registry ID: 110038718000 | | | |
| AIR PRODUCTS & CHEMICAL | 951 TRUE ST COLUMBIA SC 29209-1633 | SE | 0.01 / 47.45 | <u>3</u> |
| | Registry ID: 110017146587 | | | |
| COLUMBIA ORGANIC CHEMICAL-DRAKE | DRAKE AVE COLUMBIA SC 29209 | SW | 0.01 / 51.84 | <u>4</u> |

Equal/Higher Elevation Address Direction Distance (mi/ft) Map Key

Registry ID: 110031457670

PRP - Potentially Responsible Parties List

A search of the PRP database, dated May 25, 2022 has found that there are 3 PRP site(s) within approximately 0.02 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | Map Key |
|--------------------------------------|---|------------------|------------------|----------|
| COLUMBIA ORGANIC CHEMICAL CO., INC. | 912 DRAKE STREET COLUMBIA SC 29209 | SW | 0.01 / 51.84 | <u>4</u> |
| | Site EPA ID: SCD980558316 | | | |
| SOUTH CAROLINA REFINING AND DISPOSAL | 912 DRAKE STREET P.O. BOX 9621 COLUMBIA SC 29290 | SW | 0.01 / 51.84 | <u>4</u> |
| | Site EPA ID: WVD047989207 | | | |
| COLUMBIA ORGANIC CHEMICAL CO., INC. | 912 DRAKE STREET COLUMBIA SC 29209 | SW | 0.01 / 51.84 | <u>4</u> |
| | Site EPA ID: SCD981757149 | | | |

ICIS - Integrated Compliance Information System (ICIS)

A search of the ICIS database, dated Apr 30, 2022 has found that there are 1 ICIS site(s) within approximately 0.02 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | Map Key |
|------------------------------------|--------------------------------|------------------|------------------|----------|
| COLUMBIA ORGANIC CHEMICAL-DRAKE | DRAKE AVE COLUMBIA SC 29209 | SW | 0.01 / 51.84 | <u>4</u> |
| | Registry ID: 110031457670 | | | |

FED DRYCLEANERS - Drycleaner Facilities

A search of the FED DRYCLEANERS database, dated May 5, 2021 has found that there are 1 FED DRYCLEANERS site(s) within approximately 0.25 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | Map Key |
|-----------------------------------|--|------------------|------------------|----------|
| COLUMBAS CLEANERS INCORPORATED | 6320 GARNERS FERRY RD COLUMBIA SC 29209 | WSW | 0.24 / 1,274.74 | <u>9</u> |
| | FRS Facility ID: 110002245204 | | | |

State

DRYCLEANERS - Drycleaning Facility Restoration Trust Fund Database


A search of the DRYCLEANERS database, dated Jun 27, 2022 has found that there are 1 DRYCLEANERS site(s) within approximately 0.25 miles of the project property.


| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | <u>Map Key</u> | |
|---|---------------------------------------|------------------|------------------|----------------|--|
| COLUMBIA'S CLEANERS/FMR BURNETTE'S CLNRS | 6320 GARNERS FERRY RD; COLUMBIA SC | WSW | 0.24 / 1,274.74 | 9 | |


DRY CLEANERS - Dry Cleaners

A search of the DRY CLEANERS database, dated Jan 9, 2019 has found that there are 1 DRY CLEANERS site(s) within approximately 0.25 miles of the project property.

| Equal/Higher Elevation | <u>Address</u> | <u>Direction</u> | Distance (mi/ft) | <u>Map Key</u> |
|-------------------------|--------------------------------------|------------------|------------------|----------------|
| COLUMBIA'S CLEANERS/FMR | 6320 GARNERS FERRY RD COLUMBIA SC | WSW | 0.24 / 1,274.74 | <u>9</u> |








Aerial Year: 2021

Address: 1002 Drake Street, Columbia, SC

Source: ESRI World Imagery

Order Number: 22071200085





Topographic Map Year: 2017

Address: 1002 Drake Street, SC

Quadrangle(s): Fort Jackson North, SC; Fort Jackson South, SC

Source: USGS Topographic Map

Order Number: 22071200085



© ERIS Information Inc.

Detail Report

| Мар Кеу | Number of Records | Direction | Distance (mi/ft) | Elev/Diff (ft) | Site | DB |
|--|---|---|----------------------------------|--|---|-----------------|
| 1 | 1 of 6 | s | 0.00 / 0.00 | 249.00 / 2 | DRAKE ST. PROPERTY 1002, 1030 DRAKE ST. COLUMBIA SC 29209 | FINDS/FRS |
| Registry ID: FIPS Code: HUC Code: Site Type Na Location De | | 110038718000 45079 03050110 BROWNFIELD | | | | |
| Supplement Create Date: Update Date Interest Type SIC Codes: | al Location: | 24-JUN-09 24-SEP-14 BROWNFIELD | OS PROPERTY | | | |
| Conveyor: Federal Faci Federal Age Tribal Land | s: Descriptions: lity Code: ncy Name: Code: | ACRES | | | | |
| Fribal Land I Congression Census Bloo EPA Region County Nam IS/Mexico E | nal Dist No: ek Code: Code: e: | 02 450790116032 04 RICHLAND | 2010 | | | |
| _atitude: _ongitude: Reference P | oint: ction Method: | | A FACILITY OR S ION-SATELLITE | TATION | | |
| Datum: Source: | il Rprt URL: | NAD83 https://ofmpub | .epa.gov/frs_publi | c2/fii_query_detail | disp_program_facility?p_registry_id=11003871800 | 00 |
| ACRES:6736 | 1 | | | | | |
| 1 | 2 of 6 | s | 0.00 / 0.00 | 249.00 / 2 | DRAKE STREET PROPERTY 1002 DRAKE ST, COLUMBIA SC 29209-1624 SC | SASPL |
| EPA ID: | SCS | 123457101 | | County: | RICHLAND | |
| 1 | 3 of 6 | s | 0.00 / 0.00 | 249.00 / 2 | Drake St. Property 1002, 1030 Drake St. Columbia SC 29209 | FED BROWNFIE |
| Acres Prope Prprty Size(/ Radius: Type of Fund | Acres): 6.86 .5 | | | Cleanup I SFLLP Fa Hrznti Co Source M | Required: U ct Owship: - Ilct Mthd: Interpolation-Satellite | |

TMS R16408-01-01 Local Property No:

Ownership Entity: Private

Current Owner: M.B. Kahn, etal.

DID Ownrshp Chna: Ν **Cntmnt Fnd Petrol:** Υ **Cntmnt Fnd Asb: Cntmnt Fnd Lead:** Υ **Cntmnt Fnd PAHs:** Yes **Cntmnt Fnd PCBs:** Yes **Cntmnt Fnd VOCs:** Yes

Cntmnt Fnd Selenium: **Cntmnt Fnd Iron:**

Cntmnt Fnd Arsenic: Cntmnt Fnd Cd: Cntmnt Fnd Cr: Cntmnt Fnd Copper: Cntmnt Fnd Mercury: Cntmnt Fnd Nickel: **Cntmnt Fnd Pesticide: Cntmnt Fnd SVOCs: Cntmnt Fnd Oth Mtl:** Cntmnt Fnd Other: Yes

Cntmnt Fnd Unk: **Cntmnt Fnd None:** Clnd Up Ctl Sbst: Media Afctd Air: Media Afctd Sedi: Media Afctd Soil: Υ Media Afctd Drnk Wtr: Media Afctd Grnd Wtr: Yes Media Afctd Surf Wtr: Media Afctd Bldg Mat: Media Afctd Ind Air: Media Afctd Unk: Media Afctd None:

Cntmnt Fnd Ctrl Sbstncs:

Further Action Cleanup: Enrollment St Tribal Prg: Institutional Ctrl ICs Reg: IC Catgry Proprietary Ctrls: IC Catgry Informational Dev: IC Catgry Govmntal Ctrls: IC Catgry Enfrc Prmt TIs: ICs in Place: Date ICs in Place: Photographs are Available: Video is Available:

Cntmnt Fnd Other Descr: Dioxin/Furans

St Tribal Pra ID No:

Description History:

a construction company.

Ready for Reuse Ind: Nο

Detail Information

Grant Recipient Nme: Columbia, City of Accmplshmnt Count: 96462106 Coop Agreement No: Brwnfld Grant Type: Assessment Assessment Phase: Phase I Environmental Assessment 04/01/2007 Assmnt Start Date:

Assmnt Complete Dt: 05/08/2007 Assmnt Funding Amt: 4100 Cleanup Start Date: Clnup Complete Dt: Acres Cleaned Up: Cleanup Fnding Src:

Center of a Facility or Station Reference Point: Horiz Refer Datum: World Geodetic System of 1984

Latitude: 33.982717 Lonaitude: -80.957611

Clnd Up Petroleum: Clnd Up Asbestos: Clnd Up Lead: Clnd Up PAHs: Clnd Up PCBs: CInd Up VOCs: Clnd Up Selenium:

Clnd Up Iron: Clnd Up Arsenic: CInd Up Cadmium: Clnd Up Chromium: Clnd Up Copper: Clnd Up Mercury: Clnd Up Nickel: Clnd Up Pesticides: Clnd Up SVOCs: Clnd Oth Metals: Clnd Up Other: Clnd Up Unknown: Clnd Up None: Clnd Up Oth Desc: Clnd Up Air: Clnd Up Sediment: Clnd Up Soil: Clnd Up Drnk Wtr: Clnd Up Grnd Wtr: Clnd Up Surf Wtr: Clnd Up Bldg Mats:

Clnd Up Indoor Air:

Clnd Up Unknown:

The property was developed in the mid 1940's and has operated as a warehouse, maintenance shop and office for

Redev Funding Src: Redev Funding Amt: IC Data Address: Redev Complete Dt: 366 2010 No Blw Pvrty: 2010 Below Poverty: 18.76 2010 Median Income: 1556 2010 No Low Income: 607 2010 Low Income: 31.11 2010 No Vcnt Housng: 177 2010 Vacnt Housing: 18.15

Order No: 22071200085

Acre/Grnspc Create:

Number of Direction Distance Elev/Diff Site DΒ Map Key Records (mi/ft) (ft) Cleanup Fnding Amt: 2010 No Unemployed: 58 Redevmnt Start Dt: 2010 Unemployed: 2.97 Clnup / Redev Jobs: Assmnt Funding Src: **EPA** Entity Prvde Assmnt Fnds: US EPA - Brownfields Assessment Cooperative Agreement Enty Prvdng Clnup Fnd: **Entity Prvding Redev Funds:** Past Use Grnspace Arces: Past Use Residential Arces: Past Use Commercial Arces: 6.86 Past Use Industrial Arces: Past Use Multistory Arces: Future Use Multistory Arces: Future Use Greenspace: Future Use Residential: Future Use Commercial: Future Use Industrial: Acres Cleaned Up: Cleanup Start Date: Cleanup Completion Date: ICS in Place: Date ICS in Place: IC Catgry Govmntal Ctrls: IC Catgry Enfrcmnt Prmt Tools: Source of Cleanup Funding: **Entity Prvding Cleanup Funds: Grant Recipient Nme:** Columbia, City of Acre/Grnspc Create: Accmplshmnt Count: Ν Redev Funding Src: Coop Agreement No: 96462106 Redev Funding Amt: Brwnfld Grant Type: Assessment IC Data Address: Assessment Phase: Phase II Environmental Assessment Redev Complete Dt: Assmnt Start Date: 12/03/2007 2010 No Blw Pvrty: 366 Assmnt Complete Dt: 07/23/2008 2010 Below Poverty: 18.76 Assmnt Funding Amt: 90000 2010 Median Income: 1556 Cleanup Start Date: 2010 No Low Income: 607 Clnup Complete Dt: 2010 Low Income: 31.11 Acres Cleaned Up: 2010 No Vcnt Housng: 177 Cleanup Fnding Src: 18.15 2010 Vacnt Housing: Cleanup Fnding Amt: 2010 No Unemployed: 58 Redevmnt Start Dt: 2010 Unemployed: 2.97 Clnup / Redev Jobs: Assmnt Funding Src: **EPA** Entity Prvde Assmnt Fnds: US EPA - Brownfields Assessment Cooperative Agreement Enty Prvdng Clnup Fnd: Entity Prvding Redev Funds: Past Use Grnspace Arces: Past Use Residential Arces: Past Use Commercial Arces: 6.86 Past Use Industrial Arces: Past Use Multistory Arces: Future Use Multistory Arces: Future Use Greenspace: Future Use Residential: Future Use Commercial: Future Use Industrial: Acres Cleaned Up: Cleanup Start Date: Cleanup Completion Date: ICS in Place: Date ICS in Place: IC Catgry Govmntal Ctrls: IC Catgry Enfrcmnt Prmt Tools:

1 4 of 6 S 0.00 / 249.00 / DRAKE STREET PROPERTY 0.00 2 1002 DRAKE ST

Order No: 22071200085

Source of Cleanup Funding: Entity Prvding Cleanup Funds:

Number of Direction Distance Elev/Diff Site DΒ Map Key Records (mi/ft) (ft)

COLUMBIA SC 29209-1624

57452 File No:

06-5733-BAG" Cont No: Con Type Code: NRP: Non-Responsible Party

Status Code: **WITHDRAW**

Type Brownfield: Acerage:

Work plan Due:

2/4/2008 Work plan Received:

Work plan Reviewed: 3/18/2008

Work plan Approved: Report Received:

Report Reviewed:

IC Received:

Report Approved:

COLUMBIA CITY OF Person Company:

7/23/2008

6/15/2009

Cap Approved: Contract Mailed: Contract Executed:

Date Terminated: Coc Date Issued: RC Executed:

Contact: Fred Delk, Exec. Dir.

County: Richland

Contract Manager: GORMAN ANGELA K Prim Address 1: PO BOX 734

Prim Address 2:

Prim City: **COLUMBIA**

Prim State Code: SC Prim Zip Code: 29202

5 of 6 s 0.00/ 249.00/ DRAKE STREET PROPERTY 1 0.00

2 1002 DRAKE ST

COLUMBIA SC 29209-1624

BROWNFIELDS

BROWNFIELDS

BROWNFIELDS

Order No: 22071200085

57452 File No: Cap Approved:

Cont No: 07-5733-NRP" Contract Mailed: 10/24/2007

Con Type Code: Contract Executed: NRP: Non-Responsible Party Status Code: WITHDRAW Date Terminated: Coc Date Issued:

Type Brownfield: Acerage:

Work plan Due: Work plan Received: Work plan Reviewed:

Work plan Approved: Report Received: Report Reviewed: Report Approved:

IC Received:

9/14/2007 Person Company:

DRAKE STREET HOLDINGS LLC

RC Executed:

Contact: Mr. David Gore Richland County:

Contract Manager: GORMAN ANGELA K Prim Address 1: PO BOX 7304

Prim Address 2:

Prim City: **COLUMBIA** Prim State Code: SC

Prim Zip Code: 29202-7304

s 0.00/ 6 of 6 249.00/ DRAKE STREET PROPERTY 1

0.00 1002 DRAKE ST

COLUMBIA SC 29209-1624

File No: 57452 Cap Approved: Cont No: 06-5733-BAG" Contract Mailed:

Con Type Code: NRP: Non-Responsible Party Contract Executed: Status Code: WITHDRAW Date Terminated: Type Brownfield: Coc Date Issued: Acerage:

RC Executed: Contact:

Work plan Received: 2/4/2008 County: Richland

GORMAN ANGELA K Work plan Reviewed: 3/18/2008 Contract Manager:

Work plan Approved: Prim Address 1: PO BOX 734 Report Received: Prim Address 2:

Report Reviewed: Prim City: Report Approved: Prim State Code: SC Prim Zip Code: 29202 IC Received:

Person Company: COLUMBIA DEVELOPMENT CORPORATION

2 1 of 3 NW 0.01/ 244.53/ **CEDAR TERRACE DEVELOPMENT**

28.33 -2 1015 DRAKE ST

COLUMBIA SC 29209-1623

Fred Delk, Exec. Dir.

COLUMBIA

57882 File No: Cap Approved:

Work plan Due:

DΒ Map Key Number of Direction Distance Elev/Diff Site Records (mi/ft) (ft) 10-5924-NRP" Contract Mailed: 9/25/2010 Cont No: Con Type Code: NRP: Non-Responsible Party Contract Executed: 1/4/2011 **ACTIVE** Status Code: Date Terminated: 8/3/2012 Type Brownfield: Coc Date Issued: Acerage: 2.9 RC Executed: 12/19/2011 STEPHEN L. JOHNSON Work plan Due: Contact: Work plan Received: 11/18/2010 County: Richland Work plan Reviewed: 12/7/2010 Contract Manager: STAMPS JERRY M Work plan Approved: 12/7/2010 Prim Address 1: 441 WESTERN LN Report Received: 2/17/2011 Prim Address 2: Report Reviewed: 3/10/2011 IRMO Prim City: Report Approved: 9/13/2011 Prim State Code: SC 29063-9230 IC Received: 8/12/2010 Prim Zip Code: CEDAR TERRACE DEVELOPMENT LLC Person Company: 2 2 of 3 NW 0.01/ 244.53/ CEDAR TERRACE DEVELOPMENT **VCP** 28.33 1015 DRAKE ST -2 **COLUMBIA SC 29209-1623** 57882 33.98394, -80.95751 File No: Latitude/Longitude: Project Status Code: ACTIVE Brownfields Type: Restrict Filed Dt: 2/27/2012 Funds 128(A) Utilized: No 8/3/2012 Project Complete Dt: Resp Action Planned: No Execute Date: 1/4/2011 Acreage: Cleanup Contract Complete Dt: 8/3/2012 Contamination on Site: Please call 803-898-2000 for this information. Owner: CEDAR TERRACE DEVELOPMENT LLC Land Use Restriction: Not yet determined. NW 0.01/ CEDAR TERRACE DEVELOPMENT 2 3 of 3 244.53/ SASPL 28.33 -2 1015 DRAKE ST, COLUMBIA SC 29209-1623 SC SCS123457271 EPA ID: **RICHLAND** County: 1 of 2 SE 0.01/ 249.48/ AIR PRODUCTS & CHEMICAL 3 FINDS/FRS 951 TRUE ST 47.45 3 **COLUMBIA SC 29209-1633** Registry ID: 110017146587 FIPS Code: 45079 **HUC Code:** 03050110 Site Type Name: **STATIONARY** Location Description: Supplemental Location: Create Date: 11-MAR-04 Update Date: Interest Types: STATE MASTER SIC Codes: SIC Code Descriptions: **NAICS Codes:** NAICS Code Descriptions: FRS-GEOCODE Conveyor: Federal Facility Code: Federal Agency Name: Tribal Land Code: Tribal Land Name: Congressional Dist No: 02 Census Block Code: 450790116031057 EPA Region Code: 04 **RICHLAND** County Name:

Order No: 22071200085

US/Mexico Border Ind:

Number of Direction Distance Elev/Diff Site DΒ Map Key Records (mi/ft) (ft)

Latitude: 33.98183 Longitude: -80.9561

CENTER OF A FACILITY OR STATION Reference Point: ADDRESS MATCHING-HOUSE NUMBER **Coord Collection Method:**

Accuracy Value: 30 NAD83 Datum:

Source:

https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110017146587 Facility Detail Rprt URL:

Program Acronyms:

SC-EFIS:SC0000074447

2 of 2 SE 0.01/ 249.48/ AIR PRODUCTS & CHEMICAL 3 47.45 3 951 TRUE ST

COLUMBIA SC 29209-1633

UST

Order No: 22071200085

Site No: 07899 **RICHLAND** Search County: County: Permit: N 07899 **RICHLAND**

No. of Tanks: County Code: 40

Fac ID (Deliv Pro): Last Inspection: Fac City (Online): **COLUMBIA** Abandoned: 1

Billable: 0 Facility ST (FOI): Land Owner Phone: Fac City (FOI): **COLUMBIA**

Tank Owner Phone: 803-256-0667 Fac Contact (FOI): Operator Phone: Fac Phone (FOI):

Phone: Fac Zip (FOI): 29624 Other: 0 Zip (Online): 29209-1633

Local Fac Comp Nm: AIR PRODUCTS & CHEMICAL

Fac Addr (Online): 951 TRUE ST

https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/07899 Facility Link:

951 TRUE ST Business Addr (Online):

COLUMBIA SC 29209-1633

Retail Sales Category:

Land Owner Business Address:

KEENAN OIL CO INC Tank Owner Business Address: 3923 W BELTLINE BLVD COLUMBIA SC 29204-1503

Operator Business Address:

DHEC Management Tracking UST 'C' List; DHEC Underground Storage Tank Registry (Online) Source:

Tank Information - UST Registry Search

Tank No: 1

Case No:

Class: Ν

Status: Abandoned Notify:

Capacity:

1000 Variance:

Product:

Diesel fuel

Overfill Type: Verified: Constr Date: Operat Date: Piping Type: Compliance: Comp Status: Age at Notification: Dist to Well (ft): Spill Prevention: Left Gal:

Owner at ABD: KEENAN OIL CO INC

Last Use:

Aband: 11/11/1911 Removed Method:

Number of Direction Distance Elev/Diff Site DΒ Map Key Records (mi/ft) (ft) Chem: **Under Dispenser Cont:** False **Drop Tube:** False

Tank Const: Steel Pipe Const: Steel Tank Protect: Tank Tested: Pipe Protect:

Pipe Tested: Tank Cont Meth: Single wall Single wall Pipe Cont Meth:

Tank Leak Det: Pipe Leak Det:

Tank Information - UST 'C' List

Tank No:

Tank Owner: KEENAN OIL CO INC Tank Owner Contact: CALEB HARR Tank Owner Addr: 3923 W BELTLINE Tank Owner City: **COLUMBIA** Tank Owner State: SC Tank Owner Zip: 29204-1503

Tank Owner Phone: 803-256-0667 1000

Capacity Gal:

Age at Notif. Years:

Status Code: ABD Status Code Desc: Abandoned

Substance Code:

SW 253.36/ 1 of 10 0.01/ COLUMBIA ORGANIC CHEMICAL-4 **CERCLIS** 51.84 7 DRAKE **LIENS** DRAKE AVE

COLUMBIA SC 29209

Reg:

SCD003343571 EPA ID: LP001 Lien: Start Date: 7/2/2008

Comp Date: Effective Date:

7/2/2008

Release Date: Party Name:

> 0.01/ COLUMBIA ORGANIC CHEMICAL-4 2 of 10 SW 253.36/ **CERCLIS**

DRAKE 51.84 DRAKE AVE

COLUMBIA SC 29209

Order No: 22071200085

Site ID: 0403236 RNPL Status Code:

Not on the NPL Site EPA ID: SCD003343571 NPL Status:

Site Street Address 2: RFED Facility Code:

Site County Name: **RICHLAND** RFED Facility Desc: Not a Federal Facility

03050110 Site FIPS Code: 45079 USGS Hydro Unit No.: Region Code: 04 Site Cong. Dist. Code: 02 Site SMSA No.: 1760 ROT Desc: Other

33D58M53S Site Prim. Latitude: FR NPL Update No.: Site Prim. Longitude: 080D57M35S RFRA Code:

Lat Long Source:

NFRAP-Site does not qualify for the NPL based on existing information RNON NPL Status Desc:

CERCLIS Site Contact Name(s)

Person ID: 13002428.00 Map Key Number of Direction Distance Elev/Diff Site DB Records (mi/ft) (ft)

 First Name:
 Donna

 Last Name:
 Seadler

 Phone No.:
 4045628870

Email: seadler.donna@epa.gov

CERCLIS Site Contact Name(s)

 Person ID:
 4270660.00

 First Name:
 BROOKE

 Last Name:
 BASS

 Phone No.:
 4045628770

Email:

CERCLIS Site Contact Name(s)

 Person ID:
 4000234.00

 First Name:
 Ralph

 Last Name:
 Howard

 Phone No.:
 4045628829

Email: howard.ralph@epa.gov

CERCLIS Site Contact Name(s)

 Person ID:
 4270070.00

 First Name:
 Craig

 Last Name:
 Zeller

 Phone No.:
 4045628827

Email:

CERCLIS Site Contact Name(s)

 Person ID:
 4000583.00

 First Name:
 Craig

 Last Name:
 Zeller

 Phone No.:
 4045628827

 Email:
 zeller.craig@epa.gov

CERCLIS Site Contact Name(s)

 Person ID:
 4270495.00

 First Name:
 Paul

 Last Name:
 Wagner

 Phone No.:
 4045628792

Email: wagner.paul@epa.gov

CERCLIS Site Contact Name(s)

 Person ID:
 4000275.00

 First Name:
 William

 Last Name:
 Joyner

 Phone No.:
 4045628795

Email: joyner.william@epa.gov

CERCLIS Site Contact Name(s)

 Person ID:
 13002538.00

 First Name:
 Corey

 Last Name:
 Hendrix

 Phone No.:
 4045628738

Email:

CERCLIS Site Contact Name(s)

Person ID: 4000376.00 First Name: Mike Last Name: Norman 4045628792 Phone No.:

Email: norman.mike@epa.gov

CERCLIS Site Contact Name(s)

4000271.00 Person ID: First Name: Yvonne Last Name: Jones 4045628793 Phone No.:

Email:

CERCLIS Assess History

OU ID: 00 RALT Short Name: **EPA Fund** Act Code ID: 001 Act Start Date: 1/8/2008 00:00:00 RAT Code: RVAct Complete Date: 6/6/2008 00:00:00 70

RAT Short Name: **RMVL** AGT Order No.:

REMOVAL SH OU: RAT Name: RAT Hist. Only Flag: SH Code: В SH Seg: RAT NSI Indicator: RAT Level: SH Start Date: 1 RAT DEF OU: 00 SH Complete Date:

SH Lead: RFBS Code: V

SPA Code: 80 Response action that requires expeditious attention to reduce imminent and substantial dangers to human health, RAT Def:

welfare, or the environment or an emergency response required within hours or days to address acute situations involving actual or potential threat to human health, the environment, or real or personal property due to the release of a hazardous substance. Characterization of a removal action as removal, not immediate removal or planned removal, started at the beginning of FY 1987. This code now takes the place of immediate removal (IR) and

Order No: 22071200085

planned removal (PR).

Site Desc: Site Alias:

CERCLIS Assess History

OU ID: 00 RALT Short Name: **EPA In-House**

Act Code ID: 001 Act Start Date:

RAT Code: 10/1/2007 13:47:48 VU Act Complete Date:

UNARCHIVE RAT Short Name: AGT Order No.: 1501

RAT Name: SITE UNARCHIVED SH OU: RAT Hist. Only Flag: SH Code: RAT NSI Indicator: В SH Seq: RAT Level: SH Start Date: RAT DEF OU: 00 SH Complete Date:

RFBS Code: SH Lead:

SPA Code: 13

A decision is made that the site should no longer be archived because further activity may be necessary at the site. RAT Def:

Site Desc: Site Alias:

CERCLIS Assess History

OU ID: 00 RALT Short Name: Act Code ID: Act Start Date: RAT Code: Act Complete Date: RAT Short Name: AGT Order No.: 0

RAT Name: SH OU: RAT Hist. Only Flag: SH Code: Map Key Number of Direction Distance Elev/Diff Site DB
Records (mi/ft) (ft)

RAT NSI Indicator:

RAT Level:

RAT DEF OU:

RFBS Code:

SH Seq:

SH Start Date:

SH Complete Date:

SH Lead:

SPA Code: RAT Def: Site Desc:

No description available

Site Alias: COLUMBIA ORGANIC CHEMICALS INC,,RICHLAND,SC,;COLUMBIA ORGANIC CHEMICALS INC,DRAKE AVE,

COLUMBIA, SC, 29209; COLUMBIA ORGANIC CHEMS INC,, RICHLAND, SC,;

CERCLIS Assess History

OU ID: 00 RALT Short Name: EPA In-House

Act Code ID: 001 Act Start Date:

RAT Code: VS Act Complete Date: 1/4/2000 00:00:00

RAT Short Name: ARCH SITE AGT Order No.: 1500

SH OU: ARCHIVE SITE RAT Name: SH Code: RAT Hist. Only Flag: RAT NSI Indicator: В SH Seq: SH Start Date: RAT Level: 1 RAT DEF OU: 00 SH Complete Date: RFBS Code: SH Lead:

SPA Code: 13

RAT Def: The decision is made that no further activity is planned at the site.

Site Desc: Site Alias:

CERCLIS Assess History

OU ID: 00 RALT Short Name: EPA Fund

Act Code ID: 001 Act Start Date:

RAT Code: PA **Act Complete Date:** 5/1/1984 00:00:00

RAT Short Name: PA AGT Order No.: 130

RAT Name: PRELIMINARY ASSESSMENT SH OU:
RAT Hist. Only Flag: SH Code:
RAT NSI Indicator: B SH Seq:
RAT Level: 1 SH Start Date:
RAT DEF OU: 00 SH Complete Date:

RFBS Code: P SH Lead:

SPA Code: 13

RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to

complete the preliminary assessment within one year of site discovery.

Site Desc: Site Alias:

CERCLIS Assess History

OU ID: 00 RALT Short Name: EPA Fund

Act Code ID: 001 Act Start Date:

RAT Code: ES **Act Complete Date:** 7/9/2001 00:00:00

RAT Short Name: ESI AGT Order No.: 170

RAT Name: EXPANDED SITE INSPECTION SH OU:

RAT Hist. Only Flag: SH Code:

 RAT NSI Indicator:
 B
 SH Seq:

 RAT Level:
 1
 SH Start Date:

 RAT DEF OU:
 00
 SH Complete Date:

RFBS Code: P SH Lead: SPA Code: 13

RAT Def:Functions performed to collect additional data, beyond that required for Hazard Ranking System scoring, in order to expedite the Remedial Investigation/Feasibility Study (RI/FS) project planning phase for National Priority List (NPL)

sites. The present site inspection focus on pathways and receptors has been expanded to include site and source characterization. The information facilitates the development of RI/FS workplan and sampling and analysis plan.

Order No: 22071200085

Site Desc: Site Alias: Map Key Number of Direction Distance Elev/Diff Site DB
Records (mi/ft) (ft)

CERCLIS Assess History

 OU ID:
 00
 RALT Short Name:
 EPA Fund

 Act Code ID:
 001
 Act Start Date:
 12/4/2006 00:00:00

 RAT Code:
 RS
 Act Complete Date:
 5/10/2007 00:00:00

RAT Short Name: RV ASSESS AGT Order No.: 30

RAT Name:REMOVAL ASSESSMENTSH OU:RAT Hist. Only Flag:SH Code:RAT NSI Indicator:BSH Seq:RAT Level:1SH Start Date:RAT DEF OU:00SH Complete Date:

RFBS Code: V SH Lead: SPA Code: 08

RAT Def: Collecting site characteristics to determine whether or not a removal must be performed.

Site Desc: Site Alias:

CERCLIS Assess History

OU ID: 00 RALT Short Name: EPA Fund

 Act Code ID:
 001
 Act Start Date:
 6/30/1993 00:00:00

 RAT Code:
 EA
 Act Complete Date:
 6/30/1993 00:00:00

RAT Short Name: INT ASSESS AGT Order No.: 150

 RAT Name:
 INTEGRATED ASSESSMENT
 SH OU:

 RAT Hist. Only Flag:
 T
 SH Code:

 RAT NSI Indicator:
 B
 SH Seq:

 RAT Level:
 1
 SH Start Date:

 RAT DEF OU:
 00
 SH Complete Date:

RFBS Code: P SH Lead:

SPA Code: 13

RAT Def: Field data collected for characterizing magnitude and severity of problems at a site.

Site Desc: Site Alias:

CERCLIS Assess History

OU ID: 00 RALT Short Name: EPA Fund

Act Code ID: 001 Act Start Date:

RAT Code: DS **Act Complete Date:** 6/1/1981 00:00:00

RAT Short Name: DISCVRY AGT Order No.: 10
RAT Name: DISCOVERY SH OU:

 RAT Name:
 DISCOVERY
 SH OU:

 RAT Hist. Only Flag:
 SH Code:

 RAT NSI Indicator:
 B
 SH Seq:

 RAT Level:
 1
 SH Start Date:

 RAT DEF OU:
 00
 SH Complete Date:

RFBS Code: SH Lead:

SPA Code: 13

RAT Def:The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.

Order No: 22071200085

Site Desc: Site Alias:

CERCLIS Assess History

OU ID: 00 RALT Short Name: State (Fund)

Act Code ID: 001 Act Start Date:

RAT Code: SI **Act Complete Date:** 11/1/1984 00:00:00

 RAT Short Name:
 SI
 AGT Order No.:
 160

 RAT Name:
 SITE INSPECTION
 SH OU:
 00

 RAT Hist. Only Flag:
 SH Code:
 SH

 RAT NSI Indicator:
 B
 SH Seg:
 001

RAT Level: 1 SH Start Date:

 RAT DEF OU:
 00
 SH Complete Date:
 8/4/1993 00:00:00

 RFBS Code:
 P
 SH Lead:
 State (Fund)

Number of Direction Distance Elev/Diff Site DΒ Map Key Records (mi/ft) (ft)

13 SPA Code:

RAT Def: The process of collecting site data and samples to characterize the severity of the hazard for the hazard ranking

score and/or enforcement support.

Site Desc: Site Alias:

CERCLIS Assess History

OU ID: 00 RALT Short Name: **EPA Fund**

Act Code ID: 001 Act Start Date:

RAT Code: 2/19/2008 00:00:00 AR Act Complete Date:

ADMM REC RAT Short Name: AGT Order No.: 580

ADMINISTRATIVE RECORDS SH OU: RAT Name: RAT Hist. Only Flag: SH Code: RAT NSI Indicator: В SH Seg: RAT Level: 1 SH Start Date: 00 RAT DEF OU: SH Complete Date:

RFBS Code: SH Lead: SPA Code: 13

RAT Def: SARA specifies that administrative records be compiled at Superfund sites where remedial or removal responses

are planned, or are occurring, or where EPA is issuing a unilateral order or initiating litigation to track enforcement

case budget funds used for any RP lead activity.

Site Desc: Site Alias:

> 3 of 10 SW COLUMBIA ORGANIC CHEMICAL 4 0.01/ 253.36 / CO

51.84 7

912 DRAKE ST **COLUMBIA SC 29209** **RCRA NON GEN**

Order No: 22071200085

SCD003343571 EPA Handler ID: Gen Status Universe: No Report

UNKNOWN UNKNOWN Contact Name:

912, DRAKE ST,, COLUMBIA, SC, 29209, US Contact Address:

Contact Phone No and Ext: 999-999-9999

Contact Email:

Contact Country: US

RICHLAND County Name: EPA Region: 04 Land Type: Private Receive Date: 19861027

Location Latitude: Location Longitude:

Violation/Evaluation Summary

NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records Note:

associated with this facility (EPA ID).

Handler Summary

Importer Activity: Nο Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: Nο **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: Nο Used Oil Transfer Facility: No **Used Oil Processor:** No **Used Oil Refiner:** No **Used Oil Burner:** No Used Oil Market Burner: No

Number of Direction Distance Elev/Diff Site DΒ Map Key Records (mi/ft) (ft)

Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

19861027 Receive Date:

COLUMBIA ORGANIC CHEMICAL CO Handler Name:

Source Type: Notification

Federal Waste Generator Code: Ν

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Current Operator Owner/Operator Ind: Street No:

Private Street 1: **OPERSTREET** Type:

Name: **OPERNAME** Street 2:

Date Became Current: **OPERCITY** City: WY

Date Ended Current: State:

404-555-1212 Phone: Country:

Source Type: Notification Zip Code: 99999

Current Owner Owner/Operator Ind: Street No:

Type: Private Street 1: **OWNERSTREET**

COLUMBIA ORGANIC CHEMICALS Name: Street 2:

Date Became Current: OWNERCITY City: Date Ended Current: State: WY

404-555-1212 US Phone: Country: Notification 99999 Source Type: Zip Code:

4 4 of 10 SW 0.01/ 253.36/ COLUMBIA ORGANIC CHEMICAL-

51.84 DRAKE FINDS/FRS

Order No: 22071200085

DRAKE AVE **COLUMBIA SC 29209**

110031457670 Registry ID: FIPS Code: 45079 **HUC Code:** 03050110

POTENTIALLY CONTAMINATED SITE Site Type Name:

Location Description:

Supplemental Location:

23-OCT-07 Create Date: Update Date: 26-MAY-20

SUPERFUND (NON-NPL) Interest Types:

SIC Codes:

SIC Code Descriptions:

NAICS Codes:

NAICS Code Descriptions:

FRS-GEOCODE Conveyor:

Federal Facility Code: Federal Agency Name: Tribal Land Code: Tribal Land Name:

Congressional Dist No: 02

Census Block Code: 450790116032010

EPA Region Code: 04 County Name: **RICHLAND**

US/Mexico Border Ind:

Latitude: 33.98289 Lonaitude:

ENTRANCE POINT OF A FACILITY OR STATION Reference Point:

ADDRESS MATCHING-HOUSE NUMBER **Coord Collection Method:**

Accuracy Value: 50 NAD83 Datum:

Source:

Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110031457670

Program Acronyms:

SEMS:SCD003343571

4 5 of 10 SW 0.01 / 253.36 / COLUMBIA ORGANIC CHEMICAL-

51.84 7 DRAKE DRAKE AVE

COLUMBIA SC 29209

ICIS

Order No: 22071200085

EPA Region: 04 Federal Facility ID:

Registry ID: 110031457670 Tribal Land Code:

 Pgm Sys ID:
 SCD003343571
 County:
 Richland

 Pgm Sys Acrnm:
 CERCLIS
 Latitude 83:
 33.98289

 Permit Type:
 Longitude 83:
 -80.95817

4 6 of 10 SW 0.01/ 253.36/ COLUMBIA ORGANIC CHEMICAL-

51.84 7 DRAKE DRAKE AVE

COLUMBIA SC 29209

Start Actual:

EPA ID: SCD003343571 Primary Name(MAP): COLUMBIA ORGANIC CHEMICAL-DRAKE

Date SEMS List:27-APR-2022Loc Address(MAP):DRAKE AVEFIPS Code:City Name(MAP):COLUMBIACong District:State Code(MAP):SC

 County:
 RICHLAND
 Postal Code(MAP):
 29209

 Latitude:
 County Name(MAP):
 RICHLAND

 Longitude:
 Latitude83(MAP):
 33.98289

 Region:
 Longitude83(MAP):
 -80.95817

Site Level Information

0403236 Site ID: Superfund Alt Agmt: Nο Not on the NPL FIPS Code: 45079 NPL: Federal Facility: No Cong District: 02 Region: 04 FF Docket: Nο

Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

Action Information

Operable Units:

00

 Operable Units:
 00
 Start Actual:

 Action Code:
 VU
 Finish Actual:
 10/01/2007

Action Name: UNARCHIVE Qual:

SEQ: 1 Curr Action Lead: EPA Perf In-Hse

 Operable Units:
 00
 Start Actual:
 06/30/1993

 Action Code:
 EA
 Finish Actual:
 06/30/1993

 Action Name:
 INT ASSESS
 Qual:
 L

SEQ: 1 Curr Action Lead: EPA Perf

Action Code: VS Finish Actual: 01/04/2000

Action Name: ARCH SITE Qual:

SEQ: 1 Curr Action Lead: EPA Perf In-Hse

Operable Units: 00 Start Actual:

 Action Code:
 PA
 Finish Actual:
 05/01/1984

 Action Name:
 PA
 Qual:
 L

SEQ: 1 Curr Action Lead: EPA Perf

 Operable Units:
 00
 Start Actual:
 06/01/1981

 Action Code:
 DS
 Finish Actual:
 06/01/1981

 Action Name:
 DISCVRY
 Qual:

SEQ: 1 Curr Action Lead: EPA Perf

| | umber of ecords | Direction | Distance (mi/ft) | Elev/Diff (ft) | Site | | Di |
|------------------------------------|--------------------|---------------|----------------------|-------------------|----------------|-------------------------------------|-----|
| Operable Units: | 00 | | | Start Ac | tual: | 12/04/2006 | |
| Action Code: | RS | | | Finish A | ctual: | 05/10/2007 | |
| Action Name: | | SSESS | | Qual: | | H | |
| SEQ: | 1 | 00200 | | | ion Lead: | EPA Perf | |
| Operable Units: | 00 | | | Start Ac | tual: | | |
| Action Code: | ES | | | Finish A | | 07/09/2001 | |
| Action Name: | ESI | | | Qual: | | N | |
| SEQ: | 1 | | | | ion Lead: | EPA Perf | |
| Operable Units: | 00 | | | Start Ac | tual: | 01/08/2008 | |
| Action Code: | RV | | | Finish A | | 06/06/2008 | |
| Action Name: | RMVI | I | | Qual: | otuu | C | |
| SEQ: | 1 | _ | | | ion Lead: | EPA Perf | |
| Operable Units: | 00 | | | Start Ac | tual· | | |
| Action Code: | AR | | | Finish A | | 02/19/2008 | |
| Action Name: | | IN REC | | Qual: | ctuar. | 02/13/2000 | |
| SEQ: | 1 | IN REC | | | ion Lead: | EPA Perf | |
| Operable Units: | 00 | | | Start Ac | tual· | | |
| Action Code: | SI | | | Finish A | | 11/01/1984 | |
| Action Name: | SI | | | Qual: | ctuar. | L | |
| SEQ: | 1 | | | • | ion Lead: | St Perf | |
| Operable Units: | 00 | | | Start Ac | tual: | 01/01/2006 | |
| Action Code: | CR | | | Finish A | ctual: | 12/30/2008 | |
| Action Name: | CI | | | Qual: | | | |
| SEQ: | 1 | | | Curr Act | ion Lead: | EPA Perf | |
| REST Informatio | <u>n</u> | | | | | | |
| Registry ID: | 1100 | 31457670 | | Pgm Sys | Acrnm: | SEMS | |
| Active Status: | NOT | ON THE NPL | | Accurac | | 50 | |
| Key Field: | | SSCD003343571 | | HUC8 Co | | 03050110 | |
| Interest Type: | | ERFUND (NON-N | | HUC 12: | <i>,</i> 40. | 030501100203 | |
| Fed Agency Nam | | 5112 (1101111 | ·· - / | | Land Ind: | 330001100200 | |
| Fed Facility Code | | | | Public In | | Υ | |
| rea racility Cod EPA Region Cod | | | | | | | |
| • | | ADDDESS A | AATCUING HOUSE | Pgm Rej | JUI L. | no data yet | |
| Collect Mth Desc | ÷. | | MATCHING-HOUSE | | N I | | |
| Ref Point Desc: | | | POINT OF A FACIL | | | (111-0 | 70 |
| Fac Url: | | nttps://ofmpu | .p.epa.gov/trs_publi | cz/fii_query_deta | ıı.dısp_progra | m_facility?p_registry_id=1100314576 | 70 |
| Program Url: | | | | | | | |
| Pgm Report Url: | | no data yet | | | | | |
| Fips Code: | | 45079 | | | | | |
| 4 70 | f 10 | SW | 0.01/ | 253.36 / | SOUTH C | AROLINA REFINING AND | |
| <u>4</u> 7 o | 0 | 011 | 51.84 | 253.30 / 7 | DISPOSA | | PRP |
| | | | 31.04 | , | | L KE STREET P.O. BOX | |
| | | | | | 912 DKAP | NE SIKEEI P.U. BUX | |
| | | | | | 0624 | | |
| | | | | | 9621 | IA SC 29290 | |

Site EPA ID:WVD047989207Site Name:FIKE CHEMICAL, INC.Site NPL Status:Currently on the Final NPL

 Site Non NPL Status:

 Site Address:
 W 19TH ST

 Site City:
 NITRO

 Site State:
 WV

 Site Zip:
 25143

 Site Primary Latitude:
 38.426669

 Site Primary Longitude:
 -81.842500

Noticed Party Action Information

Action Type Seq: NJ-1

Action Name: Not Ltrs

Action Date: GENERAL NOTICE 03/03/1992

Action Type Seq: SG-3 Action Name: Spcl Not Ltrs

Action Date: SPECIAL NOTICE 06/25/1992

4 8 of 10 SW 0.01 / 253.36 / COLUMBIA ORGANIC CHEMICAL

51.84 7 CO., INC.

912 DRAKE STREET COLUMBIA SC 29209 PRP

PRP

SEMS LIEN

Order No: 22071200085

Site EPA ID: SCD981757149

Site Name: COLUMBIA ORGANIC CHEMICAL-CASSATT

Site NPL Status: Not on the NPL

Site Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

Site Address: 1 HICKMAN CIRCLE

 Site City:
 CASSATT

 Site State:
 SC

 Site Zip:
 29032

Site Primary Latitude: Site Primary Longitude:

Noticed Party Action Information

Action Type Seq: UA-1
Action Name: UNL ORDR

Action Date: SETTLEMENT DATE 04/28/1989

4 9 of 10 SW 0.01 / 253.36 / COLUMBIA ORGANIC CHEMICAL

51.84 7 CO., INC.

912 DRAKE STREET COLUMBIA SC 29209

Site EPA ID:SCD980558316Site Name:CAROLAWN, INC.Site NPL Status:Currently on the Final NPL

Site Non NPL Status:

Site Address: S. OF SC HWY 9 ON CO. RD 841

Site City: FORT LAWN

 Site State:
 SC

 Site Zip:
 29714

 Site Primary Latitude:
 34.686111

 Site Primary Longitude:
 -80.943050

Noticed Party Action Information

Action Type Seq: NJ-7
Action Name: Not Ltrs

10 of 10

Action Date: GENERAL NOTICE 11/18/1981

SW

253.36 / COLUM 7 DRAKE

912 DRAKE STREET COLUMBIA,

COLUMBIA ORGANIC CHEMICAL-

SC SC

EPA ID: SCD003343571 **Lien Effective Date:** 07/02/2008

0.01/

51.84

Lien: LP-1 Lien Release Date:

Lien Start Date: 07/02/2008 Region: 04

Lien Complete Date:

. Lien Party:

4

Map Key Number of Direction Distance Elev/Diff Site DB Records (mi/ft) (ft) 1 of 1 S 0.05/ 5 254.20 / JAMES H CARR & ASSOCIATES RCRA VSQG 289.61 919 TRUE ST

COLUMBIA SC 29290

Order No: 22071200085

EPA Handler ID: SCD987597176
Gen Status Universe: VSG
Contact Name: JAMES H CARR

Contact Address: PO BOX 90209 , , COLUMBIA , SC, 29290 , US

Contact Phone No and Ext: 803-776-7789

Contact Email:

Contact Country: US

 County Name:
 RICHLAND

 EPA Region:
 04

 Land Type:
 Private

 Receive Date:
 20080916

 Location Latitude:
 33.98054

 Location Longitude:
 -80.957971

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: Nο Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** No Commercial TSD: Nο Used Oil Transporter: No Used Oil Transfer Facility: No **Used Oil Processor:** No **Used Oil Refiner:** No Used Oil Burner: Nο **Used Oil Market Burner:** No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2

Receive Date: 20020327

Handler Name: JAMES H CARR & ASSOCIATES

Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007

Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code:D005Waste Code Description:BARIUM

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code:D008Waste Code Description:LEAD

Hazardous Waste Code: D000

Waste Code Description: DESCRIPTION

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Handler Details

Sequence No:

Receive Date: 19930428

Handler Name: JAMES H CARR & ASSOCIATES

Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Source Type: Notification

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20080916

Handler Name: JAMES H CARR & ASSOCIATES

Federal Waste Generator Code:

Generator Code Description: Very Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code:D006Waste Code Description:CADMIUM

Hazardous Waste Code: D007

Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code:D005Waste Code Description:BARIUM

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code:D008Waste Code Description:LEAD

Hazardous Waste Code: D000

Waste Code Description: DESCRIPTION

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Owner/Operator Details

Owner/Operator Ind: Current Owner Street No:

Type: Private Street 1: 919 TRUE ST

Name: JAMES H CARR JR Street 2:

Date Became Current: City: COLUMBIA

Order No: 22071200085

Date Ended Current: State: SC

Street No:

Phone: 803-776-7789 **Country:**

Source Type: Notification Zip Code: 29290

Owner/Operator Ind: Current Operator

Type: Private Street 1: 919 TRUE ST

Name: JAMES H CARR JR Street 2: Date Became Current: City:

Date Became Current:City:COLUMBIADate Ended Current:State:SC

Phone: 803-776-7789 **Country:**

Source Type: Notification Zip Code: 29290

Historical Handler Details

Receive Dt: 19930428

Generator Code Description: Small Quantity Generator

Handler Name: JAMES H CARR & ASSOCIATES

Receive Dt: 20020327

Generator Code Description: Small Quantity Generator

Handler Name: JAMES H CARR & ASSOCIATES

6 1 of 1 SW 0.22/ 259.53/ WALGREENS 17066 RCRA VSQG 1,182.71 13 6500 GARNERS FERRY RD

COLUMBIA SC 29209

Order No: 22071200085

EPA Handler ID: SCR000776377

Gen Status Universe: VSG

Contact Name: KIMBERLY DASCOLI

Contact Address: 200 WILMOT ROAD MS #2275 , , DEERFIELD , IL, 60015 , US

Contact Phone No and Ext: 847-315-2812

Contact Email:

Contact Country: US

County Name:RICHLANDEPA Region:04Land Type:PrivateReceive Date:20190719Location Latitude:33.979587Location Longitude:-80.961283

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: Nο Furnace Exemption: No **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: Nο **Used Oil Processor:** No **Used Oil Refiner:** Nο **Used Oil Burner:** No Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 4

Receive Date: 20150924 Handler Name: RITE AID 11587

Federal Waste Generator Code: 3

Generator Code Description: Very Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001

Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code:D018Waste Code Description:BENZENE

Hazardous Waste Code: U002

Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D035

Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Handler Details

Sequence No: 6

Receive Date: 20180131
Handler Name: RITE AID 11587

Federal Waste Generator Code: 3

Generator Code Description: Very Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code:D018Waste Code Description:BENZENE

Hazardous Waste Code: U002

Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D035

Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D001

Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 2

Receive Date: 20141103 Handler Name: RITE AID #11587

Federal Waste Generator Code:

Generator Code Description: Large Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D002

Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: P001

Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT

CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT

CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code:D024Waste Code Description:M-CRESOL

Hazardous Waste Code: P075

Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: D001

Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code:D010Waste Code Description:SELENIUM

Hazardous Waste Handler Details

Sequence No: 3

Receive Date: 20150731 Handler Name: RITE AID #11587

Federal Waste Generator Code:

Generator Code Description: Large Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D002

Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: P001

Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT

CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT

Order No: 22071200085

CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D024
Waste Code Description: D024
M-CRESOL

Hazardous Waste Code: P075

Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: D001

Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20160101

Handler Name: RITE AID 11587

Federal Waste Generator Code: 3

Generator Code Description: Very Small Quantity Generator

Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code:D018Waste Code Description:BENZENE

Hazardous Waste Code: U002

Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D035

Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D001

Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 5

Receive Date: 20150924 Handler Name: RITE AID 11587

Federal Waste Generator Code: 3

Generator Code Description: Very Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code:D018Waste Code Description:BENZENE

Hazardous Waste Code: U002

Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D035

Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D001

Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20190719

Handler Name: WALGREENS 17066

Federal Waste Generator Code: 3

Generator Code Description: Very Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code:D018Waste Code Description:BENZENE

Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D035

Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D001

Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20120919
Handler Name: RITE AID #11587

Federal Waste Generator Code:

Generator Code Description: Very Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D002

Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code:D007Waste Code Description:CHROMIUM

Hazardous Waste Code: P001

Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT

CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT

CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code:D024Waste Code Description:M-CRESOL

Hazardous Waste Code: P075

Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: D001

Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Owner/Operator Details

Date Became Current:

Owner/Operator Ind: Previous Owner Street No: 30

Type: Private Street 1: HUNTER LANE

Name: EDC DRUGS STORES, INC. Street 2:

Date Became Current: 20121004 **CAMP HILL** City: Date Ended Current: 20141104 PΑ State: Phone: 717-761-2633 US Country: Source Type: Notification Zip Code: 17011

Owner/Operator Ind: Current Owner

Type: Private Street 1: 3801 ROCKBRIDGE RD

Name: FORMAC LLC Street 2:

20101231 City: RIDGEWAY

Street No:

SC

Order No: 22071200085

Date Ended Current: State:

Phone: Country:

Source Type: Annual/Biennial Report update with Notification Zip Code: 29130

| Map Key | Number Record | | Direction | Distance (mi/ft) | Elev/Diff (ft) | Site | | DB |
|----------------|------------------|----------|-----------------|---------------------|-----------------------|------|--------------------------|----|
| Owner/Oper | ator Ind: | | Operator | | Street No: | | 30 | |
| Type: | | Private | | | Street 1: | | HUNTER LANE | |
| Name: | | RITE A | ID CORPORATION | | Street 2: | | | |
| Date Became | e Current: | 201210 | 04 | | City: | | CAMP HILL | |
| Date Ended | Current: | | | | State: | | PA | |
| Phone: | | 717-76 | 1-2633 | | Country: | | US | |
| Source Type | e: | Notifica | tion | | Zip Code: | | 17011 | |
| Owner/Oper | ator Ind: | | Operator | | Street No: | | | |
| Туре: | | Private | | | Street 1: | | 30 HUNTER LN ATTN EH&S | |
| Name: | | _ | RUG STORES INC | | Street 2: | | | |
| Date Becam | | 201012 | :31 | | City: | | CAMP HILL | |
| Date Ended | Current: | | | | State: | | PA | |
| Phone: | | | | | Country: | | US | |
| Source Type | e: | Notifica | tion | | Zip Code: | | 17011 | |
| Owner/Oper | ator Ind: | | Operator | | Street No: | | 300 | |
| Туре: | | Private | | | Street 1: | | WILMOT RD MS#3301 | |
| Name: | | WALG | REEN CO | | Street 2: | | | |
| Date Became | e Current: | | | | City: | | DEERFIELD | |
| Date Ended | Current: | | | | State: | | IL | |
| Phone: | | | | | Country: | | US | |
| Source Type |) : | Notifica | ition | | Zip Code: | | 60015 | |
| Owner/Oper | ator Ind | Current | Operator | | Street No: | | 30 | |
| Type: | ator ma. | Private | Орогасог | | Street 1: | | HUNTER LANE | |
| Name: | | | RUGS STORES, IN | C | Street 1: | | HOWIER EARL | |
| Date Became | o Current: | 201411 | · | C . | City: | | CAMP HILL | |
| Date Ended | | 201411 | 03 | | State: | | PA | |
| Phone: | Current. | 717-76 | 1 2622 | | | | US | |
| Source Type | e: | Notifica | | | Country: Zip Code: | | 17011 | |
| Owner/Oper | ator Ind: | Current | Owner | | Street No: | | 3801 | |
| • | ator mu. | Private | Owner | | Street 1: | | ROCKBRIDGE RD | |
| Type: Name: | | | AC LLC | | Street 1: | | KOCKBRIDGE KD | |
| | a Current | | | | | | DIDCEWAY | |
| Date Became | | 201411 | 03 | | City: | | RIDGEWAY | |
| Date Ended | Current: | 000 40 | 0 4700 | | State: | | SC | |
| Phone: | | 803-42 | | | Country: | | US | |
| Source Type | 9: | Notifica | ition | | Zip Code: | | 29130 | |
| Owner/Oper | ator Ind: | | Owner | | Street No: | | | |
| Туре: | | Private | | | Street 1: | | 3801 ROCKBRIDGE RD | |
| Name: | | | AC LLC | | Street 2: | | | |
| Date Became | e Current: | 201012 | 31 | | City: | | RIDGEWAY | |
| Date Ended | Current: | | | | State: | | SC | |
| Phone: | | | | | Country: | | | |
| Source Type |) : | Notifica | ition | | Zip Code: | | 29130 | |
| Owner/Oper | ator Ind: | | Operator | | Street No: | | | |
| Туре: | | Private | | | Street 1: | | 30 HUNTER LN ATTN EH&S | |
| Name: | | EDC D | RUG STORES INC | | Street 2: | | | |
| Date Became | e Current: | 201012 | 31 | | City: | | CAMP HILL | |
| Date Ended | Current: | | | | State: | | PA | |
| Phone: | | | | | Country: | | | |
| Source Type | e: | Notifica | tion | | Zip Code: | | 17011 | |
| Owner/Oper | ator Ind: | | Operator | | Street No: | | | |
| Туре: | | Private | | | Street 1: | | 200 WILMOT ROAD MS #2275 | |
| Name: | | WALG | REENS EASTERN (| CO INC | Street 2: | | | |
| Date Became | e Current: | | | | City: | | DEERFIELD | |
| Date Ended | Current: | | | | State: | | IL | |
| Phone: | | | | | Country: | | US | |
| Source Type | e: | Notifica | tion | | Zip Code: | | 60015 | |
| Owner/Oper | ator Ind: | Previou | is Operator | | Street No: | | 30 | |
| Type: | | Private | | | Street 1: | | HUNTER LANE | |
| Name: | | | ID CORPORATION | | Street 2: | | | |
| Date Became | e Current | 201210 | | | City: | | CAMP HILL | |
| Date Ended | | 201210 | | | State: | | PA PA | |
| Date Ellueu | Juin ent. | 201411 | 00 | | State. | | 17 | |

Number of Direction Distance Elev/Diff Site DΒ Map Key Records (mi/ft) (ft) 717-761-2633 US Phone: Country: Source Type: Notification Zip Code: 17011 Owner/Operator Ind: **Current Operator** Street No: Type: Private Street 1: 30 HUNTER LN ATTN EH&S Name: **EDC DRUG STORES INC** Street 2: Date Became Current: 20101231 City: **CAMP HILL** Date Ended Current: State: Phone: Country: Source Type: Annual/Biennial Report update with Notification Zip Code: 17011 Owner/Operator Ind: **Current Owner** Street No: **HUNTER LANE** Private Street 1: EDC DRUGS STORES, INC. Name: Street 2: Date Became Current: 20121004 City: **CAMP HILL** Date Ended Current: State: PΑ 717-761-2633 US Phone: Country: Source Type: Notification Zip Code: 17011 Owner/Operator Ind: **Current Owner** Street No: 3801 ROCKBRIDGE RD Private Type: Street 1: Name: FORMAC LLC Street 2: Date Became Current: **RIDGEWAY** 20101231 City: Date Ended Current: State: SC US Phone: Country: Notification 29130 Source Type: Zip Code: Owner/Operator Ind: **Current Owner** Street No: 200 WILMOT ROAD MS #2275 Type: Private Street 1: Name: WALGREENS EASTERN CO INC Street 2: Date Became Current: City: **DEERFIELD**

State:

Country:

Zip Code:

IL

US

60015

Order No: 22071200085

Historical Handler Details

Date Ended Current:

Phone:

Source Type:

Receive Dt: 20150924

Generator Code Description: Very Small Quantity Generator

Notification

Handler Name: RITE AID 11587

Receive Dt: 20150924

Generator Code Description: Very Small Quantity Generator

Handler Name: RITE AID 11587

Receive Dt: 20180131

Generator Code Description: Very Small Quantity Generator

Handler Name: RITE AID 11587

Receive Dt: 20160101

Generator Code Description: Very Small Quantity Generator

Handler Name: RITE AID 11587

Receive Dt: 20141103

Generator Code Description: Large Quantity Generator

Handler Name: RITE AID #11587

Receive Dt: 20150731

Generator Code Description: Large Quantity Generator

Handler Name: RITE AID #11587

Receive Dt: 20120919

Generator Code Description: Very Small Quantity Generator

Handler Name: RITE AID #11587

7 1 of 3 SW 0.24/ 258.34/ CORNER PANTRY 126 UST 1,268.59 12 6524 GARNERS FERRY RD

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft)

COLUMBIA SC 29209

Order No: 22071200085

Site No: 07791 Search County: **RICHLAND** R 07791 **RICHLAND** Permit: County: No. of Tanks: County Code:

Last Inspection: 6/23/2021 Fac ID (Deliv Pro):

COLUMBIA Abandoned: 0 Fac City (Online): Billable: Facility ST (FOI): SC

COLUMBIA Land Owner Phone: 803-932-0500 Fac City (FOI):

Tank Owner Phone: 803-779-9538 Fac Contact (FOI): Operator Phone: Fac Phone (FOI):

Phone: 803-776-9290 29624 Fac Zip (FOI): Other: Zip (Online): 29209

CORNER PANTRY 126 Local Fac Comp Nm: Fac Addr (Online): 6524 GARNERS FERRY RD

Facility Link: https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/07791

Business Addr (Online): 6524 GARNERS FERRY RD COLUMBIA SC 29209

Category: Retail Sales

UNITED OIL MARKETERS OF SC INC Land Owner Business Address:

PO BOX 503

WHITE ROCK SC 29177

Tank Owner Business Address: **CORNER PANTRY INC** 1001 IDLEWILDE BLVD COLUMBIA SC 29201

Operator Business Address:

Source: DHEC Management Tracking UST 'C' List; DHEC Underground Storage Tank Registry (Online)

Tank Information - UST Registry Search

Tank No:

Case No: R Class:

Currently in Use Status: Notify: 7/30/1987 10000 Capacity:

Variance:

Product: Gasoline RUL Alarm Overfill Type: Verified: 7/23/2021

Constr Date:

Operat Date: 9/13/1995 Piping Type: Pressure Compliance: 7/26/2021 Comp Status: In Compliance

Age at Notification: 5 Dist to Well (ft): 101 Spill Prevention: 7/10/1995

Left Gal: Owner at ABD: Last Use: Aband: Method:

Chem:

Under Dispenser Cont: False Drop Tube: True Tank Const: Steel Pipe Const: Steel

Tank Protect: Impressed Current Tank Tested: 4/26/2021 Pipe Protect: Impressed Current

Pipe Tested: 4/26/2021 Tank Cont Meth: Single wall Pipe Cont Meth: Single wall

Tank Leak Det: Automatic tank gauge

7/9/2001

Mechanical Line Leak Detector Pipe Leak Det:

| Map Key | Number of Records | Direction | Distance (mi/ft) | Elev/Diff (ft) | Site | DB |
|------------------------------|----------------------|------------------------------|---------------------|-------------------|------|----|
| | Necorus | 2/21/2221 | (IIII/IL) | (11) | | |
| | | 3/31/2021 Line Tightness | Toet | | | |
| | | 3/31/2021 | 1031 | | | |
| Tank No: | | 3 | | | | |
| Case No: | | 3 | | | | |
| Class: | | R | | | | |
| Status: Notify: | | Currently in Us 7/30/1987 | е | | | |
| Capacity: | | 10000 | | | | |
| Variance: | | | | | | |
| Product: | | Gasoline Super | r/Prem | | | |
| Overfill Type Verified: | e: | Alarm 7/23/2021 | | | | |
| Constr Date | : | | | | | |
| Operat Date | | 9/13/1995 | | | | |
| Piping Type Compliance | | Pressure 7/26/2021 | | | | |
| Comp Statu | s: | In Compliance | | | | |
| Age at Notif | | 5 | | | | |
| Dist to Well Spill Preven | | 101 7/10/1995 | | | | |
| Left Gal: | aion. | 77 107 1000 | | | | |
| Owner at Al | BD: | | | | | |
| Last Use: Aband: | | | | | | |
| Method: | | | | | | |
| Chem: | | | | | | |
| Under Dispe Drop Tube: | enser Cont: | False True | | | | |
| Tank Const. | : | Steel | | | | |
| Pipe Const: | | Steel | · ant | | | |
| Tank Protect Tank Testec | | Impressed Curi 4/26/2021 | ent | | | |
| Pipe Protec | t: | Impressed Cur | rent | | | |
| Pipe Tested Tank Cont I | | 4/26/2021 Single wall | | | | |
| Pipe Cont M | | Single wall | | | | |
| Tank Leak L | | Automatic tank | gauge | | | |
| Pipe Leak D | let· | 7/9/2001 Mechanical Lin | e Leak Detector | | | |
| . 100 20an 2 | | 3/31/2021 | | | | |
| | | Line Tightness 3/31/2021 | Test | | | |
| | | 3/3 1/202 1 | | | | |
| Tank No: | | 4 | | | | |
| Case No: Class: | | R | | | | |
| Status: | | Currently in Us | е | | | |
| Notify: | | 7/30/1987 | | | | |
| Capacity: Variance: | | 10000 | | | | |
| Product: | | Kerosene | | | | |
| Overfill Typ | e: | Alarm | | | | |
| Verified: | | 7/23/2021 | | | | |
| Constr Date Operat Date | | 9/13/1995 | | | | |
| Piping Type |): | Pressure | | | | |
| Compliance | | 7/26/2021 | | | | |
| Comp Statu Age at Notif | | In Compliance 5 | | | | |
| Dist to Well | (ft): | 101 | | | | |
| Spill Preven | tion: | 7/10/1995 | | | | |
| Left Gal: Owner at Al | BD: | | | | | |
| Last Use | | | | | | |

Order No: 22071200085

Last Use: Aband: Method: Chem:

DΒ Map Key Number of Direction Distance Elev/Diff Site Records (mi/ft) (ft) **Under Dispenser Cont:** False Drop Tube: True Tank Const: Steel

Fiberglass reinforced plastic Tank Protect: Impressed Current Tank Tested: 4/26/2021 Pipe Protect: **Fiberglass** Pipe Tested: 4/26/2021

Tank Cont Meth: Single wall Pipe Cont Meth: Single wall

Tank Leak Det: Automatic tank gauge

10/2/2018

Pipe Leak Det: Mechanical Line Leak Detector

3/31/2021

Line Tightness Test

3/31/2021

Tank No:

Case No: Class:

Pipe Const:

R

Status: Currently in Use 7/30/1987 Notify: Capacity: 10000

Variance:

Product: Gasoline RUL Overfill Type: Alarm 7/23/2021 Verified:

Constr Date:

9/13/1995 Operat Date: Piping Type: Pressure Compliance: 7/26/2021 Comp Status: In Compliance

Age at Notification: Dist to Well (ft): 101 Spill Prevention: 7/10/1995

Left Gal: Owner at ABD: Last Use: Aband: Method: Chem:

Under Dispenser Cont: False Drop Tube: True

Tank Const: Steel Pipe Const: Steel

Tank Protect: Impressed Current

Tank Tested: 4/26/2021 Impressed Current Pipe Protect:

Pipe Tested: 4/26/2021 Single wall Tank Cont Meth: Pipe Cont Meth: Single wall

Tank Leak Det: Automatic tank gauge 7/9/2001

Mechanical Line Leak Detector Pipe Leak Det:

3/31/2021

Line Tightness Test

3/31/2021

Tank No: 5 Case No:

Class:

Extended Out-of-Use Status:

7/30/1987 Notify: 6000 Capacity: Variance:

Product: Kerosene

Drop Tube Shut-off Overfill Type:

Verified: 7/10/1995

Constr Date:

9/13/1995 Operat Date: Piping Type: Pressure Compliance: 6/24/2021 Comp Status: In Compliance

Age at Notification: 101 Dist to Well (ft): Spill Prevention: 7/10/1995

Left Gal: Owner at ABD: Last Use: Aband: Method: Chem:

Under Dispenser Cont: False Drop Tube: True Tank Const: Steel

Pipe Const: Fiberglass reinforced plastic

Tank Protect: Impressed Current

Tank Tested: 4/26/2021 Pipe Protect: **Fiberglass**

Pipe Tested: Tank Cont Meth: Single wall Pipe Cont Meth: Single wall

Automatic tank gauge Tank Leak Det:

7/9/2001

Pipe Leak Det: Manifolded

Tank Information - UST 'C' List

Tank No:

CORNER PANTRY INC Tank Owner: Tank Owner Contact: **CALEB HARR** 1001 IDLEWILDE B Tank Owner Addr:

Tank Owner City: **COLUMBIA** Tank Owner State: SC 29201 Tank Owner Zip: Tank Owner Phone: 803-254-4806

Capacity Gal: 6000 Age at Notif. Years: Status Code: EOU

Status Code Desc: Extended Out of Use

Substance Code:

Tank No:

CORNER PANTRY INC Tank Owner: Tank Owner Contact: CALEB HARR 1001 IDLEWILDE B Tank Owner Addr:

Tank Owner City: **COLUMBIA** Tank Owner State: SC Tank Owner Zip: 29201 803-254-4806 Tank Owner Phone: Capacity Gal: 10000

Age at Notif. Years: CIU Status Code:

Status Code Desc: Currently in Use **RUL**

Substance Code:

Tank No:

CORNER PANTRY INC Tank Owner: Tank Owner Contact: **CALEB HARR** 1001 IDLEWILDE B

Tank Owner Addr: COLUMBIA Tank Owner City:

Tank Owner State: SC Tank Owner Zip: 29201

Tank Owner Phone: 803-254-4806 Capacity Gal: 10000

Age at Notif. Years: 5 Status Code: CIU

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft)

Currently in Use Status Code Desc:

Substance Code: ΚN

Tank No:

Tank Owner: CORNER PANTRY INC **CALEB HARR** Tank Owner Contact: 1001 IDLEWILDE B

Tank Owner Addr: **COLUMBIA** Tank Owner City: Tank Owner State: SC Tank Owner Zip: 29201 803-254-4806 Tank Owner Phone: Capacity Gal: 10000

Age at Notif. Years: Status Code: CIU

Status Code Desc: Currently in Use

PREM Substance Code:

Tank No:

Tank Owner: CORNER PANTRY INC

Tank Owner Contact: **CALEB HARR** 1001 IDLEWILDE B Tank Owner Addr: Tank Owner City: **COLUMBIA**

Tank Owner State: SC Tank Owner Zip: 29201 803-254-4806 Tank Owner Phone: 10000 Capacity Gal:

Age at Notif. Years: 5 Status Code: CIU

Status Code Desc: Currently in Use

Substance Code:

Tank Information - Financial Responsibility

Financial Mechanism: Letter of Credit **Expiration Date:** 6/5/2022

CORNER PANTRY 126 7 2 of 3 SW 0.24/ 258.34/ LUST 6524 GARNERS FERRY RD 1,268.59 12 **COLUMBIA SC 29209**

Site ID: 07791 Search County: **RICHLAND**

Site No (EFIS): UST-07791 County Code:

Facility (Web): **CORNER PANTRY 126** Permit: R 07791 Fac Street (Web): No of Tanks: 6524 GARNERS FERRY RD Facilit City (Web): 0 **COLUMBIA** Abandoned:

Billable: 5 Facility St (Web): SC Fac County (Web): Richland Other: Last Inspection: 6/23/2021 Facility Zip (Web): 29209 Phone: 803-776-9290 Land Owner Phone: 803-932-0500

COLUMBIA Facil City (EFIS): Operator Phone:

Facil State (EFIS): SC Tank Owner Phone: 803-779-9538

Facil Zip (EFIS): 29209

Facility Link: https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/07791

Facil Name (EFIS): **CORNER PANTRY 126** Facil Address (EFIS): 6524 GARNERS FERRY RD

Retail Sales Category:

6524 GARNERS FERRY RD **Business Address:**

COLUMBIA SC 29209

UNITED OIL MARKETERS OF SC INC Land Owner Business Addr:

PO BOX 503

WHITE ROCK SC 29177

Operator Business Addr:

Tank Owner Business Addr: CORNER PANTRY INC 1001 IDLEWILDE BLVD

COLUMBIA SC 29201

DHEC Online Registry - Release Report; DHEC Confirmed Release Report (LUST); DHEC EFIS Data Delivery Data Source:

Order No: 22071200085

Prohibition list

DHEC Online Registry - Release Report

Release No:

Project Manager: FULMER, SUSAN B

Reported: 12/31/1991 **Confirmed:** 6/8/1995

RBCA/ Score: 3BF - GW < 15 feet in sand or gravel / 324

Product:

Compliance Req: False
NFA: 7/9/2007
Fin Type: With SUPERB

Fin Res Mechanism:

 Abatement Met:
 7/31/1994

 Cleanup Initiated:
 5/15/1998

Cleanup Complete:

Cleanup MCL: 7/9/2007

Compliance Date:

Compliance Met: False

Emergency Resp:

Responsible Party: UNITED OIL MARKETERS INC

Superb Determ Date: Superb Qualified: Transferred:

Source: UST

Source. 00

Release No: 0

Project Manager: PLACE, DENISE M

Reported: 9/30/2008

Confirmed:

RBCA/ Score: /

Product:

Compliance Req: True NFA: 10/1/2008

Fin Type: Fin Res Mechanism: Abatement Met: Cleanup Initiated: Cleanup Complete: Cleanup MCL:

Compliance Date:

Compliance Met: False

Emergency Resp:

Responsible Party: CORNER PANTRY INC

Superb Determ Date: Superb Qualified: Transferred:

Source: UST

DHEC Confirmed Release Report

 Release No:
 1
 Substance:
 PETRO

 Status:
 3
 Reported:
 12/31/91

 NFA:
 07/09/07
 Confirmed:
 06/08/95

 Rank:
 3BF
 Proj Mgr:
 FULMERSB

Tank Öwner:

CORNER PANTRY INC

Order No: 22071200085

Score: 324

Rank Desc: GW < 15 feet in sand or gravel

DHEC EFIS Data Details

Release No:

 Release Date:
 12/31/1991

 Project Mgr:
 WS

 Confirmed Date:
 6/8/1995

Cleanup Comp Date:

Cleanup Comp Mcl Dt: 7/9/2007

Rp Name: UNITED OIL MARKETERS INC

Rp Address:PO BOX 628Rp City:PINEY FLATS

Rp State: TN

 Rp Zip:
 37686-0628

 Sstl Estab Code:
 MR

Scribestab Code: MR
Scrbca Class Code: CLASS3BF
Depth to GW: 12
GW Flow Dir Code: SW

Receptor Type Code: FULMER, SUSAN B

Rel Fin Type Cd: DEPT

CoC Concentrate Cd:

7 3 of 3 SW 0.24/ 258.34/ CORNER PANTRY 126 RCR 1,268.59 12 6524 GARNERS FERRY RD

 Site ID:
 07791

 REL:
 1

 Tax Map ID:
 R16403-03-07

 Reported:
 12/31/91

 CU>MCL:
 07/09/07

 Latitude:
 33.97885

 Longitude:
 -80.96007

8 1 of 2 WSW 0.24/ 264.31/ EXPRESS OIL CANGE AND 1,269.84 18 SERVICE CTR RCRA VSQG

6306 GARNERS FERRY RD COLUMBIA SC 29209

Order No: 22071200085

COLUMBIA SC 29209

EPA Handler ID: SCR000775411

Gen Status Universe: VSG

Contact Name: GREGG GASKINS

Contact Address: 267, HARBISON BLVD,, COLUMBIA, SC, 29212, US

Contact Phone No and Ext: 803-781-0505

Contact Email:

 Contact Country:
 US

 County Name:
 RICHLAND

 EPA Region:
 04

 Land Type:
 Private

 Receive Date:
 20120625

 Location Latitude:
 33.969197

Location Longitude: -80.94648

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS;

Compliance Monitoring and Enforcement table dated Apr, 2022.

Evaluation Details

Evaluation Start Date: 20120724

Evaluation Type Description: COMPLIANCE ASSISTANCE VISIT

Violation Short Description: Return to Compliance Date:

Evaluation Agency: State

Handler Summary

Importer Activity:NoMixed Waste Generator:NoTransporter Activity:No

DΒ Number of Direction Distance Elev/Diff Site Map Key Records (mi/ft) (ft)

Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: Nο Used Oil Transfer Facility: No **Used Oil Processor:** No Used Oil Refiner: No **Used Oil Burner:** No **Used Oil Market Burner:** Nο Used Oil Spec Marketer:

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20120625

Handler Name: EXPRESS OIL CANGE AND SERVICE CTR

Federal Waste Generator Code:

Very Small Quantity Generator Generator Code Description:

Source Type: Notification

Waste Code Details

D039 Hazardous Waste Code:

Waste Code Description: **TETRACHLOROETHYLENE**

Hazardous Waste Code:

IGNITABLE WASTE Waste Code Description:

Owner/Operator Details

Current Operator Owner/Operator Ind: Street No: 6306

GARNERS FERRY RD Type: Street 1:

Name: EXPRESS OIL CHANGE AND SERVICE CTR Street 2: Date Became Current: 20120625 City:

COLUMBIA State:

Date Ended Current:

SC 803-781-0505 US Phone: Country: Zip Code: 29212 Source Type: Notification

Current Owner 267 Owner/Operator Ind: Street No:

Type: Private Street 1: HARBISON BLVD **GREGG GASKINS** Name: Street 2:

Date Became Current: 20120625 **COLUMBIA** City:

Date Ended Current: State: SC

Phone: 803-781-0505 Country: US Notification Zip Code: 29212 Source Type:

8 2 of 2 WSW 0.24/ 264.31/ KEL TAY EXPRESS **DELISTED** 6306 GARNERS FERRY RD 1,269.84 18

LST

Order No: 22071200085

COLUMBIA SC

Delisted Leaking Above Ground Storage Tanks Details

Site ID: 4104 Release No:

Project Manager: TRENT JAN C CLOSED Status: Impacted Code: YES

Type:

Release Date: 1/20/2009 Confirmed: 3/25/2009

NFA Dt: 2/2/2012

Transfer: Product: Source: Tier:

Truncated Note: Soil Impact Code:

User Name: TRENTJC Release Xfer Date:

Suspect NFA Date: 2/2/2012

Release Source Code: Cleanup Complete Dt:

Local Fac Last Name: KEL TAY EXPRESS

Local Fac First Name:

Address 2:

 State Code:
 SC

 County:
 Richland

 Zip Code:
 29209

 Local Fac County:
 40

 District Code:
 5

Rp Identifier 1: Rp Identifier 2:

Product 2: Product 3: Product 4: Source 2: Source 3: Source 4:

rce 3:

Original Source: LAST
Record Date: 02-DEC-2019

9 1 of 7 WSW 0.24 / 262.26 / COLUMBIAS CLEANERS INC 1,274.74 15 6320 GARNERS FERRY RD RCRA SQG

COLUMBIA SC 29209

Order No: 22071200085

EPA Handler ID:SCD981756190Gen Status Universe:Small Quantity GeneratorContact Name:LARRY L KOESTER

Contact Address: 6320, GARNERS FERRY RD,, COLUMBIA, SC, 29209, US

KEL TAY EXPRESS

Contact Phone No and Ext: 803-463-5211

Contact Email: LKOESTER@BELLSOUTH.NET

Contact Country: US
County Name: RICHLAND
EPA Region: 04
Land Type: Private
Receive Date: 20210830
Location Latitude: 33.969197
Location Longitude: -80.94648

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with

this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Apr, 2022.

Violation Details

Found Violation: Yes

Citation:

Violation Short Description: TSD IS-Preparedness and Prevention

Violation Type: 265.C
Violation Determined Date: 20160413

Scheduled Compliance Date:

Return to Compliance: Observed
Actual Return to Compl: 20160603
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 140

Enforcement Type Description:

Enforcement Action Date: 20160603

Enf Disposition Status: Disposition Status Date: Enforcement Lead Agency: Proposed Penalty Amount:

State

Final Amount: Paid Amount:

Violation Details

Found Violation: Yes

Citation:

Violation Short Description: Generators - Records/Reporting

Violation Type: 262.D 20160413 Violation Determined Date:

Scheduled Compliance Date:

Return to Compliance: Observed Actual Return to Compl: 20160603 Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 140

Enforcement Type Description:

Enforcement Action Date: 20160603

Enf Disposition Status: Disposition Status Date: Enforcement Lead Agency:

State

Proposed Penalty Amount:

Final Amount: Paid Amount:

Violation Details

Found Violation: Yes

Citation:

Generators - Pre-transport Violation Short Description:

Violation Type: 262.C 20160413 Violation Determined Date:

Scheduled Compliance Date:

Return to Compliance: Observed Actual Return to Compl: 20160603 Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 140

Enforcement Type Description:

Enforcement Action Date: 20160603

Enf Disposition Status: Disposition Status Date: Enforcement Lead Agency:

State

Proposed Penalty Amount:

Final Amount: Paid Amount:

Violation Details

Found Violation:

Citation:

Violation Short Description: TSD IS-Container Use and Management

Yes

Violation Type: 265.1 Violation Determined Date: 20160413

Scheduled Compliance Date:

Return to Compliance: Observed
Actual Return to Compl: 20160603
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 140

Enforcement Type Description:

Enforcement Action Date: Enf Disposition Status:

Disposition Status Date:

Enforcement Lead Agency: Proposed Penalty Amount:

Final Amount:
Paid Amount:

20160603

State

Evaluation Details

Evaluation Start Date: 20160413

Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE

Violation Short Description: TSD IS-Preparedness and Prevention

Return to Compliance Date: 20160603 Evaluation Agency: State

Evaluation Start Date: 20160413

Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE

Violation Short Description: Generators - Pre-transport

Return to Compliance Date: 20160603 Evaluation Agency: State

Evaluation Start Date: 20160413

Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE

Violation Short Description: TSD IS-Container Use and Management

Return to Compliance Date: 20160603
Evaluation Agency: State

Evaluation Start Date: 20160413

Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE

Violation Short Description: Generators - Records/Reporting

Return to Compliance Date: 20160603 Evaluation Agency: State

Handler Summary

Nο Importer Activity: Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: No **Used Oil Processor:** Nο **Used Oil Refiner:** No **Used Oil Burner:** No **Used Oil Market Burner:** No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 11

Receive Date: 20190114

Handler Name: COLUMBIAS CLEANERS INC

Federal Waste Generator Code:

Generator Code Description: Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D040

Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Code:D008Waste Code Description:LEAD

Hazardous Waste Code: D039

Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: F002

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 10

Receive Date: 20180209

Handler Name: COLUMBIAS CLEANERS INC

Federal Waste Generator Code:

Generator Code Description: Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D040

Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Code:D008Waste Code Description:LEAD

Hazardous Waste Code: D039

Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: F002

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

Order No: 22071200085

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 3

Receive Date: 20110425

Handler Name: COLUMBIAS CLEANERS INC

Federal Waste Generator Code:

Generator Code Description: Small Quantity Generator

Source Type:

Notification

Waste Code Details

Hazardous Waste Code: D040

Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Code:D008Waste Code Description:LEAD

Hazardous Waste Code: D039

Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: F002

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 7

Receive Date: 20150213

Handler Name: COLUMBIAS CLEANERS INC

Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D040

Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Code:D008Waste Code Description:LEAD

Hazardous Waste Code: D039

Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: F002

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

Order No: 22071200085

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No:

Receive Date: 19981022

Handler Name: COLUMBIAS CLEANERS INC

Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code:D008Waste Code Description:LEAD

Hazardous Waste Code: F002

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D039

Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D040

Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20140430

Handler Name: COLUMBIAS CLEANERS INC

Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: F002

Waste Code Description:

THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE
CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2,
TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF
TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR

THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D039

Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D040

Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20160415

Handler Name: COLUMBIAS CLEANERS INC

Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: F002

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2,

TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code:D008Waste Code Description:LEAD

Waste Code Description: TETRACHLOROETHYLENE

D039

Hazardous Waste Code: D040

Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Handler Details

Hazardous Waste Code:

Sequence No: 5

Receive Date: 20130815

Handler Name: COLUMBIAS CLEANERS INC

Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code:D008Waste Code Description:LEAD

Hazardous Waste Code: F002

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D039

Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D040

Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Handler Details

 Sequence No:
 12

 Receive Date:
 20210830

Handler Name: COLUMBIAS CLEANERS INC

Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code:D008Waste Code Description:LEAD

Hazardous Waste Code: F002

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF

TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D039

Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D033

Waste Code Description: HEXACHLOROBUTADIENE

Hazardous Waste Code: D040

Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Code: D030

Waste Code Description: 2,4-DINITROTOLUENE

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20120330

Handler Name: COLUMBIAS CLEANERS INC

F002

Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code:D008Waste Code Description:LEAD

Hazardous Waste Code:

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D039

Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D040

Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20170720

Handler Name: COLUMBIAS CLEANERS INC

Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: F002

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR

Number of Direction Distance Elev/Diff DΒ Map Key Site Records (mi/ft) (ft)

THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D039

TETRACHLOROETHYLENE Waste Code Description:

Hazardous Waste Code:

TRICHLORETHYLENE Waste Code Description:

Hazardous Waste Handler Details

Seauence No:

Receive Date: 20100409

Handler Name: **COLUMBIAS CLEANERS INC**

Federal Waste Generator Code:

Small Quantity Generator Generator Code Description:

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D008 Waste Code Description: **LEAD** Hazardous Waste Code: F002

THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE Waste Code Description:

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1.2.2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1.1.2. TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

Order No: 22071200085

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D039

Waste Code Description: **TETRACHLOROETHYLENE**

Hazardous Waste Code:

TRICHLORETHYLENE Waste Code Description:

Owner/Operator Details

Owner/Operator Ind: **Current Operator** Street No:

Street 1: **OPERSTREET** Type: Private **OPERNAME** Street 2: Name:

Date Became Current: City:

OPERCITY Date Ended Current: State: WY

404-555-1212 Country: Phone: Notification 99999 Source Type: Zip Code:

Current Owner Owner/Operator Ind: Street No:

6320 GARNERS FERRY RD Type: Private Street 1:

Name: **KOESTER LARRY** Street 2:

Date Became Current: **COLUMBIA** Citv:

SC Date Ended Current: State: 803-776-4673 US Phone: Country:

Notification Zip Code: 29209 Source Type:

Current Owner Owner/Operator Ind: Street No:

6320 GARNERS FERRY RD Type: Private Street 1:

Name: **KOESTER LARRY** Street 2: Date Became Current:

City: **COLUMBIA**

SC Date Ended Current: State:

Country: Phone: 803-776-4673

Source Type: Notification Zip Code: 29209

Owner/Operator Ind: **Current Operator** Street No: Private 6320 GARNERS FERRY RD Type: Street 1:

Number of Distance Elev/Diff Site DΒ Map Key Direction Records (mi/ft) (ft)

Street 2:

KOESTER LARRY Name:

Date Became Current: 20010101 **COLUMBIA** City:

Date Ended Current:

State: SC 803-776-4673 US Phone: Country: Source Type: Notification Zip Code: 29209

Historical Handler Details

20110425 Receive Dt:

Generator Code Description: Small Quantity Generator COLUMBIAS CLEANERS INC Handler Name:

Receive Dt: 20180209

Small Quantity Generator Generator Code Description: COLUMBIAS CLEANERS INC Handler Name:

Receive Dt: 20150213

Generator Code Description: **Small Quantity Generator** COLUMBIAS CLEANERS INC Handler Name:

Receive Dt: 20160415

Generator Code Description: Small Quantity Generator Handler Name: **COLUMBIAS CLEANERS INC**

Receive Dt: 20170720

Small Quantity Generator Generator Code Description: Handler Name: COLUMBIAS CLEANERS INC

20120330 Receive Dt:

Small Quantity Generator Generator Code Description: Handler Name: **COLUMBIAS CLEANERS INC**

Receive Dt: 20190114

Small Quantity Generator Generator Code Description: Handler Name: COLUMBIAS CLEANERS INC

Receive Dt: 19981022

Generator Code Description: Small Quantity Generator **COLUMBIAS CLEANERS INC** Handler Name:

Receive Dt:

Generator Code Description: **Small Quantity Generator** Handler Name: COLUMBIAS CLEANERS INC

Receive Dt: 20140430

Generator Code Description: **Small Quantity Generator** COLUMBIAS CLEANERS INC Handler Name:

Receive Dt: 20100409

Generator Code Description: Small Quantity Generator Handler Name: **COLUMBIAS CLEANERS INC**

2 of 7 WSW 0.24/ 262.26/ **BURNETTES CLEANERS** 9 1,274.74 6320 GARNERS FERRY RD 15

Search County: Site ID: 15724 **RICHLAND**

County Code: Site No (EFIS): UST-15724 40 Permit: N 15724 Facility (Web): **BURNETTES CLEANERS** No of Tanks: 6320 GARNERS FERRY RD 3 Fac Street (Web): 3 Facilit City (Web): **COLUMBIA** Abandoned: Facility St (Web): SC

COLUMBIA SC 29209

Richland

29209

Fac County (Web):

Facility Zip (Web):

Operator Phone:

Land Owner Phone:

LUST

Order No: 22071200085

Billable: 0 Other: 0 Last Inspection:

803-776-4673 Phone: Facil City (EFIS): **COLUMBIA**

Facil State (EFIS): SC Tank Owner Phone: 803-463-5211

Facil Zip (EFIS): 29209

Facility Link: https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/15724

Facil Name (EFIS): **BURNETTES CLEANERS** Facil Address (EFIS): 6320 GARNERS FERRY RD

Category: Retail Sales

6320 GARNERS FERRY RD **Business Address:** COLUMBIA SC 29209

Land Owner Business Addr:

Operator Business Addr:

KOESTER, LARRY L Tank Owner Business Addr: 6165 RANCH RD

WADMALAW ISLAND SC 29487

DHEC Online Registry - Release Report; DHEC Confirmed Release Report (LUST); DHEC EFIS Data Delivery Data Source:

Prohibition list

DHEC Online Registry - Release Report

Release No:

Project Manager: WYKEL, JAMES M Reported: 6/23/1993 Confirmed: 7/21/1994

RBCA/ Score: 3BF - GW < 15 feet in sand or gravel / 2855

Product:

Compliance Req: False

NFA:

Fin Type: **DHEC SUPERB**

Fin Res Mechanism:

Abatement Met: 12/1/1983 Cleanup Initiated: 11/18/1998

Cleanup Complete: Cleanup MCL:

Compliance Date:

Compliance Met: False

Emergency Resp:

Responsible Party: KOESTER, LARRY L

Superb Determ Date: Superb Qualified:

Transferred:

Source: UST

DHEC Confirmed Release Report

PETRO Release No: Substance: Status: 1 Reported: 06/23/93 NFA: Confirmed: 07/21/94 3BF WYKELJM Rank: Proj Mgr: Score: 2855 Tank Owner: KOESTER, LARRY

Order No: 22071200085

GW < 15 feet in sand or gravel Rank Desc:

DHEC EFIS Data Details

Release No:

Release Date: 6/23/1993 Project Mgr: DS Confirmed Date: 7/21/1994

Cleanup Comp Date:

Cleanup Comp McI Dt:

Rp Name: LARRY L KOESTER Rp Address: 6165 RANCH RD Rp City: WADMALAW ISLAND

Rp State: SC Rp Zip: 29487 Sstl Estab Code: MR CLASS3BF Scrbca Class Code: 15.3 Depth to GW: **GW Flow Dir Code:** S

| Map Key | Number o Records | of Direction | Distance (mi/ft) | Elev/Diff (ft) | Site | DB |
|--|---------------------|---------------------|--------------------------|-------------------|--|-------|
| Receptor Type Code: Rel Fin Type Cd: CoC Concentrate Cd: | | KUHN, KIMBI DEPT | KUHN, KIMBERLY M DEPT | | | |
| 9 | 3 of 7 | wsw | 0.24 / 1,274.74 | 262.26 / 15 | COLUMBIA'S CLEANERS/FMR BURNETTE'S CLNRS 6320 GARNERS FERRY RD, COLUMBIA SC 29209 SC | SASPL |
| EPA ID: | \$ | SCDRY0052638 | | County: | RICHLAND | |
| 9 | 4 of 7 | wsw | 0.24 / 1,274.74 | 262.26 / 15 | BURNETTES CLEANERS 6320 GARNERS FERRY RD COLUMBIA SC 29209 | UST |

 Site No:
 15724
 Search County:
 RICHLAND

 Permit:
 N 15724
 County:
 RICHLAND

 No. of Tanks:
 3
 County Code:
 40

Last Inspection: Fac ID (Deliv Pro):

Abandoned: 3 Fac City (Online): COLUMBIA

Billable:0Facility ST (FOI):SCLand Owner Phone:Fac City (FOI):COLUMBIA

Tank Owner Phone:803-463-5211Fac Contact (FOI):Operator Phone:Fac Phone (FOI):

 Phone:
 803-776-4673
 Fac Zip (FOI):
 29624

 Other:
 0
 Zip (Online):
 29209

Local Fac Comp Nm:BURNETTES CLEANERSFac Addr (Online):6320 GARNERS FERRY RD

Facility Link: https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/15724

Business Addr (Online): 6320 GARNERS FERRY RD COLUMBIA SC 29209

Category: Retail Sales

Land Owner Business Address:

Tank Owner Business Address: KOESTER, LARRY L 6165 RANCH RD

WADMALAW ISLAND SC 29487

Operator Business Address:

Source: DHEC Management Tracking UST 'C' List; DHEC Underground Storage Tank Registry (Online)

Order No: 22071200085

Tank Information - UST Registry Search

Tank No:

Case No:

Class: N

 Status:
 Abandoned

 Notify:
 6/1/1993

 Capacity:
 8000

Variance:

Product: Gasoline

Overfill Type: Verified: Constr Date: Operat Date: Piping Type: Compliance: Comp Status:

Age at Notification: 25

Dist to Well (ft): Spill Prevention: Left Gal:

Owner at ABD: KOESTER, LARRY L

 Last Use:
 1/1/1983

 Aband:
 12/1/1983

 Method:
 Removed

| Мар Кеу | Number of Records | Direction | Distance (mi/ft) | Elev/Diff (ft) | Site | DB |
|------------------------------|----------------------|--------------------------|---------------------|-------------------|------|----|
| Chem: | | | | | | |
| Under Dispe | nser Cont: | False | | | | |
| Drop Tube: | | False | | | | |
| Tank Const: | | Steel | | | | |
| Pipe Const: | | Steel | | | | |
| Tank Protect | : | | | | | |
| Tank Tested: | | | | | | |
| Pipe Protect. | • | | | | | |
| Pipe Tested: | | 0' ' " | | | | |
| Tank Cont M | | Single wall | | | | |
| Pipe Cont Me | | Single wall | | | | |
| Tank Leak De Pipe Leak De | | | | | | |
| ripe Leak De | il. | | | | | |
| Tank No: | | 1 | | | | |
| Case No: | | | | | | |
| Class: | | N | | | | |
| Status: | | Abandoned | | | | |
| Notify: | | 6/1/1993 | | | | |
| Capacity: | | 10000 | | | | |
| Variance: | | 0- " | | | | |
| Product: | | Gasoline | | | | |
| Overfill Type Verified: | • | | | | | |
| Constr Date: | | | | | | |
| Operat Date: | | | | | | |
| Piping Type: | | | | | | |
| Compliance: | | | | | | |
| Comp Status | | | | | | |
| Age at Notifi | | 25 | | | | |
| Dist to Well (| | | | | | |
| Spill Prevent | ion: | | | | | |
| Left Gal: | 5 | KOECTED I M | | | | |
| Owner at AB Last Use: | D: | KOESTER, LAI 1/1/1983 | KIL | | | |
| Aband: | | 12/1/1983 | | | | |
| Method: | | Removed | | | | |
| Chem: | | | | | | |
| Under Dispe | nser Cont: | False | | | | |
| Drop Tube: | | False | | | | |
| Tank Const: | | Steel | | | | |
| Pipe Const: | _ | Steel | | | | |
| Tank Protect Tank Tested: | | | | | | |
| Pipe Protect: | | | | | | |
| Pipe Tested: | | | | | | |
| Tank Cont M | | Single wall | | | | |
| Pipe Cont Me | eth: | Single wall | | | | |
| Tank Leak D | | | | | | |
| Pipe Leak De | et: | | | | | |
| Tank No: | | 2 | | | | |
| Case No: | | _ | | | | |
| Class: | | N | | | | |
| Status: | | Abandoned | | | | |
| Notify: | | 6/1/1993 | | | | |
| Capacity: | | 10000 | | | | |
| Variance: | | . | | | | |
| Product: | | Gasoline | | | | |
| Overfill Type | : | | | | | |
| Verified: Constr Date: | | | | | | |
| Operat Date: | | | | | | |
| Piping Type: | | | | | | |
| Compliance: | | | | | | |
| Comp Status | | | | | | |
| Age at Notifi | cation: | 25 | | | | |
| Dist to Well (| ft): | | | | | |
| Spill Prevent | ion: | | | | | |

Left Gal:

Owner at ABD: KOESTER, LARRY L

Last Use: 1/1/1983 12/1/1983 Aband: Method: Removed

Chem:

Under Dispenser Cont: False False **Drop Tube:** Tank Const: Steel Pipe Const: Steel

Tank Protect: Tank Tested: Pipe Protect: Pipe Tested:

Tank Cont Meth: Single wall Pipe Cont Meth: Single wall

Tank Leak Det: Pipe Leak Det:

Tank Information - UST 'C' List

Tank No: 3

Tank Owner: **KOESTER** Tank Owner Contact: **CALEB HARR** 6165 RANCH RD Tank Owner Addr: Tank Owner City: WADMALAW ISL

Tank Owner State: SC Tank Owner Zip: 29487 803-463-5211 Tank Owner Phone: Capacity Gal: 8000 Age at Notif. Years: 25 ABD Status Code: Status Code Desc: Abandoned

GN Substance Code:

Tank No:

Tank Owner: **KOESTER** Tank Owner Contact: **CALEB HARR** Tank Owner Addr: 6165 RANCH RD Tank Owner City: WADMALAW ISL

Tank Owner State: SC 29487 Tank Owner Zip: Tank Owner Phone: 803-463-5211 10000 Capacity Gal: Age at Notif. Years: 25 Status Code: ABD Abandoned Status Code Desc:

Substance Code: GN

Tank No:

Tank Owner: **KOESTER CALEB HARR** Tank Owner Contact: Tank Owner Addr: 6165 RANCH RD Tank Owner City: WADMALAW ISL

Tank Owner State: SC Tank Owner Zip: 29487 Tank Owner Phone: 803-463-5211 Capacity Gal: 10000 Age at Notif. Years: 25 Status Code: ABD Status Code Desc: Abandoned

Substance Code: GN

5 of 7

COLUMBIA'S CLEANERS/FMR 0.24/ 262.26/ 1,274.74 15 **BURNETTE'S CLNRS**

6320 GARNERS FERRY RD **COLUMBIA SC**

DRY **CLEANERS**

WSW

erisinfo.com | Environmental Risk Information Services

9

| Map Key | Number Records | | Direction | Distance (mi/ft) | Elev/Diff (ft) | Site | | DB |
|--|-------------------|--------------|---|---------------------|--------------------------|-----------------|--|-------------------|
| File No: | | | 52638 | | | | | |
| 9 | 6 of 7 | | wsw | 0.24 / 1,274.74 | 262.26 / 15 | BURNETTE' | ERS FERRY RD; | DRYCLEANERS |
| File No: Priority Grou _l Priority Grou _l | | | 52638 TIER III Third Priority | | | | | |
| 9 | 7 of 7 | | wsw | 0.24 / 1,274.74 | 262.26 / 15 | INCORPORA | ERS FERRY RD | FED DRYCLEANER |
| FRS Facility I | ID: | | 110002245204 | | | | | |
| NPDES IDs: NAICS Codes | s: | | 81232 | | | | | |
| SIC Codes: Latitude: | | | 33.9805 | | | | | |
| Longitude: | | | -80.96241 | | | | | |
| <u>10</u> | 1 of 6 | | sw | 0.24 / 1,280.22 | 258.18 / 11 | 6506 GARNE | FIELD CHEVRON ERS FERRY RD SC 29209-1603 | UST |
| Site No: | | 07807 | | | Search Co | ounty: | RICHLAND | |
| Permit: No. of Tanks: | ;: | N 07807 4 | | | County: County C | ode: | RICHLAND 40 | |
| Last Inspection | | 4 | | | Fac ID (De | eliv Pro): | COLLINADIA | |
| Abandoned: Billable: | | 4 0 | | | Fac City (Facility S | , | COLUMBIA SC | |
| Land Owner I | | | | | Fac City (| (FOI): | COLUMBIA | |
| Tank Owner F | | 828-453-7 | 7351 | | Fac Conta | act (FOI): | | |
| Operator Pho Phone: | ne: | | | | Fac Phon Fac Zip (F | | 29624 | |
| Other: | _ | 0 | | | Zip (Onlin | | 29209-1603 | |
| Local Fac Co. Fac Addr (On | | | MEADOW FIELD 6506 GARNERS | | | | | |
| Fac Addr (On Facility Link: | | | | c.sc.gov/Environm | nent/USTRegistr | v/Registry/Deta | nils/07807 | |
| Business Add | | | 6506 GARNERS COLUMBIA SC 2 | FERRY RD | | | | |
| Category: | | | Retail Sales | .9209-1603 | | | | |
| Land Owner I | Business A | Address: | | _Y PARTNERSHIF | P | | | |
| Tank Owner L | Business A | Address: | COLUMBIA SC 2 PETROLEUM WG 681 NC 120 HWY | ORLD INC Y | | | | |
| Operator Bus Source: | siness Addı | lress: | MOORESBORO DHEC Management | | Γ 'C' List; DHEC | Underground S | Storage Tank Registry (Online) | |
| Tank Informa | ation - UST | Registry S | <u>Search</u> | | | | | |
| Tank No: | | | 1 | | | | | |
| Case No: | | | _ | | | | | |
| Class: Status: | | | R Abandoned | | | | | |
| Status. Notify: | | | Abandoned | | | | | |
| Capacity: | | | 6000 | | | | | |
| Variance: | | | | | | | | |

Elev/Diff DΒ Map Key Number of Direction Distance Site (mi/ft) Records (ft) Product: Gasoline Overfill Type: Verified: Constr Date: Operat Date: Piping Type: Compliance: Comp Status: Age at Notification: Dist to Well (ft): Spill Prevention: Left Gal: PETROLEUM WORLD INC Owner at ABD: Last Use: Aband: 11/11/1911 Method: Removed Chem: **Under Dispenser Cont:** False Drop Tube: False Tank Const: Steel Steel Pipe Const: Tank Protect: Tank Tested: Pipe Protect: Pipe Tested: Single wall Tank Cont Meth: Pipe Cont Meth: Single wall Tank Leak Det: Pipe Leak Det: Tank No: 4 Case No: Class: R Status: Abandoned Notify: 2000 Capacity: Variance: Product: Diesel fuel Overfill Type: Verified: Constr Date: Operat Date: Piping Type: Compliance: Comp Status: Age at Notification: Dist to Well (ft): Spill Prevention: Left Gal: Owner at ABD: PETROLEUM WORLD INC Last Use: Aband: 11/11/1911 Method: Removed Chem: **Under Dispenser Cont:** False Drop Tube: False

Tank Const: Steel Pipe Const: Steel

. Tank Protect: Tank Tested: Pipe Protect: Pipe Tested:

Tank Cont Meth: Single wall Pipe Cont Meth: Single wall

Tank Leak Det: Pipe Leak Det:

2 Tank No:

Case No:

| Мар Кеу | Number of Records | Direction | Distance (mi/ft) | Elev/Diff (ft) | Site | DB |
|----------------------------------|----------------------|----------------|---------------------|-------------------|------|----|
| Class: | | R | | | | |
| Status: | | Abandoned | | | | |
| Notify: | | 4000 | | | | |
| Capacity: Variance: | | 4000 | | | | |
| Product: | | Gasoline | | | | |
| Overfill Type | | Gasoniic | | | | |
| Verified: | • | | | | | |
| Constr Date: Operat Date: | | | | | | |
| Piping Type: | | | | | | |
| Compliance: | | | | | | |
| Comp Status | : | | | | | |
| Age at Notific Dist to Well (| ft): | | | | | |
| Spill Prevent | ion: | | | | | |
| Left Gal: | _ | 0 | WOD! D :::0 | | | |
| Owner at AB | D: | PETROLEUM | WORLD INC | | | |
| Last Use: Aband: | | 11/11/1911 | | | | |
| Abana: Method: | | Removed | | | | |
| Chem: | | Romoveu | | | | |
| Under Dispe | nser Cont: | False | | | | |
| Drop Tube: | | False | | | | |
| Tank Const: | | Steel | | | | |
| Pipe Const: | | Steel | | | | |
| Tank Protect | | | | | | |
| Tank Tested: Pipe Protect: | | | | | | |
| Pipe Tested: | | | | | | |
| Tank Cont M | | Single wall | | | | |
| Pipe Cont Me | | Single wall | | | | |
| Tank Leak De Pipe Leak De | | | | | | |
| Tonk No. | | 2 | | | | |
| Tank No: Case No: | | 3 | | | | |
| Class: | | R | | | | |
| Status: | | Abandoned | | | | |
| Notify: | | | | | | |
| Capacity: | | 3000 | | | | |
| Variance: | | | | | | |
| Product: | | Gasoline | | | | |
| Overfill Type Verified: | : | | | | | |
| Verifiea: Constr Date: | | | | | | |
| Operat Date: | | | | | | |
| Piping Type: | | | | | | |
| Compliance: | | | | | | |
| Comp Status | | | | | | |
| Age at Notific | | | | | | |
| Dist to Well (Spill Prevent | | | | | | |
| Spill Prevent Left Gal: | 1011. | 0 | | | | |
| Owner at AB | D: | PETROLEUM ' | WORLD INC | | | |
| Last Use: | | | - | | | |
| Aband: | | 11/11/1911 | | | | |
| Method: | | Removed | | | | |
| Chem: | | Est- | | | | |
| Under Dispe | nser Cont: | False False | | | | |
| Drop Tube: Tank Const: | | Faise Steel | | | | |
| Pipe Const: | | Steel | | | | |
| Tank Protect | : | 0.00. | | | | |
| Tank Tested: | | | | | | |
| Pipe Protect: | • | | | | | |
| Pipe Tested: | | O: | | | | |
| Tank Cont M | | Single wall | | | | |
| Pipe Cont Me | #ul: | Single wall | | | | |

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft)

Tank Leak Det: Pipe Leak Det:

Tank Information - UST 'C' List

Tank No:

PETROLEUM WORLD IN Tank Owner:

Tank Owner Contact: **CALEB HARR** Tank Owner Addr: 681 NC 120 HWY Tank Owner City: **MOORESBORO**

Tank Owner State: NC Tank Owner Zip: 28114 Tank Owner Phone: 828-453-7351 Capacity Gal: 2000

Age at Notif. Years:

Status Code: ABD Status Code Desc: Abandoned

Substance Code:

Tank No:

PETROLEUM WORLD IN Tank Owner:

Tank Owner Contact: **CALEB HARR** Tank Owner Addr: 681 NC 120 HWY **MOORESBORO** Tank Owner City:

Tank Owner State: NC Tank Owner Zip: 28114 Tank Owner Phone: 828-453-7351

Capacity Gal: 6000

Age at Notif. Years:

Status Code: ABD Status Code Desc: Abandoned

GN Substance Code:

Tank No:

Tank Owner: PETROLEUM WORLD IN

Tank Owner Contact: CALEB HARR 681 NC 120 HWY Tank Owner Addr: **MOORESBORO** Tank Owner City:

Tank Owner State: NC 28114 Tank Owner Zip: 828-453-7351 Tank Owner Phone: 4000

Capacity Gal:

Age at Notif. Years:

Status Code: ABD Status Code Desc: Abandoned

Substance Code: GN

Tank No:

PETROLEUM WORLD IN Tank Owner:

3000

Tank Owner Contact: CALEB HARR Tank Owner Addr: 681 NC 120 HWY MOORESBORO Tank Owner City:

Tank Owner State: NC Tank Owner Zip: 28114 Tank Owner Phone: 828-453-7351

Capacity Gal: Age at Notif. Years:

ABD Status Code: Status Code Desc: Abandoned

GN Substance Code:

2 of 6 SW 0.24/ 258.18/ HENRY CHEVRON 10 **UST** 1,280.22 11 6506 GARNERS FERRY RD **COLUMBIA SC 29209-1603**

Site No: 10688 Search County: **RICHLAND** Permit: P 10688 County: **RICHLAND** Map Key Number of Direction Distance Elev/Diff Site DB Records (mi/ft) (ft)

No. of Tanks: 3 County Code: 40

Last Inspection: 4/29/1997 Fac ID (Deliv Pro):

 Abandoned:
 3
 Fac City (Online):
 COLUMBIA

 Billable:
 0
 Facility ST (FOI):
 SC

 Land Owner Phone:
 Fac City (FOI):
 COLUMBIA

Tank Owner Phone: 803-783-0286 Fac Contact (FOI):

Operator Phone: Fac Phone (FOI):

 Phone:
 803-776-6341
 Fac Zip (FOI):
 29624

 Other:
 0
 Zip (Online):
 29209-1603

Local Fac Comp Nm: HENRY CHEVRON

Fac Addr (Online): 6506 GARNERS FERRY RD

Facility Link: https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/10688

Business Addr (Online): 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603

Category: Retail Sales

Land Owner Business Address:

Tank Owner Business Address: FORMAC PARTNERSHIP

PO BOX 6747

COLUMBIA SC 29260-6747

Operator Business Address:

Source: DHEC Management Tracking UST 'C' List; DHEC Underground Storage Tank Registry (Online)

Tank Information - UST Registry Search

Tank No: 2

Case No:

Class: P

 Status:
 Abandoned

 Notify:
 10/16/1987

 Capacity:
 4000

Variance:

Product: Gasoline

Overfill Type: Verified:

 Constr Date:
 10/16/1987

 Operat Date:
 3/30/1988

 Piping Type:
 Pressure

Compliance: Comp Status: Age at Notification:

Dist to Well (ft): 300

Spill Prevention:

Left Gal: Owner at ABD: Last Use:

Aband: 10/9/1997
Method: Fill with foam

Chem:

Under Dispenser Cont: False
Drop Tube: False
Tank Const: Steel
Pipe Const: Steel

Tank Protect: Cathodic Protection

Tank Tested: 8/1/1995

Pipe Protect: Cathodic Protection

Pipe Tested:
Tank Cont Meth: Single wall
Pipe Cont Meth: Single wall

Tank Leak Det: Pipe Leak Det:

Tank No: 3

Case No: Class:

 Status:
 Abandoned

 Notify:
 10/16/1987

 Capacity:
 4000

Variance:

Elev/Diff DΒ Map Key Number of Direction Distance Site Records (mi/ft) (ft) Product: Gasoline Overfill Type: Verified: Constr Date: 10/16/1987 Operat Date: 3/30/1988 Pressure Piping Type: Compliance: Comp Status: Age at Notification: 300 Dist to Well (ft): Spill Prevention: Left Gal: Owner at ABD: Last Use: 10/9/1997 Aband: Method: Fill with foam Chem: **Under Dispenser Cont:** False Drop Tube: False Tank Const: Steel Pipe Const: Steel Tank Protect: Cathodic Protection Tank Tested: Pipe Protect: Cathodic Protection Pipe Tested: Single wall Tank Cont Meth: Pipe Cont Meth: Single wall Tank Tightness Test Tank Leak Det: Pipe Leak Det: Line Tightness Test Tank No: 1 Case No: Class: Status: Abandoned Notify: 10/16/1987 Capacity: 4000 Variance: Product: Gasoline Overfill Type: Verified: 10/16/1987 Constr Date: 3/30/1988 Operat Date: Piping Type: Pressure Compliance: Comp Status: Age at Notification: 300 Dist to Well (ft): Spill Prevention: Left Gal: Owner at ABD: Last Use: Aband: 10/9/1997 Method: Fill with foam Chem: **Under Dispenser Cont:** False Drop Tube: False Tank Const: Steel Pipe Const: Steel . Tank Protect: Cathodic Protection Tank Tested: 8/1/1995

Cathodic Protection Pipe Protect:

Pipe Tested:

Tank Cont Meth: Single wall Single wall Pipe Cont Meth:

Tank Leak Det: Pipe Leak Det:

Map Key Number of Direction Distance Elev/Diff Site DΒ Records (mi/ft) (ft)

Tank No:

FORMAC PARTNERSH Tank Owner:

Tank Owner Contact: **CALEB HARR** Tank Owner Addr: PO BOX 6747 **COLUMBIA** Tank Owner City: Tank Owner State: SC

Tank Owner Zip: 29260-6747 Tank Owner Phone: 803-783-0286

Capacity Gal: 4000 Age at Notif. Years:

Status Code: ABD Status Code Desc: Abandoned

Substance Code: GN

Tank No:

Tank Owner: FORMAC PARTNERSH

Tank Owner Contact: **CALEB HARR** Tank Owner Addr: PO BOX 6747 Tank Owner City: **COLUMBIA** SC Tank Owner State: Tank Owner Zip: 29260-6747 Tank Owner Phone: 803-783-0286 4000

Capacity Gal:

Age at Notif. Years:

ABD Status Code: Abandoned Status Code Desc:

Substance Code: GN

Tank No:

Tank Owner: FORMAC PARTNERSH

Tank Owner Contact: **CALEB HARR** Tank Owner Addr: PO BOX 6747 Tank Owner City: **COLUMBIA** Tank Owner State: SC

Tank Owner Zip: 29260-6747 Tank Owner Phone: 803-783-0286

Capacity Gal: 4000

Age at Notif. Years:

Status Code: ABD Status Code Desc: Abandoned

Substance Code: GN

Tank Information - Financial Responsibility

Financial Mechanism: None

Expiration Date:

0.24/ 258.18/ **MEADOW FIELD CHEVRON** 10 3 of 6 SW **LUST** 1,280.22 6506 GARNERS FERRY RD 11 **COLUMBIA SC 29209-1603**

Order No: 22071200085

Search County: Site ID: 07807 **RICHLAND**

Site No (EFIS): UST-07807 County Code: Permit: N 07807 Facility (Web): MEADOW FIELD CHEVRON No of Tanks: Fac Street (Web): 6506 GARNERS FERRY RD 4

Facilit City (Web): **COLUMBIA** Abandoned: 4 Billable: 0 Facility St (Web): SC Other: 0 Fac County (Web): Richland 29209-1603 Last Inspection: Facility Zip (Web):

Land Owner Phone: Phone: Facil City (EFIS): **COLUMBIA** Operator Phone:

Facil State (EFIS): Tank Owner Phone: SC 828-453-7351

Facil Zip (EFIS): 29209-1603

https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/07807 Facility Link:

Facil Name (EFIS): MEADOW FIELD CHEVRON Facil Address (EFIS): 6506 GARNERS FERRY RD

Map Key Number of Direction Distance Elev/Diff Site DΒ Records (mi/ft) (ft)

Category: Retail Sales

Business Address: 6506 GARNERS FERRY RD

COLUMBIA SC 29209-1603

FORMAC FAMILY PARTNERSHIP Land Owner Business Addr:

PO BOX 9343

COLUMBIA SC 29290

Operator Business Addr:

Tank Owner Business Addr: PETROLEUM WORLD INC

681 NC 120 HWY

MOORESBORO NC 28114

DHEC Online Registry - Release Report; DHEC Confirmed Release Report (LUST); DHEC EFIS Data Delivery Data Source:

Prohibition list

DHEC Online Registry - Release Report

Release No:

Project Manager: FULMER, SUSAN B

Reported: 10/22/1987 Confirmed: 10/29/1987

RBCA/ Score: 3BF - GW < 15 feet in sand or gravel / 8 Product:

Compliance Req: False NFA: 12/19/2008 Fin Type: With insurance

Fin Res Mechanism:

10/22/1987 Abatement Met: Cleanup Initiated: 3/28/1988

Cleanup Complete:

Cleanup MCL: 12/19/2008

Compliance Date:

Compliance Met: False

Emergency Resp:

Responsible Party: Superb Determ Date:

PETROLEUM WORLD INC

Superb Qualified: Transferred:

UST Non-Superb Source:

DHEC Confirmed Release Report

Substance: **PETRO** Release No: 1 Status: 4 Reported: 10/22/87 NFA: 12/19/08 Confirmed: 10/29/87 Rank: 3BF Proj Mgr: **FULMERSB**

Tank Owner:

PETROLEUM WORLD INC

Order No: 22071200085

Score: 8

GW < 15 feet in sand or gravel Rank Desc:

DHEC EFIS Data Details

Release No:

10/22/1987 Release Date: Project Mgr: WI

Confirmed Date: 10/29/1987

Cleanup Comp Date:

Cleanup Comp McI Dt: 12/19/2008

PETROLEUM WORLD INC Rp Name:

Rp Address: 681 NC 120 HWY Rp City: MOORESBORO

Rp State: NC Rp Zip: 28114 Sstl Estab Code: MR Scrbca Class Code: CLASS3BF

Depth to GW: 17 **GW Flow Dir Code:**

FULMER, SUSAN B Receptor Type Code:

Rel Fin Type Cd: TIER II CoC Concentrate Cd:

10 4 of 6 SW 0.24/ 258.18/ HENRY CHEVRON LUST 1,280.22 11 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603

Site ID: 10688 Search County: RICHLAND

Site No (EFIS): UST-10688 County Code: 4

 Permit:
 P 10688
 Facility (Web):
 HENRY CHEVRON

 No of Tanks:
 3
 Fac Street (Web):
 6506 GARNERS FERRY RD

Facilit City (Web): **COLUMBIA** Abandoned: 3 Billable: 0 Facility St (Web): SC Other: 0 Fac County (Web): Richland Last Inspection: 4/29/1997 Facility Zip (Web): 29209-1603

Phone:803-776-6341Land Owner Phone:Facil City (EFIS):COLUMBIAOperator Phone:

Facil State (EFIS): SC Tank Owner Phone: 803-783-0286

Facil Zip (EFIS): 29209-1603

Facility Link: https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/10688

Facil Name (EFIS): HENRY CHEVRON

Facil Address (EFIS): 6506 GARNERS FERRY RD

Category: Retail Sales

Business Address: 6506 GARNERS FERRY RD

COLUMBIA SC 29209-1603

Land Owner Business Addr: Operator Business Addr:

Tank Owner Business Addr: FORMAC PARTNERSHIP

PO BOX 6747

COLUMBIA SC 29260-6747

Data Source: DHEC Online Registry - Release Report; DHEC Confirmed Release Report (LUST); DHEC EFIS Data Delivery

Prohibition list

DHEC Online Registry - Release Report

Release No:

Project Manager: AKHVLEDIANI, KONSTANTINE T

Reported: 5/21/1999 **Confirmed:** 5/25/1999

RBCA/ Score: 5A - No pending threat, additional data / 13

Product:

Compliance Req: True NFA: 6/1/2001

Fin Type: With SUPERB 25K deductible

Fin Res Mechanism:

 Abatement Met:
 10/9/1997

 Cleanup Initiated:
 1/7/2000

 Cleanup Complete:
 1/5/2000

Cleanup MCL:

Compliance Date:

Compliance Met: True

Emergency Resp:

Responsible Party: FORMAC PARTNERSHIP

Superb Determ Date: Superb Qualified: Transferred:

Source: UST

DHEC Confirmed Release Report

 Release No:
 1
 Substance:
 PETRO

 Status:
 1
 Reported:
 05/21/99

 NFA:
 06/01/01
 Confirmed:
 05/25/99

 Rank:
 5A
 Proj Mgr:
 AKHVLEKT

Score: 13 Tank Owner: FORMAC PARTNERSHIP

Order No: 22071200085

Rank Desc: No pending treat, additional data

Number of Direction Distance Elev/Diff Site Map Key Records (mi/ft) (ft)

DHEC EFIS Data Details

Release No:

5/21/1999 Release Date: Project Mgr: W25 Confirmed Date: 5/25/1999 Cleanup Comp Date: 1/5/2000

Cleanup Comp McI Dt:

Rp Name: FORMAC PARTNERSHIP

Rp Address: PO BOX 6747 **COLUMBIA** Rp City: Rp State: SC Rp Zip: 29260-6747

Sstl Estab Code:

Scrbca Class Code:

Depth to GW: GW Flow Dir Code: Receptor Type Code:

AKHVLEDIANI, KONSTANTINE T

CLASS5A

Rel Fin Type Cd: CoC Concentrate Cd:

> SW 0.24/ 10 5 of 6 258.18/ RIDGEWAYS AUTO SERVICE 1,280.22 6506 GARNERS FERRY RD 11 **COLUMBIA SC 29209-1603**

Site No: Search County: **RICHLAND** Permit: N 17230 County: **RICHLAND**

No. of Tanks:

Last Inspection: Abandoned: 0

Billable: Land Owner Phone:

Tank Owner Phone: 803-783-0286 Operator Phone:

Phone: 803-776-6341

Other: RIDGEWAYS AUTO SERVICE

Local Fac Comp Nm: 6506 GARNERS FERRY RD Fac Addr (Online):

https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/17230 Facility Link:

Business Addr (Online): 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603

Category: Retail Sales

Land Owner Business Address:

Tank Owner Business Address: RIDGEWAY, HENRY 6506 GARNERS FERRY RD COLUMBIA SC 29209-1603

Operator Business Address:

Source: DHEC Underground Storage Tank Registry (Online)

SW 0.24/ 258.18/ **MEADOW FIELD CHEVRON** 10 6 of 6 **RCR** 6506 GARNERS FERRY RD 1,280.22 11

07807 Site ID: REL:

Tax Map ID: R16403-03-01 Reported: 10/22/87 CU>MCL: 12/19/08 Latitude: 33.97929 Longitude: -80.96093

11 1 of 1 WSW 0.26/ 260.54/ WJBD VETERANS HOSPITAL **LUST** 6439 GARNERS FERRY RD 1,348.54 14 **COLUMBIA SC 29209-1638**

DΒ

UST

County Code:

Fac ID (Deliv Pro):

COLUMBIA Fac City (Online): Facility ST (FOI):

Fac City (FOI): Fac Contact (FOI): Fac Phone (FOI): Fac Zip (FOI):

Zip (Online): 29209-1603

COLUMBIA SC 29209-1603

Order No: 22071200085

Map Key Number of Direction Distance Elev/Diff Site DB Records (mi/ft) (ft)

 Site ID:
 07394
 Search County:
 RICHLAND

 Site No (EFIS):
 UST-07394
 County Code:
 40

Permit:N 07394Facility (Web):WJBD VETERANS HOSPITALNo of Tanks:9Fac Street (Web):6439 GARNERS FERRY RD

 Abandoned:
 9
 Facilit City (Web):
 COLUMBIA

 Billable:
 0
 Facility St (Web):
 SC

 Other:
 0
 Fac County (Web):
 Richland

 Last Inspection:
 10/16/1998
 Facility Zip (Web):
 29209-1638

Phone:803-776-4000Land Owner Phone:Facil City (EFIS):COLUMBIAOperator Phone:

Facil State (EFIS): SC Tank Owner Phone: 803-776-4000

Facil Zip (EFIS): 29209-1638

Facility Link: https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/07394

Facil Name (EFIS): WJBD VETERANS HOSPITAL
Facil Address (EFIS): 6439 GARNERS FERRY RD
Category: Federal Government
Business Address: 6439 GARNERS FERRY RD

COLUMBIA SC 29209-1638

Land Owner Business Addr: Operator Business Addr:

Tank Owner Business Addr: WJBD VETERANS HOSPITAL

6439 GARNERS FERRY RD COLUMBIA SC 29209-1638

Data Source: DHEC Online Registry - Release Report; DHEC Confirmed Release Report (LUST); DHEC EFIS Data Delivery

Order No: 22071200085

Prohibition list

DHEC Online Registry - Release Report

Release No:

Project Manager: LONG, KRISTEN H

Reported: 12/2/1998 **Confirmed:** 12/29/1998

RBCA/ Score: 5B - Assessment data NOT conclusive / 1

Product:

Compliance Req: True NFA: 7/23/1999

Fin Type: With SUPERB 25K deductible

Fin Res Mechanism:

 Abatement Met:
 10/29/1998

 Cleanup Initiated:
 6/4/1999

 Cleanup Complete:
 7/23/1999

Cleanup MCL: Compliance Date:

Compliance Met: True

Emergency Resp:

Responsible Party: WJBD VETERANS HOSPITAL

Superb Determ Date: Superb Qualified:

Transferred:

Source: UST

Release No:

Project Manager: STEPP, AMY K Reported: 12/2/1998

Confirmed: RBCA/ Score:

RBCA/ Score:
Product:

Compliance Req:FalseNFA:12/29/1998

Fin Type:

Fin Res Mechanism: Abatement Met: Cleanup Initiated: Cleanup Complete: Cleanup MCL: Compliance Date:

Compliance Met: False

Emergency Resp: Responsible Party: Superb Determ Date: Superb Qualified: Transferred: Source:

Release No:

Project Manager: LONG, KRISTEN H

Reported: 12/2/1998 . Confirmed: 12/29/1998

RBCA/ Score: 5B - Assessment data NOT conclusive / 1

Product:

Compliance Req: True NFA: 7/23/1999

Fin Type: With SUPERB 25K deductible

Fin Res Mechanism:

Abatement Met: 10/29/1998 Cleanup Initiated: 6/4/1999 Cleanup Complete: 7/23/1999

Cleanup MCL:

Compliance Date:

Compliance Met: True

Emergency Resp:

WJBD VETERANS HOSPITAL Responsible Party:

Superb Determ Date: Superb Qualified:

Transferred:

UST Source:

Release No:

WRIGHT, JOHN Project Manager: Reported: 8/24/1994

Confirmed:

RBCA/ Score: Product:

Compliance Req: False NFA: 11/21/1994

Fin Type:

Fin Res Mechanism: Abatement Met: Cleanup Initiated: Cleanup Complete: Cleanup MCL: Compliance Date:

Compliance Met: False

Emergency Resp: Responsible Party: Superb Determ Date: Superb Qualified: Transferred: Source:

DHEC Confirmed Release Report

Release No: Substance: **PETRO** Status: 5 Reported: 12/02/98 07/23/99 Confirmed: 12/29/98 NFA: Rank: 5B Proj Mgr: LONGKH Tank Owner: WJBD VETERANS HOSPITAL Score: 1

Assessment data NOT conclusive

Rank Desc:

Release No: 2 Status: 5 07/23/99 NFA: Rank: 5B

Score: 1 Assessment data NOT conclusive Rank Desc:

Substance: **PETRO** Reported: 12/02/98 Confirmed: 12/29/98 Proj Mgr: LONGKH

Tank Owner: WJBD VETERANS HOSPITAL

Order No: 22071200085

Map Key Number of Direction Distance Elev/Diff Site DB Records (mi/ft) (ft)

250.40/

DHEC EFIS Data Details

Release No:

 Release Date:
 12/2/1998

 Project Mgr:
 W25

 Confirmed Date:
 12/29/1998

 Cleanup Comp Date:
 7/23/1999

Cleanup Comp Mcl Dt:

Rp Name:WJBD VETERANS HOSPITALRp Address:6439 GARNERS FERRY RDRp City:COLUMBIA

 Rp City:
 COLUMBIA

 Rp State:
 SC

 Rp Zip:
 29209-1638

Sstl Estab Code:

Scrbca Class Code: CLASS5B

Depth to GW: GW Flow Dir Code:

Receptor Type Code: LONG, KRISTEN H

Rel Fin Type Cd: CoC Concentrate Cd:

DHEC EFIS Data Details

Release No: 2

 Release Date:
 12/2/1998

 Project Mgr:
 W25

 Confirmed Date:
 12/29/1998

 Cleanup Comp Date:
 7/23/1999

Cleanup Comp Mcl Dt:

Rp Name:WJBD VETERANS HOSPITALRp Address:6439 GARNERS FERRY RD

 Rp City:
 COLUMBIA

 Rp State:
 SC

 Rp Zip:
 29209-1638

 Sstl Estab Code:
 Scrbca Class Code:

Depth to GW: GW Flow Dir Code:

Receptor Type Code: LONG, KRISTEN H

Rel Fin Type Cd: CoC Concentrate Cd:

12

-in Type Ca:

1 of 1 WSW 0.29 / 1,505.90 6200 BLOCK GARNERS FERRY ROAD 6200 BLOCK GARNERS FERRY RD COLUMBIA SC

DELISTED LST

Order No: 22071200085

Delisted Leaking Above Ground Storage Tanks Details

Site ID: 3521

Release No:

Project Manager:RIVERS MIKE SStatus:CLOSED

Impacted Code: NO

Type:
Release Date: 3/9/2007
Confirmed:

NFA Dt: 7/28/2008

Transfer: Product: Source: Tier:

Number of Direction Distance Elev/Diff Site DΒ Map Key Records (mi/ft) (ft)

Truncated Note: Soil Impact Code:

RIVERSMS User Name:

Release Xfer Date:

Suspect NFA Date: 7/28/2008

Release Source Code:

Cleanup Complete Dt:

Local Fac Last Name: 6200 BLOCK GARNERS FERRY ROAD

Local Fac First Name:

Address 2: SC State Code: County: Richland Zip Code: 29 Local Fac County: 40 District Code: 5

Rp Identifier 1: Rp Identifier 2: Product 2: Product 3: Product 4: Source 2: Source 3: Source 4:

LAST

Original Source: Record Date: 02-DEC-2019

13 1 of 2 WSW 0.36/ 243.08/ **CIRCLE K 2705134** LUST 6122 GARNERS FERRY RD 1,884.74 -4 **COLUMBIA SC 29209-1353**

Operator Phone:

Order No: 22071200085

10048 Search County: **RICHLAND** Site ID:

Site No (EFIS): UST-10048 County Code:

Facility (Web): Permit: P 10048 **CIRCLE K 2705134** 6122 GARNERS FERRY RD No of Tanks: 6 Fac Street (Web):

3 Facilit City (Web): **COLUMBIA** Abandoned: Facility St (Web): Billable: 3 SC Fac County (Web): Richland Other: 0 Last Inspection: 1/4/2022 Facility Zip (Web): 29209-1353 Land Owner Phone:

803-783-0083 Phone: Facil City (EFIS): **COLUMBIA**

Facil State (EFIS): SC Tank Owner Phone: 800-476-7574

Facil Zip (EFIS): 29209-1353

Facility Link: https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/10048

Facil Name (EFIS): **CIRCLE K 2705134** 6122 GARNERS FERRY RD Facil Address (EFIS):

Category:

Business Address: 6122 GARNERS FERRY RD

COLUMBIA SC 29209-1353

Land Owner Business Addr: Operator Business Addr:

CIRCLE K STORES INC Tank Owner Business Addr:

1100 SITUS CT STE 100 RALEIGH NC 27606

DHEC Online Registry - Release Report; DHEC Confirmed Release Report (LUST); DHEC EFIS Data Delivery Data Source:

Prohibition list

DHEC Online Registry - Release Report

Release No:

SHRADER, ART A Project Manager:

Reported: 3/30/1993 Confirmed: 6/14/1993

RBCA/Score: 2BB - Watersupply wells < 1000 feet downgrade / 38

Product: Petroleum Compliance Req: False 8/23/2007 NFA: Fin Type: With SUPERB

DΒ Map Key Number of Direction Distance Elev/Diff Site Records (mi/ft) (ft)

Fin Res Mechanism:

Abatement Met: 2/23/1993 Cleanup Initiated: 6/14/1993

Cleanup Complete:

Cleanup MCL: 8/23/2007

Compliance Date:

Compliance Met: False

Emergency Resp:

Responsible Party: PHILLIPS 66 COMPANY

Superb Determ Date: Superb Qualified: Transferred:

Source:

UST

DHEC Confirmed Release Report

PETROL Release No: 1 Substance: Status: Reported: 03/30/93 08/23/07 Confirmed: 06/14/93 NFA: Rank: 2BB Proj Mgr: SHRADEAA

CIRCLE K STORES INC Score: 38 Tank Owner:

Rank Desc: Watersupply wells < 1000 feet downgrade

DHEC EFIS Data Details

Release No:

Release Date: 3/30/1993 Project Mgr: WS Confirmed Date: 6/14/1993

Cleanup Comp Date:

Cleanup Comp McI Dt: 8/23/2007

PHILLIPS 66 COMPANY Rp Name:

12911 N TELECOM PKWY STE 100 Rp Address:

W

Rp City: **TAMPA** Rp State: FL Rp Zip: 33637-0907 Sstl Estab Code: MR Scrbca Class Code: CLASS2BB Depth to GW: 10.41

GW Flow Dir Code: Receptor Type Code: SHRADER, ART A

Rel Fin Type Cd: DEPT

CoC Concentrate Cd:

13 2 of 2 WSW 0.36/ 243.08/ **CIRCLE K 2705134 RCR** 1,884.74 6122 GARNERS FERRY RD COLUMBIA SC 29209-1353

Site ID: 10048 REL:

Tax Map ID: 16404-10-03 Reported: 03/30/93 CU>MCL: 08/23/07 Latitude: 33.98137 Longitude: -80.96517

14 1 of 3 W 0.37/ 237.10/ FMR LEXINGTON DRY CLEANING SASPL 1,935.44 -10 6041 GARNERS FERRY RD,

COLUMBIA SC 29209 SC

Order No: 22071200085

EPA ID: SCDRY0050204 **RICHLAND** County:

| Map Key | Number of Records | Direction | Distance (mi/ft) | Elev/Diff (ft) | Site | DB |
|-----------|----------------------|-----------|---------------------|-------------------|--|------|
| <u>14</u> | 2 of 3 | W | 0.37 / 1,935.44 | 237.10 / -10 | LANIER BUILDING 6041 GARNERS FERRY RD COLUMBIA SC 29202-1304 | LUST |

RICHLAND

Order No: 22071200085

Search County: Site ID: Site No (EFIS): County Code: N 14085 Facility (Web): Permit: No of Tanks: Fac Street (Web): Facilit City (Web): 0 Abandoned: Billable: 0 Facility St (Web): Fac County (Web): Other: 0 Last Inspection: Facility Zip (Web): Phone: Land Owner Phone: Facil City (EFIS): Operator Phone:

Facil State (EFIS): Tank Owner Phone: 704-987-8378

Facil Zip (EFIS):

Facility Link: https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/14085

Facil Name (EFIS): Facil Address (EFIS):

Category:

Business Address: 6041 GARNERS FERRY RD COLUMBIA SC 29202-1304

Land Owner Business Addr: Operator Business Addr:

Tank Owner Business Addr: GROUND TECHNOLOGICAL SERVICES

18637 NORTHLINE DR STE G

CORNELIUS NC 28031

Data Source: DHEC Online Registry - Release Report

DHEC Online Registry - Release Report

Release No:

Project Manager: ELAM, JULIE M **Reported:** 5/24/1991

Confirmed: RBCA/ Score:

Product:

Compliance Req: False 10/20/1992

Fin Type: Fin Res Mechanism: Abatement Met: Cleanup Initiated: Cleanup Complete: Cleanup MCL: Compliance Date:

Compliance Met: False

Emergency Resp: Responsible Party: Superb Determ Date: Superb Qualified: Transferred: Source:

 14
 3 of 3
 W
 0.37 / 237.10 / 6041 GARNERS FERRY RD
 DELISTED 6041 GARNERS FERRY RD

 1,935.44
 -10
 6041 GARNERS FERRY RD
 LST

Delisted Leaking Above Ground Storage Tanks Details

 Site ID:
 2851

 Release No:
 1

Project Manager: BOYNTON S JENNIFER

Status: TRANSFER

Number of Direction Distance Elev/Diff Site DΒ Map Key Records (mi/ft) (ft) YES Impacted Code: Type: Release Date: 2/18/2005 Confirmed: NFA Dt: 5/31/2005 Transfer: Product: Source: Tier: Truncated Note: Soil Impact Code: User Name: **BOYNTOSJ** Release Xfer Date: 5/31/2005 Suspect NFA Date: Release Source Code: Cleanup Complete Dt: Local Fac Last Name: 6041 GARNERS FERRY RD Local Fac First Name: Address 2: State Code: SC Richland County: Zip Code: Local Fac County: 40 District Code: 5 Rp Identifier 1: Rp Identifier 2: Product 2: Product 3: Product 4: Source 2: Source 3: Source 4: Original Source: LAST Record Date: 02-DEC-2019 1 of 1 W 0.42 / 236.41/ WLTX 15 LUST 2,208.28 6027 GARNERS FERRY RD -10 COLUMBIA SC 29209 Site ID: 11518 Search County: **RICHLAND** Site No (EFIS): County Code: 40 Permit: N 11518 Facility (Web): WLTX No of Tanks: Fac Street (Web): 6027 GARNERS FERRY RD 1 **COLUMBIA** Abandoned: 1 Facilit City (Web): 0 Billable: Facility St (Web): SC Other: 0 Fac County (Web): Richland Last Inspection: Facility Zip (Web): 29209 803-776-3600 Land Owner Phone: Phone: Facil City (EFIS): Operator Phone: Facil State (EFIS): Tank Owner Phone: 803-776-3600 Facil Zip (EFIS): https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/11518 Facility Link: Facil Name (EFIS): Facil Address (EFIS): Category: **Business Address:** 6027 GARNERS FERRY RD COLUMBIA SC 29209 Land Owner Business Addr: Operator Business Addr: Tank Owner Business Addr: WLTX 6027 GARNERS FERRY RD COLUMBIA SC 29209 Data Source: DHEC Online Registry - Release Report; DHEC Confirmed Release Report (LUST)

Order No: 22071200085

DHEC Online Registry - Release Report

Release No:

Map Key Number of Direction Distance Elev/Diff Site DB Records (mi/ft) (ft)

 Project Manager:
 PASLEY, DOUG C

 Reported:
 11/19/1991

 Confirmed:
 4/20/1992

Confirmed: RBCA/ Score:

Product:

Compliance Req: False
NFA: 4/20/1992
Fin Type: Unknown

Fin Res Mechanism: Abatement Met:

 Cleanup Initiated:
 4/20/1992

 Cleanup Complete:
 4/20/1992

Cleanup MCL: Compliance Date:

Compliance Met: False

Emergency Resp:

Responsible Party: WLTX

Superb Determ Date: Superb Qualified: Transferred:

Source: UST

DHEC Confirmed Release Report

 Release No:
 1
 Substance:
 PETRO

 Status:
 Reported:
 11/19/91

 NFA:
 04/20/92
 Confirmed:
 04/20/92

 Rank:
 Proj Mgr:
 PASLEYDC

 Score:
 Tank Owner:
 WLTX

Rank Desc:

16 1 of 1 SE 0.46 / 251.41 / GEORGE A CREED & SON INC 2,410.50 5 813 LEESBURG RD

COLUMBIA SC 29209-0000

Order No: 22071200085

Site ID: 14568 Search County: RICHLAND

Site No (EFIS): County Code: 40

Permit:N 14568Facility (Web):GEORGE A CREED & SON INCNo of Tanks:6Fac Street (Web):813 LEESBURG RD

 No of Tanks:
 6
 Fac Street (Web):
 813 LEESBURG RI

 Abandoned:
 6
 Facilit City (Web):
 COLUMBIA

 Billable:
 0
 Facility St (Web):
 SC

 Other:
 0
 Fac County (Web):
 Pichland

Other: 0 Facility St (Web): Sc Richland
Last Inspection: Facility Zip (Web): 29209-0000

Phone: 803-776-1248 Land Owner Phone: Facil City (EFIS): Operator Phone:

Facil State (EFIS): Tank Owner Phone: 803-776-1248

Facil Zip (EFIS):

Facility Link: https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/14568

Facil Name (EFIS): Facil Address (EFIS):

Category:

Business Address: 813 LEESBURG RD COLUMBIA SC 29209-0000

Land Owner Business Addr: Operator Business Addr:

Operator Business Addr:

Tank Owner Business Addr: GEORGE A CREED & SON INC

813 LEESBURG RD COLUMBIA SC 29209-0000

Data Source: DHEC Online Registry - Release Report; DHEC Confirmed Release Report (LUST)

DHEC Online Registry - Release Report

Release No:

Project Manager: WHITE, JIM Reported: 12/30/1992 Confirmed:

Map Key Number of Direction Distance Elev/Diff Site DB Records (mi/ft) (ft)

RBCA/ Score:

Product:

Compliance Req: False NFA: 12/17/1993

Fin Type:

Fin Res Mechanism:
Abatement Met:
Cleanup Initiated:
Cleanup Complete:
Cleanup MCL:
Compliance Date:

Compliance Met: False

Emergency Resp: Responsible Party: Superb Determ Date: Superb Qualified: Transferred: Source:

Release No:

Project Manager: BERENBROK, MARK K

 Reported:
 6/20/2001

 Confirmed:
 6/29/2001

 RBCA/ Score:
 /

Product:PetroleumCompliance Req:TrueNFA:7/6/2001

Fin Type:

Fin Res Mechanism: Abatement Met:

Cleanup Initiated: 6/29/2001 Cleanup Complete: 7/6/2001

Cleanup MCL:

Compliance Date:

Compliance Met: False

Emergency Resp:

Responsible Party: GEORGE A CREED & SON INC

Superb Determ Date: Superb Qualified: Transferred:

Source: UST

Release No:

Project Manager: BERENBROK, MARK K

Reported: 6/20/2001

Confirmed: RBCA/ Score: Product:

Compliance Req: True NFA: 7/6/2001

Fin Type:

Fin Res Mechanism: Abatement Met: Cleanup Initiated: Cleanup Complete: Cleanup MCL: Compliance Date:

Compliance Met: False

Emergency Resp:

Responsible Party: GEORGE A CREED & SON INC

Superb Determ Date: Superb Qualified:

Transferred:

Source: UST

DHEC Confirmed Release Report

Release No: 1 Substance: PETROL

Order No: 22071200085

DΒ Map Key Number of Direction Distance Elev/Diff Site Records (mi/ft) (ft) 06/20/01 Status: Reported: NFA: 07/06/01 Confirmed: 06/29/01 **BERENBMK** Rank: Proj Mgr: Tank Öwner: GEORGE A CREED & SON INC Score: Rank Desc: SE 0.49/ 257.36/ FOOD SERVICE SUPPLIES INC 17 1 of 2 LUST

11

844 PEPPER ST

COLUMBIA SC 29209

Order No: 22071200085

RICHLAND Site ID: 14122 Search County:

2,608.85

County Code: Site No (EFIS):

Facility (Web): FOOD SERVICE SUPPLIES INC Permit: N 14122

No of Tanks: Fac Street (Web): 844 PEPPER ST 2 Abandoned: 2 Facilit City (Web): **COLUMBIA** Billable: 0 Facility St (Web): SC Fac County (Web): Richland Other: 0 Last Inspection: Facility Zip (Web): 29209 Phone:

Land Owner Phone: Operator Phone:

Facil State (EFIS): Tank Owner Phone: 803-776-2658 Facil Zip (EFIS):

https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/14122 Facility Link:

Facil Name (EFIS): Facil Address (EFIS):

Category:

Facil City (EFIS):

844 PEPPER ST Business Address: COLUMBIA SC 29209

Land Owner Business Addr: Operator Business Addr:

FOOD SERVICE SUPPLIES INC Tank Owner Business Addr:

> 1020 2ND AVE COLUMBIA SC 29209

Data Source: DHEC Online Registry - Release Report; DHEC Confirmed Release Report (LUST)

DHEC Online Registry - Release Report

Release No:

STOUDEMIRE, DALE W Project Manager:

Reported: 12/30/1991 . Confirmed: 12/30/1991

RBCA/ Score:

Product: Compliance Req: False NFA: 10/9/1992

Unknown Fin Type:

Fin Res Mechanism:

Abatement Met:

Cleanup Initiated: 10/9/1992 Cleanup Complete: 10/9/1992

Cleanup MCL:

Compliance Date:

Compliance Met: False

Emergency Resp.

Responsible Party: FOOD SERVICE SUPPLIES INC

Superb Determ Date: Superb Qualified: Transferred:

UST Source:

DHEC Confirmed Release Report

Release No: Substance: **PETRO** 12/30/91 Status: Reported: NFA: 10/09/92 Confirmed: 12/30/91 Rank: Proj Mgr: STOUDEDW

DΒ Map Key Number of Direction Distance Elev/Diff Site Records (mi/ft) (ft) FOOD SERVICE SUPPLIES INC Score: Tank Owner: Rank Desc: 17 2 of 2 SE 0.49/ 257.36/ PEPPER STREET TRACT **DELISTED** 2,608.85 844 PEPPER ST 11 LST COLUMBIA SC

Delisted Leaking Above Ground Storage Tanks Details

Site ID: 3448 Release No: 1

Project Manager: FORREST CHRIS M

Status: CLOSED Impacted Code: NO

Type:

Release Date: 11/17/2006

Confirmed:

NFA Dt: 2/8/2007

Transfer: Product: Source: Tier:

Truncated Note:

Soil Impact Code:

User Name: FORRESCM

Release Xfer Date:

Suspect NFA Date: 2/8/2007

Release Source Code: Cleanup Complete Dt:

Local Fac Last Name: PEPPER STREET TRACT

Local Fac First Name:

Address 2:

State Code:SCCounty:Richland

Zip Code:

Local Fac County: 40
District Code: 5

Rp Identifier 1: BURGESS Rp Identifier 2: RICHARD

Product 2: Product 3: Product 4: Source 2: Source 3: Source 4:

Original Source: LAST

Record Date: 02-DEC-2019

18 1 of 2 W 0.50 / 252.25 / GOLD CIRCLE STORE LUST 2,631.48 5 6000 GARNERS FERRY RD COLUMBIA SC 29209

Operator Phone:

Order No: 22071200085

Site ID: 11486 Search County: RICHLAND

Site No (EFIS): UST-11486 County Code: 40

Permit:N 11486Facility (Web):GOLD CIRCLE STORENo of Tanks:6Fac Street (Web):6000 GARNERS FERRY RD

Facilit City (Web): 6 **COLUMBIA** Abandoned: Billable: 0 Facility St (Web): SC Other: 0 Fac County (Web): Richland 29209 Last Inspection: Facility Zip (Web): Land Owner Phone:

Phone: Facil City (EFIS): COLUMBIA

Facil State (EFÍS): SC Tank Owner Phone: 614-438-5255

Facil Zip (EFIS): 29209

Facility Link: https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/11486

DΒ Map Key Number of Direction Distance Elev/Diff Site Records (mi/ft) (ft)

Facil Name (EFIS): **GOLD CIRCLE STORE** Facil Address (EFIS): 6000 GARNERS FERRY RD

Category:

Business Address: 6000 GARNERS FERRY RD

COLUMBIA SC 29209

Land Owner Business Addr:

Operator Business Addr: Tank Owner Business Addr:

GOLD CIRCLE STORES

PO BOX 63

WORTHINGTON OH 43085-0063

Data Source: DHEC Online Registry - Release Report; DHEC Confirmed Release Report (LUST); DHEC EFIS Data Delivery

Prohibition list

DHEC Online Registry - Release Report

Release No:

ABERNATHY, JOHN D Project Manager:

Reported: 4/11/1989 Confirmed: 3/16/1992

RBCA/ Score: 4BC - GW < 15 feet in silt or clay / 46 Product:

Compliance Req: False NFA: 10/24/2003 Fin Type: With SUPERB

Fin Res Mechanism:

Abatement Met: 12/31/1987 Cleanup Initiated: 3/16/1992

Cleanup Complete:

Cleanup MCL: 7/9/2003

Compliance Date:

Compliance Met: False

Emergency Resp:

GOLD CIRCLE STORES Responsible Party:

Superb Determ Date: Superb Qualified: Transferred:

Source: UST

DHEC Confirmed Release Report

Substance: **PETRO** Release No: 1 Status: Reported: 04/11/89 10/24/03 NFA: Confirmed: 03/16/92 Rank: 4BC Proj Mgr: **ABERNAJD GOLD CIRCLE STORES**

Tank Owner:

Order No: 22071200085

Score: 46

GW < 15 feet in silt or clay Rank Desc:

DHEC EFIS Data Details

Release No:

4/11/1989 Release Date: Project Mgr: WS Confirmed Date: 3/16/1992

Cleanup Comp Date:

Cleanup Comp Mcl Dt: 7/9/2003

GOLD C STORES Rp Name: Rp Address: PO BOX 63 Rp City: WORTHINGTON

Rp State: OH Rp Zip: 43085-0063 Sstl Estab Code: MR Scrbca Class Code: CLASS4BC

Depth to GW: 20 **GW Flow Dir Code:** S

Receptor Type Code: ABERNATHY, JOHN D

Rel Fin Type Cd:

| Map Key | Number of Records | Direction | Distance (mi/ft) | Elev/Diff (ft) | Site | DB |
|-------------|----------------------|------------|---------------------|-------------------|---|-----|
| CoC Concer | ntrate Cd: | | | | | |
| <u>18</u> | 2 of 2 | W | 0.50 / 2,631.48 | 252.25 / 5 | GOLD CIRCLE STORE 6000 GARNERS FERRY RD COLUMBIA SC 29209 | RCR |
| Site ID: | | 11486 | | | | |
| REL: | | 1 | | | | |
| Tax Map ID: | | 1371-01-09 | | | | |
| Reported: | | 04/11/89 | | | | |
| CU>MCL: | | 07/09/03 | | | | |
| Latitude: | | 33.98193 | | | | |
| Longitude: | | -80.96689 | | | | |

Order No: 22071200085

Unplottable Summary

Total: 5 Unplottable sites

| DB | Company Name/Site Name | Address | City | Zip | ERIS ID |
|--------------|----------------------------|---|--------------------|-------|-----------|
| DELISTED LST | SOUTHERN BELLHAMPTON ST | HAMPTON | COLUMBIA SC | | 875011209 |
| DELISTED LST | MCCARTHY PROPERTY | CEDAR TERRACE | COLUMBIA SC | | 875013135 |
| DELISTED LST | SAN JOSE | GARNERS FERRY RD | COLUMBIA SC | | 875014098 |
| DELISTED LST | FTJAX/750 GALLON HO UST | HAMPTON PKWY | FORT JACKSON SC | | 875014391 |
| LUST | OAKRIDGE ASSOCIATION | GARNERS FERRY RD | HOPKINS SC | 29290 | 822812108 |
| | | Site ID Permit: 16703 N 16703 NFA: 4/7/1995 | | | |

Order No: 22071200085

Unplottable Report

SOUTHERN BELLHAMPTON ST Site:

DELISTED LST HAMPTON COLUMBIA SC

Delisted Leaking Above Ground Storage Tanks Details

Site ID: 14625

Release No:

Project Manager: LANDMEYER DOLORES C

CLOSED Status: Impacted Code: NO

Type:

Release Date: Confirmed:

NFA Dt: 6/28/1995

Transfer: Product: Source: Tier:

Truncated Note: Soil Impact Code:

User Name: LANDMEDC

Release Xfer Date:

Suspect NFA Date: 6/28/1995

Release Source Code: Cleanup Complete Dt:

Local Fac Last Name: SOUTHERN BELLHAMPTON ST

Local Fac First Name:

Address 2:

SC State Code: Richland County: Zip Code:

40 Local Fac County: District Code:

PATRICK CONSTRUCTION Rp Identifier 1:

Rp Identifier 2: Product 2: Product 3: Product 4: Source 2: Source 3: Source 4:

LAST

Original Source: 02-DEC-2019 Record Date:

Site: MCCARTHY PROPERTY

DELISTED LST CEDAR TERRACE COLUMBIA SC

Order No: 22071200085

Delisted Leaking Above Ground Storage Tanks Details

Site ID: 16592 Release No:

Project Manager: **BUCKLIN CHRISTINE F**

Status:

Impacted Code: NO

Type: Release Date: Confirmed:

NFA Dt: 5/2/1996

Transfer: Product: Source: Tier:

Truncated Note:

Soil Impact Code:

BUCKLICF User Name:

Release Xfer Date:

Suspect NFA Date: 5/2/1996

Release Source Code: Cleanup Complete Dt:

Local Fac Last Name:

MCCARTHY PROPERTY

Local Fac First Name:

Address 2: State Code: SC Richland County: 29209 Zip Code: Local Fac County: 40 District Code:

MCCARTHY PROPERTY Rp Identifier 1:

Rp Identifier 2: Product 2: Product 3: Product 4: Source 2: Source 3: Source 4:

Original Source: LAST

Record Date: 02-DEC-2019

SAN JOSE Site:

GARNERS FERRY RD COLUMBIA SC

DELISTED LST

Order No: 22071200085

Delisted Leaking Above Ground Storage Tanks Details

Site ID: 17027

Release No:

Project Manager: LANDMEYER DOLORES C

Status: **TRANSFER**

Impacted Code: YES

Type:

Release Date: Confirmed: NFA Dt:

11/15/1995 Transfer:

Product: Source: Tier:

Truncated Note:

Soil Impact Code:

User Name: LANDMEDC Release Xfer Date: 11/15/1995

Suspect NFA Date: Release Source Code: Cleanup Complete Dt:

Local Fac Last Name: SAN JOSE

Local Fac First Name:

Address 2:

State Code: SC County: Richland Zip Code: 29209 Local Fac County: 40 District Code: 5 Rp Identifier 1: **LEON** Rp Identifier 2: **GREGORIO**

Product 2:

Product 3:

Product 4: Source 2: Source 3: Source 4:

Original Source: LAST Record Date: 02-DEC-2019

FTJAX/750 GALLON HO UST Site:

HAMPTON PKWY FORT JACKSON SC

DELISTED LST

LUST

Order No: 22071200085

Delisted Leaking Above Ground Storage Tanks Details

Site ID: 2421 Release No:

BISHOP MICHAEL A Project Manager:

Status: CLOSED Impacted Code: NO

Type:

5/19/2003 Release Date: Confirmed: 5/19/2003 NFA Dt: 10/10/2003

Transfer:

PETRO Product:

Source: Tier:

Truncated Note:

Soil Impact Code:

BISHOPMA User Name:

Release Xfer Date:

Suspect NFA Date: 10/10/2003

Release Source Code:

Cleanup Complete Dt:

FTJAX/750 GALLON HO UST Local Fac Last Name:

Local Fac First Name:

Address 2:

SC State Code: Richland County: Zip Code: 29207 Local Fac County: 40

District Code:

FORT JACKSON Rp Identifier 1:

Rp Identifier 2: Product 2: Product 3: Product 4: Source 2: Source 3: Source 4:

LAST Original Source:

Record Date: 02-DEC-2019

Site: **OAKRIDGE ASSOCIATION**

GARNERS FERRY RD HOPKINS SC 29290

RICHLAND Site ID: 16703 Search County:

Site No (EFIS): County Code: 40

N 16703 OAKRIDGE ASSOCIATION Permit: Facility (Web): No of Tanks: Fac Street (Web): GARNERS FERRY RD 1

HOPKINS Abandoned: Facilit City (Web): 1 Billable: 0 Facility St (Web): SC Other: 0 Fac County (Web): Richland Facility Zip (Web): Last Inspection: 29290

Land Owner Phone: Phone: Facil City (EFIS): Operator Phone: Facil State (EFIS): Tank Owner Phone: Facil Zip (EFIS):

https://apps.dhec.sc.gov/Environment/USTRegistry/Registry/Details/16703 Facility Link:

Facil Name (EFIS): Facil Address (EFIS):

Category: Retail Sales

Business Address: GARNERS FERRY RD HOPKINS SC 29290

Land Owner Business Addr: Operator Business Addr:

Tank Owner Business Addr: OAKRIDGE ASSOCIATION INC

PO BOX 9888

COLUMBIA SC 29290

Data Source: DHEC Online Registry - Release Report; DHEC Confirmed Release Report (LUST)

DHEC Online Registry - Release Report

Release No:

Project Manager:MINER, READ SReported:6/28/1993Confirmed:6/28/1993

RBCA/ Score:

Product:

Compliance Req:FalseNFA:4/7/1995Fin Type:Unknown

Fin Res Mechanism:

Abatement Met:

Cleanup Initiated:4/7/1995Cleanup Complete:4/7/1995

Cleanup MCL:

Compliance Date:

Compliance Met: False

Emergency Resp:

Responsible Party: OAKRIDGE ASSOCIATION INC

Superb Determ Date: Superb Qualified: Transferred:

Source: UST

DHEC Confirmed Release Report

 Release No:
 1
 Substance:
 PETRO

 Status:
 Reported:
 06/28/93

 NFA:
 04/07/95
 Confirmed:
 06/28/93

 Rank:
 Proj Mgr:
 MINERRS

Score: Tank Owner: OAKRIDGE ASSOCIATION INC

Order No: 22071200085

Rank Desc:

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13 and E1527-21, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

Formerly Utilized Sites Remedial Action Program:

DOE FUSRAP

Order No: 22071200085

The U.S. Department of Energy (DOE) established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from the Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations. The DOE Office of Legacy Management (LM) established long-term surveillance and maintenance (LTS&M) requirements for remediated FUSRAP sites. DOE evaluates the final site conditions of a remediated site on the basis of risk for different future uses. DOE then confirms that LTS&M requirements will maintain protectiveness.

Government Publication Date: Mar 4, 2017

National Priority List:

Sites on the United States Environmental Protection Agency (EPA)'s National Priorities List of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. The NPL, which EPA is required to update at least once a year, is based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Mar 30, 2022

National Priority List - Proposed: PROPOSED NPL

Sites proposed - by the EPA, the state agency, or concerned citizens - for addition to the NPL due to contamination by hazardous waste and identified by the Environmental Protection Agency (EPA) as a candidate for cleanup because it poses a risk to human health and/or the environment. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Mar 30, 2022

Deleted NPL: DELETED NPL

Sites deleted from the United States Environmental Protection Agency (EPA)'s National Priorities List. The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Mar 30, 2022

SEMS List 8R Active Site Inventory:

SEMS

The Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted.

Government Publication Date: Apr 27, 2022

SEMS List 8R Archive Sites:

SEMS ARCHIVE

The Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time.

Government Publication Date: Apr 27, 2022

Inventory of Open Dumps, June 1985:

ODI

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

EPA Report on the Status of Open Dumps on Indian Lands:

IODI

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (Al/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

<u>Comprehensive Environmental Response, Compensation and Liability Information System-CERCLIS:</u>

CERCLIS

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

CERCLIS - No Further Remedial Action Planned:

CERCLIS NFRAP

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS LIENS CERCLIS LIENS

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA). This database was provided by the United States Environmental Protection Agency (EPA). Refer to SEMS LIEN as the current data source for Superfund Liens.

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action:

RCRA CORRACTS

Order No: 22071200085

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Apr 11, 2022

RCRA non-CORRACTS TSD Facilities:

RCRA TSD

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites listed as treatment, storage and/or disposal facilities of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Government Publication Date: Apr 11, 2022

RCRA Generator List:

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste.

Government Publication Date: Apr 11, 2022

RCRA Small Quantity Generators List:

RCRA SQG

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month.

Government Publication Date: Apr 11, 2022

RCRA Very Small Quantity Generators List:

RCRA VSQG

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Apr 11, 2022

RCRA Non-Generators: RCRA NON GEN

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Apr 11, 2022

RCRA Sites with Controls:

List of Resource Conservation and Recovery Act (RCRA) facilities with institutional controls in place. RCRA gives the U.S. Environmental Protection Agency (EPA) the authority to control hazardous waste from the "cradle-to-grave." This includes the generation, transportation, treatment, storage, and disposal of hazardous waste. RCRA also set forth a framework for the management of non-hazardous solid wastes. The 1986 amendments to RCRA enabled EPA to address environmental problems that could result from underground tanks storing petroleum and other hazardous substances.

Government Publication Date: Apr 11, 2022

Federal Engineering Controls-ECs:

FED ENG

Engineering controls (ECs) encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Dec 30, 2021

Federal Institutional Controls- ICs:

FED INST

Order No: 22071200085

Institutional controls are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's (United States Environmental Protection Agency) expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site.

Government Publication Date: Dec 30, 2021

Land Use Control Information System:

LUCIS

The LUCIS database is maintained by the U.S. Department of the Navy and contains information for former Base Realignment and Closure (BRAC) properties across the United States.

Government Publication Date: Sep 1, 2006

Institutional Control Boundaries at NPL sites:

NPLIC

Boundaries of Institutional Control areas at sites on the United States Environmental Protection Agency (EPA)'s National Priorities List, or Proposed or Deleted, made available by the EPA's Shared Enterprise Geodata and Services (SEGS). United States Environmental Protection Agency (EPA)'s National Priorities List of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. Institutional controls are non-engineered instruments such as administrative and legal controls that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy.

Government Publication Date: Mar 30, 2022

Emergency Response Notification System:

ERNS 1982 TO 1986

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System:

ERNS 1987 TO 1989

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System:

ERNS

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Jun 5, 2022

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database:

FED BROWNFIELDS

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Aug 20, 2021

FEMA Underground Storage Tank Listing:

FEMA UST

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks

Government Publication Date: Dec 31, 2017

Facility Response Plan:

FRP

List of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Dec 31, 2021

Delisted Facility Response Plans:

DELISTED FRP

Order No: 22071200085

Facilities that once appeared in - and have since been removed from - the list of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Dec 31, 2021

HIST GAS STATIONS
HIST GAS STATIONS

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries:

List of petroleum refineries from the U.S. Energy Information Administration (EIA) Refinery Capacity Report. Includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year located in the 50 States, the District of Columbia, Puerto Rico, the Virgin Islands, Guam, and other U.S. possessions. Survey locations adjusted using public data.

Government Publication Date: Feb 4, 2022

Petroleum Product and Crude Oil Rail Terminals:

BULK TERMINAL

List of petroleum product and crude oil rail terminals made available by the U.S. Energy Information Administration (EIA). Includes operable bulk petroleum product terminals located in the 50 States and the District of Columbia with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil that were active between 2017 and 2018. Petroleum product terminals comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings. Survey locations adjusted using public data.

Government Publication Date: Feb 4, 2022

<u>LIEN on Property:</u> SEMS LIEN

The EPA Superfund Enterprise Management System (SEMS) provides LIEN information on properties under the EPA Superfund Program. Government Publication Date: Apr 27, 2022

Superfund Decision Documents:

SUPERFUND ROD

This database contains a listing of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD), along with other associated memos and files. This information is maintained and made available by the US EPA (Environmental Protection Agency).

Government Publication Date: May 3, 2022

State

<u>State Remediation Projects:</u>

REMEDIATION

A list of state remediation projects key documents from the South Carolina Department of Health and Environmental Control (DHEC) State Superfund Program. The State Superfund Program aims to protect the environment through investigation and clean up of abandoned and uncontrolled hazardous waste sites.

Government Publication Date: May 19, 2022

Permitted Landfills List: SWF/LF

The Department of Health and Environmental Control's (DHEC) Division of Mining and Solid Waste Permitting Section manages a list of permitted solid waste and landfill facilities in South Carolina.

Government Publication Date: Mar 24, 2022

Site Assessment Section Project List:

SASPL

The South Carolina Department of Health and Environmental Control (DHEC) Bureau of Land & Waste Management, Division of Site Assessment, Remediation, and Revitalization keeps record of the state hazardous waste sites in their Site Assessment Section Project List. Includes sites that have had or have ongoing assessment and/or remediation; sites assessed under CERCLA and state authority, as well as federal and state Superfund sites; sites within the Drycleaning Restoration Trust Fund; and state voluntary cleanups sites and Brownfields sites.

Government Publication Date: Jun 2, 2022

Delisted Site Assessment Section Project List:

DELISTED SHWS

Order No: 22071200085

This database contains a list of hazardous waste sites that been removed from the South Carolina Department of Health and Environmental Control (DHEC) Bureau of Land & Waste Management Site Assessment Section.

Government Publication Date: May 19, 2022

Leaking Underground Storage Tank List:

LUST

List of incidents involving releases from underground storage tanks reported to the Department of Health & Environmental Control (DHEC), including locations from the Underground Storage Tank Division's UST Registry Search with confirmed or unconfirmed releases.

Government Publication Date: Apr 27, 2022

Release Incidents - Groundwater Tracking:

LAST

A listing of incidents involving petroleum releases from unregulated sources such as aboveground storage tanks, heating oil tanks and spills during transport reported to the Department of Health & Environmental Control (DHEC).

Government Publication Date: Mar 23, 2022

Delisted Leaking Storage Tanks:

DELISTED LST

List of sites that once appeared on – and have since been removed from – the list of Leaking Aboveground Storage Tanks and/or the list of Leaking Underground Storage Tanks made available by the South Carolina Department of Health and Environmental Control (DHEC).

Government Publication Date: Apr 27, 2022

Underground Storage Tank List:

UST

The Underground Storage Tank Division of the Department of Health and Environmental Control (DHEC) manages a list of permitted underground storage tank sites.

Government Publication Date: Apr 27, 2022

Aboveground Storage Tanks (SCDA):

AST

A list of aboveground storage tanks made available by South Carolina Department of Agriculture (SCDA).

Government Publication Date: Apr 12, 2022

Aboveground Storage Tanks (SC State Fire):

AST SFM

A list of aboveground storage tanks known to South Carolina Department of Labor, Licensing and Regulation's Office of State Fire Marshal. The status of tanks on this list is unknown, as State Fire approves plans for ASTs prior to construction.

Government Publication Date: Sep 19, 2017

Delisted Underground Storage Tanks:

DELISTED TANKS

This database contains a list of storage tank sites that were removed from the Division of the Department of Health and Environmental Control (DHEC). Government Publication Date: Apr 27, 2022

Registry of Conditional Remedies:

RCR

A Conditional Remedy is an environmental remedy that includes certain qualifications. These qualifications are divided into two major categories: Remedies requiring Land Use Controls and Conditional No Further Actions (CNFA). This registry is managed by the Department of Health and Environmental Control (DHEC) and does not include UST sites where a No Further Action (NFA) letter was issued.

Government Publication Date: Jun 9, 2022

Site Assessment and Remediation Public Record Database:

VCP

The Site Assessment and Remediation Public Record Database identifies brownfield sites for potential redevelopment and sites undergoing cleanup activities and assessment. This database is managed by the Site Assessment Remediation & Revitalization Division of the South Carolina Department of Health and Environmental Control (DHEC).

Government Publication Date: May 19, 2022

Brownfields Sites Listing:

BROWNFIELDS

The South Carolina Department of Health and Environmental Control (DHEC) manages the Brownfield/Cleanup Program and maintains a list of Brownfield sites.

Government Publication Date: May 23, 2022

<u>Tribal</u>

Leaking Underground Storage Tanks (LUSTs) on Indian Lands:

INDIAN LUST

Order No: 22071200085

LUSTs on Tribal/Indian Lands in Region 4, which includes South Carolina. There are no LUST records in South Carolina at this time.

Government Publication Date: Oct 14, 2017

Underground Storage Tanks (USTs) on Indian Lands:

INDIAN UST

USTs on Tribal/Indan Lands in Region 4, which includes South Carolina. There are no UST records in South Carolina at this time.

Government Publication Date: Oct 14, 2017

Delisted Tribal Leaking Storage Tanks:

DELISTED ILST

Leaking Underground Storage Tank facilities which have been removed from the Regional Tribal LUST lists made available by the EPA. Government Publication Date: Apr 28, 2022

Delisted Tribal Underground Storage Tanks:

DELISTED IUST

Underground Storage Tank facilities which have been removed from the Regional Tribal UST lists made available by the EPA.

Government Publication Date: Apr 28, 2022

County

No County standard environmental record sources available for this State.

Additional Environmental Record Sources

Federal

Facility Registry Service/Facility Index:

FINDS/FRS

The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the Environmental Protection Agency (US EPA).

Government Publication Date: Nov 2, 2020

Toxics Release Inventory (TRI) Program:

TRIS

The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U. S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment.

Government Publication Date: Aug 24, 2021

Perfluorinated Alkyl Substances (PFAS) Releases:

PFAS TRI

List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a Per- or polyfluorinated alkyl substance (PFAS) included in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances. The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment.

Government Publication Date: Aug 24, 2021

PFOA/PFOS Contaminated Sites:

PFAS NPL

List of National Priorities List (NPL) and related Superfund Alternative Agreement (SAA) sites where PFOA or PFOS contaminants have been found in water and/or soil. The site listing is provided by the Federal Environmental Protection Agency (EPA).

Government Publication Date: Apr 15, 2022

Perfluorinated Alkyl Substances (PFAS) Water Quality:

PFAS WATER

The Water Quality Portal (WQP) is a cooperative service sponsored by the United States Geological Survey (USGS), the Environmental Protection Agency (EPA), and the National Water Quality Monitoring Council (NWQMC). This listing includes records from the Water Quality Portal where the characteristic (environmental measurement) is in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances. *Government Publication Date: Jul 20, 2020*

SSEHRI PFAS Contamination Sites:

PFAS SSEHRI

Order No: 22071200085

This PFAS Contamination Site Tracker database is compiled by the Social Science Environmental Health Research Institute (SSEHRI) at Northeastern University. According to the SSEHRI, the database records qualitative and quantitative data from each known site of PFAS contamination, including timeline of discovery, sources, levels, health impacts, community response, and government response. The goal of this database is to compile information and support public understanding of the rapidly unfolding issue of PFAS contamination. All data presented was extracted from government websites, news articles, or publicly available documents, and this is cited in the tracker. Disclaimer: The source conveys this database undergoes regular updates as new information becomes available, some sites may be missing and/or contain information that is incorrect or outdated, as well as their information represents all contamination sites SSEHRI is aware of, not all possible contamination sites. This data is not intended to be used for legal purposes. Limited location details are available with this data. Access the following for the most current informations https://pfasproject.com/pfascontamination-site-tr acker/

Government Publication Date: Dec 12, 2019

National Response Center PFAS Spills:

FRNS PFAS

National Response Center (NRC) calls from 1990 to the most recent complete calendar year where there is indication of Aqueous Film Forming Foam (AFFF) usage. NRC calls may reference AFFF usage in the "Material Involved" or "Incident Description" fields. Data made available by the US Environmental Protection Agency (EPA). Disclaimer: dataset may include initial or misidentified incident data not yet validated or investigated by a federal/state response agency.

Government Publication Date: Feb 23, 2022

Hazardous Materials Information Reporting System:

HMIRS

US DOT - Department of Transportation Pipeline and Hazardous Materials Safety Administration (PHMSA) Incidents Reports Database taken from Hazmat Intelligence Portal, U.S. Department of Transportation.

Government Publication Date: Sep 1, 2020

National Clandestine Drug Labs:

NCDL

The U.S. Department of Justice ("the Department") provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.

Government Publication Date: Apr 30, 2022

Toxic Substances Control Act:

TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.

The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI).

Government Publication Date: Apr 11, 2019

HIST TSCA:

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.

The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.

Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing:

FTTS ADMIN

An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing:

FTTS INSP

Order No: 22071200085

An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List:

PRP

Early in the cleanup process, the Environmental Protection Agency (EPA) conducts a search to find the potentially responsible parties (PRPs). EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site.

Government Publication Date: May 25, 2022

State Coalition for Remediation of Drycleaners Listing:

SCRD DRYCLEANER

The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin. Since 2017, the SCRD no longer maintains this data, refer to applicable state source data where available.

Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS):

ICIS

The Integrated Compliance Information System (ICIS) is a system that provides information for the Federal Enforcement and Compliance (FE&C) and the National Pollutant Discharge Elimination System (NPDES) programs. The FE&C component supports the Environmental Protection Agency's (EPA) Civil Enforcement and Compliance program activities. These activities include Compliance Assistance, Compliance Monitoring and Enforcement. The NPDES program supports tracking of NPDES permits, limits, discharge monitoring data and other program reports.

Government Publication Date: Apr 30, 2022

<u>Drycleaner Facilities:</u> FED DRYCLEANERS

A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) online search. The Environmental Protection Agency (EPA) tracks facilities that possess NAIC and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: May 5, 2021

<u>Delisted Drycleaner Facilities:</u>

DELISTED FED DRY

List of sites removed from the list of Drycleaner Facilities (sites in the EPA's Integrated Compliance Information System (ICIS) with NAIC or SIC codes identifying the business as a drycleaner establishment).

Government Publication Date: May 5, 2021

Formerly Used Defense Sites:

Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DoD) is responsible for an environmental restoration. This list is published by the U.S. Army Corps of Engineers.

Government Publication Date: May 26, 2021

Former Military Nike Missile Sites:

FORMER NIKE

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 2, 1984

PHMSA Pipeline Safety Flagged Incidents:

PIPELINE INCIDENT

Order No: 22071200085

A list of flagged pipeline incidents made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types.

Government Publication Date: Jul 7, 2020

Material Licensing Tracking System (MLTS):

MLTS

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: May 11, 2021

Historic Material Licensing Tracking System (MLTS) sites:

HIST MLTS

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File: MINES

The Master Index File (MIF) contains mine identification numbers issued by the Department of Labor Mine Safety and Health Administration (MSHA) for mines active or opened since 1971. Note that addresses may or may not correspond with the physical location of the mine itself.

Government Publication Date: Feb 1, 2022

Surface Mining Control and Reclamation Act Sites:

SMCRA

MRDS

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by the Office of Surface Mining Reclamation and Enforcement (OSMRE) to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of Abandoned Mine Land (AML) impacts, as well as information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Government Publication Date: Feb 22, 2022

Mineral Resource Data System:

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2016

Uranium Mill Tailings Radiation Control Act Sites:

URANIUM

The Legacy Management Office of the Department of Energy (DOE) manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The L.M. Office manages this database of sites registered under the Uranium Mill Tailings Control Act (UMTRCA).

Government Publication Date: Mar 4, 2017

Alternative Fueling Stations:

List of alternative fueling stations made available by the US Department of Energy's Office of Energy Efficiency & Renewable Energy. Includes Biodiesel stations, Ethanol (E85) stations, Liquefied Petroleum Gas (Propane) stations, Ethanol (E85) stations, Natural Gas stations, Hydrogen stations, and Electric Vehicle Supply Equipment (EVSE). The National Renewable Energy Laboratory (NREL) obtains information about new stations from trade media, Clean Cities coordinators, a Submit New Station form on the Station Locator website, and through collaborating with infrastructure equipment and fuel providers, original equipment manufacturers (OEMs), and industry groups.

Government Publication Date: May 16, 2022

Superfunds Consent Decrees:

CONSENT DECREES

Order No: 22071200085

A list of Superfund consent decrees made available by the Department of Justice, Environment & Natural Resources Division (ENRD).

Government Publication Date: May 18, 2022

AFS AFS

This EPA retired Air Facility System (AFS) dataset contains emissions, compliance, and enforcement data on stationary sources of air pollution. Regulated sources cover a wide spectrum; from large industrial facilities to relatively small operations such as dry cleaners. AFS does not contain data on facilities that are solely asbestos demolition and/or renovation contractors, or landfills. ECHO Clean Air Act data from AFS are frozen and reflect data as of October 17, 2014; the EPA retired this system for Clean Air Act stationary sources and transitioned to ICIS-Air.

Government Publication Date: Oct 17, 2014

Registered Pesticide Establishments:

SSTS

List of active EPA-registered foreign and domestic pesticide-producing and device-producing establishments based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that facilities producing pesticides, active ingredients, or devices be registered. The list of establishments is made available by the EPA.

Government Publication Date: Mar 30, 2022

Polychlorinated Biphenyl (PCB) Transformers:

PCBT

Locations of Transformers Containing Polychlorinated Biphenyls (PCBs) registered with the United States Environmental Protection Agency. PCB transformer owners must register their transformer(s) with EPA. Although not required, PCB transformer owners who have removed and properly disposed of a registered PCB transformer may notify EPA to have their PCB transformer de-registered. Data made available by EPA.

Government Publication Date: Oct 15, 2019

Polychlorinated Biphenyl (PCB) Notifiers:

PCB

Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.

Government Publication Date: Jan 20, 2022

State

SPILLS SPILLS

A list of spills and releases managed by the Department of Health and Environmental Control (DHEC).

Government Publication Date: Apr 1, 2022

Drycleaning Facility Restoration Trust Fund Database:

DRYCLEANERS

Drycleaning facilities are prone to leaking solvents contaminating the soil under and around the facility. The goal of the Drycleaning Restoration Trust Fund Act is to stop this type of ongoing environmental contamination from drycleaning facilities. This database is maintained by the Department of Health & Environmental Control.

Government Publication Date: Jun 27, 2022

<u>Dry Cleaners:</u> DRY CLEANERS

A list of dry cleaners known to the South Carolina Department of Health and Environmental Control (SC DHEC).

Government Publication Date: Jan 9, 2019

Delisted Drycleaning Facility:

DELISTED DRYCLEANERS

Order No: 22071200085

List of sites removed from the drycleaners facility database made available by the Department of Health & Environmental Control.

Government Publication Date: Jun 27, 2022

Air Permitted Facilities:

The South Carolina Department of Health and Environmental Control's Bureau of Air Quality (BAQ) is responsible for managing South Carolina's air quality permitting program. According to the BAQ, an air permit is a legal document that lists what a source must do in order to comply with the state and federal air pollution laws. The facility's potential to emit emissions determines if a facility is classified as major or minor or if the facility has to undergo a major modification. The BAQ issues construction and operating permits to industrial, commercial, and institutional sources that use or store materials with a potential to emit air pollutants into the air.

Government Publication Date: Jan 13, 2022

Underground Injection Control Wells:

UIC

This list of Underground Injection Control Class V Wells is provided by the South Carolina Department of Health and Environmental Control (DHEC). The majority of Class V Wells are aquifer remediation injection wells, and the remaining are Aquifer Storage and Recovery Wells (storage of potable water in the subsurface).

Government Publication Date: Feb 4, 2022

Agricultural Facilities:

The South Carolina Department of Health and Environmental Control (SCDHEC) provides this agricultural facilities (animal farms) database. SCDHEC makes no warranty, representation or guarantee as to the content, sequence, accuracy, timeliness or completeness of any of the database information provided herein.

Government Publication Date: Jun 18, 2013

Tribal

No Tribal additional environmental record sources available for this State.

County

No County additional environmental record sources available for this State.

Order No: 22071200085

Definitions

<u>Database Descriptions:</u> This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

<u>Detail Report</u>: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

<u>Distance:</u> The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

<u>Elevation:</u> The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

<u>Unplottables:</u> These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

Order No: 22071200085

Date: Thursday, May 10, 2007

From: Randy Nattis

Subject: Removal Site Evaluation

Columbia Organic Chemical Company 912 Drake Street, Columbia, SC

Latitude: 33.9822000 Longitude: -80.9586000

POLREP No.: 1 Site #: A4NH

Reporting Period: D.O. #:

Start Date:Response Authority:CERCLAMob Date:Response Type:Time-CriticalDemob Date:NPL Status:Non NPL

Completion Date: Incident Category: Removal Assessment

CERCLIS ID #: Contract #

RCRIS ID #:

Site Description BACKGROUND

The Columbia Organic Chemical Company (COCC) site is located at 912 Drake Street in Columbia, Richland County, South Carolina. The site is a three acre property surrounded by a mixture of residential and commercial properties. The site is bounded to the northwest by Drake Street, to the southwest by Bruce Street, to the east by residential properties along True Street, and to the north by the former M.B. Kahn Construction Company property. Several multi-unit residences and one single dwelling home are located within 50 yards of the site across Drake Street.

COCC owned and operated a specialty chemical facility from the 1944 until 1984 at which time the operation was relocated to the Cassatt community in Kershaw County, South Carolina. A wide variety of chemicals were produced at the facility, including insecticide formulations, industrial cleaners, and small quantities of specialty chemicals for use in research. Several hundred chemicals were manufactured at the plant. The primary product lines included bromine, iodine substituted aliphatics, mercaptans, alkyl phosphonates, nitriles, and dimethyl sulfide.

The original plant was destroyed by fire in 1958. The plant was subsequently rebuilt on its original location; however, over the years several other fires damaged various parts of the facility. During the course of the facility's operation, soils on the site were contaminated by waste materials which were spilled, dumped, or buried on-site. During the 1970's COCC installed a chemical holding tank, or sump, to collect liquid wastes. Records suggest that much of the waste collected in the tank eventually leaked out.

Current Activities

REMOVAL SITE EVALUATION

EPA Emergency response and removal branch (ERRB), Superfund Technical Assessment Response Team (START) and South Carolina Department of Health and Environmental Control (DHEC) conducted a removal assessment of the 3 acre COCC site during the week of December 4, 2006. A total of 86 soil samples were collected. The results from the sampling event were compared to the Region 9 residential Preliminary Remedial Goals (PRGs) for screen purposes,

except for dioxin, which was compared to the OSWER recommended clean-up standard of 1 ppb (TEQ).

For this evaluation, the data was reviewed and the maximum detected concentrations were compared to the Remedial Action Levels. The Remedial Action Levels were determined by converting the Region 9 PRGs to risk-based concentrations appropriate for time-critical removal actions. The derived RALs are based upon a residential human risk of 1x10-4 for carcinogens and a Hazard Index of 3 for non-carcinogens. The values referenced in OSWER Directive 9200.4-26 were used for screening dioxin contractions.

Based on these methods, it was determined that dioxin levels exceeded the residential RAL in six of the 25 grids established. Analytical results indicate total dioxin as high as 14.8 ppb. The six dioxin-contaminated grid squares cover approximately 37,500 square feet of the property. Contamination of the soil in these six grids squares range from six inches in depth to at least two feet deep in one grid. The estimated volume of dioxin contaminated soil based on the sample results is 1,300 cubic yards. It should be noted that all of the soil dioxin concentrations are within the range if clean-up values referenced in OSWER Directive 9200.4-26 for industrial land use, 5-20 ppb (TEQ).

Planned Removal Actions

RECOMMENDATION

Dioxin is a hazardous substance as defined by section 101(14) of the CERCLA and RCRA characteristic definitions. CERCLA contaminants, if released from the Site, have the capability of presenting a potential hazard to the general public. The threats come primarily from human exposure to these hazardous substances in the soil (i.e. trespassers) as well as a potential for surface or air migration. Direct contact, ingestion, and inhalation of dioxins are the primary pathways of exposure. Continued exposure of the dioxins in the soils may cause potential chronic health effects to persons living nearby and trespassers.

Site conditions meet the requirements for initiating a time-critical removal action according to criteria listed in Section 300.415 (b)(2) of the NCP:

- Section 300.415 (b)(2)(i): "Actual or potential exposure to nearby human populations, animals, or the food chain from hazardous substances or pollutants or contaminants." The site is bounded to the northwest by Drake Street, to the southwest by Bruce Street, to the east by residential properties along True Street, and to the north by the former M.B. Kahn Construction Company property. Several multi-unit residences and one single dwelling home are located within 50 yards of the site across Drake Street. Direct contact, ingestion, and inhalation of these hazardous substances are primary pathways of exposure.
- Section 300.415 (b)(2)(iv): "High levels of hazardous substances or pollutants or contaminants in soils largely at or near the surface, that may migrate." Sample analysis shows that six of the sample grids squares exceed the RALs and pose a threat for both, surface and air migration, through runoff or dust respectively.

Due to the threat and/or future threat to human health from the hazardous substance, the Site achieves removal eligibility base on some or all of the removal criteria in 40 CFR 300.415(b)(2).

Date: Monday, January 28, 2008

From: Randy Nattis

Subject: Initiation of Action

Columbia Organic Chemical Company 912 Drake Street, Columbia, SC

Latitude: 33.9822000 Longitude: -80.9586000

POLREP No.: 2 Site #: A4NH

Reporting Period: 01/07/2008 - 01/28/2008 **D.O.** #:

Start Date:1/7/2008Response Authority:CERCLAMob Date:1/7/2008Response Type:Time-CriticalDemob Date:NPL Status:Non NPLCompletion Date:Incident Category:Removal Action

CERCLIS ID #: Contract #

RCRIS ID #:

Site Description

The Columbia Organic Chemical Company (COCC) site is located at 912 Drake Street in Columbia, Richland County, South Carolina. The site is a three acre property surrounded by a mixture of residential and commercial properties. The site is bounded to the northwest by Drake Street, to the southwest by Bruce Street, to the east by residential properties along True Street, and to the north by the former M.B. Kahn Construction Company property. Several multi-unit residences and one single dwelling home are located within 50 yards of the site across Drake Street.

COCC owned and operated a specialty chemical facility from the 1944 until 1984 at which time the operation was relocated to the Cassatt community in Kershaw County, South Carolina. A wide variety of chemicals were produced at the facility, including insecticide formulations, industrial cleaners, and small quantities of specialty chemicals for use in research. Several hundred chemicals were manufactured at the plant. The primary product lines included bromine, iodine substituted aliphatics, mercaptans, alkyl phosphonates, nitriles, and dimethyl sulfide.

The original plant was destroyed by fire in 1958. The plant was subsequently rebuilt on its original location; however, over the years several other fires damaged various parts of the facility. During the course of the facility's operation, Records suggest that soils on the site were contaminated by waste materials which were spilled, dumped, or buried on-site. Records suggest that during the 1970's COCC installed a chemical holding tank, or sump, to collect liquid wastes. Records suggest that much of the waste collected in the tank eventually leaked out.

Current Activities

Clearing and grubbing the Six (6) cells which will require excavation.

Remove concrete pads within the excavation zone and stage for sampling.

Construct Temporary storage cell for excavated soils

Excavated Grids 5, 10 and 16 and collected conformation samples and expect a 2 week turnaround

To date an estimated 432 cubic yards of soils has been excavated and stockpiled.

Planned Removal Actions

UPCOMING ACTIVITIES

- Provide site security / access control;
- Clear and grub, setup temporary staging for contaminated soils, and support areas;

- Excavation of contaminated grids;
- 1. Perform air monitoring and dust control as needed;
- 2. Sample and profile excavated soils;
- 3. Dispose of contaminated soils offsite;
- Backfill areas with clean soil;
- Install erosion control; and
- Provide post-closure site controls, i.e., signage, deed restrictions, etc

Next Steps

Continue Excavation of Grids 4, 6, and 15

Determine total volume of soil excavated for T&D

Key Issues

Public Meeting held on January 17, 2008

Any unexpected unearthed wasted during excavation of contaminated grids

Removing and sampling the concrete from the pads within the contaminated grids as well as the soil underneath the concrete pads. Results can drastically change the cost of T&D.

Off site disposal of excavated soils

Date: Monday, March 17, 2008

From: Randy Nattis

Subject: Columbia Organic Chemical Company

912 Drake Street, Columbia, SC

Latitude: 33.9822000 Longitude: -80.9586000

POLREP No.: 3 Site #: A4NH

Reporting Period: D.O. #:

Start Date:1/7/2008Response Authority:CERCLAMob Date:1/7/2008Response Type:Time-CriticalDemob Date:NPL Status:Non NPLCompletion Date:Incident Category:Removal Action

CERCLIS ID #: Contract #

RCRIS ID #:

Site Description

The Columbia Organic Chemical Company (COCC) site is located at 912 Drake Street in Columbia, Richland County, South Carolina. The site is a three acre property surrounded by a mixture of residential and commercial properties. The site is bounded to the northwest by Drake Street, to the southwest by Bruce Street, to the east by residential properties along True Street, and to the north by the former M.B. Kahn Construction Company property. Several multi-unit residences and one single dwelling home are located within 50 yards of the site across Drake Street.

COCC owned and operated a specialty chemical facility from the 1944 until 1984 at which time the operation was relocated to the Cassatt community in Kershaw County, South Carolina. A wide variety of chemicals were produced at the facility, including insecticide formulations, industrial cleaners, and small quantities of specialty chemicals for use in research. Several hundred chemicals were manufactured at the plant. The primary product lines included bromine, iodine substituted aliphatics, mercaptans, alkyl phosphonates, nitriles, and dimethyl sulfide.

The original plant was destroyed by fire in 1958. The plant was subsequently rebuilt on its original location; however, over the years several other fires damaged various parts of the facility. During the course of the facility's operation, Records suggest that soils on the site were contaminated by waste materials which were spilled, dumped, or buried on-site. Records suggest that during the 1970's COCC installed a chemical holding tank, or sump, to collect liquid wastes. Records suggest that much of the waste collected in the tank eventually leaked out.

Current Activities

Based on the Removal Site Evaluation (RSE), six (6) dioxin contaminated grids were excavated to varied depths and stockpiled on site waiting for confirmation excavation sample results. Based on the analytical results of the confirmation samples, further excavations will be required. 5 side wall samples and 2 areas underneath removed concrete pads are above the Removal Action Limit (RAL) of 1 part per billion (ppb). During the removal action, a number of amber jars, 1 drum and 1 cylinder were unearthed. The cylinder was empty as well as the drum, but the amber jars contain an unknown liquid. There was staining around jars as well as an over powering odor. The liquid and the soil around the jars were sampled and sent off for analysis.

Planned Removal Actions

Further assessment will be required to address the 5 side wall samples. The sidewall locations are adjacent to the M.B. Kahn Construction property which was found to be below the RAL during the RSE. Once the reminder of all the dioxin contaminated soils are excavated, the off site disposal will begin. At the completion of disposal, further assessments may be needed based on the results of the soil and liquid waste samples in and around the amber jars found during the excavation. There has been a lot of hearsay of widespread illegal dumping / burial on site and possibly the M.B. Kahn Construction property, therefore, a geophysical survey and possibly trenching may be necessary.

Next Steps

Waiting on sample results.

A public meeting is tentatively planned for April 15th.

Key Issues

Unknown wastes in unearthed Jars.

Date: Monday, April 28, 2008

From: Randy Nattis

Subject: Columbia Organic Chemical Company

912 Drake Street, Columbia, SC

Latitude: 33.9822000 Longitude: -80.9586000

POLREP No.: 4 Site #: A4NH

Reporting Period: D.O. #:

Start Date:1/7/2008Response Authority:CERCLAMob Date:1/7/2008Response Type:Time-CriticalDemob Date:NPL Status:Non NPLCompletion Date:Incident Category:Removal Action

CERCLIS ID #: Contract #

RCRIS ID #:

Site Description

The Columbia Organic Chemical Company (COCC) site is located at 912 Drake Street in Columbia, Richland County, South Carolina. The site is a three acre property surrounded by a mixture of residential and commercial properties. The site is bounded to the northwest by Drake Street, to the southwest by Bruce Street, to the east by residential properties along True Street, and to the north by the former M.B. Kahn Construction Company property. Several multi-unit residences and one single dwelling home are located within 50 yards of the site across Drake Street.

COCC owned and operated a specialty chemical facility from the 1944 until 1984 at which time the operation was relocated to the Cassatt community in Kershaw County, South Carolina. A wide variety of chemicals were produced at the facility, including insecticide formulations, industrial cleaners, and small quantities of specialty chemicals for use in research. Several hundred chemicals were manufactured at the plant. The primary product lines included bromine, iodine substituted aliphatics, mercaptans, alkyl phosphonates, nitriles, and dimethyl sulfide.

The original plant was destroyed by fire in 1958. The plant was subsequently rebuilt on its original location; however, over the years several other fires damaged various parts of the facility. During the course of the facility's operation, Records suggest that soils on the site were contaminated by waste materials which were spilled, dumped, or buried on-site. Records suggest that during the 1970's COCC installed a chemical holding tank, or sump, to collect liquid wastes. Records suggest that much of the waste collected in the tank eventually leaked out.

Current Activities

Transport and Disposal (T&D) of dioxin contaminated soils started on April 28, 2008. Disposal should last approximately 10 days, weather depending.

Based on the analytical results of the confirmation samples, further excavations will be required. 5 side wall samples and 2 areas underneath removed concrete pads are above the Removal Action Limit (RAL) of 1 part per billion (ppb).

During the removal action, a number of amber jars, 1 drum and 1 cylinder were unearthed. The cylinder was empty as well as the drum, but the amber jars contain an unknown liquid. There was staining around jars as well as an over powering odor. The soil around the jars were sampled and sent off for analysis.

Please visit www.epaosc.org/sites/2960/files/clpsummaryreportrev1.pdf

Planned Removal Actions

Based on the results from the samples, a further assessment is warranted and will start after T&D of all dioxin contaminated soils is completed.

Meet with DHEC and community after assessment to discuss findings and discuss further activities if needed. Otherwise, turn the site back over to DHEC.

Key Issues

- -Possible unknown burial areas containing jars, drums and other unknowns.
- -Surface water runoff.
- -Neighborhood safety during excavation and further assessment activities
- -Further environmental assessment of Kahn property by Concurrent Technologies Corporation (Phase 2)
- -Residential neighborhood
- -Groundwater plume

Date: Tuesday, July 1, 2008

From: Randy Nattis

Subject: Clean-up Complete

Columbia Organic Chemical Company 912 Drake Street, Columbia, SC

Latitude: 33.9822000 Longitude: -80.9586000

POLREP No.: 5 **Site #:** A4NH

Reporting Period: D.O. #:

Start Date:1/7/2008Response Authority:CERCLAMob Date:1/7/2008Response Type:Time-CriticalDemob Date:NPL Status:Non NPLCompletion Date:Incident Category:Removal Action

CERCLIS ID #: Contract #

RCRIS ID #:

Site Description

The Columbia Organic Chemical Company (COCC) site is located at 912 Drake Street in Columbia, Richland County, South Carolina. The site is a three acre property surrounded by a mixture of residential and commercial properties. The site is bounded to the northwest by Drake Street, to the southwest by Bruce Street, to the east by residential properties along True Street, and to the north by the former M.B. Kahn Construction Company property. Several multi-unit residences and one single dwelling home are located within 50 yards of the site across Drake Street.

COCC owned and operated a specialty chemical facility from the 1944 until 1984 at which time the operation was relocated to the Cassatt community in Kershaw County, South Carolina. A wide variety of chemicals were produced at the facility, including insecticide formulations, industrial cleaners, and small quantities of specialty chemicals for use in research. Several hundred chemicals were manufactured at the plant. The primary product lines included bromine, iodine substituted aliphatics, mercaptans, alkyl phosphonates, nitriles, and dimethyl sulfide.

The original plant was destroyed by fire in 1958. The plant was subsequently rebuilt on its original location; however, over the years several other fires damaged various parts of the facility. During the course of the facility's operation, Records suggest that soils on the site were contaminated by waste materials which were spilled, dumped, or buried on-site. Records suggest that during the 1970's COCC installed a chemical holding tank, or sump, to collect liquid wastes. Records suggest that much of the waste collected in the tank eventually leaked out.

Current Activities

Transport and Disposal (T&D) of dioxin contaminated soils has been completed.

Based on the results of the analysis from the unearthed jars and drum the OSC determined that further assessment using exploratory trenching was necessary. During the trenching assessment, two additional bottles were found and a continued odor from the soil was noticeable around the four foot to six foot range. The two bottles were sent off for analysis. The results from the bottles showed the contents of the bottles contained pesticides. The trenched areas were covered back up.

The site has been brought back up to grade from the excavation depth using clean off site fill and riprap. Then the excavated areas were re-graded to improve drainage and prevent storm water runoff traveling offsite. The excavated areas were then seeded to prevent soil erosion.

Planned Removal Actions

No further removal actions anticipated at this time.

Next Steps

Based on the observations of the staining of the soils, jars found at depth and the odor of the soils as well

as the known groundwater issues based on the SCDHEC reports and data, the OSC feels that further investigation by the EPA remedial program may be required.

The OSC will refer the site to the EPA Remedial program.

A final POLREP to follow

Key Issues

Groundwater Soil odor and staining at depths below 3 feet Adjoining neighborhood

Date: Thursday, September 11, 2008

From: Randy Nattis

Subject: Final POLREP

Columbia Organic Chemical Company 912 Drake Street, Columbia, SC

Latitude: 33.9822000 Longitude: -80.9586000

POLREP No.: 6 Site #: A4NH

Reporting Period: D.O. #:

Start Date:1/7/2008Response Authority:CERCLAMob Date:1/7/2008Response Type:Time-CriticalDemob Date:6/6/2008NPL Status:Non NPLCompletion Date:Incident Category:Removal Action

CERCLIS ID #: Contract #

RCRIS ID #:

Site Description

The Columbia Organic Chemical Company (COCC) site is located at 912 Drake Street in Columbia, Richland County, South Carolina. The site is a three acre property surrounded by a mixture of residential and commercial properties. The site is bounded to the northwest by Drake Street, to the southwest by Bruce Street, to the east by residential properties along True Street, and to the north by the former M.B. Kahn Construction Company property. Several multi-unit residences and one single dwelling home are located within 50 yards of the site across Drake Street.

COCC owned and operated a specialty chemical facility from the 1944 until 1984 at which time the operation was relocated to the Cassatt community in Kershaw County, South Carolina. A wide variety of chemicals were produced at the facility, including insecticide formulations, industrial cleaners, and small quantities of specialty chemicals for use in research. Several hundred chemicals were manufactured at the plant. The primary product lines included bromine, iodine substituted aliphatics, mercaptans, alkyl phosphonates, nitriles, and dimethyl sulfide.

The original plant was destroyed by fire in 1958. The plant was subsequently rebuilt on its original location; however, over the years several other fires damaged various parts of the facility. During the course of the facility's operation, Records suggest that soils on the site were contaminated by waste materials which were spilled, dumped, or buried on-site. Records suggest that during the 1970's COCC installed a chemical holding tank, or sump, to collect liquid wastes. Records suggest that much of the waste collected in the tank eventually leaked out.

Current Activities

The site has been brought back up to grade from the excavation depth using clean off site fill and riprap. Then the excavated areas were re-graded to improve drainage and prevent storm water runoff traveling offsite. The excavated areas were then seeded to prevent soil erosion.

A total of 1,436.40 tons of soil was removed and disposed of. The final truckload of soil was transported from the site on May 13, 2008.

All site work has been completed.

Planned Removal Actions

The site was referred to the EPA remedial branch. One August 18, 2008, it was determined that no further actions will be taken by EPA

The site has been referred back to SCDHEC

Next Steps

The final removal report will be posted to this website within the next few fews.

APPENDIX E CREDENTIALS

Norman E. (Gene) Partin, Jr., CHMM

DEPARTMENT MANAGER - ENVIRONMENTAL SERVICES

PROFESSIONAL EXPERIENCE

Mr. Partin is the Department Manager for Environmental Services in Terracon's Columbia, South Carolina office and has over 23 years of experience.

Mr. Partin has completed hundreds of Phase I Environmental Site Assessments for a variety of sites in conjunction with lender liability transactions. He has managed and performed numerous Phase II assessments to include soil and ground water contamination investigations associated with UST, industrial, and commercial sites throughout the state.

Mr. Partin has performed asbestos, lead paint, and indoor air quality surveys including materials inspection and bulk sampling for numerous commercial facilities and schools in South Carolina. He has carried projects from initial inspection, through abatement design and oversight, to demolition as a licensed building inspector and project designer.

Mr. Partin's regulatory compliance experience includes Hazardous Waste Disposal quarterly reports for industrial facilities; Spill Prevention Control and Countermeasures (SPCC) Plans, Storm Water Pollution Prevention Plans; Form R reporting with Title V Air Permits; and monthly discharge monitoring reports for clients under State NPDES permits.

Mr. Partin also coordinates NEPA submittals to the FCC for telecommunications tower sites including SHPO, THPO, USFWS, and public notice requests for review.

PROJECT EXPERIENCE

Retail/Commercial

TD Bank

As *National Account Manager*, coordinated Phase I and II assessments with multiple offices in the Southeast. Sites have included small owner/operator commercial facilities, multi-tenant strip retail centers, high-rise office buildings, convenience stores, gas stations, large and small industrial facilities, as well as wooded and agricultural land ranging in size from less than one acre to 200+ acres.

Crown Central Petroleum

Served as Project Manager for multiple petroleum UST sites across South Carolina with varying scopes of work and deadlines. Services provided included soil and ground water investigations, UST closure oversight, sampling, and reporting.

State/Local Government

SC Department of Transportation

Through an Indefinite Delivery Contract, performed several small and large projects for the SCDOT. Project Management for multiple petroleum UST sites including UST closure and groundwater assessment investigations. Performed over 400 Asbestos (NESHAP) and Lead Paint Surveys on SCDOT-owned buildings and bridges. Some projects included preparation of abatement and demolition plans and specs, abatement oversight, and reporting. Also prepared SWP3s and SPCC Plans for several maintenance facilities.

Lancaster County Schools - Lancaster, SC

Served as consultant and project manager for School District to perform asbestos inspections prior to renovation projects, AHERA Six Month surveillance, and Indoor air quality (mold) assessments. Also coordinated awareness training for the School District personnel with our Charlotte, NC office.

EDUCATION

Master of Public Health, Environmental Health Sciences, University of South Carolina, 1998

Bachelor of Arts, Business Economics, Wofford College, 1992

Hazmat/Health and Safety Training, 40 hours, Precision Environmental Laboratory, 1998

Princeton Groundwater Pollution and Hydrology Course, 2000

CERTIFICATIONS

Asbestos Project Designer, South Carolina License No. PD-00058, 2006

Asbestos Building Inspector, South Carolina License No. BI-00473, 1998

Certified Hazardous Materials Manager, Certification No. 10680, 2000

AFFILIATIONS

2020 Carolinas Environmental Information Association-Member, Past President (2010)

2020 Environmental Information Association – Member

2020 Member Queen City Chapter of the Alliance of Hazardous Materials Professionals

WORK HISTORY

Terracon Consultants, Inc., Department Manager, 2004-Present

Earth Management Systems, Inc., Project Environmental Scientist, 2001-2004

QORE Property Sciences, Inc., Project Environmental Scientist, 1998-2001

Lorris Environmental, Inc., Staff Scientist, 1997-1998

CONTACT

Terracon Consultants, Inc. 521 Clemson Road Columbia, SC 29229 803-212-0064 -office 803-603-1004 -mobile Gene.partin@terracon.com

Norman E. (Gene) Partin, Jr., CHMM (continued)

North Carolina Department Corrections

Performed site visits and prepared SPCC Plans for several prison facilities in North Carolina.

Telecommunications

Verizon Wireless

Prepared NEPA submittals with Section 106 (SHPO and THPO) and USFWS correspondence in South Carolina and Georgia. Performed archeological shovel testing, under supervision of CRM Group Leader and SOI Qualified Professional staff and Phase I ESAs for New Tower and Collocate Tower sites.

Optima Towers, LLC

Prepared NEPA submittal with Section 106 (SHPO and THPO) and USFWS correspondence in South Carolina. Performed archeological shovel testing, under supervision of CRM Group Leader and SOI Qualified Professional staff and Phase I ESAs for new site acquisitions.

Industrial

Ducane Gas Grills - Blackville, SC

Prepared Hazardous Waste Quarterly Reporting for LQG and facility closure reporting when site moved to new county. Prepared annual EPCRA reporting including Tier II and Form R. Assessed and delineated chlorinated solvent plume inside and outside of plant, and installed injection well network for Chemical Oxidation injections for remediation.

Silver Plating Facility - Upstate, SC

Managed the ground water monitoring and reporting for Post Closure Care of Solid Waste Management Unit at this facility. Other services have included an asbestos survey prior to building renovation and addition.

Northeast Sanitary Landfill - Columbia, SC

Coordination of permit application for Subtitle D Landfill; prepared regulatory plans as part of expansion application; ground water monitoring and reporting; prepared State application for landfill to be able to accept asbestos containing waste.

FN Manufacturing - Columbia, SC

Prepared Emissions Inventory Reporting for State Title V Air Permit requirements, annual EPCRA reporting including Form R, and Greenhouse Gas Emissions calculations and reporting. Coordinated concrete and sub-slab soil investigation from former Chrome Plating Line to assess potential releases.

Former Avondale Mills - Multiple Plant Sites - Graniteville, SC

Performed asbestos and lead paint inspections of Warren Plant, Gregg Plant, Granite Plant, and Stevens Steam Plant as part of a Brownfields Investigations prior to planned redevelopment of the closed textile facilities. Inspections included miles of asbestos insulated steam piping inside buildings and outside on elevated platforms. Prepared Project Designs for asbestos abatement at Steam Plant and provided abatement oversight during abatement and demolition.

Military Housing

Shaw AFB, Family Housing Demolition - Sumter, SC

As a subcontractor, performed asbestos and lead paint inspections of 256 military family housing units prior to demolition; project design for friable asbestos abatement; abatement and demolition oversight.

Joint Base Charleston (Charleston Air Base), Family Housing Demolition - Charleston, SC

As a subcontractor, performed asbestos and lead paint inspections of 406 military family housing units prior to demolition.

MCB Camp Lejeune and MCAS Cherry Point, Hurricane Florence Disaster Response - Jacksonville, NC

Served as Authorized Project Reviewer and Field Manager for disaster response team to address water intrusion issues in military housing from Hurricane Florence. Moisture mapping, asbestos and lead paint surveys, mold/moisture post remediation verification, and abatement oversight services provided for over 2,000 military housing units.

William "Walker" Hinson

STAFF SCIENTIST

PROFESSIONAL EXPERIENCE

Mr. Hinson is a Staff Scientist for the Environmental Department of Terracon's Columbia South Carolina office. Walker performs Environmental Site Assessment Services, Regulatory Compliance Services, UST Services, Asbestos and Lead Paint Surveys, and Geotechnical and Geophysical Surveys.

Mr. Hinson has completed Phase I Environmental Site Assessments, Noise Assessments, and Limited Environmental Compliance Audits for a wide range of sites in conjunction with lender liability transactions. He has managed and performed Phase II assessments to include soil and ground water contamination investigations associated with UST, industrial, and commercial sites throughout the state. Mr. Hinson has performed various kinds of Environmental Remediation events such as injection and extraction work.

Mr. Hinson's regulatory compliance experience includes Spill Prevention Control and Countermeasures (SPCC) Plans, Storm Water Pollution Prevention (SWP3) Plans, and monthly discharge monitoring reports for clients under State NPDES permits.

PROJECT EXPERIENCE

Environmental Site Assessments

 Performed multiple Phase I and Phase II ESA's for commercial and industrial property transactions in South Carolina and North Carolina

Environmental Remediation

- Performed 48 and 96-Hour AFVR extraction events
- Performed injection events including; Persulfate, Surfactant, Carbon Slurry, Enhanced Anaerobic Bio-remediation

UST Well Monitoring Assessment and Sample Collection

 Performed UST Well Monitoring and groundwater sampling for commercial, state and federal mitigation projects in South Carolina

Geotechnical/Geophysical Services

 Performed multiple geophysical surveys for site characterization, monitoring well, recovery well, test well and injection/extraction well installations

EDUCATION

Bachelor of Arts in Environmental Studies, University of South Carolina, 2018

TRAINING AND CERTIFICATIONS

Hazmat/Health and Safety Training, 40-hour

10-hour OSHA

First Aid and CPR Training

WORK HISTORY

Terracon Consultants, Inc., Staff Scientist, 2019 - Present

Palmetto Outdoor Center, 2014-2018

APPENDIX F DESCRIPTION OF TERMS AND ACRONYMS


| Term/Acronym | Description |
|------------------------|---|
| CREC | Controlled Recognized Environmental Condition is defined in ASTM E1527-13 as "a recognized environmental condition resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by regulatory authority), with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls). A condition considered by the environmental professional to be a controlled recognized environmental condition shall be listed in the findings section of the Phase I Environmental Site Assessment report, and as a recognized environmental condition in the conclusions section of the Phase I Environmental Site Assessment report." |
| DOT | U.S. Department of Transportation |
| EPA | U.S. Environmental Protection Agency |
| ERNS | Emergency Response Notification System. An EPA-maintained federal database which stores information on notifications of oil discharges and hazardous substance releases in quantities greater than the applicable reportable quantity under CERCLA. ERNS is a cooperative datasharing effort between EPA, DOT, and the National Response Center. |
| ESA | Environmental Site Assessment |
| FRP | Fiberglass Reinforced Plastic |
| Hazardous Substance | As defined under CERCLA, this is (A) any substance designated pursuant to section 1321(b)(2)(A) of Title 33, (B) any element, compound, mixture, solution, or substance designated pursuant to section 9602 of this title; (C) any hazardous waste having characteristics identified under or listed pursuant to section 3001 of the Solid Waste Disposal Act (with some exclusions); (D) any toxic pollutant listed under section 1317(a) of Title 33; (E) any hazardous air pollutant listed under section 112 of the Clean Air Act; and (F) any imminently hazardous chemical substance or mixture with respect to which the EPA Administrator has taken action under section 2606 of Title 15. This term does not include petroleum, including crude oil or any fraction thereof which is not otherwise listed as a hazardous substance under subparagraphs (A) through (F) above, and the term include natural gas, or synthetic gas usable for fuel (or mixtures of natural gas and such synthetic gas). |
| Hazardous Waste | This is defined as having characteristics identified or listed under section 3001 of the Solid Waste Disposal Act (with some exceptions). RCRA, as amended by the Solid Waste Disposal Act of 1980, defines this term as a "solid waste, or combination of solid wastes, which because of its quantity, concentration, or physical, chemical, or infectious characteristics may (A) cause, or significantly contribute to an increase in mortality or an increase in serious irreversible, or incapacitating reversible illness; or (B) pose a substantial present or potential hazard to human health or the environment when improperly treated, stored, transported, or disposed of, or otherwise managed." |
| HREC | Historical Recognized Environmental Condition is defined in ASTM E1527-13 as "a past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted residential use criteria established by a regulatory authority, without subjecting the property to any required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls). Before calling the past release a historical recognized environmental condition, the environmental professional must determine whether the past release is a recognized environmental condition at the time of the Phase I Environmental Site Assessment is conducted (for example, if there has been a change in the regulatory criteria). If the EP considers the past release to be a recognized environmental condition at the time the Phase I ESA is conducted, the condition shall be included in the conclusions section of the report as a recognized environmental condition." |


| Term/Acronym | Description |
|--------------|--|
| IC/EC | A listing of sites with institutional and/or engineering controls in place. IC include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls. EC include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health. |
| ILP | Innocent Landowner/Operator Program |
| LQG | Large Quantity Generators |
| LUST | Leaking Underground Storage Tank. This is a federal term set forth under RCRA for leaking USTs. Some states also utilize this term. |
| MCL | Maximum Contaminant Level. This Safe Drinking Water concept (and also used by many states as a ground water cleanup criteria) refers to the limit on drinking water contamination that determines whether a supplier can deliver water from a specific source without treatment. |
| MSDS | Material Safety Data Sheets. Written/printed forms prepared by chemical manufacturers, importers and employers which identify the physical and chemical traits of hazardous chemicals under OSHA's Hazard Communication Standard. |
| NESHAP | National Emissions Standard for Hazardous Air Pollutants (Federal Clean Air Act). This part of the Clean Air Act regulates emissions of hazardous air pollutants. |
| NFRAP | Facilities where there is "No Further Remedial Action Planned," as more particularly described under the Records Review section of this report. |
| NOV | Notice of Violation. A notice of violation or similar citation issued to an entity, company or individual by a state or federal regulatory body indicating a violation of applicable rule or regulations has been identified. |
| NPDES | National Pollutant Discharge Elimination System (Clean Water Act). The federal permit system for discharges of polluted water. |
| NPL | The NPL is the EPA's database of uncontrolled or abandoned hazardous waste facilities that have been listed for priority remedial actions under the Superfund Program. |
| OSHA | Occupational Safety and Health Administration or Occupational Safety and Health Act |
| PACM | Presumed Asbestos-Containing Material. A material that is suspected of containing or presumed to contain asbestos but which has not been analyzed to confirm the presence or absence of asbestos. |
| PCB | Polychlorinated Biphenyl. A halogenated organic compound commonly in the form of a viscous liquid or resin, a flowing yellow oil, or a waxy solid. This compound was historically used as dielectric fluid in electrical equipment (such as electrical transformers and capacitors, electrical ballasts, hydraulic and heat transfer fluids), and for numerous heat and fire sensitive applications. PCB was preferred due to its durability, stability (even at high temperatures), good chemical resistance, low volatility, flammability, and conductivity. PCBs, however, do not break down in the environment and are classified by the EPA as a suspected carcinogen. 1978 regulations, under the Toxic Substances Control Act, prohibit manufacturing of PCB-containing equipment; however, some of this equipment may still be in use today. |
| pCi/L | picoCuries per Liter of Air. Unit of measurement for Radon and similar radioactive materials. |
| PLM | Polarized Light Microscopy (see ACM section of the report, if included in the scope of services) |
| PST | Petroleum Storage Tank. An AST or UST that contains a petroleum product. |


| Term/Acronym | Description |
|--------------------------------|--|
| Radon | A radioactive gas resulting from radioactive decay of naturally-occurring radioactive materials in rocks and soils containing uranium, granite, shale, phosphate, and pitchblende. Radon concentrations are measured in picoCuries per Liter of Air. Exposure to elevated levels of radon creates a risk of lung cancer; this risk generally increases as the level of radon and the duration of exposure increases. Outdoors, radon is diluted to such low concentrations that it usually does not present a health concern. However, radon can accumulate in building basements or similar enclosed spaces to levels that can pose a risk to human health. Indoor radon concentrations depend primarily upon the building's construction, design and the concentration of radon in the underlying soil and ground water. The EPA recommended annual average indoor "action level" concentration for residential structures is 4.0 pCi/l. |
| RCRA | Resource Conservation and Recovery Act. Federal act regulating solid and hazardous wastes from point of generation to time of disposal ('cradle to grave"). 42 U.S.C. 6901 et seq. |
| RCRA Generators | The RCRA Generators database, maintained by the EPA, lists facilities that generate hazardous waste as part of their normal business practices. Generators are listed as either large (LQG), small (SQG), or conditionally exempt (CESQG). LQG produce at least 1000 kg/month of non-acutely hazardous waste or 1 kg/month of acutely hazardous waste. SQG produce 100-1000 kg/month of non-acutely hazardous waste. CESQG are those that generate less than 100 kg/month of non-acutely hazardous waste. |
| RCRA CORRACTS/TS Ds | The USEPA maintains a database of RCRA facilities associated with treatment, storage, and disposal (TSD) of hazardous materials which are undergoing "corrective action". A "corrective action" order is issued when there is a release of hazardous waste or constituents into the environment from a RCRA facility. |
| RCRA Non- CORRACTS/TS Ds | The RCRA Non-CORRACTS/TSD Database is a compilation by the USEPA of facilities which report storage, transportation, treatment, or disposal of hazardous waste. Unlike the RCRA CORRACTS/TSD database, the RCRA Non-CORRACTS/TSD database does not include RCRA facilities where corrective action is required. |
| RCRA Violators List | RAATS. RCRA Administrative Actions Taken. RAATS information is now contained in the RCRIS database and includes records of administrative enforcement actions against facilities for noncompliance. |
| RCRIS | Resource Conservation and Recovery Information System, as defined in the Records Review section of this report. |
| REC | Recognized Environmental Conditions are defined by ASTM E1527-13 as "the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: 1) due to any release to the environment; 2) under conditions indicative of a release to the environment. De minimis conditions are not recognized environmental conditions." |
| SCL | State "CERCLIS" List (see SPL /State Priority List, below). |
| SPCC | Spill Prevention, Control and Countermeasures. SPCC plans are required under federal law (Clean Water Act and Oil Pollution Act) for any facility storing petroleum in tanks and/or containers of 55-gallons or more that when taken in aggregate exceed 1,320 gallons. SPCC plans are also required for facilities with underground petroleum storage tanks with capacities of over 42,000 gallons. Many states have similar spill prevention programs, which may have additional requirements. |
| SPL | State Priority List. State list of confirmed sites having contamination in which the state is actively involved in clean up activities or is actively pursuing potentially responsible parties for clean up. Sometimes referred to as a State "CERCLIS" List. |
| SQG | Small Quantity Generator |
| SWF/LF | State and/or Tribal database of Solid Waste/Landfill facilities. The database information may include the facility name, class, operation type, area, estimated operational life, and owner. |
| TPH | Total Petroleum Hydrocarbons |
| TRI | Toxic Release Inventory. Routine EPA report on releases of toxic chemicals to the environment based upon information submitted by entities subject to reporting under the Emergency Planning and Community Right to Know Act. |


| Term/Acronym | Description |
|--------------|--|
| TSCA | Toxic Substances Control Act. A federal law regulating manufacture, import, processing and distribution of chemical substances not specifically |
| ISCA | regulated by other federal laws (such as asbestos, PCBs, lead-based paint and radon). 15 U.S.C 2601 et seq. |
| USACE | United States Army Corps of Engineers |
| USC | United States Code |
| USGS | United States Geological Survey |
| USNRCS | United States Department of Agriculture-Natural Resource Conservation Service |
| UST | Underground Storage Tank. Most federal and state regulations, as well as ASTM E1527-13, define this as any tank, incl., underground piping connected to the tank, that is or has been used to contain hazardous substances or petroleum products and the volume of which is 10% or more beneath the surface of the ground (i.e., buried). |
| VCP | State and/or Tribal facilities included as Voluntary Cleanup Program sites. |
| VOC | Volatile Organic Compound |
| | Areas that are typically saturated with surface or ground water that creates an environment supportive of wetland vegetation (i.e., swamps, marshes, bogs). The Corps of Engineers Wetlands Delineation Manual (Technical Report Y-87-1) defines wetlands as areas inundated or saturated by surface or ground water at a frequency and duration sufficient to support, and that under normal circumstances do support, a prevalence of vegetation typically adapted for life in saturated soil conditions. For an area to be considered a jurisdictional wetland, it must meet the following criteria: more than 50 percent of the dominant plant species must be categorized as Obligate, Facultative Wetland, or Facultative on lists of plant species that occur in wetlands; the soil must be hydric; and, wetland hydrology must be present. |
| Wetlands | The federal Clean Water Act which regulates "waters of the US," also regulates wetlands, a program jointly administered by the USACE and the EPA. Waters of the U.S. are defined as: (1) waters used in interstate or foreign commerce, including all waters subject to the ebb and flow of tides; (2) all interstate waters including interstate wetlands; (3) all other waters such as intrastate lakes, rivers, streams (including intermittent streams), mudflats, sandflats, wetlands, sloughs, prairie potholes, wet meadows, playa lakes, or natural ponds, etc., which the use, degradation, or destruction could affect interstate/ foreign commerce; (4) all impoundments of waters otherwise defined as waters of the U.S., (5) tributaries of waters identified in 1 through 4 above; (6) the territorial seas; and (7) wetlands adjacent to waters identified in 1 through 6 above. Only the USACE has the authority to make a final wetlands jurisdictional determination. |


APPENDIX F FOI PROVIDED REPORTS














Appendix B:

Table 1 - Ground water Elevation Data

Table 2 - Soil Analytical Data (TAL Metals)

Table 3 - Soil Analytical Data (Pesticides/PCBs)

Table 4 - Soil Analytical Data (Total Dioxins/Furans)

Table 5 - Soil Analytical Data (VOCs)

Table 6 - Soil Analytical Data (SVOCs)

Table 7 - Ground water Analytical Data

Table 8 - Receptor Survey

TABLE 1 GROUND WATER ELEVATION DATA

Drake Street Property USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| WELL NUMBER | DATE MEASURED | SCREEN INTERVAL (bgs) | TOP OF CASING ELEVATION | DEPTH TO GROUND WATER (btoc) | GROUND WATER ELEVATION |
|----------------|------------------|-----------------------------|-------------------------------|---------------------------------------|------------------------------|
| BF-1 | 5/29/08 | 19.2 - 29.2 | 103.71 | 23.46 | 80.25 |
| BF-2 | 5/29/08 | 18.5 -28.5 | 104.55 | 24.50 | 80.05 |
| BF-3 | 5/29/08 | 12.2 - 22.2 | 102.23 | 14.82 | 87.41 |
| BF-4 | 5/29/08 | 7.9 - 17.9 | 100.41 | 12.06 | 88.35 |
| MW-3 | 5/29/08 | 27.2 - 37.2 | 109.95 | 31.94 | 78.01 |
| MW-8 | 5/29/08 | 25.5 - 35.5 | 105.61 | 23.73 | 81.88 |
| MW-8A | 5/29/08 | 62.7 - 72.7 | 105.55 | 41.36 | 64.19 |
| MW-15 | 5/29/08 | 7.5 -17.5 | 107.76 | 15.48 | 92.28 |

NOTES:

- 1) bgs = below ground surface
- 2) btoc = below top of casing
- 3) Data are presented in feet.
- 4) Top of casing elevations surveyed by Jay Joshi, Construction Support Services (SC PLS # 14811) on June 8, 2008, referenced to a common benchmark on site.

TABLE 2A SOIL ANALYTICAL DATA

("A" SECTION TAL METALS)

Drake Street Property

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| Analyte | Residential PRG | BG-1 [background] (0 - 1 ft.) | BG-1D [background] (1-3 ft.) | A-1 (0 - 1 ft.) | A-1D (1 - 3 ft.) | A-2 (0 - 1 ft.) | A-3 (0 - 1 ft.) |
|-----------|-----------------|--------------------------------------|------------------------------------|---------------------|----------------------|---------------------|---------------------|
| Aluminum | 76,000 | 3790 | 3830 | 8960 | 8670 | 3670 | 2390 |
| Antimony | 31 | < 2.5 | < 2.53 | < 2.61 | < 5.43 | < 2.47 | < 2.47 |
| Arsenic | 0.39 | < 1.66 | < 1.69 | 4.98 | < 25 | < 1.65 | < 1.64 |
| Barium | 5,400 | 15.9 | 16.5 | 47 | 57.2 | 25.4 | 17.9 |
| Beryllium | 150 | < 0.21 | < 0.21 | < 0.22 | < 0.45 | < 0.21 | < 0.21 |
| Cadmium | 37 | < 0.21 | < 0.21 | < 0.22 | < 0.45 | < 0.21 | < 0.21 |
| Calcium | ne | 320 | 84.6 | 686 | 1090 | 199 | 101 |
| Chromium | 210 | 3.59 | 2.6 | 27.7 | 41.7 | 2.38 | 5.64 |
| Cobalt | 900 | < 0.42 | 0.49 | < 0.44 | < 0.91 | 0.52 | 0.69 |
| Copper | 3,100 | 1.63 | 1.31 | 849 | 5140 | 2.34 | 4.61 |
| Iron | 23,000 | 2730 | 2520 | 8660 | 10100 | 2430 | 8280 |
| Lead | 400 | 9.02 | 3.22 | 158 | 710 | 5.33 | 19.5 |
| Magnesium | ne | 103 | 95.7 | 149 | 243 | 79.2 | 68.8 |
| Manganese | 1,800 | 79.2 | 29 | 180 | 328 | 116 | 43.3 |
| Mercury | 23 | 0.029 | 0.025 | 0.051 | 0.039 | < 0.01 | 0.013 |
| Nickel | 1,600 | < 1.66 | < 1.69 | 5.73 | 18.6 | < 1.65 | 2.26 |
| Potassium | ne | 113 | 77.4 | 163 | 262 | < 70.7 | 57.8 |
| Selenium | 390 | < 1.66 | < 1.69 | < 1.74 | < 3.62 | < 1.65 | < 1.64 |
| Silver | 390 | < 0.42 | < 0.42 | < 0.44 | < 0.91 | < 0.41 | < 0.41 |
| Sodium | ne | < 41.6 | < 42.1 | < 43.6 | < 90.5 | < 41.2 | < 41.1 |
| Thallium | 5.2 | < 0.83 | < 0.84 | < 0.87 | < 1.81 | < 0.82 | < 0.82 |
| Vanadium | 78 | 6.17 | 5.23 | 17.4 | 16.5 | 4.27 | 4.63 |
| Zinc | 23,000 | 6.51 | 4.07 | 119 | 167 | 5.91 | 22.3 |

Notes:

- 1) All results reported in milligrams per kilogram (mg/kg) or parts per million
- 2) PRG USEPA Region 9 Preliminary Remediation Goals
- 3) ne PRG not established
- 4) results shown in bold exceed the Residential PRG
- results shown in italics exceed three times background concentrations for compounds without an established PRG

TABLE 2B SOIL ANALYTICAL DATA

("B" SECTION TAL METALS) Drake Street Property

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| Analyte | Residential PRG | BG-1 [background] (0 - 1 ft.) | BG-1D [background] (1-3 ft.) | B-1 (0 - 1 ft.) | B-2 (0 - 1 ft.) | B-3 (0 - 1 ft.) | B-3D (1 - 3 ft.) |
|-----------|--------------------|--------------------------------------|------------------------------------|---------------------|---------------------|---------------------|----------------------|
| Aluminum | 76,000 | 3790 | 3830 | 3440 | 5320 | 8730 | 5270 |
| Antimony | 31 | < 2.5 | < 2.53 | < 2.47 | 3.51 | < 2.7 | < 2.55 |
| Arsenic | 0.39 | < 1.66 | < 1.69 | < 1.65 | < 1.76 | < 1.8 | < 1.7 |
| Barium | 5,400 | 15.9 | 16.5 | 25.1 | 326 | 370 | 251 |
| Beryllium | 150 | < 0.21 | < 0.21 | < 0.21 | < 0.22 | < 0.22 | < 0.21 |
| Cadmium | 37 | < 0.21 | < 0.21 | < 0.21 | < 0.22 | < 0.22 | < 0.21 |
| Calcium | ne | 320 | 84.6 | 236 | 5260 | 2090 | 5680 |
| Chromium | 210 | 3.59 | 2.6 | 2.97 | 54.5 | 184 | 59.4 |
| Cobalt | 900 | < 0.42 | 0.49 | 0.56 | 1.93 | 3.17 | 1.52 |
| Copper | 3,100 | 1.63 | 1.31 | 6.5 | 35.2 | 21.2 | 8.65 |
| Iron | 23,000 | 2730 | 2520 | 2160 | 7380 | 8930 | 4010 |
| Lead | 400 | 9.02 | 3.22 | 12.9 | 525 | 298 | 120 |
| Magnesium | ne | 103 | 95.7 | 73.5 | 610 | 339 | 210 |
| Manganese | 1,800 | 79.2 | 29 | 102 | 273 | 157 | 181 |
| Mercury | 23 | 0.029 | 0.025 | 0.022 | 0.1 | 0.17 | 0.036 |
| Nickel | 1,600 | < 1.66 | < 1.69 | < 1.65 | 4.73 | 68.7 | 20.3 |
| Potassium | ne | 113 | 77.4 | 46 | 150 | 200 | 91.8 |
| Selenium | 390 | < 1.66 | < 1.69 | < 1.65 | < 1.76 | < 1.8 | < 1.7 |
| Silver | 390 | < 0.42 | < 0.42 | < 0.41 | < 0.44 | < 0.45 | < 0.42 |
| Sodium | ne | < 41.6 | < 42.1 | < 41.2 | < 44.1 | < 44.9 | < 42.4 |
| Thallium | 5.2 | < 0.83 | < 0.84 | < 0.82 | < 0.88 | < 0.9 | <0.85 |
| Vanadium | 78 | 6.17 | 5.23 | 4.63 | 12.5 | 17.1 | 7.33 |
| Zinc | 23,000 | 6.51 | 4.07 | 12.8 | 335 | 253 | 300 |

Notes:

- 1) All results reported in milligrams per kilogram (mg/kg) or parts per million
- 2) PRG USEPA Region 9 Preliminary Remediation Goals
- 3) ne PRG not established
- 4) results shown in bold exceed the Residential PRG
- 5) results shown in italics exceed three times background concentrations for compounds without an established PRG

TABLE 2C SOIL ANALYTICAL DATA ("C" SECTION TAL METALS) Drake Street Property

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| Analyte | Residential PRG | BG-1 [background] (0 - 1 ft.) | BG-1D [background] (1 - 3 ft.) | C-1 (0 - 1 ft.) | C-2 (0 - 1 ft.) | C-3 (0 - 1 ft.) | C-4 (0 - 1 ft.) | C-4D (1 - 3 ft.) | C-5 (0 - 1 ft.) | C-6 (0 - 1 ft.) | C-7 (0 - 1 ft.) | C-8 (0 - 1 ft.) | C-8D (1 - 3 ft.) | C-9 (0 - 1 ft.) | C-10 (0 - 1 ft.) |
|-----------|--------------------|-------------------------------------|--------------------------------------|--------------------|--------------------|--------------------|--------------------|---------------------|--------------------|--------------------|--------------------|--------------------|---------------------|--------------------|---------------------|
| Aluminum | 76,000 | 3790 | 3830 | 3150 | 2010 | 3290 | 3950 | 2910 | 5700 | 4390 | 4950 | 5230 | 7870 | 8500 | 3500 |
| Antimony | 31 | < 2.5 | < 2.53 | < 2.69 | < 2.46 | < 2.64 | < 3.06 | < 2.52 | < 2.62 | < 2.48 | < 2.51 | < 2.54 | < 2.52 | < 2.69 | < 2.51 |
| Arsenic | 0.39 | < 1.66 | < 1.69 | < 1.8 | < 1.64 | < 1.76 | < 2.04 | < 1.68 | < 1.74 | < 1.65 | < 1.67 | < 1.7 | < 1.68 | < 1.79 | < 1.67 |
| Barium | 5,400 | 15.9 | 16.5 | 42.9 | 32.2 | 34.8 | 53.2 | 19 | 58.5 | 49.2 | 72 | 112 | 71.9 | 18.9 | 45.5 |
| Beryllium | 150 | < 0.21 | < 0.21 | < 0.22 | < 0.21 | < 0.22 | < 0.25 | < 0.21 | < 0.22 | < 0.21 | < 0.21 | < 0.21 | < 0.21 | < 0.22 | < 0.21 |
| Cadmium | 37 | < 0.21 | < 0.21 | 2.45 | 0.6 | 0.4 | 0.29 | < 0.21 | < 0.22 | 0.27 | < 0.21 | < 0.21 | < 0.21 | < 0.22 | < 0.21 |
| Calcium | ne | 320 | 84.6 | 902 | 647 | 927 | 1570 | 277 | 497 | 909 | 2360 | 807 | 1320 | 164 | 455 |
| Chromium | 210 | 3.59 | 2.6 | 19.6 | 6.2 | 36.5 | 27.2 | 2.2 | 24.6 | 12.7 | 24 | 15.1 | 22.9 | 11.9 | 11.2 |
| Cobalt | 900 | < 0.42 | 0.49 | 1.26 | < 0.41 | 1.04 | 0.86 | 0.69 | 0.83 | 1.02 | 0.98 | 0.93 | 0.59 | < 0.45 | 0.89 |
| Copper | 3,100 | 1.63 | 1.31 | 92.7 | 2140 | 84 | 103 | 1.43 | 312 | 14.7 | 15.3 | 11.3 | 67 | 66.8 | 13.7 |
| Iron | 23,000 | 2730 | 2520 | 4220 | 5210 | 5070 | 3640 | 1750 | 6930 | 4610 | 4580 | 3810 | 6990 | 8300 | 3290 |
| Lead | 400 | 9.02 | 3.22 | 279 | 349 | 242 | 78.4 | 4.91 | 523 | 59.3 | 110 | 107 | 41.4 | 15.8 | 152 |
| Magnesium | ne | 103 | 95.7 | 154 | 146 | 385 | 124 | 49.2 | 158 | 174 | 200 | 141 | 236 | 91 | 84.8 |
| Manganese | 1,800 | 79.2 | 29 | 148 | 61 | 172 | 222 | 113 | 200 | 126 | 167 | 183 | 109 | 65.2 | 235 |
| Mercury | 23 | 0.029 | 0.025 | < 0.011 | 0.017 | 0.041 | 0.032 | 0.016 | 0.033 | 0.035 | 0.033 | 0.093 | 0.19 | 0.047 | 3.09 |
| Nickel | 1,600 | < 1.66 | < 1.69 | 3.46 | 10.9 | 5.46 | 3.54 | < 1.68 | 4.45 | 2.55 | 2.23 | 2.04 | 3.17 | 1.79 | 1.67 |
| Potassium | ne | 113 | 77.4 | 87.1 | 49.9 | 218 | 79.4 | 45.6 | 80.5 | 92.2 | 166 | 76.1 | 79.7 | 71.8 | 53 |
| Selenium | 390 | < 1.66 | < 1.69 | < 1.8 | < 1.64 | < 1.76 | 2.04 | < 1.68 | < 1.74 | < 1.65 | < 1.67 | < 1.7 | < 1.68 | < 1.79 | < 1.67 |
| Silver | 390 | < 0.42 | < 0.42 | < 0.45 | < 0.41 | < 0.44 | 0.51 | < 0.42 | < 0.44 | < 0.41 | < 0.42 | < 0.42 | < 0.42 | < 0.45 | < 0.42 |
| Sodium | ne | < 41.6 | < 42.1 | < 44.9 | < 41.1 | < 43.9 | 50.9 | < 42 | < 43.6 | < 41.3 | 599 | < 42.4 | < 42 | < 44.9 | < 41.8 |
| Thallium | 5.2 | < 0.83 | < 0.84 | < 0.9 | < 0.82 | < 0.88 | 1.02 | < 0.84 | < 0.87 | < 0.83 | < 0.84 | < 0.85 | < 0.84 | < 0.9 | < 0.84 |
| Vanadium | 78 | 6.17 | 5.23 | 9.94 | 4.23 | 5.63 | 5.55 | 3.3 | 9.3 | 6.85 | 7.11 | 7.06 | 11.1 | 21.9 | 4.22 |
| Zinc | 23,000 | 6.51 | 4.07 | 85.8 | 131 | 106 | 47.5 | 2.33 | 146 | 81.7 | 69.4 | 79.5 | 54.9 | 14.2 | 47.8 |

Notes

- 1) All results reported in milligrams per kilogram (mg/kg) or parts per million
- 2) PRG USEPA Region 9 Preliminary Remediation Goals
- 3) ne PRG not established
- 4) results shown in bold exceed the Residential PRG
- 5) results shown in italics exceed three times background concentrations for compounds without an established PRG

TABLE 2D SOIL ANALYTICAL DATA

("D" SECTION TAL METALS)

Drake Street Property
USEPA Cooperative Agreement No. BF-96462106

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| Analyte | Residential PRG | BG-1 [background] (0 - 1 ft.) | BG-1D [background] (1 - 3 ft.) | D-1 (0 - 1 ft.) | D-1D (1 - 3 ft.) | D-2 (0 - 1 ft.) | D-3 (0 - 1 ft.) |
|-----------|-----------------|--------------------------------------|--------------------------------------|---------------------|----------------------|---------------------|---------------------|
| Aluminum | 76,000 | 3790 | 3830 | 3880 | 4890 | 3160 | 2540 |
| Antimony | 31 | < 2.5 | < 2.53 | < 2.43 | < 2.52 | < 2.46 | < 2.47 |
| Arsenic | 0.39 | < 1.66 | < 1.69 | < 1.62 | < 1.68 | < 1.64 | < 1.65 |
| Barium | 5,400 | 15.9 | 16.5 | 26.7 | 30.4 | 20 | 17.9 |
| Beryllium | 150 | < 0.21 | < 0.21 | < 0.2 | < 0.21 | < 0.2 | < 0.21 |
| Cadmium | 37 | < 0.21 | < 0.21 | < 0.2 | < 0.21 | < 0.2 | < 0.21 |
| Calcium | ne | 320 | 84.6 | 274 | 171 | 280 | 56.1 |
| Chromium | 210 | 3.59 | 2.6 | 3.02 | 2.78 | 3.01 | 2.22 |
| Cobalt | 900 | < 0.42 | 0.49 | 0.85 | 1.08 | 0.63 | 0.54 |
| Copper | 3,100 | 1.63 | 1.31 | 10.9 | 1.72 | 48.8 | 6.86 |
| Iron | 23,000 | 2730 | 2520 | 2560 | 3130 | 2290 | 1570 |
| Lead | 400 | 9.02 | 3.22 | 18.7 | 3.86 | 26.9 | 7.17 |
| Magnesium | ne | 103 | 95.7 | 83.5 | 78.7 | 64.1 | 52.1 |
| Manganese | 1,800 | 79.2 | 29 | 226 | 128 | 123 | 47.5 |
| Mercury | 23 | 0.029 | 0.025 | 0.017 | 0.013 | 0.026 | < 0.01 |
| Nickel | 1,600 | < 1.66 | < 1.69 | < 1.62 | < 1.68 | < 1.64 | < 1.65 |
| Potassium | ne | 113 | 77.4 | 54.5 | 68.8 | 41.7 | 45.6 |
| Selenium | 390 | < 1.66 | < 1.69 | < 1.62 | < 1.68 | < 1.64 | < 1.65 |
| Silver | 390 | < 0.42 | < 0.42 | < 0.41 | < 0.42 | < 0.41 | < 0.41 |
| Sodium | ne | < 41.6 | < 42.1 | < 40.5 | < 42.1 | < 1 | < 41.2 |
| Thallium | 5.2 | < 0.83 | < 0.84 | < 0.81 | < 0.84 | < 0.82 | < 0.82 |
| Vanadium | 78 | 6.17 | 5.23 | 4.59 | 6.2 | 4.13 | 3.25 |
| Zinc | 23,000 | 6.51 | 4.07 | 12 | 3.4 | 17.5 | 3.83 |

Notes:

- 1) All results reported in milligrams per kilogram (mg/kg) or parts per million
- 2) PRG USEPA Region 9 Preliminary Remediation Goals
- 3) ne PRG not established
- 4) results shown in bold exceed the Residential PRG
- 5) results shown in italics exceed three times background concentrations for compounds without an established PRG

TABLE 2E SOIL ANALYTICAL DATA

("E" SECTION TAL METALS)

Drake Street Property

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| Analyte | Residential PRG (mg/kg) | BG-1 [background] (0 - 1 ft.) | BG-1D [background] (1-3 ft.) | E-1 (0 - 1 ft.) | E-1D (1 - 3 ft.) | E-2 (0 - 1 ft.) | E-3 (0 - 1 ft.) |
|-----------|-------------------------------|--------------------------------------|------------------------------------|---------------------|----------------------|---------------------|---------------------|
| Aluminum | 76,000 | 3790 | 3830 | 5580 | 12600 | 2750 | 3390 |
| Antimony | 31 | < 2.5 | < 2.53 | < 2.49 | < 2.75 | < 2.7 | < 3.08 |
| Arsenic | 0.39 | < 1.66 | < 1.69 | < 1.66 | < 1.84 | < 1.8 | < 2.05 |
| Barium | 5,400 | 15.9 | 16.5 | 24.3 | 24.7 | 10.4 | 15.1 |
| Beryllium | 150 | < 0.21 | < 0.21 | < 0.21 | < 0.23 | < 0.22 | < 0.26 |
| Cadmium | 37 | < 0.21 | < 0.21 | < 0.21 | < 0.23 | < 0.22 | < 0.26 |
| Calcium | ne | 320 | 84.6 | 104 | 171 | 41.1 | 41.8 |
| Chromium | 210 | 3.59 | 2.6 | 4.47 | 22.6 | 4.5 | 2.48 |
| Cobalt | 900 | < 0.42 | 0.49 | < 0.41 | < 0.46 | < 0.45 | 0.78 |
| Copper | 3,100 | 1.63 | 1.31 | 1.83 | 1.82 | 2.55 | 3.27 |
| Iron | 23,000 | 2730 | 2520 | 3480 | 10700 | 3160 | 2090 |
| Lead | 400 | 9.02 | 3.22 | 5.26 | 5.44 | 4.15 | 7.53 |
| Magnesium | ne | 103 | 95.7 | 95 | 162 | 46.4 | 71.7 |
| Manganese | 1,800 | 79.2 | 29 | 48.8 | 17.8 | 14.5 | 49.4 |
| Mercury | 23 | 0.029 | 0.025 | 0.025 | 0.044 | 0.012 | < 0.013 |
| Nickel | 1,600 | < 1.66 | < 1.69 | < 1.66 | 2.05 | < 1.8 | < 2.05 |
| Potassium | ne | 113 | 77.4 | 72.5 | 111 | 45 | 52 |
| Selenium | 390 | < 1.66 | < 1.69 | < 1.66 | < 1.84 | < 1.8 | < 2.05 |
| Silver | 390 | < 0.42 | < 0.42 | < 0.41 | < 0.46 | < 0.45 | < 0.51 |
| Sodium | ne | < 41.6 | < 42.1 | < 41.5 | < 45.9 | < 44.9 | < 51.3 |
| Thallium | 5.2 | < 0.83 | < 0.84 | < 0.83 | < 0.92 | < 0.9 | < 1.03 |
| Vanadium | 78 | 6.17 | 5.23 | 8.86 | 29.7 | 9.66 | 4.27 |
| Zinc | 23,000 | 6.51 | 4.07 | 8.71 | 5.15 | 2.98 | 6.1 |

Notes:

- 1) All results reported in milligrams per kilogram (mg/kg) or parts per million
- 2) PRG USEPA Region 9 Preliminary Remediation Goals
- 3) ne PRG not established
- 4) results shown in bold exceed the Residential PRG
- 5) results shown in italics exceed three times background concentrations for compounds without an established PRG

TABLE 2F SOIL ANALYTICAL DATA

("F" SECTION TAL METALS)

Drake Street Property

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| Analyte | Residential PRG (mg/kg) | BG-1 [background] (0 - 1 ft.) | BG-1D [background] (1-3 ft.) | F-1 (0 - 1 ft.) | F-1D (1 - 3 ft.) | F-2 (0 - 1 ft.) | F-3 (0 - 1 ft.) |
|-----------|-------------------------------|--------------------------------------|------------------------------------|---------------------|----------------------|---------------------|---------------------|
| Aluminum | 76,000 | 3790 | 3830 | 4640 | 5200 | 6020 | 7390 |
| Antimony | 31 | < 2.5 | < 2.53 | < 3.03 | 3.49 | < 2.67 | < 2.56 |
| Arsenic | 0.39 | < 1.66 | < 1.69 | < 2.02 | < 1.76 | < 1.78 | < 1.71 |
| Barium | 5,400 | 15.9 | 16.5 | 31.8 | 15.2 | 23 | 13.3 |
| Beryllium | 150 | < 0.21 | < 0.21 | < 0.25 | < 0.22 | < 0.22 | < 0.21 |
| Cadmium | 37 | < 0.21 | < 0.21 | < 0.25 | < 0.22 | < 0.22 | < 0.21 |
| Calcium | ne | 320 | 84.6 | 142 | 219 | 190 | 48.8 |
| Chromium | 210 | 3.59 | 2.6 | 3.13 | 7.27 | 6.27 | 9.91 |
| Cobalt | 900 | < 0.42 | 0.49 | 1.03 | 0.47 | < 0.45 | < 0.43 |
| Copper | 3,100 | 1.63 | 1.31 | 4.92 | 44.1 | 13.9 | 5.08 |
| Iron | 23,000 | 2730 | 2520 | 3590 | 4660 | 4350 | 9010 |
| Lead | 400 | 9.02 | 3.22 | 6.34 | 7.2 | 3.97 | 12.6 |
| Magnesium | ne | 103 | 95.7 | 89.4 | 104 | 126 | 56.2 |
| Manganese | 1,800 | 79.2 | 29 | 121 | 42.9 | 19.8 | 11.6 |
| Mercury | 23 | 0.029 | 0.025 | < 0.013 | 8.2 | 1.48 | 0.083 |
| Nickel | 1,600 | < 1.66 | < 1.69 | < 2.02 | 2.22 | 1.89 | < 1.71 |
| Potassium | ne | 113 | 77.4 | 65.3 | 84.2 | 105 | 54.4 |
| Selenium | 390 | < 1.66 | < 1.69 | < 2.02 | < 1.76 | < 1.78 | < 1.71 |
| Silver | 390 | < 0.42 | < 0.42 | < 0.51 | 7.61 | 11.4 | < 0.43 |
| Sodium | ne | < 41.6 | < 42.1 | < 50.6 | < 44.1 | < 44.6 | < 42.7 |
| Thallium | 5.2 | < 0.83 | < 0.84 | < 1.01 | 0.95 | < 0.89 | < 0.85 |
| Vanadium | 78 | 6.17 | 5.23 | 5.34 | 8.35 | 9.21 | 21 |
| Zinc | 23,000 | 6.51 | 4.07 | 9.78 | 52.4 | 15 | 6.32 |

- 1) All results reported in milligrams per kilogram (mg/kg) or parts per million
- 2) PRG USEPA Region 9 Preliminary Remediation Goals
- 3) ne PRG not established
- 4) results shown in bold exceed the Residential PRG
- 5) results shown in italics exceed three times background concentrations for compounds without an established PRG

TABLE 3A

SOIL ANALYTICAL DATA

("A" SECTION PESTICIDES and PCBs)

Drake Street Property

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| Analyte | Residential PRG (mg/kg) | BG-1 [background] (0 - 1 ft.) | BG-1D [background] (1- 3 ft.) | A-1 (0 - 1 ft.) | A-1D (1 - 3 ft.) | A-2 (0 - 1 ft.) | A-3 (0 - 1 ft.) |
|---------------------|-------------------------------|--------------------------------------|--------------------------------------|---------------------|----------------------|---------------------|---------------------|
| 4,4'-DDD | 2,400 | < 4.19 | < 4.2 | < 438 | < 44.7 | < 4.09 | < 4.14 |
| 4,4'-DDE | 1,700 | < 4.19 | < 4.2 | 1100 | 249 | < 4.09 | < 4.14 |
| 4,4'-DDT | 1,700 | < 4.19 | < 4.2 | < 438 | 283 | < 4.09 | < 4.14 |
| Aldrin | 29 | < 2.1 | < 2.1 | < 219 | < 22.3 | < 2.05 | < 2.07 |
| Dieldrin | 30 | < 4.19 | < 4.2 | < 438 | < 44.7 | < 4.09 | < 4.14 |
| Endosulfan I | 370,000 | < 2.1 | < 2.1 | < 219 | < 22.3 | < 2.05 | < 2.07 |
| Endosulfan II | 370,000 | < 4.19 | < 4.2 | < 438 | < 44.7 | < 4.09 | < 4.14 |
| Endosulfan sulfate | ne | < 4.19 | < 4.2 | < 438 | < 44.7 | < 4.09 | < 4.14 |
| Endrin | 18,000 | < 4.19 | < 4.2 | < 438 | < 44.7 | < 4.09 | < 4.14 |
| Endrin aldehyde | ne | < 4.19 | < 4.2 | < 438 | < 44.7 | < 4.09 | < 4.14 |
| Endrin ketone | ne | < 4.19 | < 4.2 | < 438 | < 44.7 | < 4.09 | < 4.14 |
| Heptachlor | 110 | < 2.1 | < 2.1 | < 219 | < 22.3 | < 2.05 | < 2.07 |
| Heptachlor epoxide | 53 | < 2.1 | < 2.1 | < 219 | < 22.3 | < 2.05 | < 2.07 |
| Methoxychlor | 310,000 | < 21 | < 21 | < 2190 | < 223 | < 20.5 | < 20.7 |
| Toxaphene | 440 | < 210 | < 210 | < 21900 | < 2230 | < 205 | < 207 |
| alpha-BHC | 90 | < 2.1 | < 2.1 | < 219 | < 22.3 | < 2.05 | < 2.07 |
| alpha-Chlordane | 1,600 | < 2.1 | < 2.1 | 516 | 87.1 | < 2.05 | < 2.07 |
| beta-BHC | 320 | < 4.19 | < 4.2 | < 438 | < 44.7 | < 4.09 | < 4.14 |
| delta-BHC | ne | < 2.1 | < 2.1 | < 219 | < 22.3 | < 2.05 | < 2.07 |
| gamma-BHC (Lindane) | 440 | < 2.1 | < 2.2 | < 219 | < 22.3 | < 2.05 | < 2.07 |
| gamma-Chlordane | 1,600 | < 2.1 | < 2.3 | 648 | 102 | < 2.05 | < 2.07 |
| Aroclor-1016 | 3,900 | < 41.9 | < 42 | < 4380 | < 447 | < 40.9 | < 41.4 |
| Aroclor-1221 | 220 | < 41.9 | < 42 | < 4380 | < 447 | < 40.9 | < 41.4 |
| Aroclor-1232 | 220 | < 41.9 | < 42 | < 4380 | < 447 | < 40.9 | < 41.4 |
| Aroclor-1242 | 220 | < 41.9 | < 42 | < 4380 | < 447 | < 40.9 | < 41.4 |
| Aroclor-1248 | 220 | < 41.9 | < 42 | <4380 | < 447 | < 40.9 | < 41.4 |
| Aroclor-1254 | 220 | < 41.9 | < 42 | 19,800 | 2,600 | < 40.9 | < 41.4 |
| Aroclor-1260 | 220 | < 41.9 | < 42 | <4380 | < 447 | < 40.9 | < 41.4 |

- 1) All results reported in micrograms per kilogram (ug/kg) or parts per billion
- 2) PRG USEPA Region 9 Preliminary Remediation Goals
- 3) ne PRG not established
- 4) results shown in bold exceed the Residential PRG

TABLE 3B

SOIL ANALYTICAL DATA

("B" SECTION PESTICIDES and PCBs) Drake Street Property

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| Analyte | Residential PRG (mg/kg) | B-1 (0 - 1 ft.) | B-2 (0 - 1 ft.) | B-3 (0 - 1 ft.) | B-3D (1 - 3 ft.) |
|---------------------|-------------------------------|---------------------|---------------------|---------------------|----------------------|
| 4,4'-DDD | 2,400 | < 4.08 | 154 | < 178 | < 41.9 |
| 4,4'-DDE | 1,700 | < 4.08 | 511 | < 178 | < 41.9 |
| 4,4'-DDT | 1,700 | < 4.08 | 635 | 311 | < 41.9 |
| Aldrin | 29 | < 2.04 | < 22 | < 89 | < 20.9 |
| Dieldrin | 30 | < 4.08 | 109 | < 178 | < 41.9 |
| Endosulfan I | 370,000 | < 2.04 | < 22 | < 89 | < 20.9 |
| Endosulfan II | 370,000 | < 4.08 | < 44 | < 178 | < 41.9 |
| Endosulfan sulfate | ne | < 4.08 | < 44 | < 178 | < 41.9 |
| Endrin | 18,000 | < 4.08 | < 44 | < 178 | < 41.9 |
| Endrin aldehyde | ne | < 4.08 | < 44 | < 178 | < 41.9 |
| Endrin ketone | ne | < 4.08 | < 44 | < 178 | < 41.9 |
| Heptachlor | 110 | < 2.04 | < 22 | 187 | 39.3 |
| Heptachlor epoxide | 53 | < 2.04 | < 22 | 763 | 202 |
| Methoxychlor | 310,000 | < 20.4 | < 220 | < 890 | < 209 |
| Toxaphene | 440 | < 204 | < 2200 | < 8900 | < 2090 |
| alpha-BHC | 90 | < 2.04 | < 22 | < 89 | < 20.9 |
| alpha-Chlordane | 1,600 | < 2.04 | 187 | 392 | 149 |
| beta-BHC | 320 | < 4.08 | < 44 | < 178 | < 41.9 |
| delta-BHC | ne | < 2.04 | < 22 | < 89 | < 20.9 |
| gamma-BHC (Lindane) | 440 | < 2.04 | < 22 | < 89 | < 20.9 |
| gamma-Chlordane | 1,600 | < 2.04 | 186 | 795 | 329 |
| Aroclor-1016 | 3,900 | < 40.8 | < 440 | < 1780 | < 419 |
| Aroclor-1221 | 220 | < 40.8 | < 440 | < 1780 | < 419 |
| Aroclor-1232 | 220 | < 40.8 | < 440 | < 1780 | < 419 |
| Aroclor-1242 | 220 | < 40.8 | < 440 | < 1780 | < 419 |
| Aroclor-1248 | 220 | < 40.8 | < 440 | < 1780 | < 419 |
| Aroclor-1254 | 220 | < 40.8 | < 440 | < 1780 | < 419 |
| Aroclor-1260 | 220 | < 4.08 | < 440 | < 178 | < 41.9 |

- 1) All results reported in micrograms per kilogram (ug/kg) or parts per billion
- 2) PRG USEPA Region 9 Preliminary Remediation Goals
- 3) ne PRG not established
- 4) results shown in bold exceed the Residential PRG

TABLE 3C SOIL ANALYTICAL DATA

("C" SECTION PESTICIDES and PCBs)

Drake Street Property

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| Analyte | Residential PRG | C-1 (0 - 1 ft.) | C-2 (0 - 1 ft.) | C-3 (0 - 1 ft.) | C-4 (0 - 1 ft.) | C-4D (1 - 3 ft.) | C-5 (0 - 1 ft.) | C-6 (0 - 1 ft.) | C-6D (0 - 1 ft.) | C-7 (0 - 1 ft.) | C-8 (0 - 1 ft.) | C-8D (1 - 3 ft.) | C-9 (0 - 1 ft.) | C-10 (0 - 1 ft.) |
|---------------------|--------------------|---------------------|---------------------|---------------------|---------------------|----------------------|---------------------|---------------------|----------------------|---------------------|---------------------|----------------------|---------------------|----------------------|
| 4,4'-DDD | 2,400 | < 22.2 | < 4.11 | < 4.37 | 395 | 547 | 6300 | 3510 | < 45 | < 209 | < 42.3 | < 4.22 | < 44.6 | < 83.1 |
| 4,4'-DDE | 1,700 | < 22.2 | < 4.11 | 24.6 | 1210 | 1540 | < 4350 | < 2070 | 55.5 | 990 | 582 | 9.21 | 67.1 | 903 |
| 4,4'-DDT | 1,700 | < 22.2 | < 4.11 | 35.7 | 2460 | 3020 | 35700 | 15000 | 111 | 1850 | 287 | 8.47 | 99.4 | 538 |
| Aldrin | 29 | < 11.1 | < 2.05 | < 2.19 | < 126 | < 104 | < 2170 | < 1030 | < 45 | < 105 | < 21.1 | < 2.11 | < 44.6 | < 41.6 |
| Dieldrin | 30 | < 22.2 | < 4.11 | 7.53 | < 252 | < 209 | < 4350 | < 2070 | < 22.5 | < 209 | 89.9 | < 4.22 | < 22.3 | < 83.1 |
| Endosulfan I | 370,000 | < 11.1 | < 2.05 | < 2.19 | < 126 | < 104 | < 2170 | < 1030 | < 45 | < 105 | < 21.1 | < 2.11 | < 44.6 | < 41.6 |
| Endosulfan II | 370,000 | < 22.2 | < 4.11 | < 4.37 | < 252 | < 209 | < 4350 | < 2070 | < 22.5 | < 209 | < 42.3 | < 4.22 | < 22.3 | < 83.1 |
| Endosulfan sulfate | ne | < 22.2 | < 4.11 | < 4.37 | < 252 | < 209 | < 4350 | < 2070 | < 45 | < 209 | < 42.3 | < 4.22 | < 44.6 | < 83.1 |
| Endrin | 18,000 | < 22.2 | < 4.11 | < 4.37 | < 252 | < 209 | < 4350 | < 2070 | < 45 | < 209 | < 42.3 | < 4.22 | < 44.6 | < 83.1 |
| Endrin aldehyde | ne | < 22.2 | < 4.11 | < 4.37 | < 252 | < 209 | < 4350 | < 2070 | < 45 | < 209 | < 42.3 | < 4.22 | < 44.6 | < 83.1 |
| Endrin ketone | ne | < 22.2 | < 4.11 | < 4.37 | < 252 | < 209 | < 4350 | < 2070 | < 45 | < 209 | < 42.3 | < 4.22 | < 44.6 | < 83.1 |
| Heptachlor | 110 | < 11.1 | < 2.05 | < 2.19 | < 126 | < 104 | < 2170 | < 1030 | < 45 | < 105 | < 21.1 | < 2.11 | < 22.3 | < 41.6 |
| Heptachlor epoxide | 53 | < 11.1 | < 2.05 | < 2.19 | < 126 | < 104 | < 2170 | < 1030 | < 22.5 | < 105 | < 21.1 | < 2.11 | < 22.3 | < 41.6 |
| Methoxychlor | 310,000 | < 11.1 | < 20.5 | < 21.9 | < 1260 | < 1040 | < 21700 | < 10300 | < 22.5 | < 1050 | < 211 | < 21.1 | < 223 | < 416 |
| Toxaphene | 440 | < 1110 | < 205 | < 219 | < 12600 | < 10400 | < 217000 | < 103000 | < 225 | < 10500 | < 2110 | < 211 | < 2230 | < 4160 |
| alpha-BHC | 90 | < 11.1 | < 2.05 | < 2.19 | < 126 | < 104 | < 2170 | < 1030 | < 2250 | < 105 | < 21.1 | < 2.11 | < 22.3 | < 41.6 |
| alpha-Chlordane | 1,600 | < 11.1 | 4 | 16.3 | 444 | 583 | < 2170 | 1750 | 38.3 | 727 | 159 | 5.22 | < 22.3 | 524 |
| beta-BHC | 320 | < 22.2 | < 4.11 | < 4.37 | < 252 | < 209 | < 4350 | < 2070 | < 45 | < 209 | < 42.3 | < 4.22 | < 44.6 | < 83.1 |
| delta-BHC | ne | < 11.1 | < 2.05 | < 2.19 | < 126 | < 104 | < 2170 | < 1030 | < 22.5 | < 105 | < 21.1 | < 2.11 | < 22.3 | < 41.6 |
| gamma-BHC (Lindane) | 440 | < 11.1 | < 2.05 | < 2.19 | < 126 | < 104 | < 2170 | < 1030 | < 22.5 | < 105 | < 21.1 | < 2.11 | < 22.3 | < 41.6 |
| gamma-Chlordane | 1,600 | < 11.1 | 3.45 | 17.7 | 468 | 652 | < 2170 | 1720 | 39.4 | 777 | 112 | 5.99 | < 22.3 | 483 |
| Aroclor-1016 | 3,900 | < 222 | < 40.8 | < 43.7 | < 2520 | < 2090 | < 43500 | < 20700 | < 450 | < 2090 | < 423 | < 42.2 | < 446 | < 831 |
| Aroclor-1221 | 220 | < 222 | < 40.8 | < 43.8 | < 2520 | < 2090 | < 43500 | < 20700 | < 450 | < 2091 | < 423 | < 42.2 | < 446 | < 831 |
| Aroclor-1232 | 220 | < 222 | < 40.8 | < 43.9 | < 2520 | < 2090 | < 43500 | < 20700 | < 450 | < 2092 | < 423 | < 42.2 | < 446 | < 831 |
| Aroclor-1242 | 220 | < 222 | < 40.8 | < 43.10 | < 2520 | < 2090 | < 43500 | < 20700 | < 450 | < 2093 | < 423 | < 42.2 | < 446 | < 831 |
| Aroclor-1248 | 220 | < 222 | < 40.8 | < 43.11 | < 2520 | < 2090 | < 43500 | < 20700 | < 450 | < 2094 | < 423 | < 42.2 | < 446 | < 831 |
| Aroclor-1254 | 220 | < 222 | < 40.8 | < 43.12 | < 2520 | < 2090 | < 43500 | < 20700 | < 450 | < 2095 | < 423 | < 42.2 | < 446 | < 831 |
| Aroclor-1260 | 220 | < 222 | < 40.8 | < 43.13 | < 2520 | < 2090 | < 43500 | < 20700 | < 450 | < 2096 | < 423 | < 42.2 | < 446 | < 831 |

- 1) All results reported in micrograms per kilogram (ug/kg) or parts per billion
- 2) PRG USEPA Region 9 Preliminary Remediation Goals
- 3) ne PRG not established
- 4) results shown in bold exceed the Residential PRG

TABLE 3D

SOIL ANALYTICAL DATA ("D" SECTION PESTICIDES and PCBs) **Drake Street Property**

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| Analyte | Residential PRG | D-1 (0 - 1 ft.) | D-1D (1 - 3 ft.) | D-2 (0 - 1 ft.) | D-3 (0 - 1 ft.) |
|---------------------|--------------------|---------------------|----------------------|---------------------|---------------------|
| 4,4'-DDD | 2,400 | < 4.07 | < 4.15 | < 4.1 | < 4.06 |
| 4,4'-DDE | 1,700 | < 4.07 | < 4.15 | 5.21 | < 4.06 |
| 4,4'-DDT | 1,700 | < 4.07 | < 4.15 | 5.84 | 7.97 |
| Aldrin | 29 | < 2.04 | < 2.08 | < 2.05 | < 2.03 |
| Dieldrin | 30 | < 4.07 | < 4.15 | < 4.1 | < 4.06 |
| Endosulfan I | 370,000 | < 2.04 | < 2.08 | < 2.05 | <2.03 |
| Endosulfan II | 370,000 | < 4.07 | < 4.15 | < 4.1 | < 4.06 |
| Endosulfan sulfate | ne | < 4.07 | < 4.15 | < 4.1 | < 4.06 |
| Endrin | 18,000 | < 4.07 | < 4.15 | < 4.1 | < 4.06 |
| Endrin aldehyde | ne | < 4.07 | < 4.15 | < 4.1 | < 4.06 |
| Endrin ketone | ne | < 4.07 | < 4.15 | < 4.1 | < 4.06 |
| Heptachlor | 110 | < 2.04 | < 2.08 | < 2.05 | < 2.03 |
| Heptachlor epoxide | 53 | < 2.04 | < 2.08 | < 2.05 | < 2.03 |
| Methoxychlor | 310,000 | < 20.4 | < 20.8 | < 20.5 | < 20.3 |
| Toxaphene | 440 | < 204 | < 208 | < 205 | < 203 |
| alpha-BHC | 90 | < 2.04 | < 2.08 | < 2.05 | < 2.03 |
| alpha-Chlordane | 1,600 | < 2.04 | < 2.08 | < 2.05 | < 2.03 |
| beta-BHC | 320 | < 4.07 | < 4.15 | < 4.1 | < 4.06 |
| delta-BHC | ne | < 2.04 | < 2.08 | < 2.05 | < 2.03 |
| gamma-BHC (Lindane) | 440 | < 2.04 | < 2.08 | < 2.05 | < 2.03 |
| gamma-Chlordane | 1,600 | < 2.04 | < 2.08 | < 2.05 | < 2.03 |
| Aroclor-1016 | 3,900 | < 40.7 | < 41.5 | < 41.2 | < 40.6 |
| Aroclor-1221 | 220 | < 40.7 | < 41.5 | < 41.2 | < 40.6 |
| Aroclor-1232 | 220 | < 40.7 | < 41.5 | < 41.2 | < 40.6 |
| Aroclor-1242 | 220 | < 40.7 | < 41.5 | < 41.2 | < 40.6 |
| Aroclor-1248 | 220 | < 40.7 | < 41.5 | < 41.2 | < 40.6 |
| Aroclor-1254 | 220 | < 40.7 | < 41.5 | < 41.2 | < 40.6 |
| Aroclor-1260 | 220 | < 40.7 | < 41.5 | < 41.2 | < 40.6 |

- 1) All results reported in micrograms per kilogram (ug/kg) or parts per billion
- 2) PRG USEPA Region 9 Preliminary Remediation Goals
- 3) ne PRG not established 4) results shown in bold exceed the Residential PRG

TABLE 3E SOIL ANALYTICAL DATA

("E" SECTION PESTICIDES and PCBs) Drake Street Property

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| Analyte | Residential PRG | E-1 (0 - 1 ft.) | E-1D (1 - 3 ft.) | E-2 (0 - 1 ft.) | E-3 (0 - 1 ft.) |
|---------------------|-----------------|---------------------|----------------------|---------------------|---------------------|
| 4,4'-DDD | 2,400 | < 4.17 | < 4.53 | < 4.46 | < 5.11 |
| 4,4'-DDE | 1,700 | < 4.17 | < 4.53 | < 4.46 | < 5.11 |
| 4,4'-DDT | 1,700 | < 4.17 | < 4.53 | < 4.46 | < 5.11 |
| Aldrin | 29 | < 2.08 | < 2.26 | < 2.23 | < 2.56 |
| Dieldrin | 30 | 6.01 | < 4.53 | < 4.46 | < 5.11 |
| Endosulfan I | 370,000 | < 2.08 | < 2.26 | < 2.23 | < 2.56 |
| Endosulfan II | 370,000 | < 4.17 | < 4.53 | < 4.46 | < 5.11 |
| Endosulfan sulfate | ne | < 4.17 | < 4.53 | < 4.46 | < 5.11 |
| Endrin | 18,000 | < 4.17 | < 4.53 | < 4.46 | < 5.11 |
| Endrin aldehyde | ne | < 4.17 | < 4.53 | < 4.46 | < 5.11 |
| Endrin ketone | ne | < 4.17 | < 4.53 | < 4.46 | < 5.11 |
| Heptachlor | 110 | < 2.08 | < 2.26 | < 2.23 | < 2.56 |
| Heptachlor epoxide | 53 | < 2.08 | < 2.26 | < 2.23 | < 2.56 |
| Methoxychlor | 310,000 | < 20.8 | < 22.6 | < 22.3 | < 25.6 |
| Toxaphene | 440 | < 208 | < 226 | < 223 | < 256 |
| alpha-BHC | 90 | < 2.08 | < 2.26 | < 2.23 | < 2.56 |
| alpha-Chlordane | 1,600 | < 2.08 | < 2.26 | < 2.23 | < 2.56 |
| beta-BHC | 320 | < 4.17 | < 4.53 | < 4.46 | < 5.11 |
| delta-BHC | ne | < 2.08 | < 2.26 | < 2.23 | < 2.56 |
| gamma-BHC (Lindane) | 440 | < 2.08 | < 2.26 | < 2.23 | < 2.56 |
| gamma-Chlordane | 1,600 | < 2.08 | < 2.26 | < 2.23 | < 2.56 |
| Aroclor-1016 | 3,900 | < 4.17 | < 45.6 | < 44.9 | < 50.8 |
| Aroclor-1221 | 220 | < 4.17 | < 45.6 | < 44.9 | < 50.8 |
| Aroclor-1232 | 220 | < 4.17 | < 45.6 | < 44.9 | < 50.8 |
| Aroclor-1242 | 220 | < 4.17 | < 45.6 | < 44.9 | < 50.8 |
| Aroclor-1248 | 220 | < 4.17 | < 45.6 | < 44.9 | < 50.8 |
| Aroclor-1254 | 220 | < 4.17 | < 45.6 | < 44.9 | < 50.8 |
| Aroclor-1260 | 220 | < 4.17 | < 45.6 | < 44.9 | < 50.8 |

- 1) All results reported in micrograms per kilogram (ug/kg) or parts per billion
- 2) PRG USEPA Region 9 Preliminary Remediation Goals
- 3) ne PRG not established
- 4) results shown in bold exceed the Residential PRG

TABLE 3F SOIL ANALYTICAL DATA

("F" SECTION PESTICIDES and PCBs)

Drake Street Property

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| Analyte | Residential PRG | F-1 (0 - 1 ft.) | F-2 (0 - 1 ft.) | F-2D (1 - 3 ft.) | F-3 (0 - 1 ft.) |
|---------------------|--------------------|---------------------|---------------------|----------------------|---------------------|
| 4,4'-DDD | 2,400 | < 5.02 | < 4.35 | < 4.45 | < 4.31 |
| 4,4'-DDE | 1,700 | < 5.02 | < 4.35 | < 4.45 | < 4.31 |
| 4,4'-DDT | 1,700 | < 5.02 | < 4.35 | < 4.45 | < 4.31 |
| Aldrin | 29 | < 2.51 | < 2.17 | < 2.22 | < 2.15 |
| Dieldrin | 30 | < 5.02 | 33.2 | < 4.45 | 24.9 |
| Endosulfan I | 370,000 | < 2.51 | 29.1 | < 2.22 | < 2.15 |
| Endosulfan II | 370,000 | < 5.02 | < 4.35 | < 4.45 | < 4.31 |
| Endosulfan sulfate | ne | < 5.02 | < 4.35 | < 4.45 | < 4.31 |
| Endrin | 18,000 | < 5.02 | < 4.35 | < 4.45 | < 4.31 |
| Endrin aldehyde | ne | < 5.02 | < 4.35 | < 4.45 | < 4.31 |
| Endrin ketone | ne | < 5.02 | < 4.35 | < 4.45 | < 4.31 |
| Heptachlor | 110 | < 2.51 | < 2.17 | < 2.22 | < 2.15 |
| Heptachlor epoxide | 53 | < 2.51 | < 2.17 | < 2.22 | < 2.15 |
| Methoxychlor | 310,000 | < 25.1 | < 2.17 | < 22.2 | < 21.5 |
| Toxaphene | 440 | < 251 | < 217 | < 222 | < 215 |
| alpha-BHC | 90 | < 25.1 | < 2.17 | < 2.22 | < 2.15 |
| alpha-Chlordane | 1,600 | < 25.1 | < 2.17 | < 2.22 | < 2.15 |
| beta-BHC | 320 | < 5.02 | 12.7 | < 4.45 | < 4.31 |
| delta-BHC | ne | < 2.51 | < 2.17 | < 2.22 | < 2.15 |
| gamma-BHC (Lindane) | 440 | < 2.51 | < 2.17 | < 2.22 | < 2.15 |
| gamma-Chlordane | 1,600 | < 2.51 | 17.5 | < 2.22 | < 2.15 |
| Aroclor-1016 | 3,900 | < 50.2 | < 44.1 | < 44.9 | < 42.5 |
| Aroclor-1221 | 220 | < 50.2 | < 44.1 | < 44.9 | < 42.5 |
| Aroclor-1232 | 220 | < 50.2 | < 44.1 | < 44.9 | < 42.5 |
| Aroclor-1242 | 220 | < 50.2 | < 44.1 | < 44.9 | < 42.5 |
| Aroclor-1248 | 220 | < 50.2 | < 44.1 | < 44.9 | < 42.5 |
| Aroclor-1254 | 220 | < 50.2 | < 44.1 | < 44.9 | < 42.5 |
| Aroclor-1260 | 220 | < 50.2 | < 44.1 | < 44.9 | < 42.5 |

- 1) All results reported in micrograms per kilogram (ug/kg) or parts per billion
- 2) PRG USEPA Region 9 Preliminary Remediation Goals
- 3) ne PRG not established
- 4) results shown in bold exceed the Residential PRG

TABLE 4 SOIL ANALYTICAL DATA TOTAL DIOXINS and FURANS

Drake Street Property

USEPA Cooperative Agreement No. BF-96462106
Terracon Project No. 73077038

| Sample | Total Dioxin/Furans TEQ (Action level ≥ 1,000 pg/g) |
|--------|--|
| C-2 | 147 |
| C-3 | 218 |
| C-4 | 207 |
| C-5 | 145 |
| C-6 | 169 |
| C-8 | 102 |
| C-9 | 14 |
| C-10 | 165 |
| E-1 | 1.61 |
| F-2 | 7954 |
| F-3 | 53 |

- 1) All results reported in picograms per gram (pg/g) or parts per trillion
- 2) Results reported as estimated concentrations or as below detection limits are included in TEQ caluculations at half the detection limit
- 3) TEQ Toxicity Equivalent
- 4) TEQ is calculated by multiplying the actual grams weight of each dioxin and dioxin-like compound by its corresponding TEF and then summing the results. The number that results from this calculation is referred to as grams TEQ.
- Results shown in bold exceed the ATSDR action level (1000 pg/g TEQ) for Total Dioxins and Dioxin-like Compounds

TABLE 5 **SOIL ANALYTICAL DATA**

Volatile Organic Compounds (VOCs) Drake Street Property

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| Sail Parin | a | Sample Depth | | ٧ | OCs EPA N | lethod 8260 | ethod 8260 | | | |
|------------|-----------------|-----------------|-----------------------|-----------------------|-----------------------|-----------------------|------------|-----------------------|--|--|
| Soil Borin | | | 2-Butanone | Acetone | Methyl Acetate | Styrene | PCE | Toluene | | |
| | A-1 | 0 - 1 | < 5.13 | 72.9 | < 5.13 | 5.57 | < 5.13 | < 5.13 | | |
| Section A | A-1D | 1 -3 | < 5.89 | 82.4 | 19.1 | 6.53 | < 5.89 | < 5.89 | | |
| | A-2 | 0 - 1 | < 3.86 | 26.5 | < 3.86 | 3.96 | < 3.86 | < 3.86 | | |
| | A-3 | 0 - 1 | < 4.04 | 40.1 | 12.7 | < 4.04 | < 4.04 | < 4.04 | | |
| | B-1 | 0 - 1 | < 4.34 | 25 | < 4.34 | 4.55 | < 4.34 | < 4.34 | | |
| Section B | B-2 | 0 - 1 | 5.72 | < 1030 | < 4.1 | < 4.1 | < 4.1 | < 4.1 | | |
| | B-3 | 0 - 1 | < 6.15 | 70.2 | 13.7 | < 6.15 | < 6.15 | < 6.15 | | |
| | B-3D | 1 -3 | 11.5 | < 264 | 55.6 | < 4.69 | < 4.69 | < 4.69 | | |
| | C-1 | 0 - 1 | < 5.33 | 70.4 | < 5.33 | < 5.33 | < 5.33 | < 5.33 | | |
| | C-2 | 0 - 1 | < 4.08 | 34.7 | < 4.08 | < 4.08 | < 4.08 | < 4.08 | | |
| | C-3 | 0 - 1 | 6.91 | 81.3 | < 4.67 | < 4.67 | < 4.67 | < 4.67 | | |
| | C-4 | 0 - 1 | 6.77 | 58 | < 5.57 | < 5.57 | < 5.57 | < 5.57 | | |
| | C-4D | 1 -3 | < 3.92 | < 19.6 | < 3.92 | < 3.92 | < 3.92 | < 3.92 | | |
| Continu C | C-5 | 0 - 1 | 12.2 | 96.2 | < 4.44 | < 4.44 | < 4.44 | < 4.44 | | |
| Section C | C-6 | 0 - 1 | < 3.79 | 38.8 | 5.92 | < 3.79 | < 3.79 | < 3.79 | | |
| | C-6D | 0 - 1 | < 3.89 | < 19.5 | < 3.89 | < 3.89 | < 3.89 | < 3.89 | | |
| | C-7 | 0 - 1 | < 3.86 | 70.5 | < 3.86 | < 3.86 | < 3.86 | < 3.86 | | |
| | C-8 | 0 - 1 | 6.5 | 104 | < 4.87 | < 4.87 | < 4.87 | < 4.87 | | |
| | C-8D | 1 -3 | < 4.73 | 63 | < 4.73 | < 4.73 | < 4.73 | < 4.73 | | |
| | C-9 | 0 - 1 | < 5.14 | 66.2 | 12.3 | 5.28 | < 5.14 | 6.4 | | |
| | C-10 | 0 - 1 | 30.1 | 109 | < 4.72 | 5.88 | <4.72 | 6.98 | | |
| | D-1 | 0 - 1 | 5.04 | 70.2 | < 4.84 | < 4.84 | < 4.84 | < 4.84 | | |
| Section D | D-1D | 1 -3 | < 5.37 | 44.1 | < 5.37 | 6.07 | < 5.37 | < 4.84 | | |
| | D-2 | 0 - 1 | < 4.94 | 63.8 | 4.96 | 5.69 | < 4.94 | < 4.94 | | |
| | D-3 | 0 - 1 | < 4.59 | < 22.9 | < 4.59 | 5.09 | < 4.59 | < 4.59 | | |
| | E-1 | 0 - 1 | <4.23 | 56.9 | < 4.23 | 4.35 | < 4.23 | < 4.23 | | |
| Section E | E-1D | 1 -3 | < 5.3 | 29.4 | < 5.3 | 6.27 | < 5.3 | < 5.3 | | |
| | E-2 | 0 - 1 | < 4.31 | 34.3 | <4.31 | 4.43 | < 4.31 | < 4.31 | | |
| | E-3 | 0 - 1 | < 5.32 | 55.9 | < 5.32 | 5.67 | 5.67 | <5.32 | | |
| | F-1 | 0 - 1 | < 9.55 | 55.8 | < 9.55 | < 9.55 | < 9.55 | < 9.55 | | |
| Section F | F-2 | 0 - 1 | < 5.38 | 30.3 | < 5.38 | 5.82 | 6.43 | < 5.38 | | |
| | F-2D | 1 -3 | < 4.43 | < 22.1 | < 4.43 | 4.81 | < 4.43 | < 4.43 | | |
| | F-3 | 0 - 1 | < 4.72 | 60.8 | <4.72 | 5.81 | < 4.72 | < 4.72 | | |
| Background | BG-1 | 0 - 1 | < 4.38 | < 217 | 7.34 | 4.48 | < 4.38 | < 4.38 | | |
| Dackground | BG-1D | 1 -3 | < 4.46 | 23 | < 8.93 | < 4.46 | < 4.46 | < 4.46 | | |
| | Soil Trip Blank | | < 5.56 | 59.7 | < 5.56 | < 5.56 | < 5.56 | < 5.56 | | |
| | Residential PRG | | 2.2 x 10 ⁷ | 1.4 x 10 ⁷ | 2.2 x 10 ⁷ | 1.7 x 10 ⁶ | 480 | 5.2 x 10 ⁵ | | |

- 1) All results reported in micrograms per kilogram (ug/kg) or parts per billion
- 2) PRG USEPA Region 9 Preliminary Remediation Goals established for residential soils
- 3) Samples collected May 27 through 30, 2008
 4) Only those VOCs with reported concentrations above detection limits are shown

TABLE 6 SOIL ANALYTICAL DATA

Semi-Volatile Organic Compounds (SVOCs) Drake Street Property

USEPA Cooperative Agreement No. BF-96462106
Terracon Project No. 73077038

| Analyte | Residential PRG | B-2 (0 - 1 ft.) | C-6 (0 - 1 ft.) | C-8 (0 - 1 ft.) |
|--|---|---|---|--|
| Di-n-butyl phthalate Diethyl phthalate | 6.1E+06 4.9E+07 | 2,660 540 | 558 < 340 | 516 < 350 |
| PAHs Anthracene Benzo(a)anthracene Benzo(a)pyrene Benzo(b)fluroanthene Benzo(k)fluroanthene Chrysene Fluroanthene Indeno(1,2,3) Pyrene Phenanthrene Pyrene | 2.2E+07 621 62 621 621 62,145 2.3E+06 621 ne 2.3E+06 | < 366 < 366 < 366 < 366 < 366 < 366 < 366 < 366 < 366 < 366 < 366 | < 340 < 340 < 340 < 340 < 340 < 340 < 340 < 340 < 340 < 340 < 340 < 340 | 506 1,270 931 1,500 447 983 4,250 882 2,430 1,530 |

- 1) All results reported in micrograms per kilogram ug/kg or parts per billion
- 2) PRG USEPA Region 9 Preliminary Remediation Goals established for residential soils
- 3) ne PRG not established
- 4) results shown in bold exceed the Residential PRG for Soil
- 5) Results shown in italics exceed three times background for compunds with no applicable action level
- 6) Only those SVOCs with reported concentrations above detection limits are shown

TABLE 7 GROUNDWATER ANALYTICAL DATA

Drake Street Property USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| | MCL | BF-1 | BF-2 | BF-3 | BF-4 | MW-3 | MW-8 | MW-8A | MW-15 |
|--|-------|--------------|----------|--------------|--------------|----------|----------|----------|--------------|
| VOCs EPA Method 826 | 0 | | | | | | | | |
| Trichloroethene (ug/l) | 5.0 | < 5 | < 5 | < 5 | < 5 | 6.66 | < 5 | < 5 | 55.9 |
| Pesticides EPA Method 8081 <i>A</i> | 1 | | | | | | | | |
| Dieldrin (ug/l) | ne | < 0.108 | < 0.101 | < 0.103 | < 0.101 | < 0.101 | < 0.101 | < 0.105 | 0.192 |
| Metals EPA Method 6010B (n | ng/l) | | | | | | | | |
| Aluminum | ne | 9.82 | < 0.2 | 11.8 | 4.85 | 0.65 | 0.43 | 0.82 | 8.47 |
| Antimony | 0.006 | < 0.06 | < 0.06 | < 0.06 | < 0.06 | < 0.06 | < 0.06 | < 0.06 | < 0.06 |
| Arsenic | 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 |
| Barium | 2 | 0.067 | < 0.01 | 0.045 | 0.087 | < 0.01 | 0.018 | 0.028 | 0.024 |
| Beryllium | 0.004 | < 0.005 | < 0.005 | < 0.005 | < 0.005 | < 0.005 | < 0.005 | < 0.005 | < 0.005 |
| Cadmium | 0.005 | < 0.005 | < 0.005 | < 0.005 | < 0.005 | < 0.005 | < 0.005 | < 0.005 | 1.19 |
| Calcium | ne | 3.68 | 0.61 | 16.6 | 3.68 | 1.36 | 1.52 | 21.3 | 26.2 |
| Chromium | 0.1 | 0.027 | < 0.01 | 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 |
| Cobalt | ne | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | 0.027 |
| Copper | 1.3 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | 0.055 |
| Iron | ne | 16 | 0.1 | 9.03 | 23.6 | 0.65 | 1.54 | 1.13 | 10.7 |
| Lead | 0.015 | 0.059 | < 0.015 | 0.035 | 0.015 | < 0.015 | < 0.015 | < 0.015 | 0.021 |
| Magnesium | ne | 1.08 | 0.41 | 1.31 | 0.59 | 0.5 | 0.58 | 0.32 | 3.28 |
| Manganese | ne | 0.33 | < 0.015 | 0.06 | 0.5 | < 0.015 | < 0.015 | 0.022 | 1.53 |
| Mercury (Method 7074A) | 0.002 | 0.00026 | < 0.0002 | 0.00024 | < 0.0002 | < 0.0002 | < 0.0002 | < 0.0002 | 0.00097 |
| Nickel | ne | < 0.04 | < 0.04 | < 0.04 | < 0.04 | < 0.04 | < 0.04 | < 0.04 | 0.33 |
| Potassium | ne | 1.17 | < 0.5 | 1.18 | 1.1 | < 0.5 | < 0.5 | 0.88 | 17.6 |
| Selenium | 0.05 | < 0.04 | < 0.04 | < 0.04 | < 0.04 | < 0.04 | < 0.04 | < 0.04 | < 0.04 |
| Silver | ne | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 | < 0.01 |
| Sodium | ne | 5.15 | 4.1 | 4.39 | 1.82 | 4.25 | 3.75 | 1.9 | |
| Thallium | 0.002 | < 0.02 | < 0.02 | < 0.02 | < 0.02 | < 0.02 | < 0.02 | < 0.02 | < 0.02 |
| Vanadium | ne | 0.062 | < 0.02 | 0.04 | < 0.02 | < 0.02 | < 0.02 | < 0.02 | < 0.02 |
| Zinc | ne | < 0.02 | < 0.02 | 0.035 | < 0.02 | < 0.02 | < 0.02 | < 0.02 | 1.36 |

- 1) Analytes listed above were the only compounds detected in the ground water.
- 2) ug/l micrograms per liter or parts per billion
- 3) Metals results reported as milligrams per liter (mg/l) or parts per million.
- 4) MCL maximum contaminant level as listed in the South Carolina State Primary Drinking Water Regulations R.61.59
- 5) Results shown in boldface type indicate concentrations which exceed the MCL for that compound.
- 6) ne MCL not established

TABLE 8 RECEPTOR SURVEY

Drake Street Property

USEPA Cooperative Agreement No. BF-96462106 Terracon Project No. 73077038

| ID Number | | Potential receptor/ Relative gradient |
|---------------------|---------------------------------|---|
| (shown on Figure 8) | Owner/Address | with respect to the site |
| 1 | Norma Hunt | |
| ı | 6100 Sheldon Ln. | In-service irrigation well/ upgradient |
| 2 | Hampton Park (City of Columbia) | |
| 2 | 1117 Brandon Ave. | pond/ crossgradient |
| 2 | unknown | |
| 3 | 1030 Brandon Ave. | well pump observed in yard/ crossgradient |
| 4 | Patrick Baxley | |
| 4 | 934 Brandon Ave. | well pump observed in yard/ crossgradient |
| 5 | Huntington Place Benchmark | |
| 5 | 1001 True Street | pond/ crossgradient |
| | located at | |
| 6 | 150 Sallie Baxter Drive | stream/ downgradient |